
MCUXpresso SDK Release Notes Supporting twrkm34z75m

Change Logs

NXP Semiconductors



Contents

Driver Change Log

CLOCK	1
I2C	1
SPI_CMSIS	2
UART	2
ADC16	3
AFE	3
CMP	4
COMMON	4
CRC	6
DMA	6
DMAMUX	7
EWM	7
FLASH	8
GPIO	9
I2C	10
IRTC	12
LLWU	13
LPTMR	13
LPUART	14
LPUART_DMA	17

Title	Page No.
LPUART_FREERTOS	17
MMAU	17
PDB	18
PIT	18
PMC	19
PORT	19
QTMR	20
RCM	20
SIM	20
SLCD	21
SMC	21
SPI	22
SPI DMA Driver	23
SPI FreeRTOS Driver	24
UART	25
UART_DMA	27
UART_FREERTOS	28
VREF	28
WDOG	28
XBAR	28

Middleware Change Log

FreeMASTER Communication Driver	30
--	-----------

Component Change Log

SERIAL_MANAGER	31
-----------------------------	-----------

1 Driver Change Log

CLOCK

Current CLOCK driver version is 2.5.0

- 2.5.0
 - New feature:
 - * Moved SDK_DelayAtLeastUs function from clock driver to common driver.
- 2.4.0
 - New feature -Added two APIs to set slow and fast internal reference clock variable.
- 2.3.0
 - Fix the issue for MISRA-2012 check.
 - * Fixed rule 10.4, rule 10.1, rule 10.6, rule 13.5, rule 10.8.
 - Bug Fix:
 - * Fix incorrect External Oscillator Configuration sequence and ensure oscillator configuration be executed before it be enabled.
 - New feature
 - * Adding new API CLOCK_DelayAtLeastUs() to implement a delay function which allow users set delay in unit of microsecond.
- 2.2.1
 - Bug Fix:
 - * Fix the issue that MCG could not switch to FEE/FBE/PBE modes when OSCERCLK clock not enabled.
- 2.2.0
 - New Features:
 - * [KPSDK-9157] Update CLOCK_SetFeiMode/CLOCK_SetFbiMode/CLOCK_BootToFeiMode() to support set MCG_C4[DMX32]=1 in FEI/FBI modes.
 - Bug Fix:
 - * Update IP_CLOCKS array, remove unused gates and add missing gates.
- 2.1.0
 - Other Changes:
 - * Merge fsl_mcg and fsl_osc into fsl_clock.
- 2.0.0
 - Initial version.

I2C

Current I2C CMSIS driver version is 2.2.0

- 2.2.0
 - Bug Fixes
 - * Fixed the MISRA-2012 violations.
 - Fixed rule 8.4, 8.6, 10.1, 10.3, 10.4, 11.1, 11.8, 14.4, 16.1, 16.3, 17.7, 17.3, 17.7, 20.9.

- 2.0.1
 - Bug Fixes
 - * In ARM_I2C_ABORT_TRANSFER operation in I2C_InterruptControl, the method to check if I2C is operating as slave is not correct, then master may have potential risk to block at the slave check code.
- 2.0.0
 - Initial version.

SPI_CMSIS

Current spi_cmsis driver version is 2.3

- 2.3
 - Bug Fixes
 - * Fixed the MISRA-2012 violations.
 - Fixed rule 8.4, 8.6, 10.1, 10.3, 10.4, 10.8, 11.8, 11.9, 14.4, 16.1, 16.3, 16.4, 17.7, 20.9.
- 2.2
 - Bug Fixes
 - * Fixed the bug that, the parameter num of APIs ARM_SPI_Transfer, ARM_SPI_Send and ARM_SPI_Receive, and the return value of API ARM_SPI_GetDataCount should be the number of data item defined by datawidth, rather than the number of byte.
- 2.1
 - Bug Fixes
 - * Fixed the wrong clock polarity assignment in driver. For ARM_SPI_CPOL0_CPHA0 and other frame format parameters, CPOL = 0 means kSPI_ClockPolarityActiveHigh not kSPI_ClockPolarityActiveLow in driver.
 - New features
 - * Added new feature to support 3-wire mode for both master and slave instance. User can use ARM_SPI_MODE_MASTER_SIMPLEX to set the MOSI pin as output/input pin, and use the ARM_SPI_MODE_SLAVE_SIMPLEX to set the MISO pin as output/input pin.
 - * Allowed user to set up the default transmit value by using ARM_SPI_SET_DEFAULT_TX_VALUE.
- 2.0
 - Initial version.

UART

The current UART CMSIS driver version is 2.1

- 2.1
 - Bug Fixes
 - * Fixed the MISRA-2012 violations.
 - Fixed rule 8.48.610.110.310.411.111.914.415.716.116.316.416.617.720.720.9.

- 2.0
 - Initial version.

ADC16

The current ADC16 driver version is 2.3.0.

- 2.3.0
 - Improvements
 - * Added new API ADC16_EnableAsynchronousClockOutput() to enable/disable ADACK output.
 - * In ADC16_GetDefaultConfig(), set enableAsynchronousClock to false.
- 2.2.0
 - Improvements
 - * Added hardware average mode in adc_config_t structure, then the hardware average mode can be set by invoking ADC16_Init() function.
- 2.1.0
 - New Features:
 - * Supported KM series' new ADC reference voltage source, bandgap from PMC.
- 2.0.3
 - Bug Fixes
 - * Fixed IAR warning Pa082: the order of volatile access should be defined.
- 2.0.2
 - Improvements
 - * Used conversion control feature macro instead of that in IO map.
- 2.0.1
 - Bug Fixes
 - * Fixed MISRA-2012 rules.
 - Rule 16.4, 10.1, 13.2, 14.4 and 17.7.
- 2.0.0
 - Initial version

AFE

The current AFE driver version is 2.0.2.

- 2.0.2
 - Bug Fixes
 - * Fixed MISRA C-2012 rule 10.1, rule 10.4 and so on.
- 2.0.1
 - Improvements
 - * Changed type modifiers from const xx_Type * s_xxBases to xx_Type *const s_xxBases.
 - * Added static modifier for s_xxx variables defined in drivers.
- 2.0.0

- Initial version.

CMP

The current CMP driver version is 2.0.2.

- 2.0.2
 - Bug Fixes
 - * Fixed the violations of MISRA 2012 rules:
 - Rule 10.3
- 2.0.1
 - Bug Fixes
 - * Fixed MISRA-2012 rules.
 - Rule 14.4, rule 10.3, rule 10.1, rule 10.4 and rule 17.7.
- 2.0.0
 - Initial version.

COMMON

The current COMMON driver version is 2.3.2.

- 2.3.2
 - Improvements
 - * Make driver aarch64 compatible
- 2.3.1
 - Bug Fixes
 - * Fixed MAKE_VERSION overflow on 16-bit platforms.
- 2.3.0
 - Improvements
 - * Split the driver to common part and CPU architecture related part.
- 2.2.10
 - Bug Fixes
 - * Fixed the ATOMIC macros build error in cpp files.
- 2.2.9
 - Bug Fixes
 - * Fixed MISRA C-2012 issue, 5.6, 5.8, 8.4, 8.5, 8.6, 10.1, 10.4, 17.7, 21.3.
 - * Fixed SDK_Malloc issue that not allocate memory with required size.
- 2.2.8
 - Improvements
 - * Included stddef.h header file for MDK tool chain.
 - New Features:
 - * Added atomic modification macros.
- 2.2.7
 - Other Change

- * Added MECC status group definition.
- 2.2.6
 - Other Change
 - * Added more status group definition.
 - Bug Fixes
 - * Undef __VECTOR_TABLE to avoid duplicate definition in cmsis_clang.h
- 2.2.5
 - Bug Fixes
 - * Fixed MISRA C-2012 rule-15.5.
- 2.2.4
 - Bug Fixes
 - * Fixed MISRA C-2012 rule-10.4.
- 2.2.3
 - New Features
 - * Provided better accuracy of SDK_DelayAtLeastUs with DWT, use macro SDK_DELAY_USE_DWT to enable this feature.
 - * Modified the Cortex-M7 delay count divisor based on latest tests on RT series boards, this setting lets result be closer to actual delay time.
- 2.2.2
 - New Features
 - * Added include RTE_Components.h for CMSIS pack RTE.
- 2.2.1
 - Bug Fixes
 - * Fixed violation of MISRA C-2012 Rule 3.1, 10.1, 10.3, 10.4, 11.6, 11.9.
- 2.2.0
 - New Features
 - * Moved SDK_DelayAtLeastUs function from clock driver to common driver.
- 2.1.4
 - New Features
 - * Added OTFAD into status group.
- 2.1.3
 - Bug Fixes
 - * MISRA C-2012 issue fixed.
 - Fixed the rule: rule-10.3.
- 2.1.2
 - Improvements
 - * Add SUPPRESS_FALL_THROUGH_WARNING() macro for the usage of suppressing fallthrough warning.
- 2.1.1
 - Bug Fixes
 - * Deleted and optimized repeated macro.
- 2.1.0
 - New Features
 - * Added IRQ operation for XCC toolchain.
 - * Added group IDs for newly supported drivers.

- 2.0.2
 - Bug Fixes
 - * MISRA C-2012 issue fixed.
 - Fixed the rule: rule-10.4.
- 2.0.1
 - Improvements
 - * Removed the implementation of LPC8XX Enable/DisableDeepSleepIRQ() function.
 - * Added new feature macro switch "FSL_FEATURE_HAS_NO_NONCACHEABLE_SECTION" for specific SoCs which have no noncacheable sections, that helps avoid an unnecessary complex in link file and the startup file.
 - * Updated the align(x) to **attribute**(aligned(x)) to support MDK v6 armclang compiler.
- 2.0.0
 - Initial version.

CRC

The current CRC driver version is 2.0.3.

- 2.0.3
 - Bug fix:
 - * Fix MISRA issues.
- 2.0.2
 - Bug fix:
 - * Fix MISRA issues.
- 2.0.1
 - Bug fix:
 - * DATA and DATALL macro definition moved from header file to source file.
- 2.0.0
 - Initial version.

DMA

The current DMA driver version is 2.1.1.

- 2.1.1
 - Improvements
 - * Corrected the dma channel feature macro from FSL_FEATURE_DMAMUX_MODULE_CHANNEL to FSL_FEATURE_DMA_MODULE_CHANNEL.
- 2.1.0
 - Improvements
 - * Added api DMA_PrepareTransferConfig to expose option address increment.
 - * Added api DMA_EnableAutoStopRequest to support auto stop request feature.
- 2.0.2
 - Bug Fixes

- * Fixed violations of MISRA C-2012 rule 10.4, 10.3, 14.4, 16.4, 11.6, 10.1.
- 2.0.1
 - Bug Fixes
 - * By adding parenthesis, fixed the build fail of DMA driver due to rule 12.5, MISRA C 2004.
- 2.0.0
 - Initial version.

DMAMUX

The current DMAMUX driver version is 2.0.5.

- 2.0.5
 - Improvements
 - * Added feature FSL_FEATURE_DMAMUX_CHCFG_REGISTER_WIDTH for the difference of CHCFG register width.
- 2.0.4
 - Bug Fixes
 - * Fixed violations of MISRA C-2012 rule 10.4.
- 2.0.3
 - Bug Fixes
 - * Fixed the issue for MISRA-2012 check.
 - Fixed rule 10.4 and rule 10.3.
- 2.0.2
 - New Features
 - * Added an always-on enable feature to a DMA channel for ULP1 DMAMUX support.
- 2.0.1
 - Bug Fixes
 - * Fixed the build warning issue by changing the type of parameter source from uint8_t to uint32_t when setting DMA request source in DMAMUX_SetSourceChange.
- 2.0.0
 - Initial version.

EWM

The current EWM driver version is 2.0.3.

- 2.0.3
 - Bug Fixes
 - * Fixed violation of MISRA C-2012 rules: 10.1, 10.3.
- 2.0.2
 - Bug Fixes
 - * Fixed violation of MISRA C-2012 rules: 10.3, 10.4.
- 2.0.1

- Bug Fixes
 - * Fixed the hard fault in EWM_Deinit.
- 2.0.0
 - Initial version.

FLASH

Current FLASH driver version is 3.1.2

- 3.1.2
 - Bug Fixes — Remove redundant comments.
- 3.1.1
 - Bug Fixes — MISRA C-2012 issue fixed: rule 10.3
- 3.1.0
 - New Feature
 - * Support erase flash asynchronously.
- 3.0.2
 - Bug Fixes — MISRA C-2012 issue fixed: rule 8.4, 17.7, 10.4, 16.1, 21.15, 11.3, 10.7 — building warning -Wnull-dereference on arm compiler v6
- 3.0.1
 - New Features
 - * Added support FlexNVM alias for (kw37/38/39).
- 3.0.0
 - Improvements
 - * Reorganized FTFx flash driver source file.
 - * Extracted flash cache driver from FTFx driver.
 - * Extracted flexnvm flash driver from FTFx driver.
- 2.3.1
 - Bug Fixes
 - * Unified Flash IFR design from K3.
 - * New encoding rule for K3 flash size.
- 2.3.0
 - New Features
 - * Added support for device with LP flash (K3S/G).
 - * Added flash prefetch speculation APIs.
 - Improvements
 - * Refined flash_cache_clear function.
 - * Reorganized the member of flash_config_t struct.
- 2.2.0
 - New Features
 - * Supported FTFL device in FLASH_Swap API.
 - * Supported various pflash start addresses.
 - * Added support for KV58 in cache clear function.
 - * Added support for device with secondary flash (KW40).

- Bug Fixes
 - * Compiled execute-in-ram functions as PIC binary code for driver use.
 - * Added missed flexram properties.
 - * Fixed unaligned variable issue for execute-in-ram function code array.
- 2.1.0
 - Improvements
 - * Updated coding style to align with KSDK 2.0.
 - * Different-alignment-size support for pflash and flexnvm.
 - * Improved the implementation of execute-in-ram functions.
- 2.0.0
 - Initial version

GPIO

The current driver version is 2.6.0.

- 2.6.0
 - New Features
 - * Added API to get GPIO version information.
 - * Added API to control a pin for general purpose input.
 - * Added some APIs to control pin in secure and privilege status.
- 2.5.3
 - Bug Fixes
 - * Correct the feature macro typo: FSL_FEATURE_GPIO_HAS_NO_INDEP_OUTPUT_CONTORL.
- 2.5.2
 - Improvements
 - * Improved GPIO_PortSet/GPIO_PortClear/GPIO_PortToggle functions to support devices without Set/Clear/Toggle registers.
- 2.5.1
 - Bug Fixes
 - * Fixed wrong macro definition.
 - * Fixed MISRA C-2012 rule issues in the FGPIO_CheckAttributeBytes() function.
 - * Defined the new macro to separate the scene when the width of registers is different.
 - * Removed some redundant macros.
 - New Features
 - * Added some APIs to get/clear the interrupt status flag when the port doesn't control pins' interrupt.
- 2.4.1
 - Improvements
 - * Improved GPIO_CheckAttributeBytes() function to support 8 bits width GACR register.
- 2.4.0
 - Improvements
 - * API interface added:

- New APIs were added to configure the GPIO interrupt clear settings.
- 2.3.2
 - Bug Fixes
 - * Fixed the issue for MISRA-2012 check.
 - Fixed rule 3.1, 10.1, 8.6, 10.6, and 10.3.
- 2.3.1
 - Improvements
 - * Removed deprecated APIs.
- 2.3.0
 - New Features
 - * Updated the driver code to adapt the case of interrupt configurations in GPIO module. New APIs were added to configure the GPIO interrupt settings if the module has this feature on it.
- 2.2.1
 - Improvements
 - * API interface changes:
 - Refined naming of APIs while keeping all original APIs by marking them as deprecated. The original APIs will be removed in next release. The main change is updating APIs with prefix of `_PinXXX()` and `_PortXXX`.
- 2.1.1
 - Improvements
 - * API interface changes:
 - Added an API for the check attribute bytes.
- 2.1.0
 - Improvements
 - * API interface changes:
 - Added "pins" or "pin" to some APIs' names.
 - Renamed "`_PinConfigure`" to "`GPIO_PinInit`".

I2C

The current I2C driver version is 2.0.9.

- 2.0.9
 - Bug Fixes
 - * Fixed the MISRA-2012 violations.
 - Fixed rule 8.4, 10.1, 10.4, 13.5, 20.8.
- 2.0.8
 - Bug Fixes
 - * Fixed the bug that DFEN bit of I2C Status register 2 could not be set in `I2C_MasterInit`.
 - * MISRA C-2012 issue fixed: rule 14.2, 15.7, and 16.4.
 - * Eliminated IAR Pa082 warnings from `I2C_MasterTransferDMA` and `I2C_MasterTransferCallbackDMA` by assigning volatile variables to local variables and using local variables instead.

- * Fixed MISRA issues.
 - Fixed rules 10.1, 10.3, 10.4, 11.9, 14.4, 15.7, 17.7.
- Improvements
 - * Improved timeout mechanism when waiting certain state in transfer API.
 - * Updated the I2C_WAIT_TIMEOUT macro to unified name I2C_RETRY_TIMES.
 - * Moved the master manually acknowledge byte operation into static function I2C_MasterAckByte.
 - * Fixed control/status clean flow issue inside I2C_MasterReadBlocking to avoid potential issue that pending status is cleaned before it's proceeded.
- 2.0.7
 - Bug Fixes
 - * Fixed the issue for MISRA-2012 check.
 - Fixed rule 11.9 ,15.7 ,14.4 ,10.4 ,10.8 ,10.3, 10.1, 10.6, 13.5, 11.3, 13.2, 17.7, 5.7, 8.3, 8.5, 11.1, 16.1.
 - * Fixed Coverity issue of unchecked return value in I2C_RTOS_Transfer.
 - * Fixed variable redefine issue by moving i2cBases from fsl_i2c.h to fsl_i2c.c.
 - Improvements
 - * Added I2C_MASTER_FACK_CONTROL macro to enable FACK control for master transfer receive flow with IP supporting double buffer, then master could hold the SCL by manually setting TX AK/NAK during data transfer.
- 2.0.6
 - Bug Fixes
 - * Fixed the issue that I2C Master transfer APIs(blocking/non-blocking) did not support the situation of master transfer with subaddress and transfer data size being zero, which means no data followed by the subaddress.
- 2.0.5
 - Improvements
 - * Added I2C_WATI_TIMEOUT macro to allow the user to specify the timeout times for waiting flags in functional API and blocking transfer API.
- 2.0.4
 - Bug Fixes
 - * Added a proper handle for transfer config flag kI2C_TransferNoStartFlag to support transmit with kI2C_TransferNoStartFlag flag. Support write only or write+read with no start flag; does not support read only with no start flag.
- 2.0.3
 - Bug Fixes
 - * Removed enableHighDrive member in the master/slave configuration structure because the operation to HDRS bit is useless, the user need to use DSE bit in port register to configure the high drive capability.
 - * Added register reset operation in I2C_MasterInit and I2C_SlaveInit APIs. Fixed issue where I2C could not switch between master and slave mode.
 - * Improved slave IRQ handler to handle the corner case that stop flag and address match flag come synchronously.
- 2.0.2
 - Bug Fixes

- * Fixed issue in master receive and slave transmit mode with no stop flag. The master could not succeed to start next transfer because the master could not send out re-start signal.
- * Fixed the out-of-order issue of data transfer due to memory barrier.
- * Added hold time configuration for slave. By leaving the SCL divider and MULT reset values when configured to slave mode, the setup and hold time of the slave is then reduced outside of spec for lower baudrates. This can cause intermittent arbitration loss on the master side.
- New Features
 - * Added address nak event for master.
 - * Added general call event for slave.
- 2.0.1
 - New Features
 - * Added double buffer enable configuration for SoCs which have the DFEN bit in S2 register.
 - * Added flexible transmit/receive buffer size support in I2C_SlaveHandleIRQ.
 - * Added start flag clear, address match, and release bus operation in I2C_SlaveWrite/Read-Blocking API.
 - Bug Fixes
 - * Changed the kI2C_SlaveRepeatedStartEvent to kI2C_SlaveStartEvent.
- 2.0.0
 - Initial version.

IRTC

The current IRTC driver version is 2.1.1.

- 2.1.1
 - Bug Fixes
 - * MISRA C-2012 issue check.
 - Fixed rules, containing: rule-10.1, rule-10.3, rule-10.4.
- 2.1.0
 - Bug Fixes
 - * Fixed incorrect leap year check in IRTC_CheckDatetimeFormat.
 - New Feature
 - * Added new APIs for new feature FSL_FEATURE_RTC_HAS_SUBSYSTEM.
 - * Added new APIs for TAMPER, TAMPER QUEUE status get and clear.
 - * Added new API to enable/disable 32 kHz RTC OSC clock during RTC register write.
 - * Updated IRTC_SetTamperParams to support new feature FSL_FEATURE_RTC_HAS_FILTER23_CFG
 - * Updated irtc_config_t to exclude member wakeupSelect for new feature FSL_FEATURE_RTC_HAS_NO_CTRL2_WAKEUP_MODE.
- 2.0.2
 - Bug Fixes
 - * MISRA C-2012 issue check.

- Fixed rules, containing: rule-10.1, rule-10.3, rule-10.4, rule-10.6, rule-10.8, rule-11.9, rule-12.2, rule-15.5, rule-16.4, rule-17.7.
- 2.0.1
 - Bug Fixes
 - * Fixed the issue of hard code in IRTC_Init.
- 2.0.0
 - Initial version.

LLWU

The current LLWU driver version is 2.0.5.

- 2.0.5
 - Bug Fixes
 - * Fixed violations of the MISRA C-2012 rules 10.3.
 - * Fixed the issue that function LLWU_SetExternalWakeupPinMode() does not work on 32-bit width platforms.
- 2.0.4
 - Bug Fixes
 - * Fixed violations of the MISRA C-2012 rules 10.3, 10.4, 10.6, 10.7, 11.3.
 - * Fixed issue that LLWU_ClearExternalWakeupPinFlag may clear other filter flags by mistake on platforms with 32-bit LLWU registers.
- 2.0.3
 - Bug Fixes
 - * Fixed MISRA-2012 rules.
 - Rule 16.4.
- 2.0.2
 - Improvements
 - * Corrected driver function LLWU_SetResetPinMode parameter name.
 - Bug Fixes
 - * Fixed MISRA-2012 rules.
 - Rule 14.4, 10.8, 10.4, 10.3.
- 2.0.1
 - Other Changes
 - * Updates for KL8x.
- 2.0.0
 - Initial version.

LPTMR

The current LPTMR driver version is 2.1.1.

- 2.1.1
 - Improvements

- * Updated the characters from "PTMR" to "LPTMR" in "FSL_FEATURE_PTMR_HAS_NO_PRESCALER_CLOCK_SOURCE_1_SUPPORT" feature definition.
- 2.1.0
 - Improvements
 - * Implement for some special devices' not supporting for all clock sources.
 - Bug Fixes
 - * Fixed issue when accessing CMR register.
- 2.0.2
 - Bug Fixes
 - * Fixed MISRA-2012 issues.
 - Rule 10.1.
- 2.0.1
 - Improvements
 - * Updated the LPTMR driver to support 32-bit CNR and CMR registers in some devices.
- 2.0.0
 - Initial version.

LPUART

The current LPUART driver version is 2.5.3.

- 2.5.3
 - Bug Fixes
 - * Fixed comments by replacing unused status flags kLPUART_NoiseErrorInRxDataRegFlag and kLPUART_ParityErrorInRxDataRegFlag with kLPUART_NoiseErrorFlag and kLPUART_ParityErrorFlag.
- 2.5.2
 - Bug Fixes
 - * Fixed bug that when setting watermark for TX or RX FIFO, the value may exceed the maximum limit.
 - Improvements
 - * Added check in LPUART_TransferDMAHandleIRQ and LPUART_TransferEdmaHandleIRQ to ensure if user enables any interrupts other than transfer complete interrupt, the dma transfer is not terminated by mistake.
- 2.5.1
 - Improvements
 - * Use separate data for TX and RX in lpuart_transfer_t.
 - Bug Fixes
 - * Fixed bug that when ring buffer is used, if some data is received in ring buffer first before calling LPUART_TransferReceiveNonBlocking, the received data count returned by LPUART_TransferGetReceiveCount is wrong.
- 2.5.0
 - Bug Fixes
 - * Added missing interrupt enable masks kLPUART_Match1InterruptEnable and kLPUAR-

- T_Match2InterruptEnable.
- * Fixed bug in LPUART_EnableInterrupts, LPUART_DisableInterrupts and LPUART_GetEnabledInterrupts that the BAUD[LBKDIE] bit field should be soc specific.
- * Fixed bug in LPUART_TransferHandleIRQ that idle line interrupt should be disabled when rx data size is zero.
- * Deleted unused status flags kLPUART_NoiseErrorInRxDataRegFlag and kLPUART_ParityErrorInRxDataRegFlag, since firstly their function are the same as kLPUART_NoiseErrorFlag and kLPUART_ParityErrorFlag, secondly to obtain them one data word must be read out thus interfering with the receiving process.
- * Fixed bug in LPUART_GetStatusFlags that the STAT[LBKDIF], STAT[MA1F] and STAT[MA2F] should be soc specific.
- * Fixed bug in LPUART_ClearStatusFlags that tx/rx FIFO is reset by mistake when clearing flags.
- * Fixed bug in LPUART_TransferHandleIRQ that while clearing idle line flag the other bits should be masked in case other status bits be cleared by accident.
- * Fixed bug of race condition during LPUART transfer using transactional APIs, by disabling and re-enabling the global interrupt before and after critical operations on interrupt enable register.
- * Fixed DMA/eDMA transfer blocking issue by enabling tx idle interrupt after DMA/eDMA transmission finishes.
- New Features
 - * Added APIs LPUART_GetRxFifoCount/LPUART_GetTxFifoCount to get rx/tx FIFO data count.
 - * Added APIs LPUART_SetRxFifoWatermark/LPUART_SetTxFifoWatermark to set rx/tx FIFO water mark.
- 2.4.1
 - Bug Fixes
 - * Fixed MISRA advisory 17.7 issues.
- 2.4.0
 - New Features
 - * Added APIs to configure 9-bit data mode, set slave address and send address.
- 2.3.1
 - Bug Fixes
 - * Fixed MISRA advisory 15.5 issues.
- 2.3.0
 - Improvements
 - * Modified LPUART_TransferHandleIRQ so that txState will be set to idle only when all data has been sent out to bus.
 - * Modified LPUART_TransferGetSendCount so that this API returns the real byte count that LPUART has sent out rather than the software buffer status.
 - * Added timeout mechanism when waiting for certain states in transfer driver.
- 2.2.8
 - Bug Fixes
 - * Fixed issue for MISRA-2012 check.
 - Fixed rule-10.3, rule-14.4, rule-15.5.

- * Eliminated Pa082 warnings by assigning volatile variables to local variables and using local variables instead.
- * Fixed MISRA issues.
 - Fixed rules 10.1, 10.3, 10.4, 10.8, 14.4, 11.6, 17.7.
- Improvements
 - * Added check for kLPUART_TransmissionCompleteFlag in LPUART_WriteBlocking, LPUART_TransferHandleIRQ, LPUART_TransferSendDMACallback and LPUART_SendEDMACallback to ensure all the data would be sent out to bus.
 - * Rounded up the calculated sbr value in LPUART_SetBaudRate and LPUART_Init to achieve more accurate baudrate setting. Changed osr from uint32_t to uint8_t since osr's biggest value is 31.
 - * Modified LPUART_ReadBlocking so that if more than one receiver errors occur, all status flags will be cleared and the most severe error status will be returned.
- 2.2.7
 - Bug Fixes
 - * Fixed issue for MISRA-2012 check.
 - Fixed rule-12.1, rule-17.7, rule-14.4, rule-13.3, rule-14.4, rule-10.4, rule-10.8, rule-10.3, rule-10.7, rule-10.1, rule-11.6, rule-13.5, rule-11.3, rule-13.2, rule-8.3.
- 2.2.6
 - Bug Fixes
 - * Fixed the issue of register's being in repeated reading status while dealing with the IRQ routine.
- 2.2.5
 - Bug Fixes
 - * Do not set or clear the TIE/RIE bits when using LPUART_EnableTxDMA and LPUART_EnableRxDMA.
- 2.2.4
 - Improvements
 - * Added hardware flow control function support.
 - * Added idle-line-detecting feature in LPUART_TransferNonBlocking function. If an idle line is detected, a callback is triggered with status kStatus_LPUART_IdleLineDetected returned. This feature may be useful when the received Bytes is less than the expected received data size. Before triggering the callback, data in the FIFO (if has FIFO) is read out, and no interrupt will be disabled, except for that the receive data size reaches 0.
 - * Enabled the RX FIFO watermark function. With the idle-line-detecting feature enabled, users can set the watermark value to whatever you want (should be less than the RX FIFO size). Data is received and a callback will be triggered when data receive ends.
- 2.2.3
 - Improvements
 - * Changed parameter type in LPUART_RTOS_Init struct from rtos_lpuart_config to lpuart_rtos_config_t.
 - Bug Fixes
 - * Disabled LPUART receive interrupt instead of all NVICs when reading data from ring buffer. Otherwise when the ring buffer is used, receive nonblocking method will disable all NVICs to protect the ring buffer. This may have a negative effect on other IPs that are

using the interrupt.

- 2.2.2
 - Improvements
 - * Added software reset feature support.
 - * Added software reset API in LPUART_Init.
- 2.2.1
 - Improvements
 - * Added separate RX/TX IRQ number support.
- 2.2.0
 - Improvements
 - * Added support of 7 data bits and MSB.
- 2.1.1
 - Improvements
 - * Removed unnecessary check of event flags and assert in LPUART_RTOS_Receive.
 - * Added code to always wait for RX event flag in LPUART_RTOS_Receive.
- 2.1.0
 - Improvements
 - * Update transactional APIs.

LPUART_DMA

The current LPUART_DMA driver version is 2.4.0.

- 2.4.0
 - Refer LPUART driver change log 2.1.0 to 2.4.0

LPUART_FREERTOS

The current LPUART_FREERTOS driver version is 2.4.0.

- 2.4.0
 - Refer LPUART driver change log 2.1.0 to 2.4.0

MMAU

The current MMAU driver version is 2.0.1.

- 2.0.1
 - Bug Fixes
 - * MISRA C-2012 issue fixed: rule 7.3, 10.1, 10.3, 10.4.
- 2.0.0
 - Initial version.

PDB

The current PDB driver version is 2.0.4.

- 2.0.4
 - Bug Fixes
 - * Fixed violations of MISRA C-2012 rule 10.1 and 10.4.
- 2.0.3
 - Bug Fixes
 - * Fixed violations of MISRA C-2012 rule 17.7.
- 2.0.2
 - Improvement:
 - * Used macros in feature file instead of that in IO map.
- 2.0.1
 - Changed PDB register base array to const.
- 2.0.0
 - Initial version.

PIT

The current PIT driver version is 2.0.4.

- 2.0.4
 - Bug Fixes
 - * Fixed PIT_SetTimerPeriod implementation, the load value trigger should be PIT clock cycles minus 1.
- 2.0.3
 - Bug Fixes
 - * Clear all status bits for all channels to make sure the status of all TCTRL registers is clean.
- 2.0.2
 - Bug Fixes
 - * Fixed MISRA-2012 issues.
 - Rule 10.1.
- 2.0.1
 - Bug Fixes
 - * Cleared timer enable bit for all channels in function PIT_Init() to make sure all channels stay in disable status before setting other configurations.
 - * Fixed MISRA-2012 rules.
 - Rule 14.4, rule 10.4.
- 2.0.0
 - Initial version.

PMC

The current PMC driver version is 2.0.3.

- 2.0.3
 - Bug Fixes
 - * Fixed the violation of MISRA C-2012 rule 11.3.
- 2.0.2
 - Bug Fixes
 - * Fixed the violations of MISRA 2012 rules:
 - Rule 10.3.
- 2.0.1
 - Bug Fixes
 - * Fixed MISRA issues.
 - Rule 10.8, Rule 10.3.
- 2.0.0
 - Initial version.

PORT

The current PORT driver version is 2.3.0.

- 2.3.0
 - New Features
 - * Added new APIs for Electrical Fast Transient(EFT) detect.
 - * Added new API to configure port voltage range.
- 2.2.0
 - New Features
 - * Added new api PORT_EnablePinDoubleDriveStrength.
- 2.1.1
 - Bug Fixes
 - * Fixed the violations of MISRA C-2012 rules: 10.1, 10.411.311.8, 14.4.
- 2.1.0
 - New Features
 - * Updated the driver code to adapt the case of the interrupt configurations in GPIO module.
Will move the pin configuration APIs to GPIO module.
- 2.0.2
 - Other Changes
 - * Added feature guard macros in the driver.
- 2.0.1
 - Other Changes
 - * Added "const" in function parameter.
 - * Updated some enumeration variables' names.

QTMR

The current QTMR driver version is 2.0.1.

- 2.0.1
 - Bug Fixes
 - * MISRA C-2012 issue check.
 - Fixed rules, containing: rule-10.1, rule-10.3, rule-10.4, rule-11.9, rule-14.4, rule-15.5, rule-17.7.
 - * Changed FSL_COMPONENT_ID as platform.drivers.qtmr_2.
- 2.0.0
 - Initial version.

RCM

The current RCM driver version is 2.0.4.

- 2.0.4
 - Bug Fixes
 - * Fixed violation of MISRA C-2012 rule 10.3
- 2.0.3
 - Bug Fixes
 - * Fixed violation of MISRA C-2012 rules.
- 2.0.2
 - Bug Fixes
 - * Fixed MISRA issue.
 - Rule 10.8, rule 10.1, rule 13.2, rule 3.1.
- 2.0.1
 - Bug Fixes
 - * Fixed kRCM_SourceSw bit shift issue.
- 2.0.0
 - Initial version.

SIM

The current SIM driver version is 2.1.3.

- 2.1.3
 - Improvements
 - * Updated function SIM_GetUniqueId to support different register names.
- 2.1.2
 - Bug Fixes
 - * Fixed SIM_GetUniqueId bug that could not get UIDH.
- 2.1.1
 - Bug Fixes

- * Fixed violations of the MISRA C-2012 rules 10.1, 10.4
- 2.1.0
 - Improvements
 - * Added new APIs: SIM_GetRfAddr() and SIM_EnableSystickClock().
- 2.0.0
 - Initial version.

SLCD

The current SLCD driver version is 2.0.3.

- 2.0.3
 - Bug Fixes
 - * Fixed SLCD_Init bug that some bit-fields are cleared by mistake.
- 2.0.2
 - Bug Fixes
 - * Fixed violations of the MISRA C-2012 rules 3.1, 10.1, 10.3, 10.3, 10.4 11.4, 17.7
- 2.0.1
 - Bug Fixes
 - * Changed the Blink mode start setting flow.
 - Other Changes
 - * Added static to SLCD global variables.
- 2.0.0
 - Initial version.

SMC

The current SMC driver version is 2.0.7.

- 2.0.7
 - Bug Fixes
 - * Fixed MISRA-2012 issue 10.3.
- 2.0.6
 - Bug Fixes
 - * Fixed issue for MISRA-2012 check.
 - Fixed rule 10.3, rule 11.3.
- 2.0.5
 - Bug Fixes
 - * Fixed issue for MISRA-2012 check.
 - Fixed rule 15.7, rule 14.4, rule 10.3, rule 10.1, rule 10.4.
- 2.0.4
 - Bug Fixes
 - * When entering stop modes, used RAM function for the flash synchronization issue. Application should make sure that, the RW data of fsl_smc.c is located in memory region

which is not powered off in stop modes.

- 2.0.3
 - Improvements
 - * Added APIs SMC_PreEnterStopModes, SMC_PreEnterWaitModes, SMC_PostExitWaitModes, and SMC_PostExitStopModes.
- 2.0.2
 - Bug Fixes
 - * Added DSB before WFI while ISB after WFI.
 - Other Changes
 - * Updated SMC_SetPowerModeVlwpw implementation.
- 2.0.1
 - Other Changes
 - * Updated for KL8x.
- 2.0.0
 - Initial version.

SPI

The current SPI driver version is 2.1.1.

- 2.1.1
 - Bug Fixes
 - * Fixed MISRA 10.3 violation.
- 2.1.0
 - Improvements
 - * Added timeout mechanism when waiting certain states in transfer driver.
 - Bug Fixes
 - * Fixed the bug that, when working as a slave, instance that does not have FIFO may miss some rx data.
 - * Fixed master RX data overflow issue by synchronizing transmit and receive process.
 - * Fixed issue that slave should not share the same non-blocking initialization API and IRQ handler with master to prevent dead lock issue.
 - * Fixed issue that callback should be invoked after all data is sent out to bus.
 - * Added code in SPI_SlaveTransferNonBlocking to empty rx buffer before initializing transfer.
- 2.0.5
 - Bug Fixes
 - * Eliminated Pa082 warnings from SPI_WriteNonBlocking and SPI_GetStatusFlags.
 - * Fixed MISRA issues.
 - Fixed issues 10.1, 10.3, 10.4, 10.7, 10.8, 11.9, 14.4, 17.7.
- 2.0.4
 - New Features
 - * Supported 3-wire mode for SPI driver. Added new API SPI_SetPinMode() to control the transfer direction of the single wire. For master instance, MOSI is selected as I/O pin. For

- slave instance, MISO is selected as I/O pin.
 - * Added dummy data setup API to allow users to configure the dummy data to be transferred.
- 2.0.3
 - Bug Fixes
 - * Fixed the potential interrupt race condition at high baudrate when calling API SPI_MasterTransferNonBlocking.
- 2.0.2
 - New Features
 - * Allowed users to set the transfer size for SPI_TransferNoBlocking non-integer times of watermark.
 - * Allowed users to define the dummy data. Users only need to define the macro SPI_DUMMYDATA in applications.
- 2.0.1
 - Bug Fixes
 - * Fixed SPI_Enable function parameter error.
 - * Set the s_dummy variable as static variable in fsl_spi_dma.c.
 - Improvements
 - * Optimized the code size while not using transactional API.
 - * Improved performance in polling method.
 - * Added #ifndef/#endif to allow users to change the default tx value at compile time.
- 2.0.0
 - Initial version.

SPI DMA Driver

The current SPI DMA driver version is 2.1.1.

- 2.1.1
 - Bug Fixes
 - * Fixed the bug that TX data not sent to bus when transfer finish callback is called.
- 2.1.0
 - Improvements
 - * Added timeout mechanism when waiting certain states in transfer driver.
 - Bug Fixes
 - * Fixed the bug that, when working as a slave, instance that does not have FIFO may miss some rx data.
 - * Fixed master RX data overflow issue by synchronizing transmit and receive process.
 - * Fixed issue that slave should not share the same non-blocking initialization API and IRQ handler with master to prevent dead lock issue.
 - * Fixed issue that callback should be invoked after all data is sent out to bus.
 - * Added code in SPI_SlaveTransferNonBlocking to empty rx buffer before initializing transfer.
- 2.0.5

- Bug Fixes
 - * Eliminated Pa082 warnings from SPI_WriteNonBlocking and SPI_GetStatusFlags.
 - * Fixed MISRA issues.
 - Fixed issues 10.1, 10.3, 10.4, 10.7, 10.8, 11.9, 14.4, 17.7.
- 2.0.4
 - New Features
 - * Supported 3-wire mode for SPI driver. Added new API SPI_SetPinMode() to control the transfer direction of the single wire. For master instance, MOSI is selected as I/O pin. For slave instance, MISO is selected as I/O pin.
 - * Added dummy data setup API to allow users to configure the dummy data to be transferred.
- 2.0.3
 - Bug Fixes
 - * Fixed the potential interrupt race condition at high baudrate when calling API SPI_MasterTransferNonBlocking.
- 2.0.2
 - New Features
 - * Allowed users to set the transfer size for SPI_TransferNoBlocking non-integer times of watermark.
 - * Allowed users to define the dummy data. Users only need to define the macro SPI_DUMMYDATA in applications.
- 2.0.1
 - Bug Fixes
 - * Fixed SPI_Enable function parameter error.
 - * Set the s_dummy variable as static variable in fsl_spi_dma.c.
 - Improvements
 - * Optimized the code size while not using transactional API.
 - * Improved performance in polling method.
 - * Added #ifndef/#endif to allow users to change the default tx value at compile time.
- 2.0.0
 - Initial version.

SPI FreeRTOS Driver

The current SPI FreeRTOS driver version is 2.1.0.

- 2.1.0
 - Improvements
 - * Added timeout mechanism when waiting certain states in transfer driver.
 - Bug Fixes
 - * Fixed the bug that, when working as a slave, instance that does not have FIFO may miss some rx data.
 - * Fixed master RX data overflow issue by synchronizing transmit and receive process.
 - * Fixed issue that slave should not share the same non-blocking initialization API and IRQ

- handler with master to prevent dead lock issue.
 - * Fixed issue that callback should be invoked after all data is sent out to bus.
 - * Added code in SPI_SlaveTransferNonBlocking to empty rx buffer before initializing transfer.
- 2.0.5
 - Bug Fixes
 - * Eliminated Pa082 warnings from SPI_WriteNonBlocking and SPI_GetStatusFlags.
 - * Fixed MISRA issues.
 - Fixed issues 10.1, 10.3, 10.4, 10.7, 10.8, 11.9, 14.4, 17.7.
- 2.0.4
 - New Features
 - * Supported 3-wire mode for SPI driver. Added new API SPI_SetPinMode() to control the transfer direction of the single wire. For master instance, MOSI is selected as I/O pin. For slave instance, MISO is selected as I/O pin.
 - * Added dummy data setup API to allow users to configure the dummy data to be transferred.
- 2.0.3
 - Bug Fixes
 - * Fixed the potential interrupt race condition at high baudrate when calling API SPI_MasterTransferNonBlocking.
- 2.0.2
 - New Features
 - * Allowed users to set the transfer size for SPI_TransferNoBlocking non-integer times of watermark.
 - * Allowed users to define the dummy data. Users only need to define the macro SPI_DUMMYDATA in applications.
- 2.0.1
 - Bug Fixes
 - * Fixed SPI_Enable function parameter error.
 - * Set the s_dummy variable as static variable in fsl_spi_dma.c.
 - Improvements
 - * Optimized the code size while not using transactional API.
 - * Improved performance in polling method.
 - * Added #ifndef/#endif to allow users to change the default tx value at compile time.
- 2.0.0
 - Initial version.

UART

The current UART driver version is 2.5.1.

- 2.5.1
 - Improvements
 - * Use separate data for TX and RX in uart_transfer_t.

- Bug Fixes
 - * Fixed bug that when ring buffer is used, if some data is received in ring buffer first before calling `UART_TransferReceiveNonBlocking`, the received data count returned by `UART_TransferGetReceiveCount` is wrong.
- 2.5.0
 - New Features
 - * Added APIs `UART_GetRxFifoCount`/`UART_GetTxFifoCount` to get rx/tx FIFO data count.
 - * Added APIs `UART_SetRxFifoWatermark`/`UART_SetTxFifoWatermark` to set rx/tx FIFO water mark.
 - Bug Fixes
 - * Fixed bug of race condition during UART transfer using transactional APIs, by disabling and re-enabling the global interrupt before and after critical operations on interrupt enable registers.
 - * Fixed DMA/eDMA transfer blocking issue by enabling tx idle interrupt after DMA/eDMA transmission finishes.
- 2.4.0
 - New Features
 - * Added APIs to configure 9-bit data mode, set slave address and send address.
- 2.3.0
 - Bug Fixes
 - * Fixed the bug that, when framing/parity/noise/overflow flag or idle line detect flag is set, receive FIFO should be flushed to avoid FIFO pointer being in unknown state, since FIFO has no valid data.
 - Improvements
 - * Modified `UART_TransferHandleIRQ` so that txState will be set to idle only when all data has been sent out to bus.
 - * Modified `UART_TransferGetSendCount` so that this API returns the real byte count that UART has sent out rather than the software buffer status.
 - * Added timeout mechanism when waiting for certain states in transfer driver.
- 2.2.0
 - New Features
 - * Added UART hardware FIFO enable/disable API.
 - Improvements
 - * Added check for `kUART_TransmissionCompleteFlag` in `UART_TransferHandleIRQ`, `UART_SendEDMACallback` and `UART_TransferSendDMACallback` to ensure all the data would be sent out to bus.
 - Bug Fixes
 - * Eliminated IAR Pa082 warnings from `UART_TransferGetRxRingBufferLength`, `UART_GetEnabledInterrupts`, `UART_GetStatusFlags` and `UART_TransferHandleIRQ`.
 - * Added code in `UART_ReadBlocking` so that if more than one receiver errors occur, all status flags will be cleared and the most severe error status will be returned.
 - * Fixed MISRA issues.
 - Fixed rules 10.1, 10.3, 10.4, 14.4, 11.6, 17.7.
- 2.1.6

- Bug Fixes
 - * Fixed the issue of register's being in repeatedly reading status while performing the IRQ routine.
- 2.1.5
 - Improvements
 - * Added hardware flow control function support.
 - * Added idle-line-detecting feature in UART_TransferNonBlocking function. If an idle line is detected, a callback will be triggered with status kStatus_UART_IdleLineDetected returned. This feature may be useful when the number of received bytes is less than the expected receive data size. Before triggering the callback, data in the FIFO is read out (if it has FIFO), and no interrupt will be disabled except for the case that the receive data size reaches 0.
 - * Enabled the RX FIFO watermark function. With the idle-line-detecting feature enabled, you can set the watermark value to whatever you want (should not be bigger than the RX FIFO size). Data is then received and a callback will be triggered when data receive ends.
- 2.1.4
 - Improvements
 - * Changed parameter type in UART_RTOS_Init() struct rtos_uart_config -> uart_rtos_config_t.
 - Bug Fixes
 - * Disabled UART receive interrupt instead of global interrupt when reading data from ring buffer. With ring buffer used, receive nonblocking will disable global interrupt to protect the ring buffer. This has a negative effect on other IPs using interrupt.
- 2.1.3
 - New Features
 - * Added RX framing error and parity error status check when using interrupt transfer.
- 2.1.2
 - Bug Fixes
 - * Fixed baud rate fine adjust bug to make the computed baud rate more accurate.
- 2.1.1
 - Bug Fixes
 - * Removed needless check of event flags and assert in UART_RTOS_Receive.
 - * Always waited for RX event flag in UART_RTOS_Receive.
- 2.1.0
 - Improvements
 - * Added transactional API.
- 2.0.0
 - Initial version.

UART_DMA

The current UART_DMA driver version is 2.5.0.

- 2.5.0

- Refer UART driver change log 2.1.0 to 2.5.0

UART_FREERTOS

The current UART_FREERTOS driver version is 2.5.0.

- 2.5.0
 - Refer UART driver change log 2.1.0 to 2.5.0

VREF

The current VREF driver version is 2.1.2.

- 2.1.2
 - Bug Fixes
 - * Fixed the violation of MISRA-2012 rule 10.3.
 - * Fixed MISRA C-2012 rule 10.3, rule 10.4 violation.
- 2.1.1
 - Bug Fixes
 - * MISRA-2012 issue fixed.
 - Fixed rules containing: rule-10.4, rule-10.3, rule-10.1.
- 2.1.0
 - Improvements
 - * Added new functions to support L5K board: added VREF_SetTrim2V1Val() and VREF_GetTrim2V1Val() functions to supply 2V1 output mode.
- 2.0.0
 - Initial version.

WDOG

The current WDOG driver version is 2.0.1.

- 2.0.1
 - Bug Fixes
 - * MISRA C-2012 issue fixed: rule 10.3, 10.4, 10.6, 10.7 11.9 and 17.7.
- 2.0.0
 - Initial version.

XBAR

The current XBAR driver version is 2.1.0.

- 2.1.0

- Improvements
 - * Improved to support XBAR which has less than 4 interrupt output.
- Bug Fixes
 - * Fixed violations of MISRA C-2012 rule 12.2.
- 2.0.5
 - Bug Fixes
 - * Fixed violations of the MISRA C-2012 rules 10.1, 10.3, 10.4, 10.6, 10.7, 10.8, 12.2, 18.1, 20.7.
- 2.0.4
 - Bug Fixes
 - * Fixed IAR build warning Pa082.
- 2.0.3
 - Improvements
 - * Optimized XBAR_SetOutputSignalConfig.
- 2.0.2
 - Bug Fixes
 - * Corrected configuration for function XBAR_SetOutputSignalConfig.
- 2.0.1
 - Bug Fixes
 - * Fixed w1c bits for XBAR_SetOutputSignalConfig function.
- 2.0.0
 - Initial version.

2 Middleware Change Log

FreeMASTER Communication Driver

Current version is 3.0.4. Visit <https://www.nxp.com/freemaster> for more information. Reach out for a support at <https://community.nxp.com/community/freemaster>.

- 3.0.0
 - Initial version of FreeMASTER driver reworked from a standalone package to MCUXpresso SDK middleware.
 - This driver version supports new version V4 of FreeMASTER serial communication protocol.
 - Supports UART, LPUART, USART, MINIUSART, FlexCAN, USB-CDC and JTAG/BDM communication.
 - Initial version was tested with the following boards: evkmimxrt1060, frdmk64f, frdmk15z, frdmk128z, lpcxpresso54628 lpcxpresso55s69, lpcxpresso845max and twrk64f120m.
 - Use with FreeMASTER PC Host tool version 2.5 or later.
- 3.0.1
 - FreeMASTER driver extended to support wide range of Kinetis, LPC and i.MX-RT platforms.
 - Low-level communication drivers also available for few non-SDK NXP platforms like S12Z, S32x and more.
 - Use with FreeMASTER PC Host tool version 3.0 or later.
- 3.0.2
 - FreeMASTER driver support of DSC56F800EX and S12 platforms extended.
 - Removed dependency on C99 compiler features.
 - Use with FreeMASTER PC Host tool version 3.0.2 or later.
- 3.0.3
 - General update for SDK 2.9.0
 - fmstr_any demo added to selected platforms - use with MCUXpresso SDK and FreeMASTER peripheral configuration tool.
 - New example.pmp project file embedded into application flash storage.
 - USB-CDC implementation fixed, new JTAG EOnCE communication interface added to DSC 56F800E family.
 - Use with FreeMASTER PC Host tool version 3.0.3 or later. Version 3.1.x is recommended.
- 3.0.4
 - Fixed component dependency logic of FreeMASTER driver.
 - Use with FreeMASTER PC Host tool version 3.1.x
- 3.0.5
 - General update for SDK 2.11 and 2.12
 - New TCP and UDP support with lwIP stack
 - New communication over Segger RTT interface
 - Add fmstr_net and fmstr_wifi examples for selected i.MX-RT platforms
 - Add fmstr_rtt example for selected platforms
 - Fixed negative recorder threshold trigger processing

3 Component Change Log

SERIAL_MANAGER

The current Serial_Manager component version is 1.0.2.

- 1.0.2
 - Add SerialManager_WriteTimeDelay()/SerialManager_ReadTimeDelay() for serial manager's read/write non-blocking mode.
- 1.0.1
 - Add prefixing fsl_component_XXX/fsl_adapter_XXX.
- 1.0.0
 - Initial version

How to Reach Us:**Home Page:**

nxp.com

Web Support:

nxp.com/support

Information in this document is provided solely to enable system and software implementers to use NXP products. There are no express or implied copyright licenses granted hereunder to design or fabricate any integrated circuits based on the information in this document.

NXP makes no warranty, representation, or guarantee regarding the suitability of its products for any particular purpose, nor does NXP assume any liability arising out of the application or use of any product or circuit, and specifically disclaims any and all liability, including without limitation consequential or incidental damages. "Typical" parameters that may be provided in NXP data sheets and/or specifications can and do vary in different applications, and actual performance may vary over time. All operating parameters, including "typicals," must be validated for each customer application by customer's technical experts. NXP does not convey any license under its patent rights nor the rights of others. NXP sells products pursuant to standard terms and conditions of sale, which can be found at the following address: nxp.com/SalesTermsandConditions.

While NXP has implemented advanced security features, all products may be subject to unidentified vulnerabilities. Customers are responsible for the design and operation of their applications and products to reduce the effect of these vulnerabilities on customer's applications and products, and NXP accepts no liability for any vulnerability that is discovered. Customers should implement appropriate design and operating safeguards to minimize the risks associated with their applications and products.

NXP, the NXP logo, NXP SECURE CONNECTIONS FOR A SMARTER WORLD, Freescale, the Freescale logo, Kinetis, Processor Expert, and Tower are trademarks of NXP B.V. All other product or service names are the property of their respective owners. Arm, Cortex, Keil, Mbed, Mbed Enabled, and Vision are trademarks or registered trademarks of Arm Limited (or its subsidiaries) in the US and/or elsewhere. The related technology may be protected by any or all of patents, copyrights, designs and trade secrets. All rights reserved. Oracle and Java are registered trademarks of Oracle and/or its affiliates. The Power Architecture and Power.org word marks and the Power and Power.org logos and related marks are trademarks and service marks licensed by Power.org.

© 2021 NXP B.V.

