

# COMPUTER AIDED MODELING MACHINE


## SERVICE NOTES

# CAMM-3


## PNC-3000

### — SPECIFICATIONS —

<b>XY TABLE SIZE</b>	500mm × 170mm (19-11/16" × 6-11/16")	<b>CONTROLS</b>	Control—PAUSE, MOTOR ON/OFF, DISPLAY RESET, SENSOR, FEED RATE
<b>AXIS TRAVEL (X-Y-Z)</b>	180mm × 150mm × 150mm (7-1/16" × 5-7/8" × 5-7/8")		Data Input—ON/OFF, WRITE, START
<b>TOOL CHUCK</b>	Collet Type (drill chuck optional)		Positioning—Z0, Z1, Z2, P1, P2, HOME, ENTER
<b>PRECISION</b>	0.01mm/step Internal Processing at 0.005mm/step		JOG—Fast Feed Keys (X, Y, Z), Fine Adjust Dials (X, Y, Z), MANUAL ON/OFF
<b>MAX.FEED RATE (SPEED)</b>	1.2M/min. (set either manually or by programming)		Emergency Stop; Spindle Motor Control;
<b>SPINDLE MOTOR</b>	100W, AC Commutator Motor		Power Switch
<b>WEIGHT</b>	55kg. (121.3 lbs.)	<b>CONTROL COMMANDS</b>	CAMM-GL1 (CAMM Graphic Language 1)
<b>SIZE (W-H-D) (DIMENSIONS)</b>	500mm × 580mm × 580mm 19-11/16" × 22-3/4" × 22-3/4"	<b>STANDARD ACCESSORIES</b>	φ6 Collet Chuck
<b>SPINDLE RPM</b>	3,000~8,000 rpm (with manual control)		Tool Set (1)
<b>INTERFACE</b>	Parallel (Centronics)/Serial (RS-232C)		AC Cord
<b>DISPLAYS</b>	X, Y and Z Axis Digital Coordinate Displays (unit-0.01mm)  Table Feed Rate  Spindle RPM  Error Indicator		Carrying Bolts (4)
			Sensor Switch
			Fuses (2)
			AC Motor Brushes (4)
			T Nut Sets (2)
			User's Manual
			CAMM-GL1 Command Reference Manual




# — PACKAGING INSTRUCTION —



— SCHEMATIC DIAGRAM —

## MAIN BOARD



## 1

## 2



4


5

6

71


## — SCHEMATIC DIAGRAM —

## COUNTER BOARD




— SCHEMATIC DIAGRAM —

CONTROL BOARD




— SCHEMATIC DIAGRAM —

**MOTOR P.C.B 100/117**




— SCHEMATIC DIAGRAM —

MOTOR P.C.B 220/240












# COUNTER BOARD 1/2




# MOTOR BOARD



# COUNTER BOARD 2/2




# M-SENSOR BOARD




## — CIRCUIT BOARD —


## CONTROL BOARD 1/2



## CONTROL BOARD 2/2



— BLOCK DIAGRAM —



— ELECTRICAL PARTS LIST —

Ref. No.	Parts No.	Description
<b>MAIN BOARD</b>		
	22925321	Main Board Ass'y
<b>IC</b>		
IC24	15179219	TMPZ84C00P (Z80 CMOS CPU)
IC22	15179818	ROM A
IC27	15179819	ROM B
IC28, 29	15179335	HM624P-15 (64K RAM)
	or	or
	(15179336)	(TC5565PL-15)
IC33	15179195	MSM82C55A-5RS OR TMP82C55AP-5
IC13	15179337	MSM82C51ARS OR TMP82C51AP-2
IC30	15179185	MSM82C53-5 OR TMP82C53P-2
IC25	15159116T0	TC4096UBP
IC20	15159303T0	TC4584BP
IC39	15159503	TC40H000P
IC15, 18	15159504	TC40H002P
IC38	15159517	TC40H010P
IC35	15159518	TC40H027P
IC16, 17, 37	15159514	TC40H032P
IC14	15159510	TC40H074P
IC23, 36	15159525	TC40H139P
IC9	15159526	TC40H153P
IC19, 21, 42	15159530	TC40H367P
IC32, 47	15159533	TC40H368P
IC41	15159508	TC40H373P
IC40	15169512T0	TC74HCU04P
IC31	15169513	TC74HC74
IC34	15169102H0	HD7406P
IC48	15169346X0	SN74LS03N
IC43-46	15169372	M74LS299P
IC26	15169340	SN74LS374N
IC6	15219144H0	HD75188P (Line Driver)
IC5	15219145H0	HD75189P (Line Receiver)
IC7	15199519	TL497ACN
IC8	15219139	PST518A
TR2	15199106T0	TA78005AP 3-terminal Regulator
IC1	15199131P0	IR3M02
IC2-4	15219169	SI7300A (Motor Driver)
IC10-12	15219170	MB8713M-G (Motor Controller)
	or	or
	15219170SN	PMM8713
<b>TRANSISTOR</b>		
TR1	15119412	2SA1307Y
TR3	15119814	2SB1015-0
TR4-6, 10, 11	15129115	2SC1815Y
TR7-9	1529834	2SD1408-0

## — ELECTRICAL PARTS LIST —

Ref. No.	Parts No.	Description
<b>DIODE</b>		
D2-6	15019101	1S1555
D1	15019209T0	S-5500G
D7, 8	15019265	ERB44-06
DA1, 2	15019142	DAN801 Diode Array
ZD1-3	15019511	05AZ33 Zener Diode
DB2	15019248	6D4B41 Diode Bridge
DB1	15019257	4D4B41 Diode Bridge
	150196200X	05Z-16X Zener Diode
<b>RESISTOR ARRAY</b>		
RA9, 12	13910106	RMLS6-103K (10 Kohm x 6)
RA1-8, 10, 11, 13	13919140	RGLD8-103K (10 Kohm x 8)
<b>RESISTOR</b>		
R74	13829302	82 ohm 3W Metal film
R15, 16, 26-28, 36, 37	13829158	1 ohm 1W Metal film
R1	13819125	1 ohm 1/2W Solid
<b>CAPACITOR</b>		
C3	13639155S0	2200 MF/16V
C5	13659248M0	3300 MF/65V
<b>FUSE</b>		
F2	12559514	Fuse CEE-2AT (2 Ampere)
F1	12559518	Fuse CEE-5AT (5 Ampere)
<b>OTHERS</b>		
L2	12449242	RC855-221K Coil 220 $\mu$ H
L1	12449274	Coil MC-DRUM
XTAL1	12389744	X'tal 8MHz
	13429527	IC socket (28 Pin)
SW1, 2	13169660	DYS-10 Dip switch
J309	13429167	Connector 25 Pin Serial port
J310	13429622	Connector 36 Pin Parallel port
J403	13439118	MOLEX 5045-2A ( 2 Pin)
J305X, Y, Z	13439129	MOLEX 5046-2A ( 2 Pin)
	23435294	MOLEX 5273-04A ( 4 Pin)
J304	13439120	MOLEX 5045-4A ( 4 Pin)
J308, J301-2	13439133	MOLEX 5046-6A ( 6 Pin)
J301-1	13439163	MOLEX 5046-15A (15 Pin)
J311	13449714	Jack TM5RC-44
J306, 307	13449715	Jack TM5RC-66
J302	13449716	Jack TM5RC-88
	22465143	Heat sink
	22195865	Holder for jack
F3	12439512	Timer
	12199550	Fuse holder H0446
	12199567	Fuse holder F204

## — ELECTRICAL PARTS LIST —

Ref. No.	Parts No.	Description
<b>MOTOR BOARD</b>		
	<u>22925325</u>	<i>Motor Board Ass'y (100V/117V)</i>
	<u>22925339</u>	<i>Motor Board Ass'y (220V/240V)</i>
<b>SEMICONDUCTOR</b>		
IC3	15229716	Photocoupler PC-111
SSR	12439215	SSR S203DS1
	15019277	Diode bridge 1D4B1 (100V/177V)
	15019278	Diode bridge 1G4B1 (220V/240V)
D1, 2	15019101	Diode 1S1555
IC1, 2	15189134X0	OP Amp. LM2904 or TA75358
<b>POTENTIOMETER</b>		
VR1	13219130	EVHCCAK15B54 50 Kohm (B)
<b>RESISTOR</b>		
R1, 2	13829102	5.6 Kohm 1W (100V/117V)
R1, 2	13829103	10 Kohm 1W (220V/240V)
R7	13719223T0	12 Kohm 1/4W (100V/117V)
R7	13719219T0	8.2 Kohm 1/4W (220V/240V)
<b>MISCELLANEOUS</b>		
J602	13439324	Connector (2 Pin)
J601	13439120	Connector (4 Pin)
	12159734	Bushing TA-307
	12159715	Bushing TB-300
<b>MOTOR REVOLUTION SENSOR BOARD</b>		
	<u>22925326</u>	<i>Motor Revolution Sensor Board Ass'y</i>
	15229717	Photo-interrupter GP2S05
	15129121	Transistor 2SC2021R
	23495419	Wiring

## — ELECTRICAL PARTS LIST —

Ref. No.	Parts No.	Description
<b>COUNTER BOARD</b>		
	<u>22925323</u>	<u>Counter Board Ass'y</u>
<b>IC</b>		
IC10—12	15149125	IR-2C07
IC7—9	15149120	IR-2C30
IC13	15159320	TC4521BP
IC18	15159116	TC4069UBP
IC4—6	15159151	TC4077BP
IC19, 20	15159510	TC40H074P
IC16, 17	15169353HO	HD74LS145P
IC1—3	15179238	LU-55131
IC15	15219166	BA689
IC14	15219167	BA6302A
<b>LED</b>		
LED1—3	15029184	GL3D507B
LED4—6, 15	15029221	LT9000D
LED7—9	15029218	LD003MB
LED11—13	15029220	LD003YB
LED14	15029219	LD002YB
LED10	15029217	LD002MB
<b>TRANSISTOR</b>		
TR1, 2	15129615	2SD1293Q
<b>DIODE</b>		
D1—3	15019101	1S1555
<b>SEMI-FIXED RESISTOR</b>		
VR1	13299200	EVN-D1AA00B54
<b>COUNTER PANEL ASSEMBLY</b>		
	22485114	Button for Emergency Stop
	22115309	LED Housing
	22025745	LED Cover
<b>MISCELLANEOUS</b>		
SW1	13129715	Switch SKHCAA110A
	12159734	Bushing TA-307
	12159715	Bushing TB-300
J102	13439119	Connector 5045-03A ( 3 Pin)
J101-1	13439122	Connector 5045-06A ( 6 Pin)
J101-1	13439323	Connector 5045-15A (15 Pin)
	13479187	Sumi card (20 Pin)
	13479188	Sumi card (30 Pin)
	13429179	Connector (20 Pin)
	13429180	Connector (30 Pin)



## — ELECTRICAL PARTS LIST —

Ref. No.	Parts No.	Description
----------	-----------	-------------

**CONTROLLER UNIT**

	<u>7582120000</u>	<u>Controller Unit</u>
	22485115	Button (large)
	22485116	Button (small)
	22485101	JOG Dial Knob
	22215767	Controller Panel
	22025308	Controller Bottom Cover
	12369502	Bushing
	<u>22925324</u>	<u>CONTROLLER BOARD ASS'Y</u>

**IC**

IC1—4	15169371	M74LS166AP
IC9	15169361	HD74LS164
IC5—7	15219168	MSM5210RS
IC8	15149120	IR-2C30

**TRANSISTOR & DIODE**


Q1, 2	15129114	Transistor 2SC1815GR
D1	15019101	Diode 1S1555
LED1—6	15029103	LED TLR124

**OTHERS**

RM1—3	13919310	Resistor Array RMLS8-103J
	13279796	Rotary encoder (JOG dial)
CN1	13429180	Connector (30 Pin)
	13479188	Sumi card (30 Pin)
	13129715	Switch SKHCAA110A
	12159734	Bushing TA-307
	12159715	Bushing TB-300
	23485195	Controller Cable




— EXPLODED VIEW —



SPINDLE AC. MOTOR			
134	22435112	FOR	117V
135	22435113	FOR	220V
136	22435114	FOR	240V

— EXPLODED VIEW —  
REAR




AC. CORD			
144	13499108	VCTFK-3m	(100V)
145	13499107	VM-033	(117)
146	13439817F0	EC-702-J05	(220V)
147	23495110	BB6742-BB6791	(240V ENGLAND)
148	13439814F0	SC415-J06	(240V AUSTRALIA)

FUSE HOLDER		
131	12199515	SN-2250 (100V, 200V, 240V)
132	12199551	345601 (117V)


FUSE		
141	12559107	SGA-3A (100V)
142	12559348	MGC-UL3A (117V)
143	12559521	CEE 1.6A (220/240V)

## — EXPLODED VIEW —


## TABLE



## CONTROLLER UNIT





— ACCESSORY TOOL SET —



Ref. No.	7582106000	Accessory tool set
①	12569251	Hexagonal Wrench M5 × 80
②	12569302	Hexagonal Wrench M2.5 × 60
③	12439513	AC Motor Brush
④	12569304	Spanner 17mm
⑤	12569312	Spanner 22mm
⑥	22015712	Soft Tool Case
⑦	12569303	Double Head Spanner 10 × 13
	or	
⑧	12569323	Double Socket Wrench 10 × 13
	12559107	Fuse SGA-3A (100V)
	12559348	Fuse MGC-UL3A (117V)
	12559521	Fuse CEE 1.6A (220/240V)

— COLOR OF LEADS —



COLOR OF LEADS

- ① : RED
- ② : RED
- ③ : BLUE
- ④ : BLUE

## — MECHANICAL PARTS LIST —

Ref. No.	Parts No.	Description
----------	-----------	-------------

(On this list, One part, electrical parts are included.)

101	2245542801	Power Transformer
102	13149116	Power Switch
103	13429715	AC Inlet
104	12439109	Fan
105	2247026200	Knob (blue)
106	12159749	Edge Protector
107	23495420	Wiring (Main PCB↔Motor PCB)
108	23485194	Wiring (Main PCB↔Counter PCB)
109	22815546	Chassis
110	22025843	Cover for Main PCB
111	22215507	Panel for AC Inlet
112	2215051200	Hexagonal Spacer L = 6mm
113	2215050500	Hexagonal Spacer L = 28.2 mm
114	22245149	Mask of Fan for Dust
115	23495426	Wiring (Motor PCB↔AC Motor)
116	22025310	Cover of Z-axis Column
117	22215769	Side Protector (right)
118	22215768	Side Protector (left)
119	22025309	Head Cover
120	22355353	Base of Head Cover
121	22025746	Pulley Cover
122	22565260	Bellows Cover of Y-axis
123	22565261	Bellows Cover of Z-axis #1
124	22565325	Bellows Cover of Z-axis #2
125	22565263	Holder for Bellows Cover of Z-axis
126	22395120	Magnet
127	22565262	Magic Tape
128	22565276	Bracket for installing Chassis
129		Hexagonal Head Bolt M6 × 50mm CM
130	12359112	Rubber Foot
131	12199515	Fuse Holder SN-2250 (100V, 200V, 240V)
132	12199551	Fuse Holder 345601 (117V)

**MOTOR**

133	22435111	Spindle AC Motor for 100V
134	22435112	Spindle AC Motor for 117V
135	22435113	Spindle AC Motor for 220V
136	22435114	Spindle AC Motor for 240V
137	22435115	X or Y-axis Stepping Motor
138	22435116	Z-axis Stepping Motor

## — MECHANICAL PARTS LIST —

Ref. No.	Parts No.	Description
----------	-----------	-------------

( On this list, One part, electrical parts are included.)

**ACCESSORY**

139	7582121000	Senser Switch
140	22675203	Dust Cover for Controller

**FUSE**

141	12559107	SGA-3A (100V)
142	12559348	MGC-UL3A (117V)
143	12559521	CEE 1.6A (220/240V)

**AC CORD**

144	13499108	VCTFK-3m (100V)
145	13499107	VM-0033 (117V)
146	13439817FO	EC-702-J05 (220V)
147	23495110	BB6742-BB6791 (240V England)
148	13439814FO	SC415-J06 (240V Australia)

**FLAME UNIT**

149	12289345	X-axis Ball Thread
150	12289346	Y-axis Ball Thread
151	12289347	Z-axis Ball Thread
152	22025312	Cover of X-Y Table
153	22145320	Slide Bar for X or Y-axis
154	22145321	Slide Bar for Z-axis
155	22145109	Limit SW. Bracket for X-axis
156	22145110	Limit SW. Bracket for Y-axis
157	22145111	Limit SW. Bracket for Z-axis
158	22565269	Spindle Unit
159	22565272	Pulley for Spindle
160	22565273	Pulley for AC Motor
161	22125208	Plate for installing AC Motor
162	22195868	Plate for installing Z-axis Motor
163	12569326	Coupling of X or Y-axis
164	12569266	Coupling of Z-axis
165	22355355	X-Y Table
166	22355354	Base
167	22125209	Bracket
168	22565268	Collet 6mm
169	12179720	Bearing FL608ZZ
170	12569275	Belt
171	13169669	Limit Switch
172	12359131	Rubber Foot
173	22565270	Head
174	22355356	Cross Table
175	22215767	Controller Panel
176	23485195	Controller Cable
177	22485101	Jog Dial Knob
178	22485116	Button (Small)
179	12369502	Bushing
180	22115309	LED. HOUSING
181	22025745	LED. COVER

## — SCREWS, WASHERS AND NUTS LIST —

No.	DESCRIPTION	No.	DESCRIPTION
1	BINDHEAD SCREW 3 × 4mm BC	19	HEXAGONAL NUT (LONG) M3 × 6mm CM
2	BINDHEAD SCREW 3 × 6mm BC	20	OVALHEAD SCREW 4 × 8mm BC
3	BINDHEAD SCREW 3 × 8mm BC	21	OVALHEAD SCREW 4 × 12mm BC
4	BINDHEAD SCREW 4 × 10mm BC	22	FLATHEAD TAPPING SCREW 3 × 12mm B <sup>1</sup> BC
5	BINDHEAD SCREW 5 × 20mm BC	23	SOKET CAPSCREW M4 × 12mm BC
6	BINDHEAD TAPPINGSCREW 3 × 8mm BC	24	SOKET CAPSCREW M4 × 20mm BC
7	BINDHEAD TAPPINGSCREW 3 × 16mm A <sup>1</sup> BC	25	SOKET CAPSCREW M5 × 12mm BC
8	BINDHEAD TAPPINGSCREW 3 × 20mm B <sup>1</sup> BC	26	SOKET CAPSCREW M6 × 15mm BC
9	PANHEAD SCREW (DOUBLE SEMS TIPE) 3 × 6mm BC	27	PLAIN WASHER M4 CM
10	PANHEAD SCREW (DOUBLE SEMS TIPE) 3 × 20mm BC	28	PLAIN WASHER M5 CM
11	PANHEAD SCREW (DOUBLE SEMS TIPE) 4 × 8mm BC	29	PLAIN WASHER M6 CM
12	PANHEAD SCREW (DOUBLE SEMS TIPE) 4 × 10mm BC	30	SPRING LOCKWASHER M4 CM
13	PANHEAD SCREW (DOUBLE SEMS TIPE) 4 × 12mm BC	31	SPRING LOCKWASHER M5 CM
14	PANHEAD SCREW (DOUBLE SEMS TIPE) 4 × 30mm BC	32	SPRING LOCKWASHER M6 CM
15	PANHEAD SCREW 3 × 8mm CM	33	TOOTHED LOCKWASHER M3 CM
16	FLATHEAD SCREW 3 × 6mm CM	34	TOOTHED LOCKWASHER M4 CM
17	HEXAGONAL NUT M3 CM	35	HEXAGONAL NUT WITH SPRING LOCKWASHER M4 CM
18	HEXAGONAL NUT M4 CM	36	NUT, U M8 CM
		37	SOKET SET SCREW (DOUBLE POINTS,) M5 × 5mm BC
		38	HEXAGON HEAD BOLT M6 × 50mm CM


## — ADJUSTMENT & MAINTENANCE —

### GENERAL:

PARTS construction of PNC-3000 is practically performed with SCREWS or NUTS. It is necessary on the occasion of exchange of PARTS to firm, tighten and add SCREWS or NUTS. In this section, it is explained about adjustment after exchange of special PARTS and check and maintenance.


### 1. ADJUSTMENT OF PULLEYS LEVEL:

Ref. No. (159) Spindle Unit, Ref. No. (133)~(136) Spindle AC Motor, Ref. No. (159) Pulley, Ref. No. (160) Pulley  
In case of exchanging these, height LEVEL between PULLEY needs to be adjusted to a state of next manner on the occasion of installation of PULLEY.



### 2. ADJUSTMENT OF TENSION FOR BELT.

- STEP1: In adjusting a tense condition of a belt, the Ref. No. (26) Socket Cap Screws M6 × 15mm BC which have exacted spindle motor is slackened.  
STEP2: Distance between CENTER of PULLEY FOR SPINDLE UNIT and PULLEY FOR SPINDLE MOTOR are set on 121mm, and Ref. No. (26) Socket Cap Screws is secured.  
STEP3: Ref. No. (170) Belt is set on PULLEYS, measured to a state as follows.



Concerning this plan, distance between PULLEY, TENSION of BELT are generally values.

An aim of adjustment

- Do not slip in terms of BELT.
- When it is performed on over TENSION, since heavy LOAD depends on spindle, please be careful enough.



## — ADJUSTMENT & MAINTENANCE —

### 3. ADJUSTMENT OF PLAY FOR BALLTHREADS.



- X, Y axis: Trying to move a table to all directions by hand, please confirm whether there is not play.  
About a case with play, please tighten ③⑥ U nut lightly.  
(It is in need of attention on over tighten.)
- Z axis: And a spindle head tries to be moved to top and bottom by hand, please confirm whether and there is not play.  
About a case with play, please tighten ③⑥ U nut lightly.  
Please lock on each ③⑥ U nut of X, Y, Z with paint lock (THREEBOND 1401B.)

### 4. CHECK MODE

PNC-3000 has the "CHECK MODE" which is a test program with a built-in the EPROMs for service engineers. You can try a simple test without the host computer.

#### [SETTING]

- Connect the AC cord to the AC Line and turn the power switch in position "ON".
- Press "EMERGENCY STOP" button of display panel while press "PAUSE" button and "START" button of controller together.
- Set the origin with pressing "HOME" button of controller.
- At Right side of main unit, set all dip switches in "OFF" position.

CHECK ITEM	OPERATION	DISPLAY & MOTION
DIP Switch 1 Checking	<ul style="list-style-type: none"> <li>• Turn the X-axis JOG dial knob, until X-axis coordinate display indicate <span style="border: 1px solid black; padding: 0 2px;">0.01</span>, then press "ENTER" button.</li> </ul>	<div style="display: flex; justify-content: space-around; align-items: center;"> <div style="text-align: center;"> <b>X-axis</b>   </div> <div style="text-align: center;"> <b>Y-axis</b>   </div> </div> <p>"ON" LED of DATA INPUT on controller lights.</p>
	<ul style="list-style-type: none"> <li>• Set all switches of DIP-SW-1 in "ON" position, then press "ENTER" button.</li> </ul>	<p>"OVER" LED of DATA INPUT on controller lights.</p>
	<p>For next step, set all switches of DIP-SW-1 in "OFF" position and press "ENTER" button.</p>	<p>When "ON" LED and "OVER" LED light, all switches are normally. When "ON" LED and "ERROR" light, some switch is wrong. At the same time, Y-axis coordinate display indicate wrong switch's number.</p>

## — ADJUSTMENT &amp; MAINTENANCE —

## 4. CHECK MODE

CHECK ITEM	OPERATION	DISPLAY & MOTION
DIP Switch 2 Checking	<ul style="list-style-type: none"> <li>Turn the X-axis JOG dial knob, until X-axis coordinate display indicate <u>0.02</u>, then press "ENTER" button.</li> </ul>	<p>X-axis      Y-axis</p> <p>0.02      0.00</p> <p>"ON" LED of DATA INPUT on controller lights.</p>
	<ul style="list-style-type: none"> <li>Set all switches of DIP-SW-2 in "ON" position, then press "ENTER" button.</li> </ul>	<p>"OVER" LED of DATA INPUT on controller lights. Same as DIP-SW-1.</p>
	<p>For next step, set all switches of DIP-SW-2 in "OFF" position and reset by pressing "ENTER" button.</p>	
ROM version number Checking	<ul style="list-style-type: none"> <li>Turn the X-axis JOG dial knob, until X-axis coordinate display indicate <u>0.03</u>, then press "ENTER" button.</li> </ul>	<p>X-axis      Y-axis</p> <p>111      202</p>
	<p>For next step, press "ENTER" button.</p>	<p>ROM.A version is indicated on X-axis coordinate display and ROM.B version is indicated on Y-axis coordinate display.</p>
Moving check	<ul style="list-style-type: none"> <li>Turn the X-axis JOG dial knob, until X-axis coordinate display indicate <u>0.05</u>, then press "ENTER" button.</li> </ul>	<p>X-axis      Y-axis      Z-axis</p> <p>0000.00 0000.00 0000.00</p> <p>180.00 150.00 150.00</p> <p>At the same time, X-Y Table and spindle head are traveling between 0. and max. distance.</p>
	<ul style="list-style-type: none"> <li>With keeping above situation, press "PAUSE" button.</li> </ul>	<p>Traveling of X-Y Table and spindle head stop.</p>
	<ul style="list-style-type: none"> <li>Turn the spindle control knob in Max. position, and then press "PAUSE" button (PAUSE OFF).</li> </ul>	<p>Spindle Unit revolve with max. speed and X-Y Table and spindle head travel again.</p>

## — ADJUSTMENT & MAINTENANCE —

### 5. CHECK & MAINTENANCE for MOTOR BRUSH

Attrition of Motor Brush cause trouble of Spindle motor.

And it is greatly affected by revolution speed of spindle Motor and power supply voltage that is supplied to spindle Motor.

It is mentioned by USER'S MANUAL of CAMM-3 with "The CAMM-3 should be serviced after every 250 hours of use to prevent the gradual attrition of part ...".

But, attrition of Motor Brush was about 1 or 2mm by 250/h in the example that we actually checked.

An occasion of MAINTENANCE of CAMM-3

- Please check at attrition degree of Motor Brush on the right of spindle motor at first.
- If attrition degree is large, please exchange Motor Brush of right and left side at the same time.
- When Motor Brush of the left side is exchanged, loosen the Ref. No. 23 socket cap screws which secure spindle motor, then change the direction of Motor.

Please do not forget readjusting tension of a belt after Motor Brush exchange.

### 6. CHECK of TIMER

Timer has been attached in the position of F-3 on Main Board.

Mark of this part moves graduation 0 to 10 by the current which is supplied to spindle motor.

It shows Motor being used for 1000 hours when Mark moved to graduation 10.

In doing and furnishing the contrary with upper and lower, it can be used again for 1000 hours.

Please utilize on the check of Motor Brush, other Maintenance and so on efficiently.

# — DIP SWITCH SETTING LIST —

