



Aviation Investigation Final Report

Location:	Iliamna, Alaska	Accident Number:	ANC18LA064
Date & Time:	August 7, 2018, 12:15 Local	Registration:	N7379U
Aircraft:	Cessna 207	Aircraft Damage:	Substantial
Defining Event:	Loss of engine power (total)	Injuries:	1 None
Flight Conducted Under:	Part 135: Air taxi & commuter - Non-scheduled		

Analysis

The pilot reported that shortly after takeoff, as he began to configure the airplane for cruise flight, the engine began to run rough and lose power, and he elected to immediately return to the airport. The engine subsequently lost total power and the pilot performed a forced landing on tundra-covered terrain, during which the airplane sustained substantial damage.

Examination revealed that the No. 2 piston was eroded on the bottom side, and a hole was burned through. The No. 2 piston and cylinder head were mechanically damaged by loose piston ring debris. Closer examination of the No. 2 cylinder head revealed re-solidified molten metal around the bottom Heli-Coil tang notch. All damage discovered was consistent with a pre-ignition/detonation event; however, the cause of the pre-ignition and/or detonation could not be determined based on the available information.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

A total loss of engine power due to detonation/preignition damage of the No. 2 cylinder and piston for reasons that could not be determined.

Findings

Aircraft	Recip eng cyl section - Damaged/degraded
Aircraft	(general) - Failure

Factual Information

History of Flight

Initial climb	Loss of engine power (total) (Defining event)
Emergency descent	Loss of engine power (total)
Emergency descent	Collision with terr/obj (non-CFIT)

On August 7, 2018, about 1215 Alaska daylight time, a Cessna 207 airplane, N7379U, was substantially damaged when it was involved in an accident near Iliamna, Alaska. The pilot was not injured. The airplane was operated as a Title 14 *Code of Federal Regulations* (CFR) Part 135 flight.

The pilot reported that, after takeoff, he started a climbing left turn toward his destination. As the airplane reached his intended altitude of 1,000 ft mean sea level, and as he began to configure the airplane for cruise flight, the engine began to run rough and lose power, so he elected to immediately return to the departure airport. He switched fuel tanks and activated the auxiliary fuel pump in an effort to restore full engine power. He noted that the engine roughness improved momentarily, followed by a severe engine vibration and complete loss of engine power. The pilot selected a forced landing area on tundra-covered terrain, during which the airplane sustained substantial damage to the fuselage and wings.

The airplane was subsequently recovered and returned to the operator’s base. A Federal Aviation Administration inspector reported that there was no obvious damage to the engine, and an engine run was attempted. Although the engine eventually started, it ran very rough and began to vibrate and the test was discontinued. The engine was sent to the manufacturer’s facility for further examination.

The examination revealed that the No. 2 piston was eroded on the bottom side, and a hole was burned through. The No. 2 piston and cylinder head were mechanically damaged by loose piston ring debris. Closer examination of the No. 2 cylinder head revealed re-solidified molten metal around the bottom Heli-Coil tang notch. All damage discovered was consistent with a pre-ignition/detonation event. The cause of the preignition and/or detonation could not be determined.

The Pilot's Handbook of Aeronautical Knowledge (FAA-H-8083-25B), states, in part:

“Detonation is an uncontrolled, explosive ignition of the fuel/air mixture within the cylinder's combustion chamber. It causes excessive temperatures and pressures which, if not corrected, can quickly lead to a failure of the piston, cylinder, or valves. In less severe cases, detonation causes engine overheating, roughness, or loss of power.”

“Preignition occurs when the fuel/air mixture ignites prior to the engine's normal ignition event. Premature burning is usually caused by a residual hot spot in the combustion chamber, often created by a small carbon deposit on a spark plug, a cracked spark plug insulator, or other damage to the cylinder that causes a part to heat sufficiently to ignite the fuel/air charge.”

Pilot Information

Certificate:	Airline transport	Age:	60,Male
Airplane Rating(s):	Single-engine land; Single-engine sea; Multi-engine land	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	4-point
Instrument Rating(s):	Airplane	Second Pilot Present:	No
Instructor Rating(s):	Airplane single-engine	Toxicology Performed:	No
Medical Certification:	Class 2 With waivers/limitations	Last FAA Medical Exam:	April 1, 2018
Occupational Pilot:	Yes	Last Flight Review or Equivalent:	
Flight Time:	10000 hours (Total, all aircraft), 1 hours (Last 24 hours, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	Cessna	Registration:	N7379U
Model/Series:	207	Aircraft Category:	Airplane
Year of Manufacture:	1978	Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	20700427
Landing Gear Type:	Tricycle	Seats:	
Date/Type of Last Inspection:	100 hour	Certified Max Gross Wt.:	3803 lbs
Time Since Last Inspection:	51.2 Hrs	Engines:	1 Reciprocating
Airframe Total Time:	18642.1 Hrs at time of accident	Engine Manufacturer:	Continental
ELT:	C126 installed, activated, did not aid in locating accident	Engine Model/Series:	IO 520 SERIES
Registered Owner:		Rated Power:	285 Horsepower
Operator:		Operating Certificate(s) Held:	Commuter air carrier (135), On-demand air taxi (135)

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	III,192 ft msl	Distance from Accident Site:	1 Nautical Miles
Observation Time:	11:53 Local	Direction from Accident Site:	360°
Lowest Cloud Condition:	Few / 3400 ft AGL	Visibility	10 miles
Lowest Ceiling:	Broken / 6500 ft AGL	Visibility (RVR):	
Wind Speed/Gusts:	10 knots /	Turbulence Type Forecast/Actual:	/
Wind Direction:	320°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	29.75 inches Hg	Temperature/Dew Point:	12.8°C
Precipitation and Obscuration:			
Departure Point:	Iliamna, AK	Type of Flight Plan Filed:	Company VFR
Destination:	Kokhanok, AK (9K2)	Type of Clearance:	None
Departure Time:		Type of Airspace:	

Airport Information

Airport:	Iliamna Airport PAIL	Runway Surface Type:	
Airport Elevation:	192 ft msl	Runway Surface Condition:	Soft
Runway Used:		IFR Approach:	None
Runway Length/Width:		VFR Approach/Landing:	None

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:		Aircraft Explosion:	None
Total Injuries:	1 None	Latitude, Longitude:	59.745834,-154.91749

Administrative Information

Investigator In Charge (IIC):	Johnson, Clinton		
Additional Participating Persons:	Jack Devlin; Federal Aviation Administration ; Anchorage , AK Nicole Charnon; Continental Motors ; Mobile, AL		
Original Publish Date:	April 1, 2022	Investigation Class:	3
Note:	The NTSB did not travel to the scene of this accident.		
Investigation Docket:	https://data.nts.gov/Docket?ProjectID=98036		

The National Transportation Safety Board (NTSB), established in 1967, is an independent federal agency mandated by Congress through the Independent Safety Board Act of 1974 to investigate transportation accidents, determine the probable causes of the accidents, issue safety recommendations, study transportation safety issues, and evaluate the safety effectiveness of government agencies involved in transportation. The NTSB makes public its actions and decisions through accident reports, safety studies, special investigation reports, safety recommendations, and statistical reviews.

The Independent Safety Board Act, as codified at 49 U.S.C. Section 1154(b), precludes the admission into evidence or use of any part of an NTSB report related to an incident or accident in a civil action for damages resulting from a matter mentioned in the report. A factual report that may be admissible under 49 U.S.C. § 1154(b) is available [here](#).