



Aviation Investigation Final Report

Location:	Mojave, California	Accident Number:	ANC18LA042
Date & Time:	June 4, 2018, 11:52 Local	Registration:	VH-XMH
Aircraft:	GIPPSAERO PTY LTD GA10	Aircraft Damage:	Destroyed
Defining Event:	Aerodynamic stall/spin	Injuries:	2 Minor
Flight Conducted Under:	Part 91: General aviation - Flight test		

Analysis

The airplane manufacturer was conducting spin flight testing for the installation of a cargo pod when the airplane exhibited aberrant behavior and the testing was halted. The chief design engineer (CDE) was consulted, and, to provide a margin of safety for further flights, a forward center of gravity position was authorized for flaps up and flaps takeoff entries to gain more insight into the airplane's behavior on the previous flight. At the final briefing, before the next flight, the flight crew added spins with flaps in the landing configuration (flaps landing) into the test plan without the CDE's consultation or authorization.

According to the pilot flying, after two wings-level, power on, flaps landing spins with left rudder and right aileron, a third spin entry was flown in the same configuration except that the entry was from a 30° left-bank turn. The airplane entered a normal spin, and, at one turn, flight controls were inputted for a normal recovery; however, the airplane settled into a fully developed spin. When recovery attempts failed, the decision was made to deploy the anti-spin parachute. After repeated unsuccessful attempts to deploy the anti-spin parachute, and when the airplane's altitude reached about 500 ft above the briefed minimum bailout altitude, both pilots called for and executed a bailout. The airplane impacted the ground and was destroyed.

A postaccident examination of the anti-spin parachute system revealed that half of the connector hook had opened, which allowed the activation pin lanyard for the anti-spin parachute to become disengaged.

Based on the airplane's previous aberrant behavior and the conservative parameters that the CDE had previously set, it is not likely that the CDE would have authorized abused spin entries without a prior testing buildup to those entries. Thus, the flight crew made an inappropriate decision to introduce flaps landing entry spin testing, and the failure of the anti-spin parachute contributed to the accident.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

The flight crew's inappropriate decision, without authorization or consultation from the manufacturer's chief design engineer, to introduce flaps in the landing configuration into the entry spin testing, which resulted in an unrecoverable spin and impact with the ground. Contributing to the accident was the failure of the anti-spin parachute.

Findings

Personnel issues	Decision making/judgment - Flight crew
Aircraft	(general) - Failure

Factual Information

History of Flight

Maneuvering	Aerodynamic stall/spin (Defining event)
Uncontrolled descent	Collision with terr/obj (non-CFIT)

On June 4, 2018, about 1152 Pacific daylight time, an Australian registered GIPPSAERO PTY LTD, GA10 airplane, VH-XMH, was destroyed after it impacted terrain following an unrecoverable spin, and the unsuccessful deployment of the anti-spin parachute near Mojave, California. The airplane was registered to GIPPSAERO PTY LTD and operated by GIPPSAERO PTY LTD in conjunction with the National Test Pilot School (NTPS) as a visual flight rules test flight under the provisions of 14 *Code of Federal Regulations Part 91.715 Special Flight Authorization* when the accident occurred. The Australian certificated commercial pilot and the United States certificated airline transport pilot sustained minor injuries. Visual meteorological conditions prevailed, and company flight following procedures were in effect.

According to the airplane manufacturer, the purpose of the flight was to conduct spin trials with the GA-10 airplane fitted with a cargo pod installation. Initial spin trials with the cargo pod were completed in Australia with company pilots, and the aircraft configured well away from the critical flight conditions identified during the original airplane certification spin testing. Due to scheduling and personnel constraints, it was decided to send the airplane and company personnel to NTPS to conduct the more critical spin tests. The flight tests commenced and proceeded until May 31, 2018, when the airplane exhibited some aberrant behavior, and the manufacturer's Chief Design Engineer (CDE) was consulted. To provide a margin of safety for further flights, a forward CG position was authorized for flaps up and flaps takeoff entries, in an effort, to gain more information into the airplane's aberrant behavior on the previous flight. At the final briefing, prior to the next flight, spins with landing flaps were added by the flight crew without consultation or authorization from the CDE.

According to the pilot flying, the flight departed about 1105 PDT and a stall series consisting of stalls with flaps up, flaps takeoff and flaps landing was completed prior to any spin entries, with stall characteristics normal and benign. The first spin entry was a wings level, power on, flaps landing spin with left rudder and right aileron. He said that the recovery took longer than expected, and the decision was made to repeat the test point. A repeat of the same entry resulted in a very similar spin with the recovery at one additional turn. The second test point (third spin entry) was flown in the same configuration as the first two, except that the entry was from a 30° left-bank turn. The airplane entered a normal spin and at one turn, flight controls were inputted for a normal recovery; however, the airplane settled into a fully developed spin. After 3 turns, the pilots in the chase aircraft called "three turns". The control yoke was held full forward with full opposite rudder, and right aileron was inputted, in an attempt, to affect yaw rate, to no avail, so the control yoke was returned to neutral, full forward and full right rudder. Around 10,000 ft, the pilots in the chase aircraft called "chute, chute, chute". The anti-spin parachute lever was pulled aft; however, the anti-spin parachute did not deploy even after repeated

attempts. At about 8,500 ft msl, 500 ft above the briefed minimum bailout altitude, both pilots called for and executed a bailout.

A postaccident examination of the anti-spin parachute system revealed that one half the connector hook had opened allowing the activation pin lanyard for the anti-spin parachute to become disengaged.

The closest weather reporting facility was Mojave Air and Space Port (KMHV), Mojave, California, about 9 miles north of the accident site. At 1200, a METAR from KMHV was reporting, in part: wind from 300° at 15 knots, gusting 20 knots; visibility, 10 statute miles; clouds and sky condition, clear; temperature, 93° F; dew point 39° F; altimeter, 29.91 inches of mercury.

Pilot Information

Certificate:	Airline transport; Flight instructor	Age:	70, Male
Airplane Rating(s):	Single-engine land; Single-engine sea	Seat Occupied:	Left
Other Aircraft Rating(s):	Glider; Helicopter	Restraint Used:	4-point
Instrument Rating(s):	Airplane	Second Pilot Present:	Yes
Instructor Rating(s):	Airplane multi-engine; Airplane single-engine; Glider	Toxicology Performed:	No
Medical Certification:	Class 2 With waivers/limitations	Last FAA Medical Exam:	April 12, 2018
Occupational Pilot:	Yes	Last Flight Review or Equivalent:	November 9, 2017
Flight Time:	9767 hours (Total, all aircraft), 46 hours (Total, this make and model), 8315 hours (Pilot In Command, all aircraft), 53 hours (Last 90 days, all aircraft), 22 hours (Last 30 days, all aircraft), 1 hours (Last 24 hours, all aircraft)		

Pilot Information

Certificate:	Commercial; Flight instructor; Foreign	Age:	61, Male
Airplane Rating(s):	Single-engine land; Multi-engine land	Seat Occupied:	Right
Other Aircraft Rating(s):	None	Restraint Used:	4-point
Instrument Rating(s):	Airplane	Second Pilot Present:	Yes
Instructor Rating(s):	Airplane multi-engine; Airplane single-engine	Toxicology Performed:	No
Medical Certification:	Class 2 With waivers/limitations	Last FAA Medical Exam:	March 20, 2018
Occupational Pilot:	Yes	Last Flight Review or Equivalent:	April 15, 2018
Flight Time:	10980 hours (Total, all aircraft), 287 hours (Total, this make and model), 10780 hours (Pilot In Command, all aircraft), 22 hours (Last 90 days, all aircraft), 14 hours (Last 30 days, all aircraft), 1 hours (Last 24 hours, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	GIPPSAERO PTY LTD	Registration:	VH-XMH
Model/Series:	GA10 NO SERIES	Aircraft Category:	Airplane
Year of Manufacture:	2016	Amateur Built:	
Airworthiness Certificate:	Certificate of authorization or waiver (COA)	Serial Number:	GA10-TP450-16-1
Landing Gear Type:	Tricycle	Seats:	10
Date/Type of Last Inspection:	September 17, 2017 100 hour	Certified Max Gross Wt.:	4751 lbs
Time Since Last Inspection:		Engines:	1 Turbo prop
Airframe Total Time:	113.1 Hrs at time of accident	Engine Manufacturer:	Rolls Royce
ELT:	C126 installed, activated, did not aid in locating accident	Engine Model/Series:	M250-B17F/2
Registered Owner:		Rated Power:	450 Horsepower
Operator:		Operating Certificate(s) Held:	None

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	KMHV,2801 ft msl	Distance from Accident Site:	9 Nautical Miles
Observation Time:	19:00 Local	Direction from Accident Site:	350°
Lowest Cloud Condition:	Clear	Visibility	10 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	15 knots / 20 knots	Turbulence Type Forecast/Actual:	/
Wind Direction:	300°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	29.9 inches Hg	Temperature/Dew Point:	34°C / 4°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	Mojave, CA	Type of Flight Plan Filed:	Company VFR
Destination:	Mojave, CA	Type of Clearance:	VFR flight following
Departure Time:		Type of Airspace:	Military operation area

Wreckage and Impact Information

Crew Injuries:	2 Minor	Aircraft Damage:	Destroyed
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	2 Minor	Latitude, Longitude:	34.93861,-118.126663(est)

Administrative Information

Investigator In Charge (IIC):	Banning, David
Additional Participating Persons:	
Original Publish Date:	April 20, 2020
Note:	The NTSB did not travel to the scene of this accident.
Investigation Docket:	https://data.nts.gov/Docket?ProjectID=97404

The National Transportation Safety Board (NTSB), established in 1967, is an independent federal agency mandated by Congress through the Independent Safety Board Act of 1974 to investigate transportation accidents, determine the probable causes of the accidents, issue safety recommendations, study transportation safety issues, and evaluate the safety effectiveness of government agencies involved in transportation. The NTSB makes public its actions and decisions through accident reports, safety studies, special investigation reports, safety recommendations, and statistical reviews.

The Independent Safety Board Act, as codified at 49 U.S.C. Section 1154(b), precludes the admission into evidence or use of any part of an NTSB report related to an incident or accident in a civil action for damages resulting from a matter mentioned in the report. A factual report that may be admissible under 49 U.S.C. § 1154(b) is available [here](#).