



# Aviation Investigation Final Report

<b>Location:</b>	Colorado Springs, Colorado	<b>Accident Number:</b>	WPR19TA034
<b>Date &amp; Time:</b>	November 20, 2018, 09:30 Local	<b>Registration:</b>	N27LA
<b>Aircraft:</b>	Cessna 172	<b>Aircraft Damage:</b>	Substantial
<b>Defining Event:</b>	Runway excursion	<b>Injuries:</b>	2 Minor
<b>Flight Conducted Under:</b>	Part 91: General aviation - Personal		

## Analysis

The pilot reported that, during a touch-and-go landing, he applied full power to take off and, although the airplane departed the runway surface about 50 knots, it did not accelerate, and the airspeed decreased. The airplane began exhibiting characteristics consistent with a stall and he lowered the nose. The airplane then settled back onto the ground slightly off the left side of the runway surface and continued through a grassy field, a fence, and a ditch. The airplane nosed over and came to rest inverted, resulting in substantial damage. Witnesses reported observing the airplane in a nose-high attitude before it descended from view. The flaps were found extended to 40° at the accident site.

The density altitude at the time of the accident was about 7,386 ft, and there was an approximate 4-knot tailwind for the landing runway, which had a 1.4% upslope. According to the Federal Aviation Administration Airport/Facility directory, the opposite runway was recommended for touch-and-go landings in tailwind conditions up to 5 knots.

According to the manufacturer's takeoff performance chart, there was adequate runway available for takeoff; however, given the high-density altitude, the tailwind, and the runway upslope, the distance required to conduct a touch-and-go landing and takeoff distance were significantly increased, which resulted in the airplane's inability to become airborne within the remaining runway.

## Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

The pilot's decision to perform a touch-and-go landing at a high-density altitude airport, with a tailwind, and on an upsloping runway, which resulted in decreased airplane performance and the airplane's inability to become airborne within the available runway.

## Findings

<b>Personnel issues</b>	Decision making/judgment - Pilot
<b>Aircraft</b>	Climb rate - Capability exceeded
<b>Environmental issues</b>	Sloped/uneven terrain - Effect on operation
<b>Environmental issues</b>	Tailwind - Effect on operation
<b>Environmental issues</b>	High density altitude - Effect on operation

## Factual Information

### History of Flight

<b>Takeoff</b>	Runway excursion (Defining event)
<b>Takeoff-rejected takeoff</b>	Collision with terr/obj (non-CFIT)
<b>Takeoff-rejected takeoff</b>	Nose over/nose down

On November 20, 2018, about 0930 mountain standard time, a Cessna 172 airplane, N27LA, was substantially damaged when it was involved in an accident near Colorado Springs, Colorado. The commercial pilot and passenger sustained minor injuries. The airplane was operated as a Title 14 *Code of Federal Regulations* Part 91 personal flight.

The pilot reported that, after departure, they flew to a different airport and conducted three uneventful touch-and-go landings. He then proceeded to the accident airport and performed a straight-in approach to runway 33. He approached the runway at a normal speed of 60 knots with the flaps fully down and the "mixture set appropriately for the 7,000-ft field elevation"; he did not apply carburetor heat. The airplane landed, and he added full power, raised the flaps, and raised the nose to take off. The airplane became airborne about 50 knots but did not accelerate; instead, the airspeed decreased to about 45 knots. The airplane began exhibiting characteristics consistent with a stall, and he lowered the nose. The airplane settled back onto the ground slightly off the left side of the runway surface and rolled through a grassy field, a fence, and impacted a ditch. The airplane nosed over and came to rest inverted.

Witnesses reported observing the airplane in a nose-high attitude before it descended from view. Shortly thereafter, they observed people running toward the airplane.

Examination conducted by a Federal Aviation Administration (FAA) inspector revealed that the flaps were fully extended. The flap indicator in the cockpit displayed 40°.

Weather about the time of the accident was reported as wind from 130° at 4 knots, temperature 9°C, dewpoint -11°C, and an altimeter setting of 30.26 inches of mercury, which corresponded to a density altitude of about 7,386 ft. According to the FAA Airport/Facility Directory, "runway 15 is recommended for takeoff, touch and go landings when effective tailwind is less than 5 knots". The directory stated that runway 33 had an upslope of 1.4%. Runway 15/33 was 60 ft wide and about 6,000 ft long.

The takeoff performance chart in the 172M Pilot Operating Handbook indicates the following airplane configuration and environmental conditions during takeoff: Flaps up; full throttle prior to brake release; zero wind; and a paved, level, dry runway. The notes section stated, "for operation with tailwinds up to 10 knots, increase distances by 10% for each 2 knots." It further stated, "prior to takeoff from fields above 3,000 feet elevation, the mixture should be leaned to give maximum RPM in a full throttle, static runup."

## Pilot Information

<b>Certificate:</b>	Commercial	<b>Age:</b>	76, Male
<b>Airplane Rating(s):</b>	Single-engine land; Multi-engine land	<b>Seat Occupied:</b>	Left
<b>Other Aircraft Rating(s):</b>	None	<b>Restraint Used:</b>	3-point
<b>Instrument Rating(s):</b>	Airplane	<b>Second Pilot Present:</b>	No
<b>Instructor Rating(s):</b>	None	<b>Toxicology Performed:</b>	No
<b>Medical Certification:</b>	Class 3 With waivers/limitations	<b>Last FAA Medical Exam:</b>	December 4, 2016
<b>Occupational Pilot:</b>	No	<b>Last Flight Review or Equivalent:</b>	April 3, 2018
<b>Flight Time:</b>	3156 hours (Total, all aircraft), 36 hours (Total, this make and model), 2777 hours (Pilot In Command, all aircraft), 17 hours (Last 90 days, all aircraft), 6 hours (Last 30 days, all aircraft), 1 hours (Last 24 hours, all aircraft)		

## Aircraft and Owner/Operator Information

<b>Aircraft Make:</b>	Cessna	<b>Registration:</b>	N27LA
<b>Model/Series:</b>	172 M	<b>Aircraft Category:</b>	Airplane
<b>Year of Manufacture:</b>	1975	<b>Amateur Built:</b>	
<b>Airworthiness Certificate:</b>	Normal	<b>Serial Number:</b>	17265689
<b>Landing Gear Type:</b>	Tricycle	<b>Seats:</b>	4
<b>Date/Type of Last Inspection:</b>	October 19, 2018 100 hour	<b>Certified Max Gross Wt.:</b>	2299 lbs
<b>Time Since Last Inspection:</b>	66 Hrs	<b>Engines:</b>	1 Reciprocating
<b>Airframe Total Time:</b>	9188 Hrs at time of accident	<b>Engine Manufacturer:</b>	Lycoming
<b>ELT:</b>	C91 installed, not activated	<b>Engine Model/Series:</b>	O-320 SERIES
<b>Registered Owner:</b>		<b>Rated Power:</b>	160 Horsepower
<b>Operator:</b>		<b>Operating Certificate(s) Held:</b>	None
<b>Operator Does Business As:</b>	Peak Aviation	<b>Operator Designator Code:</b>	

## Meteorological Information and Flight Plan

<b>Conditions at Accident Site:</b>	Visual (VMC)	<b>Condition of Light:</b>	Day
<b>Observation Facility, Elevation:</b>	FLY,6874 ft msl	<b>Distance from Accident Site:</b>	0 Nautical Miles
<b>Observation Time:</b>	09:35 Local	<b>Direction from Accident Site:</b>	
<b>Lowest Cloud Condition:</b>	Clear	<b>Visibility</b>	10 miles
<b>Lowest Ceiling:</b>	None	<b>Visibility (RVR):</b>	
<b>Wind Speed/Gusts:</b>	4 knots /	<b>Turbulence Type Forecast/Actual:</b>	None / None
<b>Wind Direction:</b>	130°	<b>Turbulence Severity Forecast/Actual:</b>	N/A / N/A
<b>Altimeter Setting:</b>	30.26 inches Hg	<b>Temperature/Dew Point:</b>	9°C / -11°C
<b>Precipitation and Obscuration:</b>	No Obscuration; No Precipitation		
<b>Departure Point:</b>	Colorado Spring, CO (COS )	<b>Type of Flight Plan Filed:</b>	None
<b>Destination:</b>	Colorado Spring, CO (COS )	<b>Type of Clearance:</b>	None
<b>Departure Time:</b>	08:15 Local	<b>Type of Airspace:</b>	

## Airport Information

<b>Airport:</b>	Meadow Lake Airport FLY	<b>Runway Surface Type:</b>	Asphalt
<b>Airport Elevation:</b>	6874 ft msl	<b>Runway Surface Condition:</b>	Dry
<b>Runway Used:</b>	33	<b>IFR Approach:</b>	None
<b>Runway Length/Width:</b>	6000 ft / 60 ft	<b>VFR Approach/Landing:</b>	Touch and go

## Wreckage and Impact Information

<b>Crew Injuries:</b>	1 Minor	<b>Aircraft Damage:</b>	Substantial
<b>Passenger Injuries:</b>	1 Minor	<b>Aircraft Fire:</b>	None
<b>Ground Injuries:</b>	N/A	<b>Aircraft Explosion:</b>	None
<b>Total Injuries:</b>	2 Minor	<b>Latitude, Longitude:</b>	38.940555,-104.568611(est)

## Administrative Information

<b>Investigator In Charge (IIC):</b>	Link, Samantha		
<b>Additional Participating Persons:</b>	Michael Aubry; Federal Aviation Administration; Denver, CO		
<b>Original Publish Date:</b>	September 16, 2021	<b>Investigation Class:</b>	3
<b>Note:</b>	The NTSB did not travel to the scene of this accident.		
<b>Investigation Docket:</b>	<a href="https://data.nts.gov/Docket?ProjectID=98714">https://data.nts.gov/Docket?ProjectID=98714</a>		

The National Transportation Safety Board (NTSB), established in 1967, is an independent federal agency mandated by Congress through the Independent Safety Board Act of 1974 to investigate transportation accidents, determine the probable causes of the accidents, issue safety recommendations, study transportation safety issues, and evaluate the safety effectiveness of government agencies involved in transportation. The NTSB makes public its actions and decisions through accident reports, safety studies, special investigation reports, safety recommendations, and statistical reviews.

The Independent Safety Board Act, as codified at 49 U.S.C. Section 1154(b), precludes the admission into evidence or use of any part of an NTSB report related to an incident or accident in a civil action for damages resulting from a matter mentioned in the report. A factual report that may be admissible under 49 U.S.C. § 1154(b) is available [here](#).