



Aviation Investigation Final Report

| | | | |
|--------------------------------|--------------------------------------|-------------------------|-------------|
| Location: | Shreveport, Louisiana | Accident Number: | CEN18LA281 |
| Date & Time: | July 19, 2018, 08:02 Local | Registration: | N7080F |
| Aircraft: | Piper PA28 | Aircraft Damage: | Substantial |
| Defining Event: | Loss of engine power (partial) | Injuries: | 1 None |
| Flight Conducted Under: | Part 91: General aviation - Personal | | |

Analysis

The pilot departed on a postmaintenance check flight after an annual inspection on the previous day. According to the pilot, the airplane was flown in the local traffic pattern before departing the area. As the airplane climbed through 2,500 ft, it was not climbing more than 300 ft per minute without losing airspeed, and the pilot noticed a decrease in engine rpm. The pilot indicated that the oil pressure and oil temperature were normal, the vacuum gauge indicated "zero," and gyroscopic instruments began to drift and tumble. The pilot proceeded directly for the nearest airport, and when on final approach for the runway, the engine rpm and airspeed decreased. The engine did not respond to throttle inputs, and the pilot landed the airplane on a river levy. The airplane bounced, contacted a road, and came to rest against the airport perimeter fence, which resulted in substantial damage to both wings. Examination of the engine revealed that the output shaft of the vacuum pump was sheared. It could not be determined if the vacuum pump output shaft failed before or during the accident sequence. Additional engine information was not available. The reason for the partial loss of engine power could not be determined.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

The partial loss of engine power for reasons that could not be determined based on the available evidence.

Findings

| | |
|-----------------------|------------------------------------|
| Not determined | (general) - Unknown/Not determined |
| Aircraft | (general) - Failure |

Factual Information

History of Flight

| | |
|--------------------------|---|
| Maneuvering | Loss of engine power (partial) (Defining event) |
| Emergency descent | Off-field or emergency landing |
| Landing | Collision with terr/obj (non-CFIT) |

On July 19, 2018, about 0802 central daylight time, a Piper PA28A, N7080F, sustained substantial damage during a forced landing after a partial loss of engine power near the Shreveport Executive Airport (DTN), Shreveport, Louisiana. The commercial pilot, who was the sole occupant, was not injured. The airplane was owned and piloted by a private individual. Visual meteorological conditions prevailed and a flight plan was not filed. The post-maintenance check flight was conducted under the provisions of Title 14 *Federal Code of Regulations* Part 91. The flight originated about 0730 from DTN.

The annual inspection on the airplane was completed on July 18, 2018, and the purpose of the flight was a post-maintenance check flight. According to the pilot, after takeoff from DTN, he stayed in the local traffic pattern and performed two touch and go landings. He proceeded north of the airport and climbed through 2,500 ft; however, the airplane could not attain more than a 300-ft per minute rate of climb without losing airspeed, and he noticed a decrease in engine RPM's. The oil pressure and oil temperature were in the normal operating range, the vacuum gauge indicated "zero," and gyroscopic instruments began to drift and tumble. The pilot proceeded directly for DTN and planning to land on runway 14. On final, the engine RPM's decreased and the airplane airspeed decreased. The engine did not respond to throttle inputs and the pilot was forced to land the airplane on a river levy. The airplane bounced into the air and came back down, contacted a road, and came to rest against the perimeter fence of runway 14. Both wings sustained substantial damage.

Examination of the engine by a Federal Aviation Administration inspector revealed that the output shaft of the vacuum pump was sheared. The pilot did not submit the National Transportation Safety Board Accident Report Form 6120, and additional engine information was not available. The reason for the vacuum pump output shaft failure and partial loss of engine power was not determined.

Pilot Information

| | | | |
|----------------------------------|--|--|-----------------|
| Certificate: | Commercial; Private | Age: | 32,Male |
| Airplane Rating(s): | Single-engine land; Multi-engine land | Seat Occupied: | Left |
| Other Aircraft Rating(s): | None | Restraint Used: | 3-point |
| Instrument Rating(s): | Airplane | Second Pilot Present: | No |
| Instructor Rating(s): | None | Toxicology Performed: | No |
| Medical Certification: | Class 2 Without waivers/limitations | Last FAA Medical Exam: | January 5, 2018 |
| Occupational Pilot: | No | Last Flight Review or Equivalent: | January 5, 2018 |
| Flight Time: | 265 hours (Total, all aircraft), 7 hours (Total, this make and model), 3 hours (Last 90 days, all aircraft), 0.5 hours (Last 24 hours, all aircraft) | | |

Aircraft and Owner/Operator Information

| | | | |
|--------------------------------------|---------------------------------|---------------------------------------|-----------------|
| Aircraft Make: | Piper | Registration: | N7080F |
| Model/Series: | PA28 | Aircraft Category: | Airplane |
| Year of Manufacture: | 1976 | Amateur Built: | |
| Airworthiness Certificate: | None | Serial Number: | 28-7725-085 |
| Landing Gear Type: | Tricycle | Seats: | 4 |
| Date/Type of Last Inspection: | July 18, 2018 Annual | Certified Max Gross Wt.: | |
| Time Since Last Inspection: | 0 Hrs | Engines: | 1 Reciprocating |
| Airframe Total Time: | 3301.18 Hrs at time of accident | Engine Manufacturer: | Lycoming |
| ELT: | Installed, not activated | Engine Model/Series: | O-320-E3D |
| Registered Owner: | | Rated Power: | 150 Horsepower |
| Operator: | On file | Operating Certificate(s) Held: | None |

Meteorological Information and Flight Plan

| | | | |
|---|-----------------------|---|------------------|
| Conditions at Accident Site: | Visual (VMC) | Condition of Light: | Day |
| Observation Facility, Elevation: | DTN,179 ft msl | Distance from Accident Site: | 0 Nautical Miles |
| Observation Time: | 07:53 Local | Direction from Accident Site: | 0° |
| Lowest Cloud Condition: | Clear | Visibility | 10 miles |
| Lowest Ceiling: | None | Visibility (RVR): | |
| Wind Speed/Gusts: | 4 knots / | Turbulence Type Forecast/Actual: | None / None |
| Wind Direction: | 210° | Turbulence Severity Forecast/Actual: | N/A / N/A |
| Altimeter Setting: | 29.93 inches Hg | Temperature/Dew Point: | 29°C / 24°C |
| Precipitation and Obscuration: | | | |
| Departure Point: | Shreveport, LA (DTN) | Type of Flight Plan Filed: | |
| Destination: | Shreveport, LA (DTN) | Type of Clearance: | None |
| Departure Time: | 07:30 Local | Type of Airspace: | Class E |

Airport Information

| | | | |
|-----------------------------|--------------------------|----------------------------------|----------------|
| Airport: | Shreveport Executive DTN | Runway Surface Type: | |
| Airport Elevation: | 179 ft msl | Runway Surface Condition: | Vegetation |
| Runway Used: | | IFR Approach: | None |
| Runway Length/Width: | | VFR Approach/Landing: | Forced landing |

Wreckage and Impact Information

| | | | |
|----------------------------|--------|---------------------------------|---------------------------|
| Crew Injuries: | 1 None | Aircraft Damage: | Substantial |
| Passenger Injuries: | | Aircraft Fire: | None |
| Ground Injuries: | N/A | Aircraft Explosion: | None |
| Total Injuries: | 1 None | Latitude, Longitude: | 32.540279,-93.745002(est) |

Administrative Information

| | |
|--|---|
| Investigator In Charge (IIC): | Lemishko, Alexander |
| Additional Participating Persons: | Lisa Cotham; FAA FSDO; Baton Rouge, LA |
| Original Publish Date: | June 3, 2020 |
| Note: | The NTSB did not travel to the scene of this accident. |
| Investigation Docket: | https://data.nts.gov/Docket?ProjectID=97818 |

The National Transportation Safety Board (NTSB), established in 1967, is an independent federal agency mandated by Congress through the Independent Safety Board Act of 1974 to investigate transportation accidents, determine the probable causes of the accidents, issue safety recommendations, study transportation safety issues, and evaluate the safety effectiveness of government agencies involved in transportation. The NTSB makes public its actions and decisions through accident reports, safety studies, special investigation reports, safety recommendations, and statistical reviews.

The Independent Safety Board Act, as codified at 49 U.S.C. Section 1154(b), precludes the admission into evidence or use of any part of an NTSB report related to an incident or accident in a civil action for damages resulting from a matter mentioned in the report. A factual report that may be admissible under 49 U.S.C. § 1154(b) is available [here](#).