



AVIATION



HIGHWAY



MARINE



RAILROAD



PIPELINE

Aviation Investigation Final Report

Location:	Sioux Falls, South Dakota	Accident Number:	CEN16CA364
Date & Time:	August 30, 2016, 08:45 Local	Registration:	N23583
Aircraft:	Beech V35B	Aircraft Damage:	Substantial
Defining Event:	Loss of engine power (total)	Injuries:	2 None
Flight Conducted Under:	Part 91: General aviation - Instructional		

Analysis

While on final during a practice instrument approach, the engine lost total power. An attempted engine restart and switching of the fuel tanks was unsuccessful. The flight instructor took control of the airplane from the pilot receiving instruction, and executed a forced landing to a corn field. The airplane sustained substantial damage to both wings. The airplane was recovered from the field and about 1 cup of fuel was found in the right fuel tank, and the left wing fuel tank was about 3/4's full. The engine was functionally tested for about 10 minutes on the airframe with no anomalies noted. The pilot reported he did not check the wing fuel tanks during pre-flight and relied on the cockpit fuel gauges for fuel quantity.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

The pilot's failure to adequately manage the available fuel supply, resulting in fuel starvation and a total loss of engine power. Contributing to the accident was the inadequate preflight by the pilot and flight instructor, and the flight instructor's failure to monitor the fuel levels.

Findings

Aircraft	Fuel - Fluid management
Aircraft	Fuel - Fluid level
Personnel issues	Use of equip/system - Pilot
Personnel issues	Fuel planning - Pilot
Personnel issues	Fuel planning - Instructor/check pilot

Factual Information

History of Flight

Approach-IFR final approach	Loss of engine power (total) (Defining event)
Approach-IFR final approach	Collision with terr/obj (non-CFIT)

Pilot Information

Certificate:	Private	Age:	45,Male
Airplane Rating(s):	Single-engine land	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	3-point
Instrument Rating(s):	None	Second Pilot Present:	Yes
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 3 Without waivers/limitations	Last FAA Medical Exam:	May 2, 2016
Occupational Pilot:	No	Last Flight Review or Equivalent:	October 22, 2015
Flight Time:	177 hours (Total, all aircraft), 106 hours (Total, this make and model), 177 hours (Pilot In Command, all aircraft), 24 hours (Last 90 days, all aircraft), 14 hours (Last 30 days, all aircraft)		

Flight instructor Information

Certificate:	Airline transport; Commercial; Flight instructor	Age:	59,Male
Airplane Rating(s):	Single-engine land; Multi-engine land	Seat Occupied:	Right
Other Aircraft Rating(s):		Restraint Used:	3-point
Instrument Rating(s):	Airplane	Second Pilot Present:	Yes
Instructor Rating(s):	Airplane multi-engine; Airplane single-engine; Instrument airplane	Toxicology Performed:	No
Medical Certification:	Class 1 Without waivers/limitations	Last FAA Medical Exam:	June 13, 2016
Occupational Pilot:	Yes	Last Flight Review or Equivalent:	June 4, 2016
Flight Time:	14233 hours (Total, all aircraft), 30 hours (Total, this make and model), 8777 hours (Pilot In Command, all aircraft), 87 hours (Last 90 days, all aircraft), 24 hours (Last 30 days, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	Beech	Registration:	N23583
Model/Series:	V35B B	Aircraft Category:	Airplane
Year of Manufacture:	1978	Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	D-10087
Landing Gear Type:	Retractable - Tricycle	Seats:	4
Date/Type of Last Inspection:	May 24, 2016 Annual	Certified Max Gross Wt.:	3412 lbs
Time Since Last Inspection:		Engines:	1 Reciprocating
Airframe Total Time:	3669.5 Hrs as of last inspection	Engine Manufacturer:	Teledyne Continental
ELT:	C91 installed, not activated	Engine Model/Series:	IO-520-B
Registered Owner:		Rated Power:	285 Horsepower
Operator:		Operating Certificate(s) Held:	None

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	FSD, 1475 ft msl	Distance from Accident Site:	1 Nautical Miles
Observation Time:	07:56 Local	Direction from Accident Site:	30°
Lowest Cloud Condition:	Clear	Visibility	10 miles
Lowest Ceiling:	Overcast / 20000 ft AGL	Visibility (RVR):	
Wind Speed/Gusts:	5 knots /	Turbulence Type Forecast/Actual:	/ None
Wind Direction:	130°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	30.2 inches Hg	Temperature/Dew Point:	22°C / 20°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	Tea, SD (Y14)	Type of Flight Plan Filed:	None
Destination:	Sioux Falls, SD (FSD)	Type of Clearance:	VFR
Departure Time:	08:30 Local	Type of Airspace:	Class D

Airport Information

Airport:	Joe Foss Field Airport FSD	Runway Surface Type:	Concrete
Airport Elevation:	1430 ft msl	Runway Surface Condition:	Dry
Runway Used:	21	IFR Approach:	ASR;Practice
Runway Length/Width:	8999 ft / 150 ft	VFR Approach/Landing:	Forced landing

Wreckage and Impact Information

Crew Injuries:	2 None	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	2 None	Latitude, Longitude:	43.594444,-96.73278(est)

Administrative Information

Investigator In Charge (IIC):	Sauer, Aaron
Additional Participating Persons:	Ken East; Federal Aviation Administration; Rapid City, SD
Original Publish Date:	December 5, 2016
Note:	This accident report documents the factual circumstances of this accident as described to the NTSB.
Investigation Docket:	https://data.nts.gov/Docket?ProjectID=93988

The National Transportation Safety Board (NTSB), established in 1967, is an independent federal agency mandated by Congress through the Independent Safety Board Act of 1974 to investigate transportation accidents, determine the probable causes of the accidents, issue safety recommendations, study transportation safety issues, and evaluate the safety effectiveness of government agencies involved in transportation. The NTSB makes public its actions and decisions through accident reports, safety studies, special investigation reports, safety recommendations, and statistical reviews.

The Independent Safety Board Act, as codified at 49 U.S.C. Section 1154(b), precludes the admission into evidence or use of any part of an NTSB report related to an incident or accident in a civil action for damages resulting from a matter mentioned in the report. A factual report that may be admissible under 49 U.S.C. § 1154(b) is available [here](#).