



# Aviation Investigation Final Report

<b>Location:</b>	Rhome, Texas	<b>Accident Number:</b>	CEN18FA336
<b>Date &amp; Time:</b>	August 16, 2018, 19:35 Local	<b>Registration:</b>	N2893Q
<b>Aircraft:</b>	Cessna 172	<b>Aircraft Damage:</b>	Substantial
<b>Defining Event:</b>	Loss of engine power (total)	<b>Injuries:</b>	1 Fatal, 3 Serious
<b>Flight Conducted Under:</b>	Part 91: General aviation - Personal		

## Analysis

The commercial pilot was taking family members for rides in his airplane; the accident flight was the third flight of the evening. After the second flight, the pilot landed and taxied the airplane back to his property, where three family members boarded the airplane while the engine continued to run. The pilot taxied back to the runway and departed. A pilot-rated witness stated that the takeoff roll was longer than expected, and, once airborne, the airplane pitched "very high" nose-up to about 50 ft above ground level (agl), then the nose came back down. The airplane appeared to accelerate down the runway until it climbed to about 300 ft agl, then made a left turn and descended out of view. The airplane impacted several trees and continued into a field, where it came to rest inverted. Damage to the propeller was consistent with a lack of engine power at the time of impact.

Examination of the airplane revealed evidence of a longstanding pattern of inadequate maintenance, including a rodent's nest in the leading edge of the left wing, a large mud dauber nest on the oil cooler, and cobwebs in the engine compartment. An automotive hydraulic hose was used in place of the main fuel line from the gascolator to the carburetor. The gascolator fuel strainer contained 3 large pieces of organic debris similar to insect cocoons, which were the same size as the hydraulic hose and associated fuel fitting. It is likely that the fuel line was removed for an extended period of time and eventually replaced with the automotive hydraulic hose, during which time the fuel system was exposed, which allowed insects to nest inside; because there were no maintenance records associated with the airplane, it could not be determined when the hose was replaced. During the accident flight, it is likely that the organic material became dislodged and restricted fuel to the carburetor, which subsequently starved the engine of available fuel and resulted in a total loss of engine power.

The autopsy of the pilot revealed evidence of hypertension and coronary artery disease; however, it is unlikely that these conditions contributed to the accident. Toxicological testing indicated that the pilot had been using alcohol before the accident and had levels considered impairing; it is likely that alcohol impaired the pilot's decision making and his ability to operate the airplane. Toxicological testing also revealed evidence that the pilot had used marijuana before the accident; however, it could not be determined if the concentrations would have been impairing or would have affected his performance.

## Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be: The pilot's inadequate maintenance of the airplane, which resulted in a total loss of engine power due to fuel starvation when organic debris restricted available fuel to the carburetor, and the pilot's impairment due to the ingestion of alcohol, which affected his ability to safely operate the airplane following the loss of engine power.

### Findings

<b>Personnel issues</b>	(general) - Pilot
<b>Personnel issues</b>	Decision making/judgment - Pilot
<b>Personnel issues</b>	Alcohol - Pilot
<b>Aircraft</b>	Fuel distribution - Not serviced/maintained
<b>Aircraft</b>	Fuel distribution - Damaged/degraded
<b>Aircraft</b>	Hoses and tubes - Inadequate inspection
<b>Aircraft</b>	Hoses and tubes - Incorrect service/maintenance
<b>Aircraft</b>	Hoses and tubes - Incorrect use/operation
<b>Aircraft</b>	Fuel filter-strainer - Not serviced/maintained

# Factual Information

## History of Flight

Prior to flight	Preflight or dispatch event
Prior to flight	Aircraft inspection event
Initial climb	Fuel starvation
Initial climb	Loss of engine power (total) (Defining event)
Emergency descent	Off-field or emergency landing

On August 16, 2018, about 1935 central daylight time, a Cessna 172L airplane, N2893Q, impacted trees and terrain shortly after departure from Rhome Meadows Airport (T76), Rhome, Texas. The commercial pilot was fatally injured and the three passengers sustained serious injuries. The airplane sustained substantial damage. The airplane was registered to and operated by the pilot as a Title 14 *Code of Federal Regulations (CFR)* Part 91 personal flight. Visual meteorological conditions prevailed at the time of the accident and no flight plan had been filed. The local flight was departing T76 at the time of the accident.

A family member stated that the pilot retrieved the airplane from under the open-air shelter for "family fun night" and was giving rides to several family members. The family members stated that the pilot had flown the airplane about one week before the accident, then again two times immediately preceding the accident flight. The two preceding flights lasted about 20 minutes and 10 minutes respectively and the family members reported no anomalies with the airplane. They also stated that during the accident flight the airplane departed from the grass runway and did not gain much altitude before it banked hard to the left and then descended behind a tree line. Figure 1 represents a satellite map view of T76 and the accident location.



**Figure 1.** Overhead map view of airport and accident area

A pilot-rated witness reported that he saw the airplane depart T76 and then land soon after. The airplane taxied back and three passengers boarded with the engine still running. He stated that the airplane taxied back to the runway and started the takeoff roll, during which the engine did not sound like it was developing full power. The takeoff roll was longer than he expected, and once the airplane was airborne, the nose pitched up "very high" to about 50 ft above ground level (agl), then the nose came back down. The airplane flew low over the runway and appeared to accelerate until it pitched up and climbed to about 300 ft agl. The airplane then made a left turn and descended out of view.

## Pilot Information

<b>Certificate:</b>	Commercial	<b>Age:</b>	63,Male
<b>Airplane Rating(s):</b>	Single-engine land; Multi-engine land	<b>Seat Occupied:</b>	Right
<b>Other Aircraft Rating(s):</b>	None	<b>Restraint Used:</b>	Lap only
<b>Instrument Rating(s):</b>	Airplane	<b>Second Pilot Present:</b>	No
<b>Instructor Rating(s):</b>	None	<b>Toxicology Performed:</b>	Yes
<b>Medical Certification:</b>	Class 2 With waivers/limitations	<b>Last FAA Medical Exam:</b>	October 13, 2017
<b>Occupational Pilot:</b>	Yes	<b>Last Flight Review or Equivalent:</b>	
<b>Flight Time:</b>	(Estimated) 8000 hours (Total, all aircraft)		

## Passenger Information

<b>Certificate:</b>		<b>Age:</b>	36,Male
<b>Airplane Rating(s):</b>		<b>Seat Occupied:</b>	Right
<b>Other Aircraft Rating(s):</b>		<b>Restraint Used:</b>	Lap only
<b>Instrument Rating(s):</b>		<b>Second Pilot Present:</b>	No
<b>Instructor Rating(s):</b>		<b>Toxicology Performed:</b>	No
<b>Medical Certification:</b>		<b>Last FAA Medical Exam:</b>	
<b>Occupational Pilot:</b>	No	<b>Last Flight Review or Equivalent:</b>	
<b>Flight Time:</b>			

## Passenger Information

<b>Certificate:</b>		<b>Age:</b>	14,Male
<b>Airplane Rating(s):</b>		<b>Seat Occupied:</b>	Left
<b>Other Aircraft Rating(s):</b>		<b>Restraint Used:</b>	Lap only
<b>Instrument Rating(s):</b>		<b>Second Pilot Present:</b>	No
<b>Instructor Rating(s):</b>		<b>Toxicology Performed:</b>	No
<b>Medical Certification:</b>		<b>Last FAA Medical Exam:</b>	
<b>Occupational Pilot:</b>	No	<b>Last Flight Review or Equivalent:</b>	
<b>Flight Time:</b>			

## Passenger Information

<b>Certificate:</b>		<b>Age:</b>	9, Male
<b>Airplane Rating(s):</b>		<b>Seat Occupied:</b>	Left
<b>Other Aircraft Rating(s):</b>		<b>Restraint Used:</b>	Lap only
<b>Instrument Rating(s):</b>		<b>Second Pilot Present:</b>	No
<b>Instructor Rating(s):</b>		<b>Toxicology Performed:</b>	No
<b>Medical Certification:</b>		<b>Last FAA Medical Exam:</b>	
<b>Occupational Pilot:</b>	No	<b>Last Flight Review or Equivalent:</b>	
<b>Flight Time:</b>			

On his most recent second-class medical certificate application, dated October 13, 2017, the pilot reported 8,000 total hours of flight experience and 125 hours in the preceding 6 months. The pilot's wife stated that he did not log his recent flight time and had not recorded flights in his pilot logbook since the 1990s.

During the flight, the pilot was seated in the front right seat with a minor in the front left seat; an adult and minor were seated on the rear bench seat.

## Aircraft and Owner/Operator Information

<b>Aircraft Make:</b>	Cessna	<b>Registration:</b>	N2893Q
<b>Model/Series:</b>	172 L	<b>Aircraft Category:</b>	Airplane
<b>Year of Manufacture:</b>	1971	<b>Amateur Built:</b>	
<b>Airworthiness Certificate:</b>	Normal	<b>Serial Number:</b>	17259893
<b>Landing Gear Type:</b>	Tricycle	<b>Seats:</b>	4
<b>Date/Type of Last Inspection:</b>	Unknown	<b>Certified Max Gross Wt.:</b>	2299 lbs
<b>Time Since Last Inspection:</b>		<b>Engines:</b>	1 Reciprocating
<b>Airframe Total Time:</b>		<b>Engine Manufacturer:</b>	Lycoming
<b>ELT:</b>	C91A installed, not activated	<b>Engine Model/Series:</b>	O-320-E2D
<b>Registered Owner:</b>		<b>Rated Power:</b>	150 Horsepower
<b>Operator:</b>	On file	<b>Operating Certificate(s) Held:</b>	None

The pilot's wife stated that the airplane's maintenance logbooks were never received from the previous owner after the airplane was purchased in 2013. There was no documentation of maintenance performed since that time and no evidence that the airplane had received an annual inspection. A representative for the previous owner could not find the logbooks.

Family members stated that fuel cans, which were filled at another airport, were typically used to refill



the airplane; those fuel cans were used to fuel the airplane on the night of the accident. The fuel cans were filled at an unknown time the week before the accident.

### Meteorological Information and Flight Plan

<b>Conditions at Accident Site:</b>	Visual (VMC)	<b>Condition of Light:</b>	Dusk
<b>Observation Facility, Elevation:</b>	KLUD,1047 ft msl	<b>Distance from Accident Site:</b>	8 Nautical Miles
<b>Observation Time:</b>	17:35 Local	<b>Direction from Accident Site:</b>	324°
<b>Lowest Cloud Condition:</b>	Clear	<b>Visibility</b>	10 miles
<b>Lowest Ceiling:</b>	None	<b>Visibility (RVR):</b>	
<b>Wind Speed/Gusts:</b>	3 knots /	<b>Turbulence Type Forecast/Actual:</b>	/
<b>Wind Direction:</b>	150°	<b>Turbulence Severity Forecast/Actual:</b>	/
<b>Altimeter Setting:</b>	29.96 inches Hg	<b>Temperature/Dew Point:</b>	34°C / 19°C
<b>Precipitation and Obscuration:</b>	No Obscuration; No Precipitation		
<b>Departure Point:</b>	Rhome, TX (T76 )	<b>Type of Flight Plan Filed:</b>	None
<b>Destination:</b>	Rhome, TX (T76 )	<b>Type of Clearance:</b>	None
<b>Departure Time:</b>	19:35 Local	<b>Type of Airspace:</b>	Class E

### Airport Information

<b>Airport:</b>	Rhome Meadows T76	<b>Runway Surface Type:</b>	Grass/turf
<b>Airport Elevation:</b>	900 ft msl	<b>Runway Surface Condition:</b>	Dry
<b>Runway Used:</b>	13	<b>IFR Approach:</b>	None
<b>Runway Length/Width:</b>	3700 ft / 60 ft	<b>VFR Approach/Landing:</b>	None

### Wreckage and Impact Information

<b>Crew Injuries:</b>	1 Fatal	<b>Aircraft Damage:</b>	Substantial
<b>Passenger Injuries:</b>	3 Serious	<b>Aircraft Fire:</b>	None
<b>Ground Injuries:</b>	N/A	<b>Aircraft Explosion:</b>	None
<b>Total Injuries:</b>	1 Fatal, 3 Serious	<b>Latitude, Longitude:</b>	33.148056,-97.489997

The airplane came to rest inverted on a southeast heading about 350 yards north of the departure end of runway 13 (see figure 2).



**Figure 2.** Airplane inverted in a field

A postaccident examination of the accident site and wreckage revealed that the left wing leading edge was crushed aft and sustained impact damage, including evidence of tree strikes; the wing was partially separated from the fuselage and distorted aft. The right wing leading edge was crushed aft. All flight control cables were traced from their respective control surfaces to the cockpit controls with no separations or anomalies noted. The elevator trim tab was slightly nose-down but near neutral. The flaps were retracted. The right control yoke was separated at the control column, consistent with impact damage. The left control yoke was damaged consistent with impact.

There were no shoulder harnesses installed. The adult passenger reported that all occupants wore lap belts during the flight, and all four lap belts appeared to exhibit stretching in the webbing, indicative of the belts being worn during impact. The right rear lap belt was found separated from the eyelet at the floorboard. The left front seat was improperly safety-wired.

The fuel selector handle and valve were found in the OFF position; first responders reported that they moved the handle to OFF after the accident. A small amount of fuel was found in the firewall fuel



strainer. The fuel was tested for water using water-detecting paste; the test was negative. The left and right wing fuel tanks were impact damaged, but about 2 gallons of fuel were drained from the tanks during the recovery process.

Two empty beer cans were found in the front left floorboard area near the rudder pedals. A rodent's nest was found inside the left wing near an area that had been impact damaged. A significant amount of cobwebs were observed in the engine compartment. The airbox was clear of obstructions. A large mud dauber nest was found on the fins of the oil cooler. The ELT was found in place with battery acid residue on the outside of the case. An automotive battery was installed in the airplane.

The tip of the propeller spinner was bent but the rest of the spinner was mostly undamaged. The 2 propeller blades were straight and undamaged with no chordwise scratches or leading edge damage.

The gascolator fuel strainer was disassembled and organic debris similar to insect cocoons was found inside the strainer screen (see figure 3). The strainer bowl was mostly full of blue-colored fuel consistent with 100LL aviation gasoline.



### **Figure 3. Fuel fitting with organic contaminants**

The main fuel line from the gascolator to the carburetor was a hydraulic hose manufactured in July 2013 and featured a Department of Transportation marking consistent with an automotive hydraulic hose.

Engine crankshaft and camshaft continuity was confirmed by manually rotating the propeller. Thumb suction and compression was obtained for each cylinder. Normal rocker and valve movement was observed and all accessory gears rotated at the back of the engine. The exhaust system sustained damage to the heat exchanger, which was breached as a result of the accident. All of the flame cones were deteriorated and missing.

The carburetor was removed and disassembled; the float chamber contained about 5 mL of fuel. The fuel was tested for water using water-detecting paste; the test was negative. Both magnetos were secure on their respective mounts. The ignition timing was verified at 25° before top dead center on the left magneto. The left magneto was actuated by rotating the propeller by hand, it produced spark at all outlet points. The right magneto was secure on its mount. The ignition timing was verified about 30° before top dead center. The right magneto was removed from its mount and rotated using an electric drill, it produced spark at all outlet points. The top spark plugs were removed and exhibited a color consistent with normal combustion. The oil filter did not display any information regarding the last time it was changed.

### **Medical and Pathological Information**

---

Southwestern Institute of Forensic Sciences, Dallas, Texas, completed an autopsy on the pilot and determined the cause of death was "blunt force injuries." The autopsy discovered evidence of hypertensive and atherosclerotic cardiovascular disease, including cardiomegaly, left ventricular hypertrophy, a fusiform aneurysm in the right coronary artery, and moderate atherosclerosis of two other coronary arteries.

Toxicology testing performed by the FAA Forensic Sciences Laboratory identified ethanol in subclavian blood, vitreous fluid, and urine (0.154 gm/dL, 0.177 gm/dL, and 0.194 gm/dL respectively); and 0.0033 µg/mL of delta-9-tetrahydrocannabinol (THC) in the blood. THC's active metabolite, 11-hydroxy-delta-9-THC, was not detected, but the inactive metabolite, carboxy-delta-9-THC, was detected at 0.0139 µg/mL. Both THC metabolites were detected in urine; 11-hydroxy-delta-9-THC at 0.0094 µg/mL and carboxy-delta-9-THC at 0.0346 µg/mL.

Ethanol is a social drug commonly consumed by drinking beer, wine, or liquor. Ethanol acts as a central nervous system depressant; it impairs judgment, psychomotor functioning, and vigilance. Effects of ethanol on aviators are generally well understood; it significantly impairs pilots' performance, even at very low levels. Title 14 *CFR* Section 91.17 (a) prohibits any person from acting or attempting to act as a crewmember of a civil aircraft while having 0.040 gm/dL or more ethanol in the blood. Ethanol is water soluble, and after absorption it quickly and uniformly distributes throughout the body's tissues and

fluids. The distribution pattern parallels water content and blood supply of the tissue. A small amount of ethanol can be produced after death by microbial activity, usually in conjunction with other alcohols such as methanol; vitreous humor and urine do not suffer from such production. Postabsorption, vitreous humor has about 12% more ethanol than blood and urine about 25% more ethanol than blood.

THC is the primary psychoactive substance in marijuana, which is listed as a schedule I controlled substance. THC's mood-altering effects include euphoria, relaxed inhibitions, disorientation, image distortion, and psychosis. THC is stored in fatty tissues and can be released back into the blood long after consumption. While the psychoactive effects may last for a few hours, THC may be detected in the blood for days or weeks. Low THC levels of a few nanograms per milliliter in blood can result from relatively recent use (e.g., smoking within 1 to 3 hours) when some slight or even moderate impairment is likely to be present, or it can result from chronic use where no recent ingestion has occurred and no impairment is present. Thus, the level of THC in the blood and level of impairment do not appear to be closely related. See the NTSB Medical Factual Report in the public docket for additional information and references.

## Administrative Information

<b>Investigator In Charge (IIC):</b>	Lindberg, Joshua
<b>Additional Participating Persons:</b>	Robert Bennett; Federal Aviation Administration; Irving, TX John Butler; Lycoming Engines; TX Ricardo Asensio; Textron Aviation; Wichita, KS
<b>Original Publish Date:</b>	September 10, 2019
<b>Note:</b>	The NTSB traveled to the scene of this accident.
<b>Investigation Docket:</b>	<a href="https://data.nts.gov/Docket?ProjectID=98088">https://data.nts.gov/Docket?ProjectID=98088</a>

The National Transportation Safety Board (NTSB), established in 1967, is an independent federal agency mandated by Congress through the Independent Safety Board Act of 1974 to investigate transportation accidents, determine the probable causes of the accidents, issue safety recommendations, study transportation safety issues, and evaluate the safety effectiveness of government agencies involved in transportation. The NTSB makes public its actions and decisions through accident reports, safety studies, special investigation reports, safety recommendations, and statistical reviews.

The Independent Safety Board Act, as codified at 49 U.S.C. Section 1154(b), precludes the admission into evidence or use of any part of an NTSB report related to an incident or accident in a civil action for damages resulting from a matter mentioned in the report. A factual report that may be admissible under 49 U.S.C. § 1154(b) is available [here](#).