



# Aviation Investigation Final Report

<b>Location:</b>	Aguila, Arizona	<b>Accident Number:</b>	WPR18LA174
<b>Date &amp; Time:</b>	June 19, 2018, 12:00 Local	<b>Registration:</b>	N764CT
<b>Aircraft:</b>	CIRRUS DESIGN CORP SR22	<b>Aircraft Damage:</b>	Destroyed
<b>Defining Event:</b>	Powerplant sys/comp malf/fail	<b>Injuries:</b>	1 Serious, 1 Minor
<b>Flight Conducted Under:</b>	Part 91: General aviation - Personal		

## Analysis

During a cross-country flight, the pilot observed a significant increase in the engine oil pressure followed by a sudden drop. He prepared for an emergency landing during which the engine speed increased and the engine lost power. The cabin then filled with smoke and oil covered the windshield. The pilot was able to activate the airplane's parachute and the airplane landed about 5 seconds later in a ravine. The airplane was destroyed by a postcrash fire.

A postaccident examination of the engine revealed evidence of a pre-ignition/detonation event that partially eroded the Nos. 2 and 5 pistons. The eroded pistons permitted the pressurization of the crankcase, which resulted in oil starvation of the engine. Due to the severe fire damage, the cause of the preignition/detonation could not be determined.

## Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

A total loss of engine power due to pre-ignition/detonation for reasons that could not be determined based on available information.

## Findings

<b>Not determined</b>	(general) - Unknown/Not determined
<b>Aircraft</b>	Recip eng cyl section - Malfunction

# Factual Information

## History of Flight

Enroute-cruise	Powerplant sys/comp malf/fail (Defining event)
Enroute-cruise	Loss of engine power (total)
Emergency descent	Collision with terr/obj (non-CFIT)

On June 19, 2018, about 1200 mountain standard time, a Cirrus SR22, N764CT, was destroyed when it was involved in an accident near Aguila, Arizona. The pilot was seriously injured, and the passenger received minor injuries. The airplane was operated as a Title 14 *Code of Federal Regulations* Part 91 personal flight.

According to the pilot, at approximately the halfway point of his cross-country flight, the oil temperature increased past the highest limit on the oil gauge. The oil pressure then dropped to between 14 and 16 pounds per square inch (psi), and the airplane began to shudder “violently.”

The pilot turned the airplane toward the closest airport, about 40 miles away. While en route, the engine speed increased to over 5,000 rpm then dropped to almost 0 rpm. The pilot reported he was having a difficult time maintaining an altitude of 6,500 ft mean sea level and knew he would not be able to clear a nearby mountain range. As he looked for an area to make an emergency landing, the engine “completely seized.” The pilot reported the cabin then filled with smoke and oil covered the windshield. He deployed the airplane’s parachute system, and the airplane landed about 5 seconds later in a ravine. After landing, the airplane was consumed by fire.

An initial examination of the engine revealed the No. 2 connecting rod had punctured the top aft section of the crankcase. The rusted crankshaft was visible through the hole, as were the remains of the separated No. 2 connecting rod. The spark plugs were removed, and heavy erosion was observed on the electrodes; the insulators were fractured and missing significant portions. Borescope examination of the cylinders revealed signatures consistent with elevated temperatures on the pistons. The No. 5 piston was eroded around the outer circumference and there was a hole present with a portion of the top piston ring visible. Additionally, examination of the exhaust system revealed re-solidified melted metal particles, consistent with the postaccident fire.

The engine was completely disassembled for further examination. This examination revealed the Nos. 2, and 5 pistons experienced a pre-ignition/detonation event that partially eroded the pistons and resulted in oil starvation of the engine. The cause of the pre-ignition/detonation event could not be determined. Due to the severe fire damage, many of the engine components could not be tested, including the magnetos.

According to the engine maintenance records, a magneto-to-engine timing check was conducted many times, with the most recent check before the accident dated July 27, 2012; an annual inspection was performed May 9, 2018, at a total time of 1,955.4 hours with no anomalies noted. However, the required 500-hour inspection of the magnetos was not indicated in the maintenance records since their last comprehensive inspection in 2011. The magnetos had accumulated 1,284.1 hours since 2011.

### Pilot Information

<b>Certificate:</b>	Private	<b>Age:</b>	44, Male
<b>Airplane Rating(s):</b>	Single-engine land	<b>Seat Occupied:</b>	Left
<b>Other Aircraft Rating(s):</b>	None	<b>Restraint Used:</b>	4-point
<b>Instrument Rating(s):</b>	None	<b>Second Pilot Present:</b>	No
<b>Instructor Rating(s):</b>	None	<b>Toxicology Performed:</b>	No
<b>Medical Certification:</b>	Class 3 With waivers/limitations	<b>Last FAA Medical Exam:</b>	July 1, 2017
<b>Occupational Pilot:</b>	No	<b>Last Flight Review or Equivalent:</b>	May 1, 2018
<b>Flight Time:</b>	(Estimated) 0 hours (Total, all aircraft), 500 hours (Total, this make and model)		

### Passenger Information

<b>Certificate:</b>		<b>Age:</b>	Male
<b>Airplane Rating(s):</b>		<b>Seat Occupied:</b>	Right
<b>Other Aircraft Rating(s):</b>		<b>Restraint Used:</b>	4-point
<b>Instrument Rating(s):</b>		<b>Second Pilot Present:</b>	No
<b>Instructor Rating(s):</b>		<b>Toxicology Performed:</b>	
<b>Medical Certification:</b>		<b>Last FAA Medical Exam:</b>	
<b>Occupational Pilot:</b>	No	<b>Last Flight Review or Equivalent:</b>	
<b>Flight Time:</b>			

## Aircraft and Owner/Operator Information

<b>Aircraft Make:</b>	CIRRUS DESIGN CORP	<b>Registration:</b>	N764CT
<b>Model/Series:</b>	SR22 UNDESIGNAT	<b>Aircraft Category:</b>	Airplane
<b>Year of Manufacture:</b>	2008	<b>Amateur Built:</b>	
<b>Airworthiness Certificate:</b>	Normal	<b>Serial Number:</b>	2908
<b>Landing Gear Type:</b>	Tricycle	<b>Seats:</b>	
<b>Date/Type of Last Inspection:</b>	May 8, 2018 100 hour	<b>Certified Max Gross Wt.:</b>	
<b>Time Since Last Inspection:</b>	20 Hrs	<b>Engines:</b>	1 Reciprocating
<b>Airframe Total Time:</b>	1953.4 Hrs as of last inspection	<b>Engine Manufacturer:</b>	Continental Motors
<b>ELT:</b>	C126 installed, not activated	<b>Engine Model/Series:</b>	IO-550-N50B
<b>Registered Owner:</b>		<b>Rated Power:</b>	310 Horsepower
<b>Operator:</b>		<b>Operating Certificate(s) Held:</b>	None

## Meteorological Information and Flight Plan

<b>Conditions at Accident Site:</b>	Visual (VMC)	<b>Condition of Light:</b>	Day
<b>Observation Facility, Elevation:</b>	PRC,1537 ft msl	<b>Distance from Accident Site:</b>	52 Nautical Miles
<b>Observation Time:</b>	18:53 Local	<b>Direction from Accident Site:</b>	45°
<b>Lowest Cloud Condition:</b>	Clear	<b>Visibility</b>	10 miles
<b>Lowest Ceiling:</b>	None	<b>Visibility (RVR):</b>	
<b>Wind Speed/Gusts:</b>	4 knots /	<b>Turbulence Type Forecast/Actual:</b>	/ None
<b>Wind Direction:</b>	290°	<b>Turbulence Severity Forecast/Actual:</b>	/
<b>Altimeter Setting:</b>	30.11 inches Hg	<b>Temperature/Dew Point:</b>	28°C / -4°C
<b>Precipitation and Obscuration:</b>	No Obscuration; No Precipitation		
<b>Departure Point:</b>	Scottsdale, AZ (SDL )	<b>Type of Flight Plan Filed:</b>	None
<b>Destination:</b>	Lake Havasu City, AZ (HII )	<b>Type of Clearance:</b>	VFR
<b>Departure Time:</b>	10:30 Local	<b>Type of Airspace:</b>	Class E

## Wreckage and Impact Information

<b>Crew Injuries:</b>	1 Serious	<b>Aircraft Damage:</b>	Destroyed
<b>Passenger Injuries:</b>	1 Minor	<b>Aircraft Fire:</b>	On-ground
<b>Ground Injuries:</b>		<b>Aircraft Explosion:</b>	None
<b>Total Injuries:</b>	1 Serious, 1 Minor	<b>Latitude, Longitude:</b>	34.067779,-113.2061

## Administrative Information

<b>Investigator In Charge (IIC):</b>	Cornejo, Tealeye		
<b>Additional Participating Persons:</b>	Steven Meisner; Federal Aviation Administration; Scottsdale, AZ Brannon Mayer; Cirrus Aircraft ; Duluth , MN Phillip Grice; Continental Aerospace Technologies; Mobile, AL James Crupi; AmSafe ; Phoenix, AZ		
<b>Original Publish Date:</b>	April 21, 2022	<b>Investigation Class:</b>	3
<b>Note:</b>	The NTSB did not travel to the scene of this accident.		
<b>Investigation Docket:</b>	<a href="https://data.nts.gov/Docket?ProjectID=97531">https://data.nts.gov/Docket?ProjectID=97531</a>		

The National Transportation Safety Board (NTSB), established in 1967, is an independent federal agency mandated by Congress through the Independent Safety Board Act of 1974 to investigate transportation accidents, determine the probable causes of the accidents, issue safety recommendations, study transportation safety issues, and evaluate the safety effectiveness of government agencies involved in transportation. The NTSB makes public its actions and decisions through accident reports, safety studies, special investigation reports, safety recommendations, and statistical reviews.

The Independent Safety Board Act, as codified at 49 U.S.C. Section 1154(b), precludes the admission into evidence or use of any part of an NTSB report related to an incident or accident in a civil action for damages resulting from a matter mentioned in the report. A factual report that may be admissible under 49 U.S.C. § 1154(b) is available [here](#).