



AVIATION



HIGHWAY



MARINE



RAILROAD



PIPELINE

# Aviation Investigation Final Report

<b>Location:</b>	Plant City, Florida	<b>Accident Number:</b>	ERA19LA021
<b>Date &amp; Time:</b>	October 18, 2018, 14:05 Local	<b>Registration:</b>	N3631K
<b>Aircraft:</b>	Piper PA28	<b>Aircraft Damage:</b>	Substantial
<b>Defining Event:</b>	Fuel related	<b>Injuries:</b>	1 Minor
<b>Flight Conducted Under:</b>	Part 91: General aviation - Personal		

## Analysis

The pilot reported that he was practicing flight maneuvers before returning to the departure airport. As he approached the airport, he entered on the downwind leg of the traffic pattern for a touch-and-go landing. After the touch-and-go landing, while the airplane was climbing out and accelerating, the engine began to “sputtering” several times and then lost power completely. The pilot performed a forced landing to trees below and the airplane’s wings and fuselage were substantially damaged. Postaccident examination of the engine did not reveal evidence of any mechanical malfunctions or failures that would have precluded normal operation.

Based on the pilot’s description of the fuel onboard at the time he departed, and the duration of the flight, sufficient fuel should have been available when the loss of engine power occurred. The pilot also reported that at the time of the loss of engine power, the carburetor heat was off. He did not report activating it prior to or following the time the engine began losing power. The temperature and dew point at the time of the accident was conducive to the formation of carburetor icing. Given this information, it is likely that the loss of engine power was due to the formation of carburetor ice during the approach to landing and subsequent takeoff.

## Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

The pilot’s failure to utilize carburetor heat in conditions conducive to the formation of

carburetor icing, which resulted in a total loss of engine power.

## Findings

<b>Environmental issues</b>	Conducive to carburetor icing - Effect on equipment
<b>Personnel issues</b>	Decision making/judgment - Pilot

# Factual Information

## History of Flight

Initial climb	Fuel related (Defining event)
Emergency descent	Off-field or emergency landing
Landing	Collision with terr/obj (non-CFIT)

On October 18, 2018, about 1405 eastern daylight time, a Piper PA-28-140, N3631K, sustained substantial damage when it was involved in an accident near Plant City, Florida. The commercial pilot sustained minor injuries. The airplane was operated as a Title 14 *Code of Federal Regulations* Part 91 personal flight.

Before departure, the pilot conducted a preflight inspection, and no anomalies were noted. The pilot also recalled that all pre-takeoff checks were normal, and there were 6 quarts of oil in the engine. He confirmed that both fuel tanks were full, which amounted to 18 gallons in each tank. The pilot was practicing flight maneuvers that consisted of visual approaches, pattern work and landings at Plant City Airport (PCM), Plant City, Florida.

After takeoff from PCM, and about 45 minutes into the flight, the pilot switched fuel tanks from the right tank to the left tank. After finishing his flight maneuvers, he proceeded back to PCM and entered on the downwind leg of the traffic pattern for runway 10 for a touch-and-go landing. After the touch-and-go landing, while climbing out and accelerating to 85 mph, the engine “sputtered” several times. The pilot leveled off the airplane about 400 ft mean sea level and checked the engine indications and controls, with all appearing normal. The carburetor heat was off, and the pilot did not activate it before or during the loss of engine power. The engine then lost power completely. The pilot was unable to turn the airplane due to the low airspeed and performed a forced landing into the trees below. The pilot exited the airplane and waited for emergency services to arrive.

Pictures taken at the accident site showed that the airplane sustained substantial damage to the wings and fuselage. The left wing was broken away from the fuselage, and the right wing and cabin section buckled. Postaccident examination of the engine revealed that while the engine could not be test run due to damage sustained during the accident, no mechanical anomalies were discovered that would have prevented normal operation.

The weather conditions at PCM about the time of the accident included a temperature of 33° C, and a dew point of 20° C. Review of the icing probability chart contained within Federal Aviation Administration Special Airworthiness Information Bulletin CE-09-35 revealed the atmospheric conditions at the time of the accident were conducive to the formation of carburetor icing at cruise and serious icing at glide power settings.

## Pilot Information

<b>Certificate:</b>	Commercial	<b>Age:</b>	76, Male
<b>Airplane Rating(s):</b>	Single-engine land; Multi-engine land	<b>Seat Occupied:</b>	Left
<b>Other Aircraft Rating(s):</b>	None	<b>Restraint Used:</b>	Lap only
<b>Instrument Rating(s):</b>	Airplane	<b>Second Pilot Present:</b>	No
<b>Instructor Rating(s):</b>	None	<b>Toxicology Performed:</b>	No
<b>Medical Certification:</b>	Class 3 With waivers/limitations	<b>Last FAA Medical Exam:</b>	May 26, 2017
<b>Occupational Pilot:</b>	No	<b>Last Flight Review or Equivalent:</b>	June 18, 2018
<b>Flight Time:</b>	(Estimated) 4839 hours (Total, all aircraft), 538 hours (Total, this make and model), 3000 hours (Pilot In Command, all aircraft), 14 hours (Last 90 days, all aircraft), 5 hours (Last 30 days, all aircraft), 1 hours (Last 24 hours, all aircraft)		

## Aircraft and Owner/Operator Information

<b>Aircraft Make:</b>	Piper	<b>Registration:</b>	N3631K
<b>Model/Series:</b>	PA28 140	<b>Aircraft Category:</b>	Airplane
<b>Year of Manufacture:</b>	1967	<b>Amateur Built:</b>	
<b>Airworthiness Certificate:</b>	Normal	<b>Serial Number:</b>	28-23661
<b>Landing Gear Type:</b>	Tricycle	<b>Seats:</b>	4
<b>Date/Type of Last Inspection:</b>	June 15, 2018 Annual	<b>Certified Max Gross Wt.:</b>	2150 lbs
<b>Time Since Last Inspection:</b>	19 Hrs	<b>Engines:</b>	1 Reciprocating
<b>Airframe Total Time:</b>	5312 Hrs at time of accident	<b>Engine Manufacturer:</b>	Lycoming
<b>ELT:</b>	C91 installed, activated, did not aid in locating accident	<b>Engine Model/Series:</b>	320-E2A
<b>Registered Owner:</b>		<b>Rated Power:</b>	160 Horsepower
<b>Operator:</b>	On file	<b>Operating Certificate(s) Held:</b>	None

## Meteorological Information and Flight Plan

<b>Conditions at Accident Site:</b>	Visual (VMC)	<b>Condition of Light:</b>	Day
<b>Observation Facility, Elevation:</b>	KPCM,152 ft msl	<b>Distance from Accident Site:</b>	0 Nautical Miles
<b>Observation Time:</b>	18:15 Local	<b>Direction from Accident Site:</b>	0°
<b>Lowest Cloud Condition:</b>	Clear	<b>Visibility</b>	10 miles
<b>Lowest Ceiling:</b>	Broken / 4700 ft AGL	<b>Visibility (RVR):</b>	
<b>Wind Speed/Gusts:</b>	9 knots /	<b>Turbulence Type Forecast/Actual:</b>	None / None
<b>Wind Direction:</b>	60°	<b>Turbulence Severity Forecast/Actual:</b>	N/A / N/A
<b>Altimeter Setting:</b>	30.15 inches Hg	<b>Temperature/Dew Point:</b>	33°C / 20°C
<b>Precipitation and Obscuration:</b>	No Obscuration; No Precipitation		
<b>Departure Point:</b>	Plant City, FL (PCM )	<b>Type of Flight Plan Filed:</b>	None
<b>Destination:</b>	Plant City, FL (PCM )	<b>Type of Clearance:</b>	None
<b>Departure Time:</b>	13:00 Local	<b>Type of Airspace:</b>	Class E

## Airport Information

<b>Airport:</b>	Plant City PCM	<b>Runway Surface Type:</b>	Asphalt
<b>Airport Elevation:</b>	152 ft msl	<b>Runway Surface Condition:</b>	Dry
<b>Runway Used:</b>	10	<b>IFR Approach:</b>	None
<b>Runway Length/Width:</b>	3950 ft / 75 ft	<b>VFR Approach/Landing:</b>	Forced landing

## Wreckage and Impact Information

<b>Crew Injuries:</b>	1 Minor	<b>Aircraft Damage:</b>	Substantial
<b>Passenger Injuries:</b>		<b>Aircraft Fire:</b>	None
<b>Ground Injuries:</b>		<b>Aircraft Explosion:</b>	None
<b>Total Injuries:</b>	1 Minor	<b>Latitude, Longitude:</b>	28.000278,-82.16333(est)

## Preventing Similar Accidents

### Preventing Carburetor Icing

Accident involving carburetor ice stem for pilots not recognizing when weather conditions are favorable to carburetor icing and inaccurately believing that carburetor icing is only a cold- or wet-weather

problem. Pilots also may not use the carburetor heat according the aircraft's approved procedures to prevent carburetor ice formation. Carburetor icing accident can occur when pilots do not recognize and promptly act upon the signs of carburetor icing.

Be sure to check the temperature and dew point to determine whether the conditions are favorable for carburetor icing. Remember, serious carburetor icing can occur in ambient temperatures as high as 90° F or in relative humidity conditions as low as 35 percent at glide power. Consider installing a carburetor temperature gauge, if available.

Refer to the approved aircraft flight manual or operating handbook to ensure that carburetor heat is used according to the approved procedures and properly perform the following actions: 1) Check the functionality of the carburetor heat before flight. 2) Use carburetor heat to prevent the formation of carburetor ice when operating in conditions and at power settings in which carburetor icing is probable. Remember, ground idling or taxiing time can allow carburetor ice to accumulate before takeoff. 3) Immediately apply carburetor heat at the first sign of carburetor icing, which typically includes a drop in rpm or manifold pressure (depending upon how your airplane is equipped). Engine roughness may follow.

Engines that run on automobile gas may be more susceptible to carburetor icing than engines that run on Avgas.

See [http://www.nts.gov/safety/safety-alerts/documents/SA\\_029.pdf](http://www.nts.gov/safety/safety-alerts/documents/SA_029.pdf) for additional resources.

The NTSB presents this information to prevent recurrence of similar accidents. Note that this should not be considered guidance from the regulator, nor does this supersede existing FAA Regulations (FARs).

### Administrative Information

<b>Investigator In Charge (IIC):</b>	Alleyne, Eric		
<b>Additional Participating Persons:</b>	Loftis J Rollins; FAA/FSDO; Tampa, FL		
<b>Original Publish Date:</b>	August 24, 2021	<b>Investigation Class:</b>	3
<b>Note:</b>	The NTSB did not travel to the scene of this accident.		
<b>Investigation Docket:</b>	<a href="https://data.nts.gov/Docket?ProjectID=98519">https://data.nts.gov/Docket?ProjectID=98519</a>		

The National Transportation Safety Board (NTSB), established in 1967, is an independent federal agency mandated by Congress through the Independent Safety Board Act of 1974 to investigate transportation accidents, determine the probable causes of the accidents, issue safety recommendations, study transportation safety issues, and evaluate the safety effectiveness of government agencies involved in transportation. The NTSB makes public its actions and decisions through accident reports, safety studies, special investigation reports, safety recommendations, and statistical reviews.

The Independent Safety Board Act, as codified at 49 U.S.C. Section 1154(b), precludes the admission into evidence or use of any part of an NTSB report related to an incident or accident in a civil action for damages resulting from a matter mentioned in the report. A factual report that may be admissible under 49 U.S.C. § 1154(b) is available [here](#).