



Aviation Investigation Final Report

Location:	Red Rock, Arizona	Accident Number:	WPR19LA140
Date & Time:	May 5, 2019, 17:56 Local	Registration:	N8887U
Aircraft:	Cessna 172	Aircraft Damage:	Substantial
Defining Event:	Loss of engine power (partial)	Injuries:	4 None
Flight Conducted Under:	Part 91: General aviation - Personal		

Analysis

The pilot reported that, while descending in the single-engine airplane toward the destination airport, the engine lost partial power. He performed a forced landing to a dirt road, during which the airplane contacted a bush, resulting in substantial damage.

Postaccident examination of the engine and an engine test run revealed no anomalies that would have precluded normal operation. Atmospheric conditions at the time of the accident were not conducive to the development of carburetor icing. The reason for the partial loss of engine power could not be determined based on the available information.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

A partial loss of engine power for reasons that could not be determined based on the available information.

Findings

Not determined	(general) - Unknown/Not determined
----------------	------------------------------------

Factual Information

History of Flight

Enroute-descent	Loss of engine power (partial) (Defining event)
-----------------	---

On May 5, 2019, about 1756 mountain standard time, a Cessna 172F airplane, N8887U, was substantially damaged when it was involved in an accident near Red Rock, Arizona. The commercial pilot and three passengers were not injured. The airplane was operated as a Title 14 *Code of Federal Regulations* Part 91 personal flight.

The pilot reported that he canceled flight-following about 15 miles west of his destination. During the descent, the engine rpm dropped from 2,600 rpm to 1,300 rpm once or twice, then dropped to 1,000 rpm and remained there. The pilot reported that he checked the magnetos, verified that the fuel selector was on BOTH, and set the fuel mixture to full rich. The pilot performed a forced landing to a dirt road, during which the left wing clipped a bush, resulting in substantial damage. The pilot mentioned that he did not use carburetor heat, as the humidity was very low; calculated relative humidity for the area of the accident site was 27%. Additionally, the pilot reported no additional anomalies with the airplane that would have precluded normal operation.

Review of the Carburetor Icing Probability Chart indicated that conditions were not conducive to carburetor icing.

The airplane was equipped with a Continental Motors O-300-D engine, serial number 29754-D-5-0. Maintenance records revealed that about 6 days before the accident, the Nos. 2- and 3-cylinder assemblies were replaced, and the lower forward crankcase through bolt and hardware were replaced.

Examination of the engine revealed no anomalies, and the engine operated normally during a subsequent test run to about 2,280 rpm.

Pilot Information

Certificate:	Commercial	Age:	34, Male
Airplane Rating(s):	Single-engine land	Seat Occupied:	Left
Other Aircraft Rating(s):	Helicopter	Restraint Used:	3-point
Instrument Rating(s):	Helicopter	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 2 Without waivers/limitations	Last FAA Medical Exam:	December 18, 2018
Occupational Pilot:	No	Last Flight Review or Equivalent:	April 18, 2019
Flight Time:	(Estimated) 2000 hours (Total, all aircraft), 90 hours (Total, this make and model), 1260 hours (Pilot In Command, all aircraft), 75 hours (Last 90 days, all aircraft), 35 hours (Last 30 days, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	Cessna	Registration:	N8887U
Model/Series:	172 F	Aircraft Category:	Airplane
Year of Manufacture:	1965	Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	17252806
Landing Gear Type:	Tricycle	Seats:	4
Date/Type of Last Inspection:	May 4, 2018 Annual	Certified Max Gross Wt.:	2299 lbs
Time Since Last Inspection:	266 Hrs	Engines:	1 Reciprocating
Airframe Total Time:	5279 Hrs as of last inspection	Engine Manufacturer:	Continental
ELT:	Installed, not activated	Engine Model/Series:	O-300 SER
Registered Owner:		Rated Power:	145 Horsepower
Operator:	On file	Operating Certificate(s) Held:	None

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	KMZJ, 1892 ft msl	Distance from Accident Site:	13 Nautical Miles
Observation Time:	17:55 Local	Direction from Accident Site:	145°
Lowest Cloud Condition:	Clear	Visibility	10 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	10 knots /	Turbulence Type Forecast/Actual:	None / None
Wind Direction:	250°	Turbulence Severity Forecast/Actual:	N/A / N/A
Altimeter Setting:	29.7 inches Hg	Temperature/Dew Point:	32.2°C / -8.9°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	Carlsbad, CA (CRQ)	Type of Flight Plan Filed:	None
Destination:	Marana, AZ (AVQ)	Type of Clearance:	VFR flight following
Departure Time:	14:45 Local	Type of Airspace:	Class G

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:	3 None	Aircraft Fire:	None
Ground Injuries:		Aircraft Explosion:	None
Total Injuries:	4 None	Latitude, Longitude:	32.538333,-111.423614(est)

Administrative Information

Investigator In Charge (IIC):	Vanover, Jackie		
Additional Participating Persons:	Daniel W Meeker; FAA; Scottsdale, AZ		
Original Publish Date:	February 9, 2022	Investigation Class:	3
Note:	The NTSB did not travel to the scene of this accident.		
Investigation Docket:	https://data.nts.gov/Docket?ProjectID=99402		

The National Transportation Safety Board (NTSB), established in 1967, is an independent federal agency mandated by Congress through the Independent Safety Board Act of 1974 to investigate transportation accidents, determine the probable causes of the accidents, issue safety recommendations, study transportation safety issues, and evaluate the safety effectiveness of government agencies involved in transportation. The NTSB makes public its actions and decisions through accident reports, safety studies, special investigation reports, safety recommendations, and statistical reviews.

The Independent Safety Board Act, as codified at 49 U.S.C. Section 1154(b), precludes the admission into evidence or use of any part of an NTSB report related to an incident or accident in a civil action for damages resulting from a matter mentioned in the report. A factual report that may be admissible under 49 U.S.C. § 1154(b) is available [here](#).