



Aviation Investigation Final Report

| | | | |
|--------------------------------|--------------------------------------|-------------------------|-------------|
| Location: | Arecibo, Puerto Rico | Accident Number: | ERA18TA193 |
| Date & Time: | July 14, 2018, 17:40 Local | Registration: | N594TC |
| Aircraft: | Quicksilver MXL II | Aircraft Damage: | Substantial |
| Defining Event: | Fuel exhaustion | Injuries: | 1 Serious |
| Flight Conducted Under: | Part 91: General aviation - Personal | | |

Analysis

After the local flight, the noncertificated pilot approached the airport for landing. During the approach, he performed a go-around, and the airplane encountered strong winds, so he decided to turn 180° to land on the opposite runway. While turning, about 1/2 mile from the runway, the engine lost total power, so the pilot landed the airplane straight ahead into marshy terrain in a nose-low attitude. The empennage and fuselage sustained substantial damage.

Postaccident examination of the airplane revealed no evidence of any preimpact mechanical malfunctions or failures that would have precluded normal operation. The 6-gallon fuel tank was found empty, and the fuel cap was found secured to the tank. The pilot reported that the airplane departed with 5 gallons of fuel onboard for the flight, which was about 1 hour 10 minutes long, and the estimated fuel consumption for the airplane was between about 5.3 and 6 gallons per hour. It is likely that, during the go-around and maneuver to return to the airport, the fuel supply was exhausted, which resulted in a total loss of engine power.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

The noncertificated pilot's improper fuel planning and management, which resulted in a total loss of engine power due to fuel exhaustion.

Findings

| | |
|-------------------------|-------------------------------------|
| Personnel issues | Decision making/judgment - Pilot |
| Aircraft | Fuel - Fluid level |
| Aircraft | Fuel - Fluid management |
| Personnel issues | Fuel planning - Pilot |
| Personnel issues | Qualification/certification - Pilot |

Factual Information

History of Flight

| | |
|------------------------|------------------------------------|
| Approach-VFR go-around | Other weather encounter |
| Approach-VFR go-around | Fuel exhaustion (Defining event) |
| Approach-VFR go-around | Loss of engine power (total) |
| Approach-VFR go-around | Collision with terr/obj (non-CFIT) |

On July 14, 2018, about 1740 Atlantic standard time, an experimental light sport Quicksilver MXL II, N594TC, was substantially damaged when it impacted terrain during a forced landing at Antonio (Nery) Juarbe Pol Airport (ABO), Arecibo, Puerto Rico. The non-certificated pilot sustained serious injuries. The airplane was operated by the pilot as a personal flight conducted under the provisions of Title 14 *Code of Federal Regulations* Part 91. Visual meteorological conditions prevailed, and no flight plan was filed for the local flight, which departed at 1630.

According to a Federal Aviation Administration (FAA) inspector, the pilot reported that he was returning to ABO after about a one-hour local flight and approached runway 8. During the approach, he performed a go-around and subsequently encountered strong wind, and decided to turn 180° to land on runway 26. While turning, about 1/2 mile from runway 26, the engine experienced a total loss of engine power. The pilot landed straight ahead into marshy terrain in a nose low attitude. The pilot reported that he took off with 5 gallons of fuel on board.

According to a FAA inspector who examined the airplane at the accident site, the airplane sustained substantial damage to the empennage and fuselage. Flight control continuity was confirmed from the flight control surfaces to the cockpit. Engine cylinder compression and powertrain continuity were established by rotating the propeller by hand. The fuel selector was found in the off position. The fuel tank was found empty, the fuel cap remained secured, and there was no sign of fuel leakage. The fuel filter container was about 1/2 full of fuel. The ABO airport's daily aircraft activity logbook showed that the accident airplane departed at 1630 local, which resulted in a total flight time of 1 hour and 10 minutes.

According to FAA airman records, the pilot was issued a third class medical and student pilot certificate in December 2011, which expired in December 2013. There was no record found that the pilot held an airman certificate.

According to Title 14 Code of Federal Regulations Part 61, the pilot was required to hold at least a student pilot certificate, with appropriate solo endorsements, to operate the airplane.

According to FAA airworthiness records, the two-seat, single-engine, high-wing airplane was manufactured in 1995. It was equipped with a Rotax 503 DI/SC engine. The airplane had a total fuel capacity of 6-gallons. The Rotax 503 engine data sheet stated that the fuel consumption was about 5.3 to 6 gallons per hour.

The weather conditions reported at 1750 at Rafael Hernandez Airport (BQN), Aguadilla, Puerto Rico, 27 miles from the accident site, included wind from 090° at 16 knots, gusting to 23 knots, visibility 10 statute miles, broken clouds at 1,800 ft, temperature 28°C, and dew point 23°C.

Student pilot Information

| | | | |
|----------------------------------|-----------|--|------------------|
| Certificate: | None | Age: | 74,Male |
| Airplane Rating(s): | None | Seat Occupied: | Left |
| Other Aircraft Rating(s): | None | Restraint Used: | Unknown |
| Instrument Rating(s): | None | Second Pilot Present: | No |
| Instructor Rating(s): | None | Toxicology Performed: | No |
| Medical Certification: | None None | Last FAA Medical Exam: | December 7, 2011 |
| Occupational Pilot: | No | Last Flight Review or Equivalent: | |
| Flight Time: | | | |

Aircraft and Owner/Operator Information

| | | | |
|--------------------------------------|------------------------------------|---------------------------------------|-----------------|
| Aircraft Make: | Quicksilver | Registration: | N594TC |
| Model/Series: | MXL II | Aircraft Category: | Airplane |
| Year of Manufacture: | 1995 | Amateur Built: | |
| Airworthiness Certificate: | Experimental light sport (Special) | Serial Number: | 5690 |
| Landing Gear Type: | Tricycle | Seats: | 2 |
| Date/Type of Last Inspection: | Unknown | Certified Max Gross Wt.: | 720 lbs |
| Time Since Last Inspection: | | Engines: | 1 Reciprocating |
| Airframe Total Time: | 320.1 Hrs at time of accident | Engine Manufacturer: | Rotax |
| ELT: | Not installed | Engine Model/Series: | 503 |
| Registered Owner: | | Rated Power: | 100 |
| Operator: | On file | Operating Certificate(s) Held: | None |

Meteorological Information and Flight Plan

| | | | |
|---|----------------------------------|---|-------------------|
| Conditions at Accident Site: | Visual (VMC) | Condition of Light: | Day |
| Observation Facility, Elevation: | BQN,8 ft msl | Distance from Accident Site: | 27 Nautical Miles |
| Observation Time: | 17:50 Local | Direction from Accident Site: | 270° |
| Lowest Cloud Condition: | | Visibility | 10 miles |
| Lowest Ceiling: | Broken / 1800 ft AGL | Visibility (RVR): | |
| Wind Speed/Gusts: | 16 knots / 23 knots | Turbulence Type Forecast/Actual: | None / None |
| Wind Direction: | 90° | Turbulence Severity Forecast/Actual: | N/A / N/A |
| Altimeter Setting: | 30.04 inches Hg | Temperature/Dew Point: | 28°C / 23°C |
| Precipitation and Obscuration: | No Obscuration; No Precipitation | | |
| Departure Point: | Arecibo, PR (ABO) | Type of Flight Plan Filed: | None |
| Destination: | Arecibo, PR (ABO) | Type of Clearance: | None |
| Departure Time: | | Type of Airspace: | Class G |

Airport Information

| | | | |
|-----------------------------|-----------------------------|----------------------------------|--------------------------------|
| Airport: | Antonio/Nery/Juarbe Pol ABO | Runway Surface Type: | Asphalt |
| Airport Elevation: | 20 ft msl | Runway Surface Condition: | Vegetation |
| Runway Used: | 26 | IFR Approach: | None |
| Runway Length/Width: | 3963 ft / 60 ft | VFR Approach/Landing: | Forced landing;Traffic pattern |

Wreckage and Impact Information

| | | | |
|----------------------------|-----------|-----------------------------|---------------------------|
| Crew Injuries: | 1 Serious | Aircraft Damage: | Substantial |
| Passenger Injuries: | | Aircraft Fire: | None |
| Ground Injuries: | N/A | Aircraft Explosion: | None |
| Total Injuries: | 1 Serious | Latitude, Longitude: | 18.455278,-66.663055(est) |

Administrative Information

| | |
|--|---|
| Investigator In Charge (IIC): | Gerhardt, Adam |
| Additional Participating Persons: | Luis Nunez; FAA/FSDO; San Juan, PR |
| Original Publish Date: | April 30, 2019 |
| Note: | The NTSB did not travel to the scene of this accident. |
| Investigation Docket: | https://data.nts.gov/Docket?ProjectID=97798 |

The National Transportation Safety Board (NTSB), established in 1967, is an independent federal agency mandated by Congress through the Independent Safety Board Act of 1974 to investigate transportation accidents, determine the probable causes of the accidents, issue safety recommendations, study transportation safety issues, and evaluate the safety effectiveness of government agencies involved in transportation. The NTSB makes public its actions and decisions through accident reports, safety studies, special investigation reports, safety recommendations, and statistical reviews.

The Independent Safety Board Act, as codified at 49 U.S.C. Section 1154(b), precludes the admission into evidence or use of any part of an NTSB report related to an incident or accident in a civil action for damages resulting from a matter mentioned in the report. A factual report that may be admissible under 49 U.S.C. § 1154(b) is available [here](#).