



AVIATION



HIGHWAY



MARINE



RAILROAD



PIPELINE

# Aviation Investigation Final Report

<b>Location:</b>	Whitewater, Kansas	<b>Accident Number:</b>	CEN18LA342
<b>Date &amp; Time:</b>	August 17, 2018, 18:15 Local	<b>Registration:</b>	N9076R
<b>Aircraft:</b>	Cessna A188	<b>Aircraft Damage:</b>	Substantial
<b>Defining Event:</b>	Powerplant sys/comp malf/fail	<b>Injuries:</b>	1 None
<b>Flight Conducted Under:</b>	Part 137: Agricultural		

## Analysis

The pilot was performing an aerial application flight with the airplane loaded with product near its maximum gross weight. As the pilot pulled up to reverse course after the second application pass, the airplane did not fly as expected. Because of his low altitude, he conducted a forced landing in the cornfield. The airplane came to rest upright and sustained substantial damage to left wing, vertical stabilizer, horizontal stabilizers, elevators, and rudder.

A postaccident examination of the engine revealed that one of the cylinders had low compression. This would have resulted in a partial loss of engine power. It is likely the airplane was at a low energy state during the pull-up maneuver to reverse direction, and the partial engine power loss would have further reduced the airplane's energy. These issues, combined with the airplane's high gross weight, would have made sustained flight difficult.

## Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

The partial loss of engine power due to low cylinder compression, which led to the forced landing following a pull-up maneuver. Contributing to the accident was the airplane's high gross weight.

## Findings

<b>Aircraft</b>	Recip eng cyl section - Damaged/degraded
<b>Aircraft</b>	(general) - Attain/maintain not possible

## Factual Information

### History of Flight

<b>Maneuvering-low-alt flying</b>	Powerplant sys/comp malf/fail (Defining event)
<b>Maneuvering-low-alt flying</b>	Loss of engine power (partial)
<b>Landing</b>	Off-field or emergency landing

*\*\*\*This report was modified on July 2, 2020. Please see the docket for this accident to view the original report.\*\*\**

On August 17, 2018, about 1815 central daylight time, a Cessna A188 airplane, N9076R, was substantially damaged when it was involved in an accident near Whitewater, Kansas. The pilot was not injured. The airplane was operated under Title 14 *Code of Federal Regulations* Part 137 as an aerial application flight.

According to the pilot, the airplane departed on an aerial application flight from a nearby airport at 1800. The airplane was loaded with applicant bringing it near it's maximum gross weight. The flight was normal until the second application pass, As the pilot pulled up to reverse course, the airplane did not fly as expected. Due to the low altitude, the pilot attempted to dump the applicant and conducted a forced landing in the cornfield. The pilot was able to flare the airplane prior to impacting in the cornfield. The airplane came to rest upright and sustained substantial damage to left wing, vertical stabilizer, horizontal stabilizers, elevators, and rudder.

Federal Aviation Administration inspectors performed a limited examination when the airplane was removed from the cornfield and could not find any preimpact anomalies with the airframe and engine. Once recovered to a maintenance facility it was discovered that one of the engine cylinders could only hold 10 psi of pressure.

## Pilot Information

<b>Certificate:</b>	Commercial; Private	<b>Age:</b>	21,Male
<b>Airplane Rating(s):</b>	Single-engine land; Multi-engine land	<b>Seat Occupied:</b>	Single
<b>Other Aircraft Rating(s):</b>	None	<b>Restraint Used:</b>	
<b>Instrument Rating(s):</b>	Airplane	<b>Second Pilot Present:</b>	No
<b>Instructor Rating(s):</b>	None	<b>Toxicology Performed:</b>	No
<b>Medical Certification:</b>	Class 2 Without waivers/limitations	<b>Last FAA Medical Exam:</b>	February 14, 2018
<b>Occupational Pilot:</b>	Yes	<b>Last Flight Review or Equivalent:</b>	
<b>Flight Time:</b>	(Estimated)		

## Aircraft and Owner/Operator Information

<b>Aircraft Make:</b>	Cessna	<b>Registration:</b>	N9076R
<b>Model/Series:</b>	A188 B	<b>Aircraft Category:</b>	Airplane
<b>Year of Manufacture:</b>	1975	<b>Amateur Built:</b>	
<b>Airworthiness Certificate:</b>	Restricted (Special)	<b>Serial Number:</b>	18802101T
<b>Landing Gear Type:</b>	Tailwheel	<b>Seats:</b>	
<b>Date/Type of Last Inspection:</b>	Unknown	<b>Certified Max Gross Wt.:</b>	
<b>Time Since Last Inspection:</b>		<b>Engines:</b>	
<b>Airframe Total Time:</b>		<b>Engine Manufacturer:</b>	
<b>ELT:</b>		<b>Engine Model/Series:</b>	
<b>Registered Owner:</b>		<b>Rated Power:</b>	
<b>Operator:</b>		<b>Operating Certificate(s) Held:</b>	Agricultural aircraft (137)
<b>Operator Does Business As:</b>	TRI-ROTOR SPRAY AND CHEMICAL INC	<b>Operator Designator Code:</b>	72TG

## Meteorological Information and Flight Plan

<b>Conditions at Accident Site:</b>	Visual (VMC)	<b>Condition of Light:</b>	Day
<b>Observation Facility, Elevation:</b>	KEWK, 1532 ft msl	<b>Distance from Accident Site:</b>	9 Nautical Miles
<b>Observation Time:</b>	17:56 Local	<b>Direction from Accident Site:</b>	299°
<b>Lowest Cloud Condition:</b>		<b>Visibility</b>	9 miles
<b>Lowest Ceiling:</b>	Broken / 4500 ft AGL	<b>Visibility (RVR):</b>	
<b>Wind Speed/Gusts:</b>	6 knots /	<b>Turbulence Type Forecast/Actual:</b>	/
<b>Wind Direction:</b>	50°	<b>Turbulence Severity Forecast/Actual:</b>	/
<b>Altimeter Setting:</b>	30.06 inches Hg	<b>Temperature/Dew Point:</b>	28°C / 19°C
<b>Precipitation and Obscuration:</b>	No Obscuration; No Precipitation		
<b>Departure Point:</b>	Newton, KS (KEWK)	<b>Type of Flight Plan Filed:</b>	None
<b>Destination:</b>	Newton, KS (KEWK)	<b>Type of Clearance:</b>	None
<b>Departure Time:</b>	18:00 Local	<b>Type of Airspace:</b>	Class E

## Wreckage and Impact Information

<b>Crew Injuries:</b>	1 None	<b>Aircraft Damage:</b>	Substantial
<b>Passenger Injuries:</b>		<b>Aircraft Fire:</b>	None
<b>Ground Injuries:</b>	N/A	<b>Aircraft Explosion:</b>	None
<b>Total Injuries:</b>	1 None	<b>Latitude, Longitude:</b>	37.999168,-97.11528(est)

## Administrative Information

<b>Investigator In Charge (IIC):</b>	Aguilera, Jason
<b>Additional Participating Persons:</b>	Michael LeBlanc; FAA FSDO; Wichita, KS
<b>Original Publish Date:</b>	August 3, 2020
<b>Note:</b>	The NTSB did not travel to the scene of this accident.
<b>Investigation Docket:</b>	<a href="https://data.nts.gov/Docket?ProjectID=98108">https://data.nts.gov/Docket?ProjectID=98108</a>

The National Transportation Safety Board (NTSB), established in 1967, is an independent federal agency mandated by Congress through the Independent Safety Board Act of 1974 to investigate transportation accidents, determine the probable causes of the accidents, issue safety recommendations, study transportation safety issues, and evaluate the safety effectiveness of government agencies involved in transportation. The NTSB makes public its actions and decisions through accident reports, safety studies, special investigation reports, safety recommendations, and statistical reviews.

The Independent Safety Board Act, as codified at 49 U.S.C. Section 1154(b), precludes the admission into evidence or use of any part of an NTSB report related to an incident or accident in a civil action for damages resulting from a matter mentioned in the report. A factual report that may be admissible under 49 U.S.C. § 1154(b) is available [here](#).