



AVIATION



HIGHWAY



MARINE



RAILROAD



PIPELINE

# Aviation Investigation Final Report

<b>Location:</b>	Boulder, Utah	<b>Accident Number:</b>	WPR18LA136
<b>Date &amp; Time:</b>	April 28, 2018, 17:15 Local	<b>Registration:</b>	N3377U
<b>Aircraft:</b>	Cessna 182F	<b>Aircraft Damage:</b>	Substantial
<b>Defining Event:</b>	Loss of engine power (partial)	<b>Injuries:</b>	1 Minor, 2 None
<b>Flight Conducted Under:</b>	Part 91: General aviation - Personal		

## Analysis

Following a cross-country flight, the pilot was circling in the area of the destination airport when he noticed an excessively high exhaust gas temperature (EGT) indication. He enriched the fuel/air mixture to full rich and leveled the airplane in an attempt to "cool down" the engine, then noted that the airplane would not maintain altitude and that engine power was decreasing. The pilot performed a forced landing to a field, during which the airplane impacted two ditches, resulting in substantial damage.

Examination of the airframe and the engine failed to reveal any mechanical anomalies that would have precluded normal operation and the reason for the decreased engine power could not be determined. The calculated density altitude at the time of the accident was 8,814 ft.

## Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

A partial loss of engine power for reasons that could not be determined due to the available evidence.

## Findings

<b>Not determined</b>	(general) - Unknown/Not determined
<b>Aircraft</b>	(general) - Unknown/Not determined

# Factual Information

## History of Flight

<b>Maneuvering-low-alt flying</b>	Loss of engine power (partial) (Defining event)
<b>Landing</b>	Off-field or emergency landing
<b>Landing-landing roll</b>	Collision with terr/obj (non-CFIT)

On April 28, 2018, about 1715 mountain daylight time, a Cessna 182F, N3377U, was substantially damaged when it was involved in an accident near Boulder, Utah. The private pilot sustained a minor injury, while his two passengers were not injured. The airplane was operated as a Title 14 *Code of Federal Regulations* Part 91 personal flight.

The pilot departed on a 172-nautical (nm) mile cross-country flight. Upon arriving in the area of the destination, they were circling over the town when the pilot observed a high exhaust gas temperature (EGT) indication. He stated that, at this time he enriched the fuel mixture setting to full rich, leveled off to cool the engine down, and immediately began looking for a possible emergency landing site. When he realized that the airplane could not maintain altitude, as engine power was decreasing, he chose a grassy field for a forced landing. During the landing roll, the airplane collided with a ditch, which separated the nose landing gear. The pilot reported that he then applied the brakes, but collided with a second ditch, which brought the airplane to a stop partially on its nose at about a 20° tail-high angle. The airplane came to rest on a magnetic heading of about 111° at an elevation of 6,627 ft mean sea level (msl), and sustained substantial damage to its firewall and engine mounts.

The airplane was examined after recovery from the site. Both wings had been separated from the fuselage for purposes of recovery. All four engine mounts were broken, and the engine was pushed aft.

The lower cowl, lower exhaust tubing, and cowl flap were impact damaged. The position of the cowl flap could not be determined. The propeller governor control and the carburetor heat cables were impact damaged and could not be functionally tested. The oil cooler coils were unremarkable.

Electrical continuity of the cylinder head temperature/exhaust gas temperature/outside air temperature gauges was confirmed. The mixture control cable and the throttle cable remained connected and moved freely and correctly. The fuel selector valve was free to rotate when activated by hand; each detent was defined.

The upper spark plugs and valve covers were removed. The engine was rotated at the propeller flange, with no binding noted through the valve train to the accessory section. Valve movement was noted on all cylinders, and thumb compression was detected on all cylinders. Spark was noted on the upper p-leads.

The upper spark plugs exhibited signatures consistent with a lean mixture and worn-out condition when compared to a Champion Spark Plug Check-a-Plug chart. The lower spark plugs were also removed and exhibited signatures consistent with normal to worn-out condition.

Examination revealed no evidence of anomalies that would have precluded normal operation.

The 1653 weather observation at Bryce Canyon Airport (BCE), Bryce Canyon, Utah, located about 60 nm west of the accident site, reported temperature 21°C, dew point 13°C, and an altimeter setting of 29.95 inches of mercury. Based on these conditions, the computed density altitude at the time of the accident was 8,814 ft msl.

## Pilot Information

<b>Certificate:</b>	Private	<b>Age:</b>	64, Male
<b>Airplane Rating(s):</b>	Single-engine land	<b>Seat Occupied:</b>	Left
<b>Other Aircraft Rating(s):</b>	None	<b>Restraint Used:</b>	3-point
<b>Instrument Rating(s):</b>	Airplane	<b>Second Pilot Present:</b>	No
<b>Instructor Rating(s):</b>	None	<b>Toxicology Performed:</b>	No
<b>Medical Certification:</b>	Class 3 Unknown	<b>Last FAA Medical Exam:</b>	February 11, 2011
<b>Occupational Pilot:</b>	No	<b>Last Flight Review or Equivalent:</b>	
<b>Flight Time:</b>	1454 hours (Total, all aircraft), 694 hours (Total, this make and model), 1318 hours (Pilot In Command, all aircraft), 6 hours (Last 90 days, all aircraft), 3 hours (Last 30 days, all aircraft), 2 hours (Last 24 hours, all aircraft)		

## Aircraft and Owner/Operator Information

<b>Aircraft Make:</b>	Cessna	<b>Registration:</b>	N3377U
<b>Model/Series:</b>	182F F	<b>Aircraft Category:</b>	Airplane
<b>Year of Manufacture:</b>	1963	<b>Amateur Built:</b>	
<b>Airworthiness Certificate:</b>	Normal	<b>Serial Number:</b>	18254777
<b>Landing Gear Type:</b>	Tricycle	<b>Seats:</b>	4
<b>Date/Type of Last Inspection:</b>	August 1, 2015 Annual	<b>Certified Max Gross Wt.:</b>	2800 lbs
<b>Time Since Last Inspection:</b>	12.3 Hrs	<b>Engines:</b>	1 Reciprocating
<b>Airframe Total Time:</b>	2497.7 Hrs at time of accident	<b>Engine Manufacturer:</b>	CONT MOTOR
<b>ELT:</b>	Installed, not activated	<b>Engine Model/Series:</b>	O-470 SERIES
<b>Registered Owner:</b>		<b>Rated Power:</b>	0 Horsepower
<b>Operator:</b>	On file	<b>Operating Certificate(s) Held:</b>	None

## Meteorological Information and Flight Plan

<b>Conditions at Accident Site:</b>	Visual (VMC)	<b>Condition of Light:</b>	Day
<b>Observation Facility, Elevation:</b>	BCE, 7590 ft msl	<b>Distance from Accident Site:</b>	37 Nautical Miles
<b>Observation Time:</b>	16:53 Local	<b>Direction from Accident Site:</b>	250°
<b>Lowest Cloud Condition:</b>	Clear	<b>Visibility</b>	10 miles
<b>Lowest Ceiling:</b>	None	<b>Visibility (RVR):</b>	
<b>Wind Speed/Gusts:</b>	25 knots / 33 knots	<b>Turbulence Type Forecast/Actual:</b>	None / None
<b>Wind Direction:</b>	240°	<b>Turbulence Severity Forecast/Actual:</b>	N/A / N/A
<b>Altimeter Setting:</b>	29.95 inches Hg	<b>Temperature/Dew Point:</b>	21°C / 13°C
<b>Precipitation and Obscuration:</b>	No Obscuration; No Precipitation		
<b>Departure Point:</b>	Salt Lake City, UT (SLC )	<b>Type of Flight Plan Filed:</b>	None
<b>Destination:</b>	Boulder, UT	<b>Type of Clearance:</b>	None
<b>Departure Time:</b>	15:30 Local	<b>Type of Airspace:</b>	Class G

## Wreckage and Impact Information

<b>Crew Injuries:</b>	1 Minor	<b>Aircraft Damage:</b>	Substantial
<b>Passenger Injuries:</b>	2 None	<b>Aircraft Fire:</b>	None
<b>Ground Injuries:</b>		<b>Aircraft Explosion:</b>	None
<b>Total Injuries:</b>	1 Minor, 2 None	<b>Latitude, Longitude:</b>	37.904722,-111.41833(est)

## Administrative Information

<b>Investigator In Charge (IIC):</b>	Little, Thomas		
<b>Additional Participating Persons:</b>	Rhaundale Hinsen; Federal Aviation Administration; Salt Lake City, UT		
<b>Original Publish Date:</b>	May 27, 2021	<b>Investigation Class:</b>	3
<b>Note:</b>	The NTSB did not travel to the scene of this accident.		
<b>Investigation Docket:</b>	<a href="https://data.nts.gov/Docket?ProjectID=97194">https://data.nts.gov/Docket?ProjectID=97194</a>		

The National Transportation Safety Board (NTSB), established in 1967, is an independent federal agency mandated by Congress through the Independent Safety Board Act of 1974 to investigate transportation accidents, determine the probable causes of the accidents, issue safety recommendations, study transportation safety issues, and evaluate the safety effectiveness of government agencies involved in transportation. The NTSB makes public its actions and decisions through accident reports, safety studies, special investigation reports, safety recommendations, and statistical reviews.

The Independent Safety Board Act, as codified at 49 U.S.C. Section 1154(b), precludes the admission into evidence or use of any part of an NTSB report related to an incident or accident in a civil action for damages resulting from a matter mentioned in the report. A factual report that may be admissible under 49 U.S.C. § 1154(b) is available [here](#).