



AVIATION



HIGHWAY



MARINE



RAILROAD



PIPELINE

Aviation Investigation Final Report

Location:	Spring, Texas	Accident Number:	CEN19LA113
Date & Time:	March 28, 2019, 15:45 Local	Registration:	N494JB
Aircraft:	Cessna 172	Aircraft Damage:	Substantial
Defining Event:	Loss of control on ground	Injuries:	2 None
Flight Conducted Under:	Part 91: General aviation - Personal		

Analysis

The pilot was taxiing the airplane to the runway to depart on a personal flight when the airplane veered to the right and the right main landing gear descended into a drainage ditch. The pilot and the passenger were not injured. The right horizontal stabilizer and elevator were substantially damaged.

In a postaccident statement, the pilot reported no anomalies with the wheel brake system before she began taxiing the airplane. She also reported that the tailwind during taxi caused a high groundspeed but that the airplane was “uncontrollable” via the rudder and brakes.

The airplane’s pilot operating handbook states that the groundspeed and use of brakes should be held to a minimum while taxiing, directional control should be maintained with the steerable nosewheel and the rudder, and the proper positioning of the ailerons and elevator for wind direction is required to maintain directional control and balance. Additionally, according to the FAA’s *Airplane Flying Handbook*, a pilot must maintain a safe taxiing speed to ensure directional control and must have the ability to recognize any potential hazards in time to avoid them and to stop or turn where and when desired without undue reliance on the wheel brakes.

Postaccident examination and testing revealed no anomalies with the airplane’s wheel brake system or the steerable nosewheel. The wind at the airport about the time of the accident was from 140° at 13 knots gusting to 21 knots. Thus, the pilot likely allowed the airplane to accelerate to an unsafe groundspeed during taxi, resulting in a loss of directional control.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

The pilot's failure to maintain airplane directional control while taxiing at an unsafe ground speed.

Findings

Aircraft	Surface speed/braking - Incorrect use/operation
Personnel issues	Aircraft control - Pilot

Factual Information

History of Flight

Taxi-to runway	Loss of control on ground (Defining event)
Taxi-to runway	Collision with terr/obj (non-CFIT)

On March 28, 2019, about 1545 central daylight time, a Cessna 172S airplane, N494JB, was substantially damaged when it was involved in an accident at David Wayne Hooks Memorial Airport (DWH), Spring, Texas. The private pilot and passenger were not injured. The airplane was operated as a Title 14 *Code of Federal Regulations* Part 91 personal flight.

The pilot reported that her taxi clearance to runway 17L was via taxiways Juliet and Kilo. The pilot completed an uneventful right turn from the ramp to join the north/south taxiway Mike, but the airplane did not respond to her left rudder pedal input to turn left to join taxiway Juliet. The pilot then attempted to steer the airplane by applying the left brake, but the airplane still did not respond. She reduced engine power to idle and depressed both brake pedals to stop the airplane, but the airplane continued north toward taxiway November. The airplane’s right main landing gear then departed the pavement and descended into a drainage ditch. The airplane came to rest in the grass alongside the ditch.

In a postaccident statement, the pilot reported that the brakes “worked normally” before starting to taxi the airplane from the ramp. The pilot stated that a “strong” tailwind resulted in a high groundspeed during taxi but that the airplane was “uncontrollable” via the rudder and brakes. Additionally, she stated that her passenger (who she noted was a pilot) had also been unable to apply wheel brakes while she was having a problem maintaining airplane directional control.

The airplane was examined by Federal Aviation Administration (FAA) inspectors from the Houston, Texas, flight standards district office. The right horizontal stabilizer and elevator were substantially damaged. A visual examination of the brake assemblies revealed no anomalies, and a functional check of the brake system confirmed its proper operation. No fluid leaks were observed in the brake system, and both brake master cylinders contained an adequate amount of hydraulic fluid for normal operation. A functional check of the nosewheel confirmed proper rotation with the corresponding rudder pedal input.

Additional Information

The Cessna 172S *Pilot Operating Handbook* states that effective ground control while taxiing is accomplished through nosewheel steering by using the rudder pedals. The handbook notes that the ground speed and use of brakes should be “held to a minimum” and that the proper positioning of the ailerons and elevator for wind direction is required to maintain directional control and balance. Additionally, the handbook notes that strong quartering tailwinds require

caution while taxiing, sudden applications of engine throttle and sharp braking should be avoided with a tailwind, and directional control should be maintained with the steerable nosewheel and the rudder.

According to the FAA *Airplane Flying Handbook* (FAA-H-8083-3C, a pilot must maintain a safe taxiing speed to ensure directional control and that safe taxiing involves the pilot's ability to recognize any potential hazards in time to avoid them and to stop or turn where and when desired without undue reliance on the wheel brakes. The handbook recommends that the taxi speed be slow enough so that the airplane can be stopped promptly when the engine throttle is closed.

Pilot Information

Certificate:	Private	Age:	22,Female
Airplane Rating(s):	Single-engine land	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	3-point
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 3 With waivers/limitations	Last FAA Medical Exam:	June 5, 2018
Occupational Pilot:	No	Last Flight Review or Equivalent:	December 21, 2018
Flight Time:	197.6 hours (Total, all aircraft), 83.5 hours (Total, this make and model), 89.2 hours (Pilot In Command, all aircraft), 73.7 hours (Last 90 days, all aircraft), 34.1 hours (Last 30 days, all aircraft), 1.4 hours (Last 24 hours, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	Cessna	Registration:	N494JB
Model/Series:	172 S	Aircraft Category:	Airplane
Year of Manufacture:	2002	Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	172S9099
Landing Gear Type:	Tricycle	Seats:	4
Date/Type of Last Inspection:	February 20, 2019 100 hour	Certified Max Gross Wt.:	2550 lbs
Time Since Last Inspection:	94.5 Hrs	Engines:	1 Reciprocating
Airframe Total Time:	8427.6 Hrs at time of accident	Engine Manufacturer:	Lycoming
ELT:	Installed, not activated	Engine Model/Series:	IO-360-L2A
Registered Owner:		Rated Power:	180 Horsepower
Operator:		Operating Certificate(s) Held:	Pilot school (141)

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	DWH, 152 ft msl	Distance from Accident Site:	0 Nautical Miles
Observation Time:	15:53 Local	Direction from Accident Site:	
Lowest Cloud Condition:	Few / 4700 ft AGL	Visibility	10 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	13 knots / 21 knots	Turbulence Type Forecast/Actual:	None / None
Wind Direction:	140°	Turbulence Severity Forecast/Actual:	N/A / N/A
Altimeter Setting:	30.12 inches Hg	Temperature/Dew Point:	24°C / 13°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	Spring, TX (DWH)	Type of Flight Plan Filed:	None
Destination:	Austin, TX (AUS)	Type of Clearance:	VFR flight following
Departure Time:	15:45 Local	Type of Airspace:	Class D

Airport Information

Airport:	David Wayne Hooks Memorial DWH	Runway Surface Type:	
Airport Elevation:	153 ft msl	Runway Surface Condition:	Dry
Runway Used:		IFR Approach:	None
Runway Length/Width:		VFR Approach/Landing:	None

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:	1 None	Aircraft Fire:	None
Ground Injuries:		Aircraft Explosion:	None
Total Injuries:	2 None	Latitude, Longitude:	30.061666,-95.55278(est)

Administrative Information

Investigator In Charge (IIC):	Fox, Andrew	
Additional Participating Persons:	Rick Bolton; Federal Aviation Administration - Houston FSDO; Houston, TX Daniel Prince; Federal Aviation Administration - Houston FSDO; Houston, TX	
Original Publish Date:	March 3, 2022	Investigation Class: 3
Note:	The NTSB did not travel to the scene of this accident.	
Investigation Docket:	https://data.nts.gov/Docket?ProjectID=99203	

The National Transportation Safety Board (NTSB), established in 1967, is an independent federal agency mandated by Congress through the Independent Safety Board Act of 1974 to investigate transportation accidents, determine the probable causes of the accidents, issue safety recommendations, study transportation safety issues, and evaluate the safety effectiveness of government agencies involved in transportation. The NTSB makes public its actions and decisions through accident reports, safety studies, special investigation reports, safety recommendations, and statistical reviews.

The Independent Safety Board Act, as codified at 49 U.S.C. Section 1154(b), precludes the admission into evidence or use of any part of an NTSB report related to an incident or accident in a civil action for damages resulting from a matter mentioned in the report. A factual report that may be admissible under 49 U.S.C. § 1154(b) is available [here](#).