

```

#include <p18f4550.h> // Include Controller specific .h

void myMsDelay (unsigned int time) // Definition of delay subroutine
{
    unsigned int i, j;
    for (i = 0; i < time; i++) // Loop for itime
        for (j = 0; j < 710; j++); // Calibrated for a 1 ms delay in MPLAB
}

void main()
{
    TRISCbits.TRISC2 = 0; // CCP1 pin (PWM output) as output
    TRISD = 0; // Configure PORTD (RD5 and RD6 for direction control)
    as output
    PR2 = 0xBA; // Set PR2 value for 4 kHz PWM frequency (calculated
    based on the system clock)

    CCP1CON = 0x0C; // Configure CCP1 for PWM mode
    T2CON = 0x07; // Configure Timer2 (prescaler 1:16, internal clock)

    // Initial motor direction (clockwise)
    PORTDbits.RD5 = 1; // RD5 high for clockwise direction
    PORTDbits.RD6 = 0; // RD6 low for clockwise direction

    while(1) // Endless Loop
    {
        // Set Duty Cycle to 50% (for 4 kHz frequency, 50% duty cycle corresponds
        to CCPR1L = 0x80)
        CCPR1L = 0x80; // Set 50% duty cycle (0x80 is 50% of 0xFF)

        // Enable PWM
        T2CONbits.TMR2ON = 1; // Start Timer2 for PWM generation

        myMsDelay(2000); // Wait for 2 seconds (adjust delay as needed)

        // Change direction to anticlockwise (RD5 low, RD6 high)
        PORTDbits.RD5 = 0; // RD5 low for anticlockwise direction
        PORTDbits.RD6 = 1; // RD6 high for anticlockwise direction

        myMsDelay(2000); // Wait for 2 seconds

        // Change direction to clockwise (RD5 high, RD6 low)
        PORTDbits.RD5 = 1; // RD5 high for clockwise direction
        PORTDbits.RD6 = 0; // RD6 low for clockwise direction

        myMsDelay(2000); // Wait for 2 seconds

        // You can modify the duty cycle and test different speeds here
        // Example: Set Duty Cycle to 80% (0xC0 for 80% duty cycle)
        CCPR1L = 0xC0; // Set 80% duty cycle

        myMsDelay(2000); // Wait for 2 seconds
    }
}

```