

CNC MACHINES AND AUTOMATION




AMIT JANGRA

Lecturer

Mechanical Engineering Department

GP HISAR



Chapter 5

(Problems in CNC machines)

Classification of CNC machine faults

```
graph TD; A[Classification of CNC machine faults] --> B[According to elements]; A --> C[According to phenomenon]; A --> D[According to nature]; A --> E[According to characteristics]; B --> B1[Mechanical]; B --> B2[Electrical]; C --> C1[Reproducibility]; C --> C2[Random failure]; D --> D1[Recoverable fault]; D --> D2[Unrecoverable fault]; E --> E1[No failure alarm]; E --> E2[Failure alarm];
```

According to
elements

Mechanical

Electrical

According to
phenomenon

Reproducibility

Random failure

According to
nature

Recoverable
fault

Unrecoverable
fault

According to
characteristics

No failure
alarm

Failure alarm

Common Problems in Mechanical Components


- i) Bed
- ii) Tail stock and Head stock
- iii) Slideways Tool Pallettes
- iv) Mechanical Switches
- v) Host part

Common Problems in Electrical Components

- i) Switching Devices
- ii) Solenoids
- iii) Drive System

Common Problems in Pneumatic Components

- i) Cylinder
- ii) Piston and Piston rings
- iii) Valves



Common Problems in Electronic Components

- i) Display Screen/Monitor
- ii) Tele Communication Lines
- iii) Sensors
- iv) Feedback Unit
- v) CPU
- vi) Converters
- vii) Control Panel

Common Problems in Electronic Components

- Visual Inspection
- Oscilloscope
- Logic Probe
- Current Tracer
- Logic Pulser
- Logic Clip
- Logic Comparator
- Arbitrary Waveform Generator
- Signature Analyzer
- Digital Multimeter

Fault	Cause	Remedies
1. Panel is not Working	Main Supply is not given to panel. Inbuilt panel short circuit protected M.C. BTO OFF Emergency Stop is pressed. Key switch off.	Main supply is given to panel. M.C.B is always on. Emergency stop is released. Key switch is on.
2. Machine is not working	Supply is not given to Panel CNC switch is off.	Proper supply is given to panel. CNC switch is on.
3. We are in CNC software but progress in not exciting.	Power failure Emergency Stop is pressed. Limit switched operated. Communication cable is not connected or it is broken.	Power is on. Emergency stop is released limit switched released communication cable is connected properly.
4. Lubrication motor not working	Proper 240 volt supply not given. Signal relay not working.	Proper 240 volt supply given. Signal relay is changed.
5. X-motor and Z-motor drive not working.	Main supply is not given to drive. Wire is not connected from interfacing card to drive. Motor wires are broken. Communication fail.	Main supply is given to drive. Interface wire is connected properly. Check Motor wires are proper connect.
6. The material barns on outside edge.	Tool is blunt Feed speed too low	Replace with sharp tool Increase feed speed
7. Burnt edge of holes	Tool is blunt Tool put in wrong spindle	Replace with sharp tool Insert tool in correct spindle
8. Rough edge , cutter marks visible	Machine is travelling too fast	Reduce the feed speed
9. Component not the correct size	Tool data has been entered incorrectly Component size is entered incorrectly	Edit tool data setting Edit component data

Online Time Fault finding/Diagnosis Tools in CNC machines

- i) Direct Observation Method
- ii) Make use of the CNC system hardware, software and alarm function
- iii) Hammering method
- iv) Theory analysis method
- v) Measurement comparison method
- vi) Interface signal method
- vii) Self diagnosis technique
- viii) Parameter test method
- ix) Malfunction and failure analysis
- x) Control start-up diagnosis
- xi) Preventive maintenance notices
- xii) Tool life monitoring Programming diagnostics

NC words

- i) **n-words:** - They denote the sequence number to identify the block. The complete word usually consist of three digits with 'n' as a prefix.
- ii) **g-words:** - These are called preparatory words i.e., the words used to prepare the controlling unit for the operating instructions, which are to follow.
- iii) **x, y, z, a and b words:** - They are knowns as coordinate words or dimension data words. The first three words x, y, z followed by actual dimensions, represent the coordinate position of tool along the three principal axis while the words 'a' and 'b' indicate the angular positions.
- iv) **f-words:** - These words carry the alphabet 'f' as prefix and may contain upto 8 digit maximum. They are used to specify feed rate in mm/min.
- v) **s-words:** - These words carry the alphabet 's' as prefix and specify cutting speed in rev./min of the spindle.
- vi) **t-words:** - These words carry the alphabet 't' as prefix and may contain upto 5 digit maximum. They are known as tool selection words and used only for those NC machines which carry a tool turret or an ATC.
- vii) **m-words:** - These are known as Miscellaneous Function words. They consists of three digits as a maximum, including the alphabet 'm' as a prefix. Such function is always the last word in the block to indicate an operation.
- viii) **EOB:** - It means the End of Block and it indicates the end of instructions contained in the block.

Machine tool Zero Point Setting

- i) **Manual Setting:** - The operator can use MCU controls to locate the spindle over the desired part zero and then set X and Y coordinate registers on the console to zero.
- ii) **Absolute zero shift:** - This method can change the position of the coordinate system by a command line in the CNC program.
 N1 G28 X0 Y0 Z0 (sends spindle to home zero position)





Zero Point

Machine tool zero point

Program zero point

Workpiece zero point

Tool zero point



Part Programming Format

Tab sequential format (NC only)

N010 G00 X100.00 Y200 Z10 F30 M08
010 > 00 > 100.00 > 200 > 10 > 30 > 08

Fixed Format (NC only)

N010 G01 X10 Y20 Z30 F30 S1000
010 01 10 20 30 30 1000

Word address format (NC & CNC)

This format is standardized by EIA and there are no TAB codes used.

N01 G01 X30 Y20 Z10 S500 F80 T01 M01

Compatible format (NC & CNC)

It is similar to word address format, but TAB codes are added in it.

Part Programme Structure

<u>N03</u>	<u>G02</u>	<u>X300</u>	<u>Y200</u>	<u>Z10</u>	<u>I100</u>	<u>J-10</u>	<u>K20</u>	<u>S450</u>	<u>F80</u>	<u>T03</u>	<u>M01#</u>
Block No	Preparatory Code	Location along X-axis	Location along Y-axis	Location along Z-axis	Center position along X-axis Curved paths	Center position along Y-axis Curved paths	Center position along Z-axis Curved paths	Spindle speed	Feed speed	Tool Specification	Miscellaneous code

M-Codes

M00 Program Stop

M01 Program Optional Stop

M02 End the Program

M03 Spindle On Clockwise, Laser, Flame, Power ON

M04 Spindle On Counter Clockwise

M05 Spindle Stop, Laser, Flame, Power OFF

M06 Tool Change

M08 Coolant On

M09 Coolant Off

M10 Reserved for tool height offset

M13 Spindle On, Coolant On

M30 End the Program when macros are used

M91 Readout Display Incremental

M92 Readout Display Absolute

M97 Go to or jump to line number


M98 Jump to macro or subroutine

M99 Return from macro or subroutine

M100 Machine Zero Reset

M199 Mid program start


Simple Programming for Rational Components



Part Programme of Turning operation

% 1000;	(Main Programme)
N01 G54 G90 G71 G94 M03 S800;	(Parameter Settings)
N05 G01 X-12.5 Z0 F2;	(Facing the job)
N10 G00 Z1;	(Retrieval of tool)
N15 G00 X00;	(Tool Clearance)
N20 G01 Z-100;	(Starting cut)
N25 G00 X1 Z1;	(Clearance position)
N30 G00 X-2;	(Position of cut)
N35 G01 Z-60;	(Cutting length)
N40 G00 X-1 Z1;	(Retrieval of tool)
N45 G00 X-3;	(Position of cut)
N50 G01 Z-60;	(Cutting length)
N55 G00 X-2 Z1;	(Retrieval of tool)
N60 G00 X-4;	(Position of cut)
N65 G01 Z-60;	(Cutting length)
N70 G00 X-3 Z1;	(Retrieval of tool)
N75 G00 X-4.5;	(Position of cut)
N80 G01 Z-60;	(cutting length)
N85 G00 X5 Z5;	(Final position of tool)
N90 M02;	(End of Programme)

Tool Offsets: Correction for dimensions of the tools and movements of the workpiece has to be incorporated to give the exact machining of the component. This is known as tool offset. Normally, it is found that the size of the workpiece is not within the tolerance due to wear of the tool; it is then possible to edit the value of offsets to obtain the correct size, this is known as tool wear compensation.



Tool Compensation

```
graph TD; A[Tool Compensation] --> B[Cutter radius Compensation]; A --> C[Tool wear compensation]; B --> D[This code command allows the programmer to ignore the cutting tool's radius or diameter during programming]; C --> E[Similar to the cutter radius compensation, tool wear compensation is also used in part programming.]
```

Cutter radius Compensation

This code command allows the programmer to ignore the cutting tool's radius or diameter during programming

Tool wear compensation

Similar to the cutter radius compensation, tool wear compensation is also used in part programming.

Canned Cycles: - Canned cycle or fixed cycle may be defined as a set of instructions, inbuilt or stored in the system memory, to perform a fixed sequence of operations. A canned cycles defines a series of machining sequence for drilling, boring, tapping etc. The canned cycle G81 to G89 are stored as subroutines L81 to L89. These cycles are used for repetitive and commonly used machining operations.

Sub Routines: - These are also known as subprograms, a very powerful saving method. The subroutines provide the capability of programming certain program that are repeated frequently. They are independent programmes that can be called any time and any number of times.

Do Loops: - The Do loops gives the facility to programmer to jump back to an earlier part of programme and execute the intervening programme and not separately like subroutines. It is given in the main program itself.

Refer to book for more details

Thank You