

CNC MACHINES AND AUTOMATION




AMIT JANGRA

Lecturer

Mechanical Engineering Department

GP HISAR



Chapter 5

(Problems in CNC machines)

Classification of CNC machine faults

```
graph TD; A[Classification of CNC machine faults] --> B[According to elements]; A --> C[According to phenomenon]; A --> D[According to nature]; A --> E[According to characteristics]; B --> B1[Mechanical]; B --> B2[Electrical]; C --> C1[Reproducibility]; C --> C2[Random failure]; D --> D1[Recoverable fault]; D --> D2[Unrecoverable fault]; E --> E1[No failure alarm]; E --> E2[Failure alarm];
```

According to
elements

Mechanical

Electrical

According to
phenomenon

Reproducibility

Random failure

According to
nature

Recoverable
fault

Unrecoverable
fault

According to
characteristics

No failure
alarm

Failure alarm

Common Problems in Mechanical Components


- i) Bed
- ii) Tail stock and Head stock
- iii) Slideways Tool Pallettes
- iv) Mechanical Switches
- v) Host part

Common Problems in Electrical Components

- i) Switching Devices
- ii) Solenoids
- iii) Drive System

Common Problems in Pneumatic Components

- i) Cylinder
- ii) Piston and Piston rings
- iii) Valves



Common Problems in Electronic Components

- i) Display Screen/Monitor
- ii) Tele Communication Lines
- iii) Sensors
- iv) Feedback Unit
- v) CPU
- vi) Converters
- vii) Control Panel

Fault finding techniques

- Visual Inspection
- Oscilloscope
- Logic Probe
- Current Tracer
- Logic Pulser
- Logic Clip
- Logic Comparator
- Arbitrary Waveform Generator
- Signature Analyzer
- Digital Multimeter

Fault	Cause	Remedies
1. Panel is not Working	Main Supply is not given to panel. Inbuilt panel short circuit protected M.C. BTO OFF Emergency Stop is pressed. Key switch off.	Main supply is given to panel. M.C.B is always on. Emergency stop is released. Key switch is on.
2. Machine is not working	Supply is not given to Panel CNC switch is off.	Proper supply is given to panel. CNC switch is on.
3. We are in CNC software but progress in not exciting.	Power failure Emergency Stop is pressed. Limit switched operated. Communication cable is not connected or it is broken.	Power is on. Emergency stop is released limit switched released communication cable is connected properly.
4. Lubrication motor not working	Proper 240 volt supply not given. Signal relay not working.	Proper 240 volt supply given. Signal relay is changed.
5. X-motor and Z-motor drive not working.	Main supply is not given to drive. Wire is not connected from interfacing card to drive. Motor wires are broken. Communication fail.	Main supply is given to drive. Interface wire is connected properly. Check Motor wires are proper connect.
6. The material barns on outside edge.	Tool is blunt Feed speed too low	Replace with sharp tool Increase feed speed
7. Burnt edge of holes	Tool is blunt Tool put in wrong spindle	Replace with sharp tool Insert tool in correct spindle
8. Rough edge , cutter marks visible	Machine is travelling too fast	Reduce the feed speed
9. Component not the correct size	Tool data has been entered incorrectly Component size is entered incorrectly	Edit tool data setting Edit component data

Online Time Fault finding/Diagnosis Tools in CNC machines

- i) Direct Observation Method
- ii) Make use of the CNC system hardware, software and alarm function
- iii) Hammering method
- iv) Theory analysis method
- v) Measurement comparison method
- vi) Interface signal method
- vii) Self diagnosis technique
- viii) Parameter test method
- ix) Malfunction and failure analysis
- x) Control start-up diagnosis
- xi) Preventive maintenance notices
- xii) Tool life monitoring Programming diagnostics

Thank You