

test\_app.csv

	variable	value
fulcrum_id		c1270b8b-67e0-4857-b82f-3c34145efdc1
created_at		2018-08-23 14:47:56 UTC
updated_at		2021-06-08 20:23:41 UTC
created_by		mike.a.king@wv.gov
updated_by		mike.a.king@wv.gov
system_created_at		2018-08-23 14:47:56 UTC
system_updated_at		2021-06-08 20:23:45 UTC
version		19
status		NaN
project		NaN
assigned_to		NaN
latitude		37.324906
longitude		-81.133673
geometry		POINT (-81.13367292 37.32490618)
inspection_report_number		2300.11.02.2017.R
structure_number		2300
inspection_type		Acceptance
non_inventoried_structure		yes
newly_erected_structure		yes
state_project_number_example_s320		1646
state_project_number_example_60		16
state_project_number_example_10		16
state_project_number_example_16		56
state_project_number_example_57		67
state_project_number_example_00		16
state_project_number		1646-16/16-56.67 16
federal_project_number_example_stp		STP
federal_project_number_example_0060		46
federal_project_number_example_311		613
federal_project_number_example_d		R
federal_project_number		STP-0046(613)R
purchase_order_number		68a1651d6
contract_id_number		NaN
construction_plan_assembly_number		sa1863
fabricator		Hurt Fabricating Corporation
contractor		PDK Construction
date_of_erection		10/2018
date_of_inspection		2020-10-29
inspection_firm		Jimmy Bob Consulting
team_leader		Josh Cook
traffic_control_supervisor		Curtis Thomas
ndt_technician		Dave Bowling
special_inspection_purpose		For the purpose of inspecting
location_diagram_sketch_updated		yes
ut_report		no
other_nd_testing_report		yes
other_nd_testing_description		The test did happen
special_access_requirements		yes
special_access_requirement_notes		There was a giant boulder in the way
district		3
county		Kanawha
gps_latitude		37.324906
gps_longitude		-81.133672
wvdoh_gis_tool_1		NaN
example_image_1_route_id		NaN
example_image_2_route_id		NaN
route_id		20301140000SB
wvdoh_gis_tool_2		NaN
milepost		169.75
signal_intersection_identification_number		1646681
superstructure_mounted		yes
bridge_id_number		61848
painted		yes
paint_color		Brown
overhead_signs		yes
number_of_overhead_signs		3
total_overhead_sign_area_sq_ft		200
sign_lighting_luminaires		yes
number_of_sign_lighting_luminaires		1
roadway_lighting_luminaires		yes
number_of_roadway_lighting_luminaires		1
breakaway_base_mechanism		Coupler
primary_strain_pole		yes
signalized_intersection_control_cabinet		yes
tether_wire		yes
boxed_span_wire		yes
strain_pole_or_mast_arm_luminaire		yes

number_of overhead_signal heads	variable	1	value
number_of other_overhead_attachments		1	
number_of support_leg_or_pole_signal heads		1	
number_of other_support_leg_or_pole_attachments		1	
example_image_sign_size_area_fab_code_text		NaN	
assembly_type		Structure	
general_support_type		Large Support	
support_type		High Mast Tower	
example_image_1_base_connection_type_a_parapet_mount		NaN	
example_image_2_base_connection_type_b_parapet_mount		NaN	
example_image_3_base_connection_type_b_parapet_mount		NaN	
example_image_4_base_connection_other		NaN	
base_connection		Type B Parapet Mount	
general_structure_type		Span	
specific_structure_type_cantilever		NaN	
specific_structure_type_butterfly		NaN	
specific_structure_type_span		TE5-7	
specific_structure_type_signal_strain_pole		NaN	
specific_structure_type_traffic_signal_mast_arm		NaN	
specific_structure_type_high_mast_tower		TEL-16A	
specific_structure_type_light_pole		NaN	
specific_structure_type		TE5-7, TEL-16A	
standard_detail		yes	
standard_detail_version_te4_3		NaN	
standard_detail_version_te4_4		NaN	
standard_detail_version_te3_2		NaN	
standard_detail_version_te3_1		NaN	
standard_detail_version_te5_1_3x3		NaN	
standard_detail_version_te5_1_5x5		NaN	
standard_detail_version_te5_7		NaN	
standard_detail_version_tes_20		NaN	
standard_detail_version_tes_10		NaN	
standard_detail_version_tes_13		NaN	
standard_detail_version_tel_16a		NaN	
standard_detail_version_tel_11		NaN	
standard_detail_version_tel_12		NaN	
standard_detail_version_tel_13		NaN	
standard_detail_version_tel_15a		NaN	
standard_detail_version		NaN	
revised_standard_detail		yes	
special_detail		yes	
material_type		Weathering Steel	
support_legs		yes	
number_of support legs		3	
support_leg_1_length_ft		30	
support_leg_2_length_ft		30	
support_leg_3_length_ft		30	
pole		yes	
pole_length_ft		13	
chords		yes	
number_of chords		1	
span_length_ft		20	
secondary_span		yes	
secondary_span_length_ft		5	
arms		yes	
number_of arms		2	
arm_length_ft		15	
secondary_arm		yes	
secondary_arm_length_ft		15	
strain_pole_span_1_length_ft		17	
strain_pole_span_2_length_ft		18	
strain_pole_span_3_length_ft		19	
strain_pole_span_4_length_ft		20	
example_image_cantilever_1_point_of_support		NaN	
example_image_span_2_points_of_support		NaN	
example_image_span_3_points_of_support		NaN	
example_image_ground_mounted_foundation_without_pedestal		NaN	
example_image_ground_mounted_foundation_with_pedestal		NaN	
example_image_concrete_barrier_foundation		NaN	
example_image_ground_mounted_foundation_shielded_by_barrier		NaN	
example_image_parapet_foundation_direct_vertical		NaN	
example_image_1_parapet_foundation_connection_plate_horizontal		NaN	
example_image_2_parapet_foundation_connection_plate_horizontal		NaN	
example_image_fixed_structure_direct_concrete_horizontal		NaN	
example_image_fixed_structure_direct_concrete_vertical		NaN	
example_image_1_fixed_structure_connection_plate_concrete_horizontal		NaN	
example_image_2_fixed_structure_connection_plate_concrete_horizontal		NaN	
example_image_1_fixed_structure_direct_steel_vertical_fixed_structure_direct_steel_horizontal		NaN	
example_image_2_fixed_structure_direct_steel_vertical_fixed_structure_direct_steel_horizontal		NaN	
		NaN	

variable	value
example_image_steel_haunch	NaN
example_image_light_pole_bracket	3
number_of_points_of_support	
point_of_support_1_type	Ground Mounted Foundation With Pedestal
point_of_support_2_type	Fixed Structure Direct Concrete Vertical
point_of_support_3_type	Fixed Structure Connection Plate Concrete Horizontal
example_image_fixed_structure_direct_steel_horizontal_type_point_of_support_with_numerous_structural_connection_bolts	NaN
example_image_concrete_barrier_foundation_type_point_of_support_with_eight_8_anchor_bolts	NaN
example_image_parapet_foundation_connection_plate_horizontal_type_point_of_support_with_four_4_structural_studs	NaN
point_of_support_1_number_of_anchorconnection_bolts_or_structural_studs	2
point_of_support_2_number_of_anchorconnection_bolts_or_structural_studs	3
point_of_support_3_number_of_anchorconnection_bolts_or_structural_studs	4
point_of_support_1_anchorconnection_bolt_or_structural_stud_diameter_inches	2-1/2
point_of_support_2_anchorconnection_bolt_or_structural_stud_diameter_inches	2-3/8
point_of_support_3_anchorconnection_bolt_or_structural_stud_diameter_inches	1-1/8
example_image_base_plate_with_grout_pad	NaN
point_of_support_1_grout_pad	yes
point_of_support_2_grout_pad	yes
point_of_support_3_grout_pad	yes
structure_not_over_paved_lane_or_shoulder	False
number_of_lanes	5
low_clearance_noted	True
low_clearance_descriptions	text sample
sign_structures_table	NaN
signal_structures_table	NaN
pole_structures_table	NaN
clearance_element_category_lowest_rating	3
attachments_element_category_lowest_rating	2
structure_element_category_lowest_rating	3
foundation_or_other_support_structure_element_category_lowest_rating	3
additional_information	sample text
overall_summary	sample text
example_photos	NaN
cover_photo	87f9f0dd-ad0c-4546-9d55-f04fad4b01df
cover_photo_caption	This is a photo
cover_photo_url	https://web.fulcrumapp.com/photos/view?photos=87f9f0dd-ad0c-4546-9d55-f04fad4b01df

## test\_app\_additional\_comments\_pse13.csv

variable	value
fulcrum_id	8d84af31-7c55-4ef7-bfbb-ab16b37f5bbb
fulcrum_parent_id	c1270b8b-67e0-4857-b82f-3c34145efdc1
fulcrum_record_id	c1270b8b-67e0-4857-b82f-3c34145efdc1
version	1
latitude	NaN
longitude	NaN
geometry	NaN
created_at	2021-01-07 19:41:06 UTC
updated_at	2021-01-07 19:41:06 UTC
created_by	mike.a.king@wv.gov
updated_by	mike.a.king@wv.gov
element_pse13ed	Grout
element_non_standard_pse13en	sample text
element_category_pse13ec	Structure
deficiency_pse13dd	torque indicator nut still present above base plate.
deficiency_non_standard_pse13dn	sample text
deficiency_criteria_pse13dcd	15% <= through bolts (total) or adhesive/expansion anchorage nuts (total) missing < 30%
deficiency_criteria_non_standard_pse13dcn	sample text
element_rating_pse13er	1
recommended_priority_pse13rp	High
recommendation_pse13rd	Remove cover and inspect.
recommendation_non_standard_pse13m	sample text
supplemental_information_pse13si	sample text
referenced_photos_pse13rp	sample text

## test\_app\_additional\_comments\_sse21.csv

variable	value
fulcrum_id	d4f967cb-2a5a-4010-9a22-0cd302de5ed7
fulcrum_parent_id	c1270b8b-67e0-4857-b82f-3c34145efdc1
fulcrum_record_id	c1270b8b-67e0-4857-b82f-3c34145efdc1
version	1
latitude	NaN
longitude	NaN
geometry	NaN
created_at	2020-10-29 18:26:48 UTC
updated_at	2020-10-29 18:26:48 UTC
created_by	mike.a.king@wv.gov
updated_by	mike.a.king@wv.gov
element_sse21ed	Concrete Foundation

variable	value
element_non_standard_sse21en	a broken bolt
element_category_sse21ec	Clearance
deficiency_sse21dd	Chord connection plate or arm plate broken or cracked.
deficiency_non_standard_sse21dn	a broken bolt
deficiency_criteria_sse21dcd	2 or more nuts in a 4 bolt configuration, OR 2 or more nuts in a 6 bolt configuration, OR 3 or more nuts in an 8 or more bolt configuration
deficiency_criteria_non_standard_sse21dcn	a broken bolt
element_rating_sse21er	2
recommended_priority_sse21rp	High
recommendation_sse21rd	Lower structure, retrofit short anchor bolt assembly to restore full capacity, or remove structure.
recommendation_non_standard_sse21m	a broken bolt
supplemental_information_sse21si	a broken bolt
referenced_photos_sse21rp	88

## test\_app\_additional\_comments\_tse15.csv

variable	value
fulcrum_id	0d2b69c0-f1d6-499c-9d07-c1f1d2279e49
fulcrum_parent_id	c1270b8b-67e0-4857-b82f-3c34145ef1c1
fulcrum_record_id	c1270b8b-67e0-4857-b82f-3c34145ef1c1
version	1
latitude	NaN
longitude	NaN
geometry	NaN
created_at	2021-01-07 19:37:32 UTC
updated_at	2021-01-07 19:37:32 UTC
created_by	mike.a.king@wv.gov
updated_by	mike.a.king@wv.gov
element_tse15ed	Erosion or Undermining
element_non_standard_tse15dn	sample text
element_category_tse15ec	Attachments
deficiency_tse15dd	Bullet holes in signal heads.
deficiency_non_standard_tse15dn	sample text
deficiency_criteria_tse15dcd	15% <= section loss < 30%
deficiency_criteria_non_standard_tse15dcn	sample text
element_rating_tse15er	3*
recommended_priority_tse15rp	High
recommendation_tse15rd	No recommendation or brace/straighten affected member if necessary.
recommendation_non_standard_tse15m	sample text
supplemental_information_tse15si	sample text
referenced_photos_tse15rp	sample text

## test\_app\_anchorBolts\_or\_structural\_studs\_sse17.csv

variable	value
fulcrum_id	b3b5fb3b-c2f7-4a88-a72f-35108e678f03
fulcrum_parent_id	c1270b8b-67e0-4857-b82f-3c34145ef1c1
fulcrum_record_id	c1270b8b-67e0-4857-b82f-3c34145ef1c1
version	1
latitude	NaN
longitude	NaN
geometry	NaN
created_at	2020-10-29 18:25:27 UTC
updated_at	2020-10-29 18:25:27 UTC
created_by	mike.a.king@wv.gov
updated_by	mike.a.king@wv.gov
deficiency_sse17dd	Chord connection plate or arm plate broken or cracked.
deficiency_non_standard_sse17dn	a broken bolt
deficiency_criteria_sse17dcd	2 or more nuts or bolt in a 4 bolt configuration, OR 2 or more nuts or bolts in a 6 bolt configuration, OR 3 or more nuts or bolts in an 8 or more bolt configuration
deficiency_criteria_non_standard_sse17dcn	a broken bolt
element_rating_sse17er	3*
recommended_priority_sse17rp	Medium
recommendation_sse17rd	Regrade around affected components.
recommendation_non_standard_sse17m	a broken bolt
supplemental_information_sse17si	a broken bolt
referenced_photos_sse17rp	41

## test\_app\_anchorBolts\_pse9.csv

variable	value
fulcrum_id	3f3d2595-145b-4222-a3b7-38e07ed3285f
fulcrum_parent_id	c1270b8b-67e0-4857-b82f-3c34145ef1c1
fulcrum_record_id	c1270b8b-67e0-4857-b82f-3c34145ef1c1
version	1
latitude	NaN
longitude	NaN
geometry	NaN
created_at	2021-01-07 19:40:02 UTC
updated_at	2021-01-07 19:40:02 UTC
created_by	mike.a.king@wv.gov
updated_by	mike.a.king@wv.gov

variable	value
deficiency_pse9dd	Coating exhibits oxidation or peeling at the transformer
deficiency_non_standard_pse9dn	sample text
deficiency_criteria_pse9dcd	15% <= section loss < 30%
deficiency_criteria_non_standard_pse9dcn	sample text
element_rating_pse9er	2*
recommended_priority_pse9rp	Medium
recommendation_pse9rd	Lower/Retrofit/Replace affected components.
recommendation_non_standard_pse9rm	sample text
supplemental_information_pse9si	sample text
referenced_photos_pse9rp	sample text

test\_app\_anchor\_bolts\_tse11.csv

variable	value
fulcrum_id	cbfd960f-d503-47c7-8bad-3328416d56d1
fulcrum_parent_id	c1270b8b-67e0-4857-b82f-3c34145efdc1
fulcrum_record_id	c1270b8b-67e0-4857-b82f-3c34145efdc1
version	1
latitude	NaN
longitude	NaN
geometry	NaN
created_at	2021-01-07 19:36:15 UTC
updated_at	2021-01-07 19:36:15 UTC
created_by	mike.a.king@wv.gov
updated_by	mike.a.king@wv.gov
deficiency_tse11dd	Coating exhibits oxidation/peeling.
deficiency_non_standard_tse11dn	sample text
deficiency_criteria_tse11dcd	some evidence of standing water
deficiency_criteria_non_standard_tse11dcn	sample text
element_rating_tse11er	2*
recommended_priority_tse11rp	Low
recommendation_tse11rd	Lower structure, retrofit short anchor bolt assembly to restore full capacity, or remove structure. Project Manager notified.
recommendation_non_standard_tse11rm	sample text
supplemental_information_tse11si	sample text
referenced_photos_tse11rp	sample text

test\_app\_arm\_or\_wire\_splices\_tse10.csv

variable	value
fulcrum_id	fba6ba0b-e98f-4f62-b873-62f4b8e115e9
fulcrum_parent_id	c1270b8b-67e0-4857-b82f-3c34145efdc1
fulcrum_record_id	c1270b8b-67e0-4857-b82f-3c34145efdc1
version	1
latitude	NaN
longitude	NaN
geometry	NaN
created_at	2021-01-07 19:35:59 UTC
updated_at	2021-01-07 19:35:59 UTC
created_by	mike.a.king@wv.gov
updated_by	mike.a.king@wv.gov
deficiency_tse10dd	Connection hardware loose or missing in arm compression splice.
deficiency_non_standard_tse10dn	sample text
deficiency_criteria_tse10dcd	some evidence of standing water
deficiency_criteria_non_standard_tse10dcn	sample text
element_rating_tse10er	3
recommended_priority_tse10rp	High
recommendation_tse10rd	No recommendation.
recommendation_non_standard_tse10rm	sample text
supplemental_information_tse10si	sample text
referenced_photos_tse10rp	sample text

test\_app\_arm\_or\_wire\_tse9.csv

variable	value
fulcrum_id	c06e070f-d6e7-4ced-adc5-70da3d9edb0e
fulcrum_parent_id	c1270b8b-67e0-4857-b82f-3c34145efdc1
fulcrum_record_id	c1270b8b-67e0-4857-b82f-3c34145efdc1
version	1
latitude	NaN
longitude	NaN
geometry	NaN
created_at	2021-01-07 19:35:42 UTC
updated_at	2021-01-07 19:35:42 UTC
created_by	mike.a.king@wv.gov
updated_by	mike.a.king@wv.gov
deficiency_tse9dd	Coating exhibits oxidation/peeling.
deficiency_non_standard_tse9dn	sample text
deficiency_criteria_tse9dcd	not conditional
deficiency_criteria_non_standard_tse9dcn	sample text

variable	value
element_rating_tse9er	2*
recommended_priority_tse9rp	High
recommendation_tse9rd	Regrade, install retaining wall, or relocate structure.
recommendation_non_standard_tse9m	sample text
supplemental_information_tse9si	sample text
referenced_photos_tse9rp	sample text

test\_app\_arm\_to\_support\_leg\_or\_wire\_to\_pole\_connection\_tse8.csv

variable	value
fulcrum_id	ca772051-bb8c-4071-8490-dd0000c8ad1a
fulcrum_parent_id	c1270b8b-67e0-4857-b82f3c34145efdc1
fulcrum_record_id	c1270b8b-67e0-4857-b82f3c34145efdc1
version	1
latitude	NaN
longitude	NaN
geometry	NaN
created_at	2021-01-07 19:35:26 UTC
updated_at	2021-01-07 19:35:26 UTC
created_by	mike.a.king@wv.gov
updated_by	mike.a.king@wv.gov
deficiency_tse8dd	Coating exhibits oxidation/peeling.
deficiency_non_standard_tse8dn	sample text
deficiency_criteria_tse8dcd	top of foundation submerged
deficiency_criteria_non_standard_tse8dcn	sample text
element_rating_tse8er	3*
recommended_priority_tse8rp	Medium
recommendation_tse8rd	Lower structure, retrofit short anchor bolt assembly to restore full capacity, or remove structure. Project Manager notified.
recommendation_non_standard_tse8m	sample text
supplemental_information_tse8si	sample text
referenced_photos_tse8rp	vsample text

test\_app\_chord\_or\_arm\_splices\_sse11.csv

variable	value
fulcrum_id	fe30296f-c83c-4fb9-8c05-0d25e4eb9b29
fulcrum_parent_id	c1270b8b-67e0-4857-b82f3c34145efdc1
fulcrum_record_id	c1270b8b-67e0-4857-b82f3c34145efdc1
version	1
latitude	NaN
longitude	NaN
geometry	NaN
created_at	2020-10-29 18:22:56 UTC
updated_at	2020-10-29 18:22:56 UTC
created_by	mike.a.king@wv.gov
updated_by	mike.a.king@wv.gov
deficiency_sse11dd	Connection hardware for luminaires, conduits, or light arms are loose, missing, or broken
deficiency_non_standard_sse11dn	a broken bolt
deficiency_criteria_sse11dcd	25% <= section loss < 50%
deficiency_criteria_non_standard_sse11dcn	a broken bolt
element_rating_sse11er	1*
recommended_priority_sse11rp	Low
recommendation_sse11rd	Regrade, install retaining wall, or relocate structure.
recommendation_non_standard_sse11m	a broken bolt
supplemental_information_sse11si	a broken bolt
referenced_photos_sse11rp	59

test\_app\_chord\_or\_arm\_sse10.csv

variable	value
fulcrum_id	c2d37d74-fa8b-4f2a-80ad-5fac4cbb8d1
fulcrum_parent_id	c1270b8b-67e0-4857-b82f3c34145efdc1
fulcrum_record_id	c1270b8b-67e0-4857-b82f3c34145efdc1
version	1
latitude	NaN
longitude	NaN
geometry	NaN
created_at	2020-10-29 15:31:18 UTC
updated_at	2020-10-29 15:31:18 UTC
created_by	mike.a.king@wv.gov
updated_by	mike.a.king@wv.gov
deficiency_sse10dd	Bulb or light broken at sign lighting
deficiency_non_standard_sse10dn	a broken bolt
deficiency_criteria_sse10dcd	15% <= section loss < 30%
deficiency_criteria_non_standard_sse10dcn	a broken bolt
element_rating_sse10er	3*
recommended_priority_sse10rp	High
recommendation_sse10rd	Regrade around affected components.
recommendation_non_standard_sse10m	a broken bolt
supplemental_information_sse10si	a broken bolt

referenced_photos_sse10rp	variable	78	value
---------------------------	----------	----	-------

test\_app\_chord\_or\_arm\_to\_support\_leg\_connection\_sse9.csv

variable	value
fulcrum_id	61741d5d-4d0d-421f-9f92-c81d5ce89544
fulcrum_parent_id	c1270b8b-67e0-4857-b82f-3c34145efdc1
fulcrum_record_id	c1270b8b-67e0-4857-b82f-3c34145efdc1
version	1
latitude	NaN
longitude	NaN
geometry	NaN
created_at	2020-10-29 15:30:58 UTC
updated_at	2020-10-29 15:30:58 UTC
created_by	mike.a.king@wv.gov
updated_by	mike.a.king@wv.gov
deficiency_sse9dd	Chord connection plate or arm plate broken or cracked.
deficiency_non_standard_sse9dn	a broken bolt
deficiency_criteria_sse9dcd	20% <= through bolts (total) or adhesive/expansion anchorage nuts (total) loose < 40%
deficiency_criteria_non_standard_sse9dcn	a broken bolt
element_rating_sse9er	2*
recommended_priority_sse9rp	Low
recommendation_sse9rd	No recommendation.
recommendation_non_standard_sse9rm	a broken bolt
supplemental_information_sse9si	a broken bolt
referenced_photos_sse9rp	28

test\_app\_chord\_or\_arm\_trussing\_sse12.csv

variable	value
fulcrum_id	9e453b9f-cdcf-4cc4-a8d7-eda325151832
fulcrum_parent_id	c1270b8b-67e0-4857-b82f-3c34145efdc1
fulcrum_record_id	c1270b8b-67e0-4857-b82f-3c34145efdc1
version	1
latitude	NaN
longitude	NaN
geometry	NaN
created_at	2020-10-29 18:23:14 UTC
updated_at	2020-10-29 18:23:14 UTC
created_by	mike.a.king@wv.gov
updated_by	mike.a.king@wv.gov
deficiency_sse12dd	Bullet holes in or graffiti on sign panel
deficiency_non_standard_sse12dn	a broken bolt
deficiency_criteria_sse12dcd	20% <= through bolts (total) or adhesive/expansion anchorage nuts (total) loose < 40%
deficiency_criteria_non_standard_sse12dcn	a broken bolt
element_rating_sse12er	3
recommended_priority_sse12rp	Low
recommendation_sse12rd	Notify Project Manager
recommendation_non_standard_sse12rm	a broken bolt
supplemental_information_sse12si	a broken bolt
referenced_photos_sse12rp	48

test\_app\_clearance\_comments\_sse1.csv

variable	value
fulcrum_id	a2bcd220-d9e3-492f-ac67-174430f6d3be
fulcrum_parent_id	c1270b8b-67e0-4857-b82f-3c34145efdc1
fulcrum_record_id	c1270b8b-67e0-4857-b82f-3c34145efdc1
version	1
latitude	NaN
longitude	NaN
geometry	NaN
created_at	2020-10-29 15:19:51 UTC
updated_at	2020-10-29 15:19:51 UTC
created_by	mike.a.king@wv.gov
updated_by	mike.a.king@wv.gov
deficiency_sse1dd	Base plate varmint screen could not be removed, preventing inspection of anchor bolts.
deficiency_non_standard_sse1dn	a broken bolt
deficiency_criteria_sse1dcd	15% <= section loss < 25%
deficiency_criteria_non_standard_sse1dcn	a broken bolt
element_rating_sse1er	3
recommended_priority_sse1rp	Medium
recommendation_sse1rd	Notify Project Manager
recommendation_non_standard_sse1rm	a broken bolt
supplemental_information_sse1si	a broken bolt
referenced_photos_sse1rp	13

test\_app\_clearance\_comments\_tse1.csv

variable	value
fulcrum_id	47a47807-0c95-4b57-9995-00658154974a
fulcrum_parent_id	c1270b8b-67e0-4857-b82f-3c34145efdc1
fulcrum_record_id	c1270b8b-67e0-4857-b82f-3c34145efdc1
version	1
latitude	NaN
longitude	NaN
geometry	NaN
created_at	2021-01-07 19:33:34 UTC
updated_at	2021-01-07 19:33:34 UTC
created_by	mike.a.king@wv.gov
updated_by	mike.a.king@wv.gov
deficiency_tse1dd	Base plate to foundation height exceeds tolerance. Height between bottom of base plate and top of concrete foundation is vertical distance H". Tolerance is related to anchor bolt diameter D".
deficiency_non_standard_tse1dn	sample text
deficiency_criteria_tse1dcd	2 nuts in an 8 or more bolt configuration
deficiency_criteria_non_standard_tse1dcn	sample text
element_rating_tse1er	3
recommended_priority_tse1rp	High
recommendation_tse1rd	Lower structure, retrofit short anchor bolt assembly to restore full capacity, or remove structure.
recommendation_non_standard_tse1m	sample text
supplemental_information_tse1si	sample text
referenced_photos_tse1rp	sample text

test\_app\_concrete\_foundation\_pse10.csv

variable	value
fulcrum_id	2d1e8fd6-1b19-4092-8df5-0b6f6e616fd6
fulcrum_parent_id	c1270b8b-67e0-4857-b82f-3c34145efdc1
fulcrum_record_id	c1270b8b-67e0-4857-b82f-3c34145efdc1
version	1
latitude	NaN
longitude	NaN
geometry	NaN
created_at	2021-01-07 19:40:14 UTC
updated_at	2021-01-07 19:40:14 UTC
created_by	mike.a.king@wv.gov
updated_by	mike.a.king@wv.gov
deficiency_pse10dd	Breakaway couplings broken, sheared, or cracked.
deficiency_non_standard_pse10dn	sample text
deficiency_criteria_pse10dcd	1% <= V/H < 2%
deficiency_criteria_non_standard_pse10dcn	sample text
element_rating_pse10er	2
recommended_priority_pse10rp	Medium
recommendation_pse10rd	Regrade around affected components.
recommendation_non_standard_pse10m	sample text
supplemental_information_pse10si	sample text
referenced_photos_pse10rp	sample text

test\_app\_concrete\_foundation\_sse18.csv

variable	value
fulcrum_id	07769b27-cf06-4ed1-9405-bd228f2d5b80
fulcrum_parent_id	c1270b8b-67e0-4857-b82f-3c34145efdc1
fulcrum_record_id	c1270b8b-67e0-4857-b82f-3c34145efdc1
version	1
latitude	NaN
longitude	NaN
geometry	NaN
created_at	2020-10-29 18:25:42 UTC
updated_at	2020-10-29 18:25:42 UTC
created_by	mike.a.king@wv.gov
updated_by	mike.a.king@wv.gov
deficiency_sse18dd	Chord connection plate or arm plate broken or cracked.
deficiency_non_standard_sse18dn	a broken bolt
deficiency_criteria_sse18dcd	2 or more nuts or bolt in a 4 bolt configuration, OR 2 or more nuts or bolts in a 6 bolt configuration, OR 3 or more nuts or bolts in an 8 or more bolt configuration
deficiency_criteria_non_standard_sse18dcn	a broken bolt
element_rating_sse18er	1*
recommended_priority_sse18rp	Medium
recommendation_sse18rd	Notify Project Manager
recommendation_non_standard_sse18m	a broken bolt
supplemental_information_sse18si	a broken bolt
referenced_photos_sse18rp	50

test\_app\_concrete\_foundation\_tse12.csv

variable	value
fulcrum_id	10832827-4157-4506-91dd-433f34a8024a
fulcrum_parent_id	c1270b8b-67e0-4857-b82f-3c34145efdc1
fulcrum_record_id	c1270b8b-67e0-4857-b82f-3c34145efdc1



version	variable	1	value
latitude			NaN
longitude			NaN
geometry			NaN
created_at			2021-01-07 19:36:33 UTC
updated_at			2021-01-07 19:36:33 UTC
created_by			mike.a.king@wv.gov
updated_by			mike.a.king@wv.gov
deficiency_tse12dd			Vegetation growth on and around foundation.
deficiency_non_standard_tse12dn			sample text
deficiency_criteria_tse12dcd			V/H < 1%
deficiency_criteria_non_standard_tse12dcn			sample text
element_rating_tse12er			4
recommended_priority_tse12rp			Medium
recommendation_tse12rd			Regrade, install retaining wall, or relocate structure.
recommendation_non_standard_tse12m			sample text
supplemental_information_tse12si			sample text
referenced_photos_tse12rp			sample text

## test\_app\_condition\_of\_attachment\_to\_bridge\_beam\_or\_girder\_sse13.csv

variable	value
fulcrum_id	98f0b1fe-5ecd-4c2d-a195-02e34b7b67a7
fulcrum_parent_id	c1270b8b-67e0-4857-b82f-3c34145efdc1
fulcrum_record_id	c1270b8b-67e0-4857-b82f-3c34145efdc1
version	1
latitude	NaN
longitude	NaN
geometry	NaN
created_at	2020-10-29 18:23:33 UTC
updated_at	2020-10-29 18:23:33 UTC
created_by	mike.a.king@wv.gov
updated_by	mike.a.king@wv.gov
deficiency_sse13dd	Connection hardware for luminaires, conduits, or light arms are loose, missing, or broken
deficiency_non_standard_sse13dn	a broken bolt
deficiency_criteria_sse13dcd	2 nuts in an 8 or more bolt configuration
deficiency_criteria_non_standard_sse13dcn	a broken bolt
element_rating_sse13er	2
recommended_priority_sse13rp	High
recommendation_sse13rd	Notify Project Manager
recommendation_non_standard_sse13m	a broken bolt
supplemental_information_sse13si	a broken bolt
referenced_photos_sse13rp	78

## test\_app\_condition\_of\_attachment\_to\_concrete\_frame\_mount\_structures\_and\_other\_structures\_attachment

variable	value
fulcrum_id	b6d2d043-cc18-45d7-9e12-495a543fe867
fulcrum_parent_id	c1270b8b-67e0-4857-b82f-3c34145efdc1
fulcrum_record_id	c1270b8b-67e0-4857-b82f-3c34145efdc1
version	1
latitude	NaN
longitude	NaN
geometry	NaN
created_at	2020-10-29 18:25:10 UTC
updated_at	2020-10-29 18:25:10 UTC
created_by	mike.a.king@wv.gov
updated_by	mike.a.king@wv.gov
deficiency_sse16dd	Bullet holes in or graffiti on sign panel
deficiency_non_standard_sse16dn	a broken bolt
deficiency_criteria_sse16dcd	15% <= section loss < 30%
deficiency_criteria_non_standard_sse16dcn	a broken bolt
element_rating_sse16er	2
recommended_priority_sse16rp	Medium
recommendation_sse16rd	Notify Project Manager
recommendation_non_standard_sse16m	a broken bolt
supplemental_information_sse16si	a broken bolt
referenced_photos_sse16rp	18

## test\_app\_condition\_of\_concrete\_at\_attachments\_frame\_mount\_structures\_and\_other\_structures\_attachment

variable	value
fulcrum_id	3ea787ae-f8fa-46f1-a917-3a0a7e62a61d
fulcrum_parent_id	c1270b8b-67e0-4857-b82f-3c34145efdc1
fulcrum_record_id	c1270b8b-67e0-4857-b82f-3c34145efdc1
version	1
latitude	NaN
longitude	NaN
geometry	NaN
created_at	2020-10-29 18:24:54 UTC

updated_at	variable
	2020-10-29 18:24:54 UTC
created_by	value
	mike.a.king@wv.gov
updated_by	
	mike.a.king@wv.gov
deficiency_sse15dd	Coating exhibits oxidation or peeling
deficiency_non_standard_sse15dn	a broken bolt
deficiency_criteria_sse15dcd	25% <= loose components < 50%
deficiency_criteria_non_standard_sse15dcn	a broken bolt
element_rating_sse15er	2
recommended_priority_sse15rp	Critical
recommendation_sse15rd	No recommendation.
recommendation_non_standard_sse15rm	a broken bolt
supplemental_information_sse15si	a broken bolt
referenced_photos_sse15rp	64

test\_app\_cover\_photo.csv

variable	value
fulcrum_id	87f9f0dd-ad0c-4546-9d55-f04fad4b01df
fulcrum_parent_id	c1270b8b-67e0-4857-b82f-3c34145efdc1
fulcrum_record_id	c1270b8b-67e0-4857-b82f-3c34145efdc1
version	1
caption	This is a photo
latitude	38.338686
longitude	-81.610294
geometry	POINT (-81.61029444444443 38.338686111111116)
file_size	246561
uploaded_at	2021-06-08 20:17:46 UTC
exif_date_time	2021-06-08 16:16:07 UTC
exif_gps_altitude	184.597317
exif_gps_date_stamp	NaN
exif_gps_time_stamp	NaN
exif_gps_dop	65.0
exif_gps_img_direction	122.052994
exif_gps_img_direction_ref	T
exif_gps_latitude	38.338686
exif_gps_latitude_ref	N
exif_gps_longitude	-81.610294
exif_gps_longitude_ref	W
exif_make	Apple
exif_model	iPhone XR
exif_orientation	NaN
exif_pixel_x_dimension	1080.0
exif_pixel_y_dimension	810.0
exif_software	Fulcrum iOS 2.27.0 (5525), iOS 14.4.2, Apple, iPhone XR
exif_x_resolution	72.0
exif_y_resolution	72.0

test\_app\_erosion\_or\_undermining\_pse11.csv

variable	value
fulcrum_id	0f43952b-2904-4741-ad5f-bb7a078f7dd9
fulcrum_parent_id	c1270b8b-67e0-4857-b82f-3c34145efdc1
fulcrum_record_id	c1270b8b-67e0-4857-b82f-3c34145efdc1
version	1
latitude	NaN
longitude	NaN
geometry	NaN
created_at	2021-01-07 19:40:32 UTC
updated_at	2021-01-07 19:40:32 UTC
created_by	mike.a.king@wv.gov
updated_by	mike.a.king@wv.gov
deficiency_pse11dd	Coating exhibits oxidation or peeling
deficiency_non_standard_pse11dn	sample text
deficiency_criteria_pse11dcd	1% <= V/H < 2%
deficiency_criteria_non_standard_pse11dcn	sample text
element_rating_pse11er	3*
recommended_priority_pse11rp	Medium
recommendation_pse11rd	No recommendation or replace affected member if necessary.
recommendation_non_standard_pse11rm	sample text
supplemental_information_pse11si	sample text
referenced_photos_pse11rp	sample text

test\_app\_erosion\_or\_undermining\_tse13.csv

variable	value
fulcrum_id	3049a8fc-1e25-4184-b0b5-1bf739599ade
fulcrum_parent_id	c1270b8b-67e0-4857-b82f-3c34145efdc1
fulcrum_record_id	c1270b8b-67e0-4857-b82f-3c34145efdc1
version	1

latitude	variable	value
longitude		NaN
geometry		NaN
created_at		2021-01-07 19:36:48 UTC
updated_at		2021-01-07 19:36:48 UTC
created_by		mike.a.king@wv.gov
updated_by		mike.a.king@wv.gov
deficiency_tse13dd		Coating exhibits oxidation/peeling.
deficiency_non_standard_tse13dn		sample text
deficiency_criteria_tse13dcd		standard hole, not conditional
deficiency_criteria_non_standard_tse13dcn		sample text
element_rating_tse13er		3
recommended_priority_tse13rp		Low
recommendation_tse13rd		No recommendation or brace/straighten affected member if necessary.
recommendation_non_standard_tse13rm		sample text
supplemental_information_tse13si		sample text
referenced_photos_tse13rp		sample text

## test\_app\_erosionundermining\_sse19.csv

latitude	variable	value
longitude		NaN
geometry		NaN
created_at		2020-10-29 18:25:58 UTC
updated_at		2020-10-29 18:25:58 UTC
created_by		mike.a.king@wv.gov
updated_by		mike.a.king@wv.gov
deficiency_sse19dd		Coating exhibits oxidation or peeling.
deficiency_non_standard_sse19dn		a broken bolt
deficiency_criteria_sse19dcd		2 or more nuts in a 4 bolt configuration, OR 2 or more nuts in a 6 bolt configuration, OR 3 or more nuts in an 8 or more bolt configuration
deficiency_criteria_non_standard_sse19dcn		a broken bolt
element_rating_sse19er		3
recommended_priority_sse19rp		Low
recommendation_sse19rd		No recommendation.
recommendation_non_standard_sse19rm		a broken bolt
supplemental_information_sse19si		a broken bolt
referenced_photos_sse19rp		41

## test\_app\_general\_alignment\_of\_structure\_pse2.csv

latitude	variable	value
longitude		NaN
geometry		NaN
created_at		2021-01-07 19:38:13 UTC
updated_at		2021-01-07 19:38:13 UTC
created_by		mike.a.king@wv.gov
updated_by		mike.a.king@wv.gov
deficiency_pse2dd		Coating exhibits oxidation or peeling.
deficiency_non_standard_pse2dn		sample text
deficiency_criteria_pse2dcd		W <= 1/16"
deficiency_criteria_non_standard_pse2dcn		sample text
element_rating_pse2er		3
recommended_priority_pse2rp		Medium
recommendation_pse2rd		Notify Project Manager
recommendation_non_standard_pse2rm		sample text
supplemental_information_pse2si		sample text
referenced_photos_pse2rp		sample text

## test\_app\_general\_alignment\_of\_structure\_sse3.csv

latitude	variable	value
longitude		NaN
geometry		NaN
created_at		2020-10-29 15:25:57 UTC
updated_at		2020-10-29 15:25:57 UTC

variable	value
created_by	mike.a.king@wv.gov
updated_by	mike.a.king@wv.gov
deficiency_sse3dd	Bullet holes in or graffiti on sign panel
deficiency_non_standard_sse3dn	a broken bolt
deficiency_criteria_sse3dcd	2 nuts in an 8 or more bolt configuration
deficiency_criteria_non_standard_sse3dcn	a broken bolt
element_rating_sse3er	2
recommended_priority_sse3rp	Medium
recommendation_sse3rd	No recommendation or brace/straighten affected member if necessary.
recommendation_non_standard_sse3rm	a broken bolt
supplemental_information_sse3si	a broken bolt
referenced_photos_sse3rp	15

### test\_app\_general\_alignment\_of\_structure\_tse3.csv

variable	value
fulcrum_id	8d7bfa13-e186-45e4-acc5-2edec620157a
fulcrum_parent_id	c1270b8b-67e0-4857-b82f-3c34145efdc1
fulcrum_record_id	c1270b8b-67e0-4857-b82f-3c34145efdc1
version	1
latitude	NaN
longitude	NaN
geometry	NaN
created_at	2021-01-07 19:34:08 UTC
updated_at	2021-01-07 19:34:08 UTC
created_by	mike.a.king@wv.gov
updated_by	mike.a.king@wv.gov
deficiency_tse3dd	Coating exhibits oxidation/peeling.
deficiency_non_standard_tse3dn	sample text
deficiency_criteria_tse3dcd	2 or more nuts in a 4 bolt configuration, OR 2 or more nuts in a 6 bolt configuration, OR 3 or more nuts in an 8 or more bolt configuration
deficiency_criteria_non_standard_tse3dcn	sample text
element_rating_tse3er	2
recommended_priority_tse3rp	Low
recommendation_tse3rd	No recommendation or brace/straighten affected member if necessary.
recommendation_non_standard_tse3rm	sample text
supplemental_information_tse3si	sample text
referenced_photos_tse3rp	sample text

### test\_app\_general\_appearance\_of\_luminaire\_heads\_cameras\_or\_other\_attachments\_pse1.csv

variable	value
fulcrum_id	ede5e53c-aa91-49c7-bcf2-138a72215377
fulcrum_parent_id	c1270b8b-67e0-4857-b82f-3c34145efdc1
fulcrum_record_id	c1270b8b-67e0-4857-b82f-3c34145efdc1
version	1
latitude	NaN
longitude	NaN
geometry	NaN
created_at	2021-01-07 19:37:56 UTC
updated_at	2021-01-07 19:37:56 UTC
created_by	mike.a.king@wv.gov
updated_by	mike.a.king@wv.gov
deficiency_pse1dd	Coating exhibits oxidation or peeling.
deficiency_non_standard_pse1dn	sample text
deficiency_criteria_pse1dcd	1/16" < W < 1/8"
deficiency_criteria_non_standard_pse1dcn	sample text
element_rating_pse1er	1
recommended_priority_pse1rp	Low
recommendation_pse1rd	No recommendation.
recommendation_non_standard_pse1rm	sample text
supplemental_information_pse1si	sample text
referenced_photos_pse1rp	sample text

### test\_app\_general\_appearance\_of\_signal\_head\_or\_other\_attachments\_tse2.csv

variable	value
fulcrum_id	aab7d04f-8025-4fbd-a658-76daa21584f0
fulcrum_parent_id	c1270b8b-67e0-4857-b82f-3c34145efdc1
fulcrum_record_id	c1270b8b-67e0-4857-b82f-3c34145efdc1
version	1
latitude	NaN
longitude	NaN
geometry	NaN
created_at	2021-01-07 19:33:53 UTC
updated_at	2021-01-07 19:33:53 UTC
created_by	mike.a.king@wv.gov
updated_by	mike.a.king@wv.gov
deficiency_tse2dd	Coating exhibits oxidation or peeling.
deficiency_non_standard_tse2dn	sample text

deficiency_criteria_tse2dcd	variable	15% <= section loss < 25%	value
deficiency_criteria_non_standard_tse2dcn		sample text	
element_rating_tse2er		2*	
recommended_priority_tse2rp		Medium	
recommendation_tse2rd		No recommendation or brace/straighten affected member if necessary.	
recommendation_non_standard_tse2m		sample text	
supplemental_information_tse2si		sample text	
referenced_photos_tse2rp		sample text	

## test\_app\_general\_condition\_appearance\_of\_signs\_luminaires\_or\_other\_attachments\_sse2.csv

	variable	value
fulcrum_id		95b7e867-0685-4022-ba67-1f5415afc5e8
fulcrum_parent_id		c1270b8b-67e0-4857-b82f3c34145efdc1
fulcrum_record_id		c1270b8b-67e0-4857-b82f3c34145efdc1
version		1
latitude		NaN
longitude		NaN
geometry		NaN
created_at		2020-10-29 15:25:32 UTC
updated_at		2020-10-29 15:25:32 UTC
created_by		mike.a.king@wv.gov
updated_by		mike.a.king@wv.gov
deficiency_sse2dd		Bent member.
deficiency_non_standard_sse2dn		a broken bolt
deficiency_criteria_sse2dcd		2 nuts in an 8 or more bolt configuration
deficiency_criteria_non_standard_sse2dcn		a broken bolt
element_rating_sse2er		3
recommended_priority_sse2rp		Medium
recommendation_sse2rd		Lower base plate to allow proper base to foundation gap or analyze for engineered solution.
recommendation_non_standard_sse2m		a broken bolt
supplemental_information_sse2si		a broken bolt
referenced_photos_sse2rp		12

## test\_app\_grout\_pse12.csv

	variable	value
fulcrum_id		e19675d9-84cc-49c0-b802-9ec6f2149f49
fulcrum_parent_id		c1270b8b-67e0-4857-b82f3c34145efdc1
fulcrum_record_id		c1270b8b-67e0-4857-b82f3c34145efdc1
version		1
latitude		NaN
longitude		NaN
geometry		NaN
created_at		2021-01-07 19:40:46 UTC
updated_at		2021-01-07 19:40:46 UTC
created_by		mike.a.king@wv.gov
updated_by		mike.a.king@wv.gov
deficiency_pse12dd		Connection hardware loose, missing, or broken at arm connection to pole.
deficiency_non_standard_pse12dn		sample text
deficiency_criteria_pse12dcd		1 or more nuts in a 4 bolt configuration, OR 2 or more nuts in a 6 bolt configuration, OR 3 or more nuts in an 8 or more bolt configuration
deficiency_criteria_non_standard_pse12dcn		sample text
element_rating_pse12er		4
recommended_priority_pse12rp		Medium
recommendation_pse12rd		Notify Project Manager
recommendation_non_standard_pse12m		sample text
supplemental_information_pse12si		sample text
referenced_photos_pse12rp		sample text

## test\_app\_grout\_sse20.csv

	variable	value
fulcrum_id		cb3f0794-d786-4e10-807b-0199bddc00aa
fulcrum_parent_id		c1270b8b-67e0-4857-b82f3c34145efdc1
fulcrum_record_id		c1270b8b-67e0-4857-b82f3c34145efdc1
version		1
latitude		NaN
longitude		NaN
geometry		NaN
created_at		2020-10-29 18:26:16 UTC
updated_at		2020-10-29 18:26:16 UTC
created_by		mike.a.king@wv.gov
updated_by		mike.a.king@wv.gov
deficiency_sse20dd		Chord connection plate or arm plate broken or cracked.
deficiency_non_standard_sse20dn		a broken bolt
deficiency_criteria_sse20dcd		20% <= through bolts (total) or adhesive/expansion anchorage nuts (total) loose < 40%
deficiency_criteria_non_standard_sse20dcn		a broken bolt
element_rating_sse20er		2*
recommended_priority_sse20rp		Low
recommendation_sse20rd		Notify Project Manager

variable	value
recommendation_non_standard_sse20si	a broken bolt
supplemental_information_sse20si	a broken bolt
referenced_photos_sse20rp	60

## test\_app\_grout\_tse14.csv

variable	value
fulcrum_id	9898526c-0a77-4e81-bea8-215c54812f3e
fulcrum_parent_id	c1270b8b-67e0-4857-b82f-3c34145efdc1
fulcrum_record_id	c1270b8b-67e0-4857-b82f-3c34145efdc1
version	1
latitude	NaN
longitude	NaN
geometry	NaN
created_at	2021-01-07 19:37:06 UTC
updated_at	2021-01-07 19:37:06 UTC
created_by	mike.a.king@wv.gov
updated_by	mike.a.king@wv.gov
deficiency_tse14dd	Coating exhibits oxidation or peeling at signal head, sign, antenna, camera, or sensor.
deficiency_non_standard_tse14dn	sample text
deficiency_criteria_tse14dcd	some evidence of standing water
deficiency_criteria_non_standard_tse14dcn	sample text
element_rating_tse14er	3*
recommended_priority_tse14rp	Medium
recommendation_tse14rd	No recommendation.
recommendation_non_standard_tse14m	sample text
supplemental_information_tse14si	sample text
referenced_photos_tse14rp	sample text

## test\_app\_luminaire\_arm\_pse8.csv

variable	value
fulcrum_id	37ef1d20-6b18-4013-b93d-390476e9490c
fulcrum_parent_id	c1270b8b-67e0-4857-b82f-3c34145efdc1
fulcrum_record_id	c1270b8b-67e0-4857-b82f-3c34145efdc1
version	1
latitude	NaN
longitude	NaN
geometry	NaN
created_at	2021-01-07 19:39:48 UTC
updated_at	2021-01-07 19:39:48 UTC
created_by	mike.a.king@wv.gov
updated_by	mike.a.king@wv.gov
deficiency_pse8dd	Coating exhibits oxidation or peeling at the transformer base.
deficiency_non_standard_pse8dn	sample text
deficiency_criteria_pse8dcd	V/H < 1%
deficiency_criteria_non_standard_pse8dcn	sample text
element_rating_pse8er	3
recommended_priority_pse8rp	Low
recommendation_pse8rd	No recommendation.
recommendation_non_standard_pse8m	sample text
supplemental_information_pse8si	sample text
referenced_photos_pse8rp	sample text

## test\_app\_luminaire\_arm\_to\_pole\_connection\_pse7.csv

variable	value
fulcrum_id	22d53e65-0f7a-43cf-ac20-ade64cf85162
fulcrum_parent_id	c1270b8b-67e0-4857-b82f-3c34145efdc1
fulcrum_record_id	c1270b8b-67e0-4857-b82f-3c34145efdc1
version	1
latitude	NaN
longitude	NaN
geometry	NaN
created_at	2021-01-07 19:39:31 UTC
updated_at	2021-01-07 19:39:31 UTC
created_by	mike.a.king@wv.gov
updated_by	mike.a.king@wv.gov
deficiency_pse7dd	Coating exhibits oxidation or peeling at the transformer base.
deficiency_non_standard_pse7dn	sample text
deficiency_criteria_pse7dcd	no danger of collapse
deficiency_criteria_non_standard_pse7dcn	sample text
element_rating_pse7er	2*
recommended_priority_pse7rp	Medium
recommendation_pse7rd	Lower base plate to allow proper base to foundation gap or analyze for engineered solution.
recommendation_non_standard_pse7m	sample text
supplemental_information_pse7si	sample text
referenced_photos_pse7rp	sample text

test\_app\_luminaire\_heads\_cameras\_or\_other\_attachments\_to\_pole\_connections\_pse3.csv

variable	value
fulcrum_id	2358ebf3-e348-48fc-8569-43f4595d9d0b
fulcrum_parent_id	c1270b8b-67e0-4857-b82f-3c34145efdc1
fulcrum_record_id	c1270b8b-67e0-4857-b82f-3c34145efdc1
version	1
latitude	NaN
longitude	NaN
geometry	NaN
created_at	2021-01-07 19:38:28 UTC
updated_at	2021-01-07 19:38:28 UTC
created_by	mike.a.king@wv.gov
updated_by	mike.a.king@wv.gov
deficiency_pse3dd	Coating exhibits oxidation or peeling.
deficiency_non_standard_pse3dn	sample text
deficiency_criteria_pse3dcd	not affecting anchor bolts, with exposed reinforcing steel
deficiency_criteria_non_standard_pse3dcn	sample text
element_rating_pse3er	2*
recommended_priority_pse3rp	Medium
recommendation_pse3rd	No recommendation or replace affected member if necessary.
recommendation_non_standard_pse3rn	sample text
supplemental_information_pse3si	sample text
referenced_photos_pse3rp	sample text

test\_app\_other\_overhead\_attachment\_quantities\_and\_descriptions.csv

variable	value
fulcrum_id	bb2c8104-e899-4673-b503-5e729f9895cf
fulcrum_parent_id	c1270b8b-67e0-4857-b82f-3c34145efdc1
fulcrum_record_id	c1270b8b-67e0-4857-b82f-3c34145efdc1
version	1
latitude	NaN
longitude	NaN
geometry	NaN
created_at	2020-10-27 19:42:08 UTC
updated_at	2020-10-27 19:42:08 UTC
created_by	mike.a.king@wv.gov
updated_by	mike.a.king@wv.gov
other_overhead	Primary Mast Arm: 2 cameras, 3 antennas, 1 sensor.

test\_app\_other\_support\_leg\_or\_pole\_attachment\_quantities\_and\_descriptions.csv

variable	value
fulcrum_id	6bfb490f-d68c-48d8-95f3-5507f628a102
fulcrum_parent_id	c1270b8b-67e0-4857-b82f-3c34145efdc1
fulcrum_record_id	c1270b8b-67e0-4857-b82f-3c34145efdc1
version	1
latitude	0.001545
longitude	0.003498
geometry	POINT (0.003498 0.001545)
created_at	2020-10-27 19:45:03 UTC
updated_at	2020-10-27 19:45:03 UTC
created_by	mike.a.king@wv.gov
updated_by	mike.a.king@wv.gov
other_support_leg_or_pole	Right Support Leg: 1 sensor

test\_app\_pole\_base\_plate\_pse4.csv

variable	value
fulcrum_id	6d6ed57f-372a-4acd-94c4-04bfb4fb6405
fulcrum_parent_id	c1270b8b-67e0-4857-b82f-3c34145efdc1
fulcrum_record_id	c1270b8b-67e0-4857-b82f-3c34145efdc1
version	1
latitude	NaN
longitude	NaN
geometry	NaN
created_at	2021-01-07 19:38:44 UTC
updated_at	2021-01-07 19:38:44 UTC
created_by	mike.a.king@wv.gov
updated_by	mike.a.king@wv.gov
deficiency_pse4dd	Breakaway coupling assemblies too high. Height H" of coupler measured from top of foundation to bottom of coupler.
deficiency_non_standard_pse4dn	sample text
deficiency_criteria_pse4dcd	15% <= section loss < 25%
deficiency_criteria_non_standard_pse4dcn	sample text
element_rating_pse4er	1*
recommended_priority_pse4rp	Medium
recommendation_pse4rd	No recommendation or replace affected member if necessary.
recommendation_non_standard_pse4rn	sample text

supplemental_information_pse4si	variable	sample text	value
referenced_photos_pse4rp		sample text	

## test\_app\_pole\_or\_support\_leg\_welded\_joints\_note\_exclusively\_for\_welded\_splices\_in\_poles\_or\_support

variable	value
fulcrum_id	d42d3f80-e6a5-45b4-b6ce-c27f455a7b39
fulcrum_parent_id	c1270b8b-67e0-4857-b82f-3c34145efdc1
fulcrum_record_id	c1270b8b-67e0-4857-b82f-3c34145efdc1
version	1
latitude	NaN
longitude	NaN
geometry	NaN
created_at	2021-01-07 19:34:55 UTC
updated_at	2021-01-07 19:34:55 UTC
created_by	mike.a.king@wv.gov
updated_by	mike.a.king@wv.gov
deficiency_tse6dd	Coating exhibits oxidation/peeling.
deficiency_non_standard_tse6dn	sample text
deficiency_criteria_tse6dcd	some evidence of standing water
deficiency_criteria_non_standard_tse6den	sample text
element_rating_tse6er	2*
recommended_priority_tse6rp	Medium
recommendation_tse6rd	No recommendation or brace/straighten affected member if necessary.
recommendation_non_standard_tse6rn	sample text
supplemental_information_tse6si	sample text
referenced_photos_tse6rp	sample text

## test\_app\_pole\_pse6.csv

variable	value
fulcrum_id	d9624044-dafe-49d9-ac40-da20ca98f429
fulcrum_parent_id	c1270b8b-67e0-4857-b82f-3c34145efdc1
fulcrum_record_id	c1270b8b-67e0-4857-b82f-3c34145efdc1
version	1
latitude	NaN
longitude	NaN
geometry	NaN
created_at	2021-01-07 19:39:13 UTC
updated_at	2021-01-07 19:39:13 UTC
created_by	mike.a.king@wv.gov
updated_by	mike.a.king@wv.gov
deficiency_pse6dd	Top or leveling nuts missing or loose.
deficiency_non_standard_pse6dn	sample text
deficiency_criteria_pse6dcd	V/H >= 2%
deficiency_criteria_non_standard_pse6den	sample text
element_rating_pse6er	2
recommended_priority_pse6rp	Medium
recommendation_pse6rd	Notify Project Manager
recommendation_non_standard_pse6rn	sample text
supplemental_information_pse6si	sample text
referenced_photos_pse6rp	sample text

## test\_app\_pole\_slip\_joint\_pse5.csv

variable	value
fulcrum_id	536dbf17-5218-44b8-9ccd-d85cdc255928
fulcrum_parent_id	c1270b8b-67e0-4857-b82f-3c34145efdc1
fulcrum_record_id	c1270b8b-67e0-4857-b82f-3c34145efdc1
version	1
latitude	NaN
longitude	NaN
geometry	NaN
created_at	2021-01-07 19:38:59 UTC
updated_at	2021-01-07 19:38:59 UTC
created_by	mike.a.king@wv.gov
updated_by	mike.a.king@wv.gov
deficiency_pse5dd	Breakaway couplings broken, sheared, or cracked.
deficiency_non_standard_pse5dn	sample text
deficiency_criteria_pse5dcd	slotted/oversize hole, nut not embedded into hole
deficiency_criteria_non_standard_pse5den	sample text
element_rating_pse5er	3*
recommended_priority_pse5rp	Medium
recommendation_pse5rd	Lower/Retrofit/Replace affected components.
recommendation_non_standard_pse5rn	sample text
supplemental_information_pse5si	sample text
referenced_photos_pse5rp	sample text

## test\_app\_sign\_or\_other\_attachment\_to\_chord\_or\_arm\_connection\_sse4.csv



variable	value
fulcrum_id	56235e8d-f2d1-4461-9236-e91ae6df7326
fulcrum_parent_id	c1270b8b-67e0-4857-b82f-3c34145efdc1
fulcrum_record_id	c1270b8b-67e0-4857-b82f-3c34145efdc1
version	1
latitude	NaN
longitude	NaN
geometry	NaN
created_at	2020-10-29 15:26:17 UTC
updated_at	2020-10-29 15:26:17 UTC
created_by	mike.a.king@wv.gov
updated_by	mike.a.king@wv.gov
deficiency_sse4dd	Bent member.
deficiency_non_standard_sse4dn	a broken bolt
deficiency_criteria_sse4dcd	2 nuts in an 8 or more bolt configuration
deficiency_criteria_non_standard_sse4dcn	a broken bolt
element_rating_sse4er	3*
recommended_priority_sse4rp	Low
recommendation_sse4rd	No recommendation or brace/straighten affected member if necessary.
recommendation_non_standard_sse4rn	a broken bolt
supplemental_information_sse4si	a broken bolt
referenced_photos_sse4rp	15

## test\_app\_sign\_size\_area\_fab\_code\_text.csv

variable	value
fulcrum_id	2d57a097-1837-4f98-91cb-c9765f8e2a98
fulcrum_parent_id	c1270b8b-67e0-4857-b82f-3c34145efdc1
fulcrum_record_id	c1270b8b-67e0-4857-b82f-3c34145efdc1
version	1
latitude	NaN
longitude	NaN
geometry	NaN
created_at	2020-10-27 19:38:02 UTC
updated_at	2020-10-27 19:38:02 UTC
created_by	mike.a.king@wv.gov
updated_by	mike.a.king@wv.gov
sign	Sign 1: 16â€™™ x 11.5â€™™ / 184 sf / OTHER / I-64 I-77 I-79; Huntington; Parkersburg; JCT 2 MILES

## test\_app\_signal\_head\_or\_other\_attachment\_to\_arm\_or\_wire\_connection\_tse4.csv

variable	value
fulcrum_id	90b490eb-a1af-4560-bcbe-8612c5cd7577
fulcrum_parent_id	c1270b8b-67e0-4857-b82f-3c34145efdc1
fulcrum_record_id	c1270b8b-67e0-4857-b82f-3c34145efdc1
version	1
latitude	NaN
longitude	NaN
geometry	NaN
created_at	2021-01-07 19:34:24 UTC
updated_at	2021-01-07 19:34:24 UTC
created_by	mike.a.king@wv.gov
updated_by	mike.a.king@wv.gov
deficiency_tse4dd	Connection hardware loose or missing in arm tension splice.
deficiency_non_standard_tse4dn	sample text
deficiency_criteria_tse4dcd	2D < H <= 2D + 1"
deficiency_criteria_non_standard_tse4dcn	sample text
element_rating_tse4er	2
recommended_priority_tse4rp	Medium
recommendation_tse4rd	Regrade, install retaining wall, or relocate structure.
recommendation_non_standard_tse4rn	sample text
supplemental_information_tse4si	sample text
referenced_photos_tse4rp	sample text

## test\_app\_structural\_members\_of\_frame\_structures\_sse14.csv

variable	value
fulcrum_id	36969ea0-8375-4a45-868a-ec8d976d2afc
fulcrum_parent_id	c1270b8b-67e0-4857-b82f-3c34145efdc1
fulcrum_record_id	c1270b8b-67e0-4857-b82f-3c34145efdc1
version	1
latitude	NaN
longitude	NaN
geometry	NaN
created_at	2020-10-29 18:24:38 UTC
updated_at	2020-10-29 18:24:38 UTC
created_by	mike.a.king@wv.gov
updated_by	mike.a.king@wv.gov
deficiency_sse14dd	Coating exhibits oxidation or peeling at sign lighting luminaire housing

variable	value
deficiency_non_standard_sse14dn	a broken bolt
deficiency_criteria_sse14dcd	2 nuts in an 8 or more bolt configuration
deficiency_criteria_non_standard_sse14dcn	a broken bolt
element_rating_sse14er	2*
recommended_priority_sse14rp	Low
recommendation_sse14rd	Regrade, install retaining wall, or relocate structure.
recommendation_non_standard_sse14m	a broken bolt
supplemental_information_sse14si	a broken bolt
referenced_photos_sse14rp	94

test\_app\_support\_leg\_base\_or\_connection\_plate\_sse5.csv

variable	value
fulcrum_id	494e0b06-760e-45d0-9e58-4a2ec203393c
fulcrum_parent_id	c1270b8b-67e0-4857-b82f3c34145efdc1
fulcrum_record_id	c1270b8b-67e0-4857-b82f3c34145efdc1
version	1
latitude	NaN
longitude	NaN
geometry	NaN
created_at	2020-10-29 15:26:41 UTC
updated_at	2020-10-29 15:26:41 UTC
created_by	mike.a.king@wv.gov
updated_by	mike.a.king@wv.gov
deficiency_sse5dd	Bullet holes in or graffiti on sign panel
deficiency_non_standard_sse5dn	a broken bolt
deficiency_criteria_sse5dcd	2 or more nuts in a 4 bolt configuration, OR 2 or more nuts in a 6 bolt configuration, OR 3 or more nuts in an 8 or more bolt configuration
deficiency_criteria_non_standard_sse5dcn	a broken bolt
element_rating_sse5er	2
recommended_priority_sse5rp	Medium
recommendation_sse5rd	No recommendation.
recommendation_non_standard_sse5m	a broken bolt
supplemental_information_sse5si	a broken bolt
referenced_photos_sse5rp	18

test\_app\_support\_leg\_or\_pole\_base\_plate\_tse5.csv

variable	value
fulcrum_id	1cf67e4b-a4e0-4f3c-b109-1f4fbad05a01
fulcrum_parent_id	c1270b8b-67e0-4857-b82f3c34145efdc1
fulcrum_record_id	c1270b8b-67e0-4857-b82f3c34145efdc1
version	1
latitude	NaN
longitude	NaN
geometry	NaN
created_at	2021-01-07 19:34:39 UTC
updated_at	2021-01-07 19:34:39 UTC
created_by	mike.a.king@wv.gov
updated_by	mike.a.king@wv.gov
deficiency_tse5dd	Coating exhibits oxidation or peeling at signal head, sign, antenna, camera, or sensor.
deficiency_non_standard_tse5dn	sample text
deficiency_criteria_tse5dcd	15% <= section loss < 30%
deficiency_criteria_non_standard_tse5dcn	sample text
element_rating_tse5er	2*
recommended_priority_tse5rp	Medium
recommendation_tse5rd	Lower structure, retrofit short anchor bolt assembly to restore full capacity, or analyze for engineered solution.
recommendation_non_standard_tse5m	sample text
supplemental_information_tse5si	sample text
referenced_photos_tse5rp	sample text

test\_app\_support\_leg\_or\_pole\_tse7.csv

variable	value
fulcrum_id	16255514-0efa-42d1-8b55-545612e4eb33
fulcrum_parent_id	c1270b8b-67e0-4857-b82f3c34145efdc1
fulcrum_record_id	c1270b8b-67e0-4857-b82f3c34145efdc1
version	1
latitude	NaN
longitude	NaN
geometry	NaN
created_at	2021-01-07 19:35:10 UTC
updated_at	2021-01-07 19:35:10 UTC
created_by	mike.a.king@wv.gov
updated_by	mike.a.king@wv.gov
deficiency_tse7dd	Coating exhibits oxidation or peeling.
deficiency_non_standard_tse7dn	sample text
deficiency_criteria_tse7dcd	tension member
deficiency_criteria_non_standard_tse7dcn	sample text
element_rating_tse7er	2

recommended_priority_tse7rp	High
recommendation_tse7rd	Regrade around affected components.
recommendation_non_standard_tse7m	sample text
supplemental_information_tse7si	sample text
referenced_photos_tse7rp	sample text

test\_app\_support\_leg\_sse8.csv

variable	value
fulcrum_id	85fa120e-9825-4d9e-9176-c436950851c3
fulcrum_parent_id	c1270b8b-67e0-4857-b82F-3c34145efdc1
fulcrum_record_id	c1270b8b-67e0-4857-b82F-3c34145efdc1
version	1
latitude	NaN
longitude	NaN
geometry	NaN
created_at	2020-10-29 15:30:41 UTC
updated_at	2020-10-29 15:30:41 UTC
created_by	mike.a.king@wv.gov
updated_by	mike.a.king@wv.gov
deficiency_sse8dd	Chord connection plate or arm plate broken or cracked.
deficiency_non_standard_sse8dn	a broken bolt
deficiency_criteria_sse8dcd	15% <= through bolts (total) or adhesive/expansion anchorage nuts (total) missing < 30%
deficiency_criteria_non_standard_sse8den	a broken bolt
element_rating_sse8er	3*
recommended_priority_sse8rp	Medium
recommendation_sse8rd	Notify Project Manager
recommendation_non_standard_sse8m	a broken bolt
supplemental_information_sse8si	a broken bolt
referenced_photos_sse8rp	49

test\_app\_support\_leg\_trussing\_sse6.csv

variable	value
fulcrum_id	08881ab6-8d20-4928-82f6-98ea13706d88
fulcrum_parent_id	c1270b8b-67e0-4857-b82F-3c34145efdc1
fulcrum_record_id	c1270b8b-67e0-4857-b82F-3c34145efdc1
version	1
latitude	NaN
longitude	NaN
geometry	NaN
created_at	2020-10-29 15:30:01 UTC
updated_at	2020-10-29 15:30:01 UTC
created_by	mike.a.king@wv.gov
updated_by	mike.a.king@wv.gov
deficiency_sse6dd	Chord connection plate or arm plate broken or cracked.
deficiency_non_standard_sse6dn	a broken bolt
deficiency_criteria_sse6dcd	15% <= through bolts (total) or adhesive/expansion anchorage nuts (total) missing < 30%
deficiency_criteria_non_standard_sse6den	a broken bolt
element_rating_sse6er	1*
recommended_priority_sse6rp	Medium
recommendation_sse6rd	Notify Project Manager
recommendation_non_standard_sse6m	a broken bolt
supplemental_information_sse6si	a broken bolt
referenced_photos_sse6rp	29

test\_app\_support\_leg\_welded\_joints\_note\_exclusively\_for\_welded\_splices\_in\_support\_legs\_not\_truss\_to

variable	value
fulcrum_id	80ccc989-f7d9-44c5-b8fa-ccdec20a1874
fulcrum_parent_id	c1270b8b-67e0-4857-b82F-3c34145efdc1
fulcrum_record_id	c1270b8b-67e0-4857-b82F-3c34145efdc1
version	1
latitude	NaN
longitude	NaN
geometry	NaN
created_at	2020-10-29 15:30:23 UTC
updated_at	2020-10-29 15:30:23 UTC
created_by	mike.a.king@wv.gov
updated_by	mike.a.king@wv.gov
deficiency_sse7dd	Bullet holes in or graffiti on sign panel
deficiency_non_standard_sse7dn	a broken bolt
deficiency_criteria_sse7dcd	2 or more nuts in a 4 bolt configuration, OR 2 or more nuts in a 6 bolt configuration, OR 3 or more nuts in an 8 or more bolt configuration
deficiency_criteria_non_standard_sse7den	a broken bolt
element_rating_sse7er	3*
recommended_priority_sse7rp	High
recommendation_sse7rd	Remove excess washers.
recommendation_non_standard_sse7m	a broken bolt
supplemental_information_sse7si	a broken bolt
referenced_photos_sse7rp	48

variable	value
----------	-------