

Stepper Mount Spindle:

The stepper for the spindle is mounted on top of the spindle. It is driving the spindle using a gear and an idler gear. Using a lever, the stepper can be engaged. When engaged, the stepper is also driving the original lathe motor.

The stepper and gearbox slide in a holder. The lever, mounted a-centric, is either pressing the stepper (gear) on the spindle gear or lifting the stepper of the spindle gear. The original (steel) lathe T20 gear is driving the original (POM) lathe T50 idler gear that is driving the original T45 gear on the spindle. The holder is mounted on a bracket that is 1.5 mm adjustable in height. The screw holes for the cover are used to mount the bracket.

It is a lot easier to mount the stepper below the spindle, using the tumbler assembly to engage the stepper.

Gears:

T50 gear (POM) between the spindle and the stepper (idler gear)

T20 gear (Steel) on the stepper

Power supply:

20 V

Stepper:

The Nema 24 stepper has more torque for threading large diameters in tough steel like M40 Cr42Mo4

Nema 23 57BYGH627

4 wires, 2 phase

200 steps

1.9 Nm at 3A

Nema 24 24HS39-3008D

8 wires, 2 phase

200 steps

4 Nm at 4.24A

TB6600 settings

Nema 23 57BYGH627

Nema 24 24HS39-3008D

Excitation 8

Excitation 8

(1 for threading large diameter)

(1 for threading large diameter)

GRBL settings:

\$101

C-axis resolution

120

steps/mm = steps/°

\$112

C-axis max rate

30000

mm/min = °/min


\$122

Z-axis acceleration


1.250

mm/s² = °/s²

Stepper lifted, gears disengaged:



Stepper lowered gears engaged:




Stepper Holder disassembled:



Stepper gearbox disassembled:



Stepper gearbox and holder assembled:



Stepper assembly mounted on top of lathe spindle:

