


emco

innovative machine tools



SIEMENS 840D 50/55 MILL TRAINING GUIDE


10/15/03 Version 1
Made by EMCO
Authored by Chad Hawk

Training Index


Control Keyboard	Pg 1
• Siemens 840D Control	
• Machine Control	
Siemens 840D Screen	Pg 2
Siemens 840D Keys	Pg 3
Address and Numeric keyboard	Pg 4
• Vertical Soft Key Module	
• Horizontal Soft Key Module	
Machine Keys	Pg 5
• Machine Function Keys	
Direction Keys	Pg 6
• Spindle Override Keys	
• Accessory Functions	
Mode Dial	Pg 7
• Feed Override Dial	
Pc Keyboard Keys	Pg 8
Referencing the Machine	Pg 9
Work Shift Description (Picture)	Pg 10
Work Shift (How to do Work Shift)	Pg 11
Tool Offset Description (Picture)	Pg 13

Tool Offset (Setup of Tools)	Pg 14
• Creating Tools	
Tool Offset (How to do Tool Offsets for X)	Pg 15
• Manually programming Turret Index	
• Manually programming Spindle on	
Tool Offset (How to do Tool Offsets for Z)	Pg 16
Program Training.....	Pg 19
Needed tooling	Pg 20
Starting a Work folder	Pg 21
Starting a Main Program File (MPF)	Pg 22
• Starting a Sub Program File (SPF)	
Demo 1 (creating a contour in Sub Program files)	Pg23
• (Using support pages from Siemens)	
Demo1 (Making a Main program file)	Pg 24
2-D Simulation (setup and running)	Pg 26
Saving & Reading programs out to a drive unit	Pg 27
Saving & Reading Offsets out to a drive unit	Pg 28
Run Program on the machine	Pg 29
Demo 2	Pg 30
Ball Hitch	Pg 34


CONTROL KEYBOARD



Siemens 840D CONTROL






MACHINE CONTROL



SIEMENS 840D SCREEN

Machine 1	Channel 1 2	AUTO 3	4		
Channel reset 5		6		Trans./G function	
Program aborted 7		ROV 8			
9				Auxiliary function	
WCS		Position		Dist-to-go	
X	3.2283	inch	0.0000		
Z	3.1890	inch	0.0000		
10		Master spindle		S1	
		Act.		0.000 rpm	
		Set		0.000 rpm	
		Pos		0.0000 deg	
				100.0000 %	
		Power [%]		<input type="text"/>	
Actual block		11		Feedrate	
				inch/min	
		Act.		0.000 100.0000 %	
		Set 10		0.000	
		Tool			
		Preselected tool: 10			
		T-1			
		G00		G40	
13		14		15	
Program control 16		Block search		Correct program	
				Program overview 17	

1. Display of the active Operating Area
2. Display of the active channel
3. Operating mode, when a sub mode is active, it also will be displayed (e.g. REF, INC)
4. Program path and name of the selected program
5. Channel status
6. Channel operating messages
7. Program status
8. Channel status display (SKIP, DRY, SBL)
9. Alarm and message line
10. Working window, NC display the working windows (program editor) and NC displays (feed, tool) available in the active Operating Area are displayed here.
11. The selected window is marked with a border and the headline is displayed inverted. The keyboard inputs are effective here.
12. Vertical soft keys These 8 fields show the functions of the keys right beside. (at the PC: Shift F1..F8)
13. When this symbol is displayed, the key  is active (jump back to superior menu is possible).
14. Dialogue line with operator notes
15. When this symbol is displayed, the key  is active (information available).
16. Horizontal soft keys These 8 fields show the functions of the keys below. (at the PC: F1..F8)
17. When this symbol is displayed, the key  is active (more soft key functions available in this line).

SIEMENS 840D KEYS



= Direct jump to the Operating Area Machine



= Jump back to the superior menu (recall)



= Expanding the soft key line in the same menu



= Show basic menu (selection Operating Areas)

If pressed again jump back to the previous menu



= Confirm alarm



= Show information for the actual operating status - works only when the dialogue line shows an "i".



= Select window (when several windows are on the screen)
Keyboard inputs are valid for the selected window only.



= Cursor down / up



= Cursor left / right



= Leaf backward / forward



= Blank



= Clear (Backspace)



= Selection key / Toggle key

- Selection of predefined input values in input fields and lists, which are marked with this symbol
- Activate / deactivate switch box / radio button

☒ ☒ = active
☐ ☐ = not active



= Edit key / Undo

- Switch to edit mode in tables and input fields
- Undo function for table elements and input fields (leaving a field with this key does not store the entered value but reestablishes the old value)



= End Jump to line end (list end)




= Input key

- Take over an edited value
- Open / close directory
- Open file




= Shift key



Address and Numeric Keyboard

The shift key bottom left shifts to the second key function (indicated in the left top edge of the keys).

Example:



Double-Shift Function

1 x Shift:

For the following key press the second key function will be done, for all following inputs the first key function.

2 x Shift:

For all following key presses the second key function will be done (shift lock).

3 x Shift:


For the following key press the first key function will be done, for all following inputs the second key function.

4 x Shift:

Deselect the 2x or 3x shift function.

VERTICAL SOFT KEY MODULE

HORIZONTAL SOFT KEY MODULE



MACHINE KEYS

MACHINE FUNCTION KEYS



= Press skip for any block lines with (/) (Slash) before block number will be skipped



= Press for test run without spindle on (remove raw material from vise)



= (Single piece) for continuous mode active only on automatic material loading



= (Optional stop) for programs with (m1)



= (Reset) cancels most alarms, resets program, interrupts programs




= (Single block) reads one block line at a time



= (Cycle stop) program hold, feed hold



= (Cycle start) program start




DIRECTION KEYS

These keys control axis directional movements

+4 & -4 = Additional axis

Feed stop (Red) / Feed start (Green)
Works all modes but EDIT & ZRN




SPINDLE OVERRIDE KEYS

Arrow key pointing right increase the Spindle speed (120% high)

Arrow key pointing left decrease the Spindle speed (50% low)

100% key jumps speed to 100%

Spindle stop (Red) / Spindle start (Green)
Works all modes except EDIT & ZRN



ACCESSORY FUNCTIONS

Arrow right door open

Arrow left door closed

Press for Rotary axis Indexing

Press once vise closed

Press once vise open


Press once coolant on

Press again coolant off

Press auxiliary drives on (Green)

Press auxiliary drives off (Red)

MODE DIAL



- (1) REF = Zero / Reference or Home mode
- (2) AUTO = Automatic mode for running a program
- (3) EDIT = Edit mode for program changes or entering a new program
- (4) MDI = Manual Data Input mode for manually running the machine
- (5) JOG = Manual moving the axis in X, Y, Z
- (6) STEPS = Incremental feed movements
- (7) STEPS = .0001 or tenths
- (8) STEPS = .001 or thousands
- (9) STEPS = .010 or ten thousands
- (10) STEPS = .100 or hundred thousands
- (11) STEPS = .100 or hundred thousands

FEED OVERRIDE DIAL




Controls feed for jogging in the X, Y, Z Axis.
Overrides from 0% to 120% of the
programmed feed rate or the rapid rate


Turning Machine On/Entering Siemens Software

Referencing the Machine

1. Move the MODE dial to ZRN position also know as Reference make sure your feed rate is not on "0"




2. Make sure the Door is closed
3. Press the Z+ (arrow pointing up) this references the Z axis. (Wait until Z is fully reference)
4. Press the X- (arrow pointing left) this references the X axis
5. Press the Y- (arrow pointing left) this references the Y axis



Note: Every time you enter Siemens Software or Turn the Machine On you must reference the axis

WORK SHIFT

Pages 10 – 18 is setting the Work shift & offsets to the lower left corner & the top of the part with the Spindle nose



Reference points in the working area

Reference Points of the EMCO Milling Machines

M = Machine zero point

An unchangeable reference point established by the machine manufacturer.

Proceeding from this point the entire machine is measured.

At the same time "M" is the origin of the coordinate system.

R = Reference point

A position in the machine working area which is determined exactly by limit switches. The slide positions are reported to the control by the slides approaching the "R".


Required after every power failure.

N = Tool mount reference point

Starting point for the measurement of the tools. "N" lies at a suitable point on the tool holder system and is established by the machine manufacturer.

W = Workpiece zero point

Starting point for the dimensions in the part program. Can be freely established by the programmer and moved as desired within the part program.



This is a example only Work Shift can be placed anywhere on the part

Work Shift:


1. Move the MODE dial to JOG position
2. Jog the Spindle nose to the top of the


Work Piece & touch using the Direction keys.




Note: Use Feed Dial or Steps to approach at a slower feed rate.

Use piece of paper between nose and Work Piece



3. Press the  button on the horizontal soft keys
4. Press the **Blue** horizontal soft key for **Parameter** F2 (Picture 1)
5. Press the **Blue** horizontal soft key for **Work offset** F4 (Picture 1)
6. Cursor down to Z using cursor keys
7. Press the Blue vertical soft key **Accept position** (Picture 2)
Write the value down
(This value is the distance from the Spindle Nose to the end of the Work Piece)
8. Press the **Blue** vertical soft key for **Save** (Picture 2)

Picture 1 →



WinNC SINUMERIK 840D MILL (c) Emco

Machine Channel 1 JOG WKS.DIR/DEMO1.WPD
DEMO1.MPF

Channel reset
Program aborted

ROV

WCS	Position	Dist-to-go
X	11.2691 inch	0.0000
Y	4.2315 inch	0.0000
Z	8.3524 inch	0.0000

Master spindle S1


Act. 0.000 rpm
Set 0.000 rpm
Pos 0.0000 deg
100.0000 %
Power [%]

Feederate inch/min
Act. 0.000 95.0000 %
Set 0.000

Tool
Preselected tool:
T-1
G01 G40

Machine F1 Parameter F2 Program F3 Services F4 Diagnosis F5 F6 F7 F8

Picture 2 →



WinNC SINUMERIK 840D MILL (c) Emco

Parameter Channel 1 JOG WKS.DIR/DEMO1.WPD
DEMO1.MPF

Channel reset
Program aborted

ROV







Settable work offset

\$P_UIFR [1] G code G54

Axis	Offset		Position	Rotation (degree)	Scale	Mirroring
	Coarse	Fine				
X	0.0000	0.0000	7.8309 inch	0.000	1.0000	<input type="checkbox"/>
Y	0.0000	0.0000	0.9582 inch	0.000	1.0000	<input type="checkbox"/>
Z	2.2734	0.0000	2.2734 inch	0.000	1.0000	<input type="checkbox"/>


Selected WO
Overview
Accept position
Determine WO
Reject
Save

Tool offset F1 R variables F2 Setting data F3 Work offset F4 F5 F6 F7 F8


9. Jog Spindle up away from WORK PIECE using Z+
10. Place a edge finder or tool in the Spindle (Example uses 3/8 end mill)
11. Move the MODE Dial to MDI position
12. Press the  button on the horizontal soft keys then press **Blue** horizontal soft key for 
13. Press the  button on the horizontal soft keys for active screen on MDI program
14. Type S1000  M3 then press input button 
S1000 = Spindle speed M3 = spindle on clockwise
15. Press CYCLE START  (make sure door is closed)
16. Move the MODE Dial to JOG position
17. Jog the Tool to the left side of the Work Piece & touch using the Direction keys.




(Use Feed Override Dial or Steps to approach at a slower feed)



Note: Machine 0 in X is the center of the spindle to the left side of the Machine bed.

18. Press the  button on the horizontal soft keys
19. Press the **Blue** horizontal soft key for **Parameter** F2 (Picture 1)
20. Press the **Blue** horizontal soft key for **Work offset** F4 (Picture 1)
21. Cursor down to X using cursor keys
22. Press the Blue vertical soft key **Accept position** ↑F5 (Picture 2)
- Write the value down
(This value is the distance from the left end of the table to the left side of the Work Piece)
23. Press the **Blue** vertical soft key for **Save** ↑F6 (Picture 2)

Picture 1




WCS	Position	Dist-to-go
X	11.2691 inch	0.0000
Y	4.2315 inch	0.0000
Z	8.3524 inch	0.0000

Master spindle S1	
Act.	0.000 rpm
Set	0.000 rpm
Pos	0.0000 deg
	100.0000 %
Power [%]	

Feedrate inch/min	
Act.	0.000 95.0000 %
Set	0.000

Tool	
Preselected tool: ▶T-1	
G01	G40


Picture 2





Axis	Offset		Position	Rotation (degree)	Scale	Mirroring
	Coarse	Fine				
X	7.5977	0.0000	7.5977 inch	0.000	1.0000	<input type="checkbox"/>
Y	0.0000	0.0000	0.9582 inch	0.000	1.0000	<input type="checkbox"/>
Z	2.2734	0.0000	2.2734 inch	0.000	1.0000	<input type="checkbox"/>

24. Spindle up away from WORK PIECE using Z+
25. Jog the Tool to the Front of the Work Piece & touch using the Direction keys.


(Use Feed Dial or Steps to approach at a slower feed)



Note: Machine 0 in Y is the center of the spindle to the Front of the Machine bed.

26. Press the  button on the horizontal soft keys
27. Press the **Blue** horizontal soft key for **Parameter** F2 (Picture 1)
28. Press the **Blue** horizontal soft key for **Work offset** F4 (Picture 1)
29. Cursor down to Y using cursor keys 
30. Press the **Blue** vertical soft key **Accept position** ↑F5 (Picture 2)
Write the value down
(This value is the distance from the left end of the table to the left side of the Work Piece)
31. Press the **Blue** vertical soft key for **Save** ↑F6 (Picture 2)

Picture 1



WinNC SINUMERIK 840D MILL (c) Emco

Machine Channel 1 JOG WKS.DIR\DEMO1.WPD
Channel reset DEMO1.MPF
Program aborted

ROV

%	WCS	Position	Dist-to-go
X		11.2691 inch	0.0000
Y		4.2315 inch	0.0000
Z		8.3524 inch	0.0000

Master spindle S1


Act. 0.000 rpm
Set 0.000 rpm
Pos 0.0000 deg
100.0000 %
Power [%]

Feedrate Inch/min
Act. 0.000 95.0000 %
Set 0.000

Tool
Preselected tool:
T-1
G01 G40

Machine F1 Parameter F2 Program F3 Services F4 Diagnosis F5 F6 F7 F8

Picture 2



WinNC SINUMERIK 840D MILL (c) Emco

Parameter Channel 1 JOG WKS.DIR\DEMO1.WPD
Channel reset DEMO1.MPF
Program aborted

ROV

WO +
WO -

Selected WO
Overview
Accept position
Determine WO
Reject
Save

Settable work offset


\$P_UIFR [1] G code G54

Axis	Offset		Position	Rotation (degree)	Scale	Mirroring
	Coarse	Fine				
X	7.5977	0.0000	7.5977 inch	0.000	1.0000	<input type="checkbox"/>
Y	0.9582	0.0000	0.9582 inch	0.000	1.0000	<input type="checkbox"/>
Z	2.2734	0.0000	2.2734 inch	0.000	1.0000	<input type="checkbox"/>

Tool offset F1 R variables F2 Setting data F3 Work offset F4 F5 F6 F7 F8

32. Jog the Tool up above the Work Piece using Z+

TOOL OFFSET



WinNC SINUMERIK 840D MILL (c) Emco

Parameter Channel 1 JOG WKS.DIR\DEMO1.WPD
DEMO1.MPF

Channel reset
Program aborted

TO area 1

T number 1 D number 1 No. of c.edges 1
Tool type 100 Milling tool to CLDATA

Tool length comp.		Geometry	Wear	Base	
Length 1 :	0.0000	0.0000	0.0000	0.0000	inch
Length 2 :	0.0000	0.0000	0.0000	0.0000	inch
Length 3 :	0.0000	0.0000	0.0000	0.0000	inch

Radius compensation

Radius		Geometry	Wear	Base	
Radius :	0.0000	0.0000	0.0000	0.0000	inch
DP7,16 res:	0.0000	0.0000	0.0000	0.0000	
DP8,17 res:	0.0000	0.0000	0.0000	0.0000	
DP9,18 res:	0.0000	0.0000	0.0000	0.0000	
DP10,19 res:	0.0000	0.0000	0.0000	0.0000	
DP11,20 res:	0.0000	0.0000	0.0000	0.0000	





Technology


Clear.angle		Geometry	Wear	Base	
Clear.angle :	0.0000	0.0000	0.0000	0.0000	Deg.
DP25 res:	0.0000	0.0000	0.0000	0.0000	




Tool offset F1 R F2 Setting data F3 Work offset F4 F5 F6 F7 Determine F8 compensa.


Tool Offsets

When the Software is loaded there will be tools created already

- A. Press the **Blue** horizontal soft key for **Tool offset** 
- B. Press the **Blue** vertical soft key for **Overview** 
- C. Press the **Blue** vertical soft key for **Delete tool**  until there are no tools remaining
- D. Press the **Blue** vertical soft key for **Abort** 



1. Press the **Blue** vertical soft key for **New**  then press the **Blue** vertical soft key for **New tool** 
2. Cursor to the T number and type in 1
3. Cursor down to Tool type & type in 100 for Milling tool to CLDATA
4. Press the **Blue** vertical soft key for **OK** 



5. Place a tool to be measured in the spindle
6. Jog Tool tip down & touch the Top of the Work Piece
(Use Feed Dial or Steps to approach at a slower feed)

WinNC SINUMERIK 840D MILL (c) Emco

Parameter	Channel 1	JOG	\WKS.DIR\DEMO1.WPD DEMO1.MPF	
Channel reset				
Program aborted		ROV		


Tool offsets				TO area	1
T number	1	D number	1	No. of c.edges	1
Tool type	100	Milling tool to CLDATA			
Tool length comp.		Geometry	Wear	Base	
Length 1 :	0.0000	0.0000	0.0000	0.0000	inch
Length 2 :	0.0000	0.0000	0.0000	0.0000	inch
Length 3 :	0.0000	0.0000	0.0000	0.0000	inch
Radius compensation		inch			
Radius :	0.0000	0.0000			
DP7,16 res:	0.0000	0.0000			
DP8,17 res:	0.0000	0.0000			
DP9,18 res:	0.0000	0.0000			
DP10,19 res:	0.0000	0.0000			
DP11,20 res:	0.0000	0.0000			
Technology					
Clear.angle :	0.0000	Deg.			
DP25 res:	0.0000				

Tool offset	F1 R variables	F2 Setting data	F3 Work offset	F4	F5	F6	F7	F8 Determine compensa.
-------------	----------------	-----------------	----------------	----	----	----	----	------------------------


7. To set more Tools Repeat Steps 1thru 5
 - Drills & Taps need no Radius set for them

Program Training


Program O0001




Program O0003




Program O0005




Change the Mode Dial to Edit & Press the  to do functions below & on the next 2 Page

- **INSERT A NEW PROGRAM**


1. Press letter o then program number
2. Press insert button 

Example: Q0001 OR Q1

- **CALL A EXISTING PROGRAM UP**

1. Press letter o then program number
2. Press cursor down button 

- **INSERT A WORD**



1. Press letter then number
2. Press insert button 

Example: press once letter Q appears press again number 7 appears

HINT: When inserting a word place the cursor one word on the left before the place being inserted

Example: _N5 G01 X 0.25; G01 is the word being inserted

- **INSERT END OF BLOCK**


1. Press the (EOB) button 
2. Press insert button 

HINT: at the end of each number line needs an End Of Block looks like a Semicolon (;)

Example: N5 G01 X1.00 F.003;


NOTE: IN EDIT & IN PROGRAM USE INSERT ONLY.
USE INPUT ALL OTHER APPLICATIONS.

- **DELETE A PROGRAM**

1. Press letter o then program number
2. Press delete button 


Example: O0001 OR O1

- **DELETE ALL PROGRAMS**

1. Press letter o plus the – & 9999
2. Press delete button 

Example: O – 9999

- **DELETE A WORD**

1. Press letter then number
2. Press delete button 


Example: press once S appears press again 0 appears

HINT: Deleting a word; place the cursor on the left side
before the word being deleted

Example: BEFORE N5_S1000; AFTER N5;

(S1000) is the word being deleted?

- **DELETE A BLOCK OR LINE NUMBER**

1. Type the number line
2. Press delete button 

Example: _N10 G0 X1.0 F.003; make sure cursor is on
the line being deleted (_N10)

- **CANCEL MISTYPED WORD**

1. Press cancel button



HINT: In the ADRS. (Address) at the lower left of the screen is the word and numbers that you typed in. Before pressing insert check if what was typed in is correct. If not press cancel and retype word and numbers.

- **ALTER A WORD**

1. Type the Word needed altered
2. Press alter button



Example: Make sure the cursor is to the left of the words being altered (_N5 CHANGE TO _N10)

- **SEARCH FOR NUMBER BLOCK**

1. Press letter n and the number of the block
2. Press cursor down button



Example:(N50)

HINT: The arrow button pointing down

- **SEARCH FOR WORD**

1. Type in Word & number **Example: (M30)**
2. Press cursor down button



- **SEARCH FOR LETTER**

1. Press letter
2. Press cursor down button



HINT: This goes to the first (G). Follow steps 1 & 2 cursor goes to the next (G)

Survey commands G CODES: Mostly used only

G00 Rapid motion

- G01 Linear interpolation in working feed
- G02 Circular interpolation, clockwise
- G03 Circular interpolation, counter-clockwise
- G04 Dwell time, active block by block
- G09 Exact hold

G17 Selection of plane X-Y

- G18 Selection of plane Z-X
- G19 Selection of plane Y-Z
- G20 Dimension in inch
- G21 Dimension in millimeter
- G28 Approach reference point

G40 Deselect miller radius compensation

- G41 Miller radius compensation left
- G42 Miller radius compensation right
- G43 Tool length compensation positive
- G44 Tool length compensation negative

G49 Deselect tool length compensation

- G53 Machine coordinate system

G54 Zero point shift 1

- G55 Zero point shift 2
- G56 Zero point shift 3
- G57 Zero point shift 4
- G58 Zero point shift 5
- G59 Zero point shift 6
- G73 Chip break cycle

G80 Delete drilling cycle (G83 to G85)

- G81 Drilling cycle
- G83 Excavation drilling cycle

G90 Absolute value programming

- G91 Incremental value programming

G94 Feed in inch/min

- G95 Speed with feed in inch/revolution

G97 Spindle speed per minute

G98 Retract to plane of start (drilling cycles)

Survey commands M-CODES: Mostly used



M00	Programmed stop, unconditional
M01	Programmed stop, conditional
M03	Spindle ON clockwise
M04	Spindle ON counter clockwise
M05	Spindle OFF
M25	Open clamping vice
M26	Close clamping vice
M30	Main program end with new start of program
M71	Blow-off ON
M72	Blow-off OFF
M98	Subroutine call-up
M99	Subroutine end

A maximum of three M commands allowed for each program block!

Used Addresses

C	Chamfer
F	Feed rate, thread pitch
G	Path function
H	Tool height, tool radius
I, J, K	Circle parameter, scale factor, K number of repetition
M	Miscellaneous function
N	Block number 1 to 9999
O	Program number 1 to 9499
P	Dwell, subroutine
Q	Cutting depth or shift value
R	Radius, retraction height
S	Spindle speed
T	Tool called out
X, Y, Z	Position data
;	Block end

Tools needed for Programs 1, 2, 3, 4, 5, 6

F1Z 010	<u>Collet holder</u>	For ESX-25 collets	
225 100	(9.0-10.0mm)Ø 3/8"	ESX 25 COLLETS	
764 308	Acc. to DIN 327, shape B cutting-Ø10 mm / shank-Ø10mm	<u>Slot end mill, HSS</u>	

Program screen & Edit mode


- To edit / change a program / insert new programs & input or output excising programs & offsets

Program screen & MDI mode

- To manually program the spindle speed / move the axis (X,Y,Z) to a specified location and or Index to a certain tool

Note: Material is 2024-T4 Alum, All feeds & speeds are programmed for this type of Aluminum

Program Q0001



N5 G00 G17 G40 G80 (Demo 1) (2 X 2 X .5 Alum.)

N10 G90 G94 G98

N15 G54

N20 G43 T1 H1 M0 (3/8 or 10mm Endmill)

N25 S1800 M3

N30 G0 Z1

N35 X-1 Y1

N40 Z-.1

N45 G1 G41 H11 X.1 F7

N50 Y1.9

N55 X1.9

N60 Y.1

N65 X.1

N70 Y1

N75 G0 G40 X-1

N80 G28 Z3

N85 G28 X2.5 Y2.5

N90 M30

2D Simulation

1. Press **Graph** button on the Display Keys for the Graph screen to appear

F:100% S:100%

PATH GRAPHIC (PARAMETER-1) 00011 N0000

AXIS P= 0
(XY=0, XZ=1, YZ=2)

ANGLE
ROTATION A= 0
TILTING A= 0.00

SCALE K=

MAXIMUM/MINIMUM
X= 3.0000 Y= 1.5000 Z= 0.0000
I= -0.5000 J= -0.5000 K= 0.0000

START SEQ. NO. N= 0
END SEQ. NO. N= 9999

NO. _

JOG


F3 PATH	F4 SOLID	F5 AUX	F6	F7
------------	-------------	-----------	----	----

>

Note: There are only 7 values you can change on this page the rest of them change by the values you will enter. This graph only works with an active program and runs only the current program selected

2. Axis P = 0 means G17 1 means G18 2 means G19
3. Maximum/Minimum X = Overall Length of the stock in X direction this is a positive value
4. Maximum/Minimum Y = Overall Width of the stock in Y direction this is a positive value
5. Maximum/Minimum Z = Overall Height of the stock in Z direction this is a positive value
6. Maximum/Minimum I = This value is normally a negative number and this is the viewable area passed X0 going negative
7. Maximum/Minimum J = This value is normally a negative number and this is the viewable area passed Y0 going negative
8. Maximum/Minimum K = This value is normally a negative number and this is the viewable area passed Z0 going negative

9. Press the Soft key **PATH**
10. Press the Soft key **EXEC** for Execution screen



Note: If you press the AUTO on this screen this will auto scale for you. You will need to press the arrow left on the soft keys to go back and enter your values that you originally had.

11. Now press **Cycle start** or Soft Key **Start** and you will see the tool movements of the program

- **Changing I/O to floppy drive** (Only need to do this once stays default)

1. Move the Mode Dial to **EDIT**
2. Press **Parameter** on the display keys
3. Page down until you see Parameter (Setting 1)
4. Cursor down to I/O
5. Type A (for the Floppy Drive) press Input key

Other Drives useable: **B (Drive), C (Drive), P (Printer), 1, 2 (Com Ports)**

- **Output Program from Fanuc software to Drive unit**

1. Press the **Program** on the display key
2. Type program number to be send out

Example: letter Q and program number
(Q0002) or (Q2)

3. Press (**Output Start**) key

- **Output Offsets from Fanuc software to Drive unit**

1. Press the **Menu Offset** display key
2. Press (**Output Start**) key

- **Input Program into Fanuc Software from Drive unit**

1. Press the **Program** display key
2. Type program number to be read


Example: letter Q and program number
(Q0002) or (Q2)

3. Press (**Input**) key

- **Input Offsets into Fanuc Software from Drive unit**

1. Press the **Menu Offset** display key
2. Press (**Input**) key

Program Q0001 (C & R)



N5 G00 G17 G40 G80 (Demo 1) (2 X 2 X .5 Alum.)

N10 G90 G94 G98

N15 G54

N20 G43 T1 H1 M0 (3/8 or 10 mm end mill)

N25 S1800 M3

N30 G0 Z1

N35 X-1 Y1

N40 Z-.1

N45 G1 G41 H11 X.1 F7

N50 Y1.9 C.1

N55 X1.9 C.1

N60 Y.1 R.1

N65 X.1 R.1

N70 Y1


N75 G0 G40 X-1

N80 G28 Z3

N85 G28 X2.5 Y2.5

N90 M30

Program Q0002 (Deep Hole Drilling)



G83 X = Location of hole Y = location of hole

Z = Overall Depth of hole P = Dwell at bottom of hole

R = Retract after Cycle **Q = incremental peck depth per pass**

K = Incremental repeats only used with G91 **F = Feed rate**

N5 G54 (Demo 2) (2 X 2 X .5 Alum.)

N10 G43 T1 H1 M0 (3/8 or 10 mm end mill)

N15 S1500 M3

N20 G0 Z1

N25 X1 Y1

N30 Z.05

N35 G83 Z-.2 R.1 Q.05 F3


N40 G80

N45 G28 Z3

N50 G28 X2.5 Y2.5

N55 M30

Program Q0003 (I & J)



N5 G54 (Demo 3) (2 X 2 X .5 Alum.)

N10 G43 T1 H1 M0 (3/8 or 10 mm end mill)

N15 S1500 M3

N20 G0 Z1

N25 X1 Y1

N30 Z.1

N35 G1 Z-.1 F3

N40 S1800

N45 G1 G42 H11 X.5 F5

N50 G2 X.5 Y1 I.5 J0 (360 degrees)


N55 G0 G40 X1

N60 G28 Z3

N65 G28 X2.5 Y2.5

N70 M30

Program Q0003 (R)



```
N5 G54 (Demo 3) (2 X 2 X .5 Alum.)
N10 G43 T1 H1 M0 (3/8 or 10 mm end mill)
N15 S1500 M3
N20 G0 Z1
N25 X1 Y1
N30 Z.1
N35 G1 Z-.1 F3
N40 S1800
N45 G1 G42 H11 X.5 F5
N50 G2 X1.5 Y1 R.5 (180 Degrees)
N55 G2 X.5 Y1 R.5 (180 Degrees)
N60 G0 G40 X1
N65 G28 Z3
N65 G28 X2.5 Y2.5
N70 M30
```

1. To make all programs tie together or all programs Q0001 thru Q0003 to run together. Use M98 this calls out Sub programs or Sub routines.
Example: M98 P010001
2. After M98 P is identified with 6 digits.
 - The First 2 digits is the number of times program is to be repeated
 - The next 4 digits is the program number without the letter Q
3. Programs that are being used as a Sub Programs must end with M99 instead of M30.
4. All programs can be used as Sub Programs or Main Programs
M99 means program is Sub, M30 means program is a Main
5. A main Program can also use M99 at the end.
 - Program is being used to repeat without cutting multiple parts.
 - This is mainly used for Demo's for just seeing Tool movements.
6. To link all 3 programs together follow Program O0004
 - Program O0001, O0002(R), O0003 must all have M99 at the end to link together

Program Q0004 (Main Program)

N5 G54 (Tie Prog. 1,2,3 together)


N10 M98 P010001

N15 M98 P010002

N20 M98 P010003

N25 M30

Program Q0005 (Pocket Milling) (Making a Cycle)



```
N5 G54 (Demo 5) (2 X 2 X .5 Alum.)  
N10 G43 T1 H1 M0 (3/8 or 10 mm end mill)  
N15 S1500 M3  
N20 G0 Z1  
N25 X1 Y1  
N30 Z.1  
N35 G1 Z0 F3  
N40 M98 P030006  
N45 G0 G28 Z3  
N50 G28 X2.5 Y2.5  
N55 M30
```

Program Q0006 (Sub for program 5)

N5 G91 (Sub Prog. for Prog. 5)

N10 G1 Z-.1 F2

N15 G90

N20 S1800

N25 G41 H11 X.4 Y1.35 F7

N30 X.2 Y1

N35 X.6 Y.3

N40 X1.4

N45 X1.8 Y1

N50 X1.4 Y1.7

N55 X.6

N60 X.2 Y1

N65 X.4

N70 X.8 Y.5

N75 X1.2

N80 X1.6 Y1

N85 X1.2 Y1.5

N90 X.8

N95 X.4 Y1

N100 G0 G40 X1

N105 M99