





WinCAM Milling Level 1

WinCAM is an icon driven system with three basic parts:
Cad, Cam and Machine. In this picture you can see the





F1Z 010	<u>Collet holder</u>	For ESX-25 collets	
225 100	(9.0-10.0mm)Ø 3/8"	ESX 25 COLLETS	
764 308	Acc. to DIN 327, shape B cutting-Ø10 mm / shank-Ø10mm	<u>Slot end mill, HSS</u>	


PART SIZE = “2 X 2 X .5” OF 2024-T4 ALUMINUM




WinCAM Mill Step by Step CAD Setup


1. LEFT CLICK ON **SETUP** (THE TOP BAR OF THE SCREEN)
2. CLICK ON DEFINE **UNMACHINED PART/CLAMPING POINT**






3. UNDER DIMINSIONS HIGHLIGHT
4. TYPE **2.** (LENGTH OF THE PART); THEN PRESS TAB
5. TYPE **2.** IN THE **Y** VALUE BOX (WIDTH) THEN PRESS TAB
6. TYPE **.5** IN THE **Z** VALUE BOX (HEIGHT) THEN PRESS TAB
7. TYPE **0.** IN THE **cX** VALUE BOX (AMOUNT OF STOCK STICKING IN OR OUT OF THE VISE) THEN PRESS TAB
8. TYPE **.4** IN THE **cZ** VALUE (STOCK ABOVE THE VISE)
9. CLICK OK 




NOTE: PLACE THE MOUSE POINTER OVER ANY ICON AND WINCAM AUTOMATICALLY IDENTIFY THE ICON AT THE LOWER LEFT OF THE SCREEN.

10. CLICK ON THE **ZOOM DRAWING ELEMENT** ICON  (A)
11. PLACE THE **MOUSE POINTER** OR + SIMBOL TO THE UPPER LEFT SIDE OF THE VISE (B)
12. CLICK & HOLD THE **LEFT** MOUSE BUTTON & DRAG TO THE BOTTOM RIGHT SIDE OF THE VISE (C)
13. LET GO OF MOUSE; YOUR VEIW WILL ENLARGE






14. CLICK ON THE **POLYLINE** ICON  (MULTIPLE LINE)
15. TYPE **.625, .350** FOR THE START POINT / THEN PRESS **ENTER** ON THE PC KEYBOARD
16. TYPE **1.35, .350** FOR THE NEXT POINT / PRESS **ENTER**
17. TYPE **1.75, 1.00** FOR THE NEXT POINT / PRESS **ENTER**
18. TYPE **1.375, 1.65** FOR THE NEXT POINT / PRESS **ENTER**
19. TYPE **.625, 1.65** FOR THE NEXT POINT / PRESS **ENTER**
20. TYPE **.25, 1.00** FOR THE ENDING POINT / PRESS **ENTER**



NOTES:

- 1: CORDINATES ARE ABSOLUTE FROM REFERENCE POINT
- 2: ALL VALUES TYPED IN ARE LOCATED AT LOWER LEFT OF THE SCREEN

21. CLICK ON THE **RIGHT** MOUSE BUTTON
22. **HIGHLIGHT SEARCH POINT** THEN **LEFT** CLICK
23. CLICK ON THE OTHER SIDE OF THE ENDING LINE SEGMENT (1)
24. CLICK ON **POLYLINE** ICON  THIS DESELECTS POLYLINE (2)





25. CLICK ON **CIRCLE** ICON 


26. CLICK ON **CIRCLE WITH CENTER AND RADIUS** ICON 

27. TYPE **1.0,1.0** LOCATES CENTER OF THE PART / THEN PRESS ENTER

28. TYPE **.25** FOR THE RADIUS OF THE CIRCLE / THEN PRESS ENTER



1. CLICK ON **FILE** (TOP LEFT OF THE SCREEN)
2. CLICK ON **SAVE AS**
3. TYPE **HEX**
4. CLICK **OK**




You have just completed the CAD portion
of the Step by Step guide, go to the next
page for CAM

WinCAM Mill Step by Step CAM Setup


1. CLICK ON **CAM** ICON (UPPER MIDDLE OF SCREEN) 
THIS SWITCHES MODES TO COMPUTER AIDED MACHINING

Note: Only use steps (2, 3 & 4) if you purchased the option(s) for Siemens, Fanuc, Num 760 or Emcotronic TM02


2. CLICK ON **SETUP** (TOP LEFT OF THE SCREEN)
3. CLICK ON **TARGET CONTROL**



4. CLICK ON THE **POST** FOR THE PROGRAM TO BE FORMATED example (**FANUC O**) THEN CLICK OK 




5. CLICK ON **TOOL LIBRARY** (TOP LEFT OF THE SCREEN)
6. CLICK THE GRAY BOX ☒ **#3: 3/8" endmill** (UNDER TOOL LIBRARY)
7. CLICK THE GRAY BOX ☒ **T1, empty** (UNDER TOOL HOLDER)



8. CLICK ON THE **TRANSFER** ICON  (THIS PLACES TOOL IN TOOL HOLDER)


9. CLICK OK 



10. CLICK ON THE **TOOL CHANGE** ICON 

11. CLICK ON THE GRAY BOX  T1, #3: 3/8" endmill / THEN


CLICK OK 




12. CLICK ON THE **PERIPHERY** ICON 

13. CLICK ON **MAIN SPINDLE ON RIGHT**  (M03)

14. CLICK ON **MACHINE** ICON 




15. CLICK ON **MOVEMENT IN RAPID MOTION IN PLANE** ICON




16. PLACE THE **MOUSE** IN THE CENTER OF THE PART /

LEFT CLICK OR YOU CAN TYPE IN 1,1 THEN ENTER

17. THE TOOL WILL LOOK AS IF IT IS THROUGH THE PART




OR



18. CLICK ON **MOVEMENT IN RAPID MOTION IN FEED**


DIRECTION ICON  (G0 in Z)

19. TYPE IN **.100** FOR THE HIEGHT (ABOVE THE PART)




20. PRESS **ENTER** ON PC KEYBOARD

21. CLICK ON **POCKET MILLING WITH ISLAND** ICON 





22. CLICK ON THE **HEX**

23. CLICK THE **GREEN** CHECK MARK  (BOTTOM RIGHT)




24. CLICK ON THE **CIRCLE** (MIDDLE OF THE PART)

25. CLICK THE **GREEN** CHECK MARK  2 TIMES (THIS IS COMFERMATION OF THE SELECTED ITEM)




26. DOUBLE CLICK ON THE **T** = DEPTH (WHITE AREA)
27. TYPE IN **-.1** / THEN PRESS TAB
28. TYPE IN **.05** IN **Z(t)** FOR ADVANCE DEPTH / PRESS TAB
29. TYPE IN **.1** IN **RE** FOR RETURN PLANE / PRESS TAB
30. TYPE IN **0** IN **SE** FOR START PLANE / PRESS TAB
31. TYPE IN **0** IN **SA** FOR FINISH OFFSET / PRESS TAB
32. TYPE IN **3** IN **F(t)** FOR Z FEED (FEED PER MINUTE) /
PRESS TAB
33. TYPE IN **5** IN **F(f)** FOR X,Y FEED (FEED PER MINUTE) /
PRESS TAB
34. TYPE IN **1500** IN **S** FOR SPINDLE SPEED (DIRECT RPM)
35. CLICK ON **OK**



36. CLICK ON **MOVEMENT IN RAPID MOTION IN FEED**

DIRECTION ICON  (G0 in Z)


37. TYPE **2.** / PRESS ENTER




38. CLICK ON **MOVEMENT IN RAPID MOTION IN PLANE** ICON

 (G0 in X, Y)

39. MOVE THE **MOUSE** TO THE UPPER RIGHT CORNER OF THE **WISE** PART (1) / THEN LEFT CLICK




1. CLICK ON **FILE** (TOP LEFT OF THE SCREEN)
2. CLICK ON **SAVE AS**
3. CLICK ON **HEX.DFM**
4. CLICK YES TO FILE ALREADY EXISTS
5. CLICK OK



You have just completed the CAM portion
of the Step-by-Step guide, go to the next
page for Machine


WinCAM Mill Step by Step MACHINE Setup

1. CLICK ON **MACHINE ICON**  (NC)




Note: Make sure Door is closed

2. CLICK ON **REFERENCE ICON** 




3) CLICK ON **NC PARAMETERS ON/OFF**  & **POSITION**

DISPLAY ON/OFF 




4) MOVE BOTH SCREENS TO A VEIWABLE POSITION BY
CLICKING IN THE GRAY BAR AND DRAGGING THE
WINDOW TO A NEW POSITION



5) CLICK ON **TOOL CHANGE ICON**




6) CLICK ☒ **T1, #3: 3/8" endmill** THEN CLICK **O.K.**



7) MOVE THE Z AXIS UP USING 8 ON # KEYS (**Put tool in**)

8) CLICK ON **SETUP**

9) CLICK ON **DEFINE VISE POSITION**



HINT 1

THE NUMBER KEYS ON THE NUMERIC KEYPAD WITH ARROWS MOVES THE AXIS IN THE X, Y OR Z PLANE

KEY (1) MOVES THE AXIS FORWARD (-Y)

KEY (2) MOVES THE SPINDLE AXIS DOWN (-Z)

KEY (4) MOVES THE AXIS LEFT (-X)

KEY (6) MOVES THE AXIS RIGHT (+X)

KEY (8) MOVES SPINDLE AXIS UP (+Z)

KEY (9) MOVES THE AXIS BACKWARDS (+Y)

HINT 2

The plus key on the number Keypad increases the feed rate

The minus key decreases the feed rate

Press & hold CTRL Key with the plus Key this increases the spindle speed

Press & hold CTRL Key with the minus key this decreases the spindle speed

Toggle Back

Esc

Mode

F3

F4

F5

F6

F7

F8

Output

Input

>

Display

Over Toggle

Turret

Air

Rotary

Jog

Jog

Spindle

Spindle

Vise

Vise

Door

1

2

3

4

5

6

7

8

9

0

.

-

=

Backspace

Cancel

Tab

Q

W

E

R

T

Y

U

I

O

P

Caps Lock

A

S

D

F

G

H

J

K

L

EOB

Insert

Input

Shift

Z

X

C

V

B

N

M

Shift

Ctrl

Alt

Alt

Ctrl

Alter

Delete

End

Page Up

Page Down

^

<

v

>

Number Keys

Num Lock

Dry Run

Skip

Y+

Y-

REF

ALL

X+

X-

Reset

Op Stop

SBL

+

-

X+

X-

NC

Start



NC


or



(cycle start)


- Any key with Gray highlight Press Ctrl + the key for that function
 - Some keys have two functions to them for 1st function just press the key
 - 2nd function will be Grey press Ctrl + the key for the function
 - Some automotive keys when you press them 1 time this will close/turn off press them again will open/turn on
 - F1 is a toggle key for the modes: Zero, Auto, Edit, MDI, Jog and F1 then F11 give Increment Step
 - F12 is a toggle key for the Display screens: Position, Program, Offsets, Parameter, Alarm and F12 then F11 then F3 gives Graph
 - F12 then F11 then F3 then F11 then F3 gives you 3D view
 - Press enter 2 times this is the same as pressing EOB insert
 - Alt + F4 will exit the software back to the desktop
 - The Top right corner will allow the screen to be minimized, restored and close just like a standard windows screen
- The machine functions are active only with NUM LOCK on


Keys are active they will move the axes if used as numbers. Use numbers on the keyboard.


- 10) MOVE THE **TOOL** TO THE **WISE** & TOUCH **EDGE** OF THE **WISE** IN THE **X AXIS** DIRECTION
- 11) CLICK ON **CLAMPING DEVICE X DIAMOND** ICON  (THIS IS DISTANCE FROM MACHINE 0 TO WISE LOCATION IN X)
- 12) MOVE THE **TOOL** TO THE **WISE** & TOUCH FRONT **EDGE** OF THE **WISE** IN THE **Y AXIS** DIRECTION
- 13) CLICK ON **CLAMPING DEVICE Y DIAMOND** ICON  (THIS IS DISTANCE FROM MACHINE 0 TO WISE LOCATION IN Y)
- 14) THEN CLICK **OK**





- 15) CLICK ON **TOOL CHANGE** ICON 
- 16) CLICK **T2 EMPTY** THEN CLICK **O.K.**
- 17) MOVE Z AXIS UP USING 8 ON # KEYS (**TAKE TOOL OUT**)
- 18) CLICK ON **SETUP**
- 19) CLICK ON **DEFINE VISE POSITION**
- 20) MOVE THE **SPINDLE** TO THE **WISE** & TOUCH ON THE **TOP** OF THE **WISE** IN THE **Z AXIS** DIRECTION
- 21) CLICK ON **CLAMPING DEVICE Z DIAMOND** ICON  (THIS IS DISTANCE FROM MACHINE 0 TO VISE LOCATION IN Z) THEN CLICK **OK**
- 22) MOVE THE **Z AXIS** UP





- 23) CLICK ON **EDIT**
- 24) CLICK ON **MARK NC WORKPIECE**
- 25) MOVE THE **SPINDLE** TO THE **TOP** OF THE **WORKPIECE** &
TOUCH IN THE **Z AXIS** DIRECTION
- 26) CLICK ON THE **WORKPIECE OFFSET Z DIAMOND** ICON 
(WRITE DOWN NUMBERS ON PIECE OF PAPER) CLICK **OK**




- 27) MOVE THE Z AXIS UP USING 8 ON THE # KEYS
- 28) **(PUT TOOL IN)**

- 29) CLICK ON **TOOL CHANGE ICON** 
- 30) CLICK GRAY BOX **T1, #3: 3/8" End Mill** THEN CLICK **O.K.**
- 31) CLICK ON **EDIT** CLICK ON **MARK NC WORKPIECE**
- 32) MOVE THE **TOOL** TO THE **WORKPIECE** & TOUCH **SIDE OF WORKPIECE** IN THE **X AXIS** DIRECTION
- 33) CLICK ON THE **WORKPIECE OFFSET X DIAMOND ICON** 




- 34) MOVE THE **TOOL** TO THE **WORKPIECE** & TOUCH **FRONT OF WORKPIECE** IN THE **Y AXIS** DIRECTION
- 35) CLICK ON **WORKPIECE OFFSET Y DIAMOND ICON**  THEN CLICK **OK**





36) MOVE THE Z AXIS UP

37) CLICK ON TOOL LIBRARY CLICK ON T1 3/8 ENDMILL
(UNDER TOOL HOLDER)





38) CLICK ON 



- 39) HIGHLIGHT TOOL OFFSET Z REFERENCE POINT
- 40) TYPE NUMBERS IN FROM LINE 26
- 41) MOVE TOOL DOWN & TOUCH THE TOP OF THE WORKPIECE
- 42) CLICK ON THE TOOL OFFSET Z TOOL OFFSET DIAMOND ICON  CLICK OK 2 TIMES







DO STEPS 36- 42 FOR ANY OTHER TOOLS YOU WISH TO SET



NOW CLICK ON **START PROGRAM** (CYCLE START) **2 / 3**
TIMES

Make sure tool is in the spindle

NOTE

Start program _____	
Stop program (NC stop) _____	
Stop program (Reset) _____	
Skip Block (skip) _____	
Single block operation (single) _____	
Test run without main spindle (dry run) _____	
Go for Reference _____	