


emco

innovative machine tools



GE FANUC O 50/55 MILL TRAINING GUIDE


7/11/08 Version 7
Made by EMCO
Authored by Chad Hawk

Training Index

Control Keyboard.....	Pg 1
• Fanuc O Control	
• Machine Control	
Fanuc O Screen	Pg 2
Fanuc O Keys	Pg 3
• Cursor Movement Keys	
• Change Keys	
• Store Keys	
Data Input Keys	Pg 4
• Function Keys (Display Keys)	
• Soft Key Module	
Machine Keys	Pg 5
• Machine Function Keys	
Direction Keys	Pg 6
• Spindle Override Keys	
• Accessory Functions	
Mode Dial	Pg 7
• Feed Override Dial	
Pc Keyboard Keys	Pg 8
Referencing the Machine	Pg 9
Work Shift Description (Picture)	Pg 10
Work Shift (How to do Z Work Shift)	Pg 11
Work Shift (How to do X Work Shift)	Pg 13
• Manually starting the Spindle	
Work Shift (How to do Y Work Shift)	Pg 15
Tool Offset Description (Picture)	Pg 17
Tool Offset (How to do Tool Offsets)	Pg 18

Program Training & Tool listing.....	Pg 17
Inserting a New Program	Pg 18
• Calling a Existing Program up	
• Insert a word	
• Insert a End of Block	
Delete a Program	Pg 19
• Delete all Programs	
• Delete a word	
• Delete a Block	
Cancel word	Pg 20
• Alter a word	
• Search for number Block	
• Search for word	
G Codes	Pg 21
M Codes	Pg 22
• Used Addresses	
Program 1 (Contour Out Side)	Pg 24
2D simulation (Setup)	Pg 25
Input & Output the Programs & offsets thru the Fanuc Software.....	Pg 27
Running a Program	Pg 28
Program 2 (C & R)	Pg 29
Program 3 (Drilling)	Pg 30
Program 4 (R's)....	Pg 31
Program 5 (I&J)	Pg 32
I & J Test.....	Pg 33
Program 6 (Main Program) using M98 (sub programs)	Pg 34
Program 7 (Main for Pocket Milling)	Pg 35
Program 8 (Sub program for program 7)	Pg 36
Quiz	Pg 37
Appendix	


CONTROL KEYBOARD




FANUC O CONTROL



MACHINE CONTROL



The Fanuc O Screen



1. Displays of Feed and Spindle Speed override
2. Display of Program and Number block
3. Display of active Screen
4. Entry line
5. Display of active Mode
6. Display of Soft key Functions

FANUC O KEYS



RESET = cancels most alarms, resets program, interrupts programs

CURSOR MOVEMENT KEYS



CURSOR UP = moves cursor up



CURSOR DOWN = moves cursor down, search function, program call up



PAGE UP = moves one page up



PAGE DOWN = moves one page down

CHANGE KEYS



ALTER = alter word (replace word)



INSRT = insert word, create new program



DELET = deletes word / block or a program



EOB = end of block, skip block



CAN = deletes entries in the address

STORE KEYS



INPUT = inputs program / offsets / word / numbers



OUTPT / START = sends program / offsets out

DATA INPUT KEYS



Continually press keys to see all possibilities of that Key.

Press one time a letter appears
Press again a number appears

FUNCTION KEYS (DISPLAY KEYS)



POS = displays actual, relative, machine positions



PRGRM = displays program, library page



MENU / OFFSET = displays Offsets, Work shifts



DGNOS / PARAM = displays parameters, diagnostic pages




OPR / ALARM = displays operator & alarm messages



AUX / GRAPH = displays 2-D graph

SOFT KEY MODULE



SCROLL BACK

SOFT KEYS

PAGES OVER

MACHINE KEYS

MACHINE FUNCTION KEYS



= Press skip for any block lines with (/) (Slash) before block number will be skipped



= Press for test run without spindle on (remove raw material from vise)



= (Single piece) for continuous mode active only on automatic material loading



= (Optional stop) for programs with (m1)



= (Reset) cancels most alarms, resets program, interrupts programs




= (Single block) reads one block line at a time



= (Cycle stop) program hold, feed hold



= (Cycle start) program start




DIRECTION KEYS

These keys control axis directional movements

+4 & -4 = Additional axis

Feed stop (Red) / Feed start (Green)
Works all modes but EDIT & ZRN




SPINDLE OVERRIDE KEYS

Arrow key pointing right increase the Spindle speed (120% high)

Arrow key pointing left decrease the Spindle speed (50% low)

100% key jumps speed to 100%

Spindle stop (Red) / Spindle start (Green)
Works all modes except EDIT & ZRN



ACCESSORY FUNCTIONS

Arrow right door open

Arrow left door closed

Press for Rotary axis Indexing

Press once vise closed

Press once vise open


Press once coolant on

Press again coolant off

Press auxiliary drives on (Green)

Press auxiliary drives off (Red)

MODE DIAL



- (1) ZRN = Zero / Reference or Home mode
- (2) AUTO = Automatic mode for running a program
- (3) EDIT = Edit mode for program changes or entering a new program
- (4) MDI = Manual Data Input mode for manually running the machine
- (5) JOG = Manual moving the axis in X, Y, Z
- (6) STEPS = Incremental feed movements
- (7) STEPS = .0001 or tenths
- (8) STEPS = .001 or thousands
- (9) STEPS = .010 or ten thousands
- (10) STEPS = .100 or hundred thousands
- (11) STEPS = .100 or hundred thousands

FEED OVERRIDE DIAL



Controls feed for jogging in the X, Y, Z Axis.
Overrides from 0% to 120% of the
programmed feed rate or the rapid rate

Toggle Back

Esc

Mode

F3

F4

F5

F6

F7

F8

Output

Input

>

Display

Over Toggle

~	1	2	3	4	5	6	7	8	9	0	-	=	Backspace
`	!@	~	#	\$	%	^	&	*	()	_	+	Cancel
Tab	Q	W	E	R	T	Y	U	I	O	P			
Caps Lock	A	S	D	F	G	H	J	K	L	EOB			Insert Input
Shift	Z	X	C	V	B	N	M						Shift
Ctrl		Alt								Alt			Ctrl

Alter

Delete

End

Page Up

Page Down

^

<

v

>

Number Keys

Num Lock	Dry Run	Op Stop	Stop	NC
	Skip	SBL	NC	
Z+	Y+			
REF	X+			
ALL	NC			
Y-	Z-			
Reset	NC			
	Start			
	or			
	(cycle start)			

- Any key with Gray highlight Press Ctrl + the key for that function
 - Some keys have two functions to them for 1st function just press the key
 - 2nd function will be Grey press Ctrl + the key for the function
 - Some automotive keys when you press them 1 time this will close/turn off press them again will open/turn on
 - F1 is a toggle key for the modes: Zero, Auto, Edit, MDI, Jog and F11 then F11 give Increment Step
 - F12 is a toggle key for the Display screens: Position, Program, Offsets, Parameter, Alarm and F12 then F11 then F3 gives Graph
 - F12 then F11 then F3 then F11 then F3 gives you 3D view
 - Press enter 2 times this is the same as pressing EOB insert
 - Alt + F4 will exit the software back to the desktop
 - The Top right corner will allow the screen to be minimized, restored and close just like a standard windows screen
- The machine functions are active only with NUM LOCK on

Keys are active they will move the axes if used as numbers. Use numbers on the keyboard.


Turning the Machine On/Entering Fanuc Software

Referencing the Machine

1. Move the MODE dial to ZRN position also know as Reference make sure your feed rate is not on "0"




2. Make sure the Door is closed
3. Press the Z+ (arrow pointing up) this references the Z axis. (Wait until Z is fully reference)
4. Press the X- (arrow pointing left) this references the X axis
5. Press the Y- (arrow pointing left) this references the Y axis



Note: Every time you enter Fanuc O Software or Turn the Machine On you must reference the axis

WORK SHIFT

Pages 10 – 18 is setting the Work shift & offsets to the lower left corner & the top of the part with the Spindle nose



Reference points in the working area

Reference Points of the EMCO Milling Machines

M = Machine zero point

An unchangeable reference point established by the machine manufacturer.

Proceeding from this point the entire machine is measured.

At the same time "M" is the origin of the coordinate system.

R = Reference point

A position in the machine working area which is determined exactly by limit switches. The slide positions are reported to the control by the slides approaching the "R".


Required after every power failure.

N = Tool mount reference point

Starting point for the measurement of the tools. "N" lies at a suitable point on the tool holder system and is established by the machine manufacturer.

W = Workpiece zero point

Starting point for the dimensions in the part program. Can be freely established by the programmer and moved as desired within the part program.



This is a example only Work Shift can be placed anywhere on the part


Work Shift:



1. Move the MODE dial to JOG position
2. Jog the Spindle nose to the top of the Work Piece & touch using the Direction keys.



Note: Use Feed Dial or Steps to approach at a slower feed rate.

Use piece of paper between nose and Work Piece



3. Press the MENU/OFFSET button 
 4. Press the WORK Soft key (Gray Button) Example 2
 5. Make sure that X, Y, Z are all 0 if they have values then the Work Shift will be taken from those values not from the machine 0
 6. Press the OFFSET Soft key (Gray Button)
 - Example 1 in the picture below
 - Record the value in the Actual Position Relative Z
 7. Press the WORK Soft key (Gray Button) Example 2
 8. Move Cursor to 01 location
 9. Recorded value in Work Coordinates 01(Z) which is G54
- Example: Type Z 2.463 press Input button 

This value is the distance from the top of the Machine bed to the top of the Work Piece.

Example 1 F:100% S:100%

OFFSET		00001 N0005	
NO.	DATA	NO.	DATA
001	0.0000	009	0.0000
002	0.0000	010	0.0000
003	0.0000	011	0.0000
004	0.0000	012	0.0000
005	0.0000	013	0.0000
006	0.0000	014	0.0000
007	0.0000	015	0.0000
008	0.0000	016	0.0000

ACTUAL POSITION (RELATIVE)

X	0.0000	Y	0.0000
Z	0.0000		

NO. -

F3 OFFSET
F4
F5
EDIT F6 WORK
F7

Example 2 F:100% S:100%

WORK COORDINATES 00001 N0005


NO.		DATA	NO.		DATA
00	X	0.0000	02	X	0.0000
	Y	0.0000		Y	0.0000
	Z	0.0000		Z	0.0000
01	X	0.0000	03	X	0.0000
	Y	0.0000		Y	0.0000
	Z	0.0000		Z	0.0000

ADRS. -

F3 OFFSET
F4
F5
EDIT F6 WORK
F7


Note: Machine 0 is the spindle nose touching the top of the Machine bed.


10. Jog Spindle up away from WORK PIECE using Z+
11. Place a edge finder or tool in the Spindle (Example uses 3/8 end mill)
12. Either follow step 13 or follow step 14 when finished go on to step 15
13. Jog the Tool to the left side of the Work Piece & touch using the Direction keys. (Use Feed Dial or Steps to approach at a slower feed)
14. For Scratching move MODE Dial to MDI

- Press the PROGRAM display button  until top of the screen shows MDI (Program)

- Type S1000  M03 

S = RPM M03 = Spindle on Clockwise

- Then press CYCLE START  (**Door must be closed**)
- Move MODE Dial to Jog then Jog the Tool to the left side of the Work Piece & touch using the Direction keys.



Note: Machine 0 in X is the center of the spindle to the left side of the Machine bed.

15. Press the MENU/OFFSET button

- Example 1 in the picture below
- Record the value in the Actual Position Relative X

16. Press the WORK Soft key (Gray Button) Example 2

17. Move Cursor to 01 location

18. The Recorded value PLUS the radius of the tool being used to scratch (3/8 Tool) type in Work Coordinates 01 (X)

Example 1

F: 100% S: 100%

OFFSET				O0001 N0005	
NO.	DATA	NO.	DATA		
_001	0.0000	009	0.0000		
002	0.0000	010	0.0000		
003	0.0000	011	0.0000		
004	0.0000	012	0.0000		
005	0.0000	013	0.0000		
006	0.0000	014	0.0000		
007	0.0000	015	0.0000		
008	0.0000	016	0.0000		
ACTUAL POSITION (RELATIVE)					
X	0.0000	Y	0.0000		
Z	0.0000				
NO. —					

EDIT

F3
OFFSET
F4
F5
F6
WORK
F7

Example 2

F: 100% S: 100%


WORK COORDINATES				O0001 N0005	
NO.	DATA	NO.	DATA		
00	X 0.0000	02	X 0.0000		
	Y 0.0000		Y 0.0000		
	Z 0.0000		Z 0.0000		
_01	X 0.0000	03	X 0.0000		
	Y 0.0000		Y 0.0000		
	Z 0.0000		Z 0.0000		
ADRS. —					

EDIT

F3
OFFSET
F4
F5
F6
WORK
F7

19. Jog Spindle up away from WORK PIECE using Z+
20. Jog the Tool to the Front of the Work Piece & touch using the Direction keys.

(Use Feed Dial or Steps to approach at a slower feed)



Note: Machine 0 in Y is the center of the spindle to the Front of the Machine bed.

MENU
OFFSET

21. Press the MENU/OFFSET button

- Example 1 in the picture below
- Record the value in the Actual Position Relative Y

22. Press the WORK Soft key (Gray Button) Example 2

23. Move Cursor to 01 location

24. The Recorded value plus the radius of the tool being used to scratch (3/8) type in Work Coordinates 01 (Y)

Example 1 F:100% S:100%

OFFSET O0001 N0005

NO.	DATA	NO.	DATA
001	0.0000	009	0.0000
002	0.0000	010	0.0000
003	0.0000	011	0.0000
004	0.0000	012	0.0000
005	0.0000	013	0.0000
006	0.0000	014	0.0000
007	0.0000	015	0.0000
008	0.0000	016	0.0000

ACTUAL POSITION (RELATIVE)

X	0.0000	Y	0.0000
Z	0.0000		

NO. —

F3
F4
F5
EDIT
F6
F7

OFFSET

WORK

Example 2 F:100% S:100%

WORK COORDINATES O0001 N0005

NO.		DATA	NO.		DATA
00	X	0.0000	02	X	0.0000
	Y	0.0000		Y	0.0000
	Z	0.0000		Z	0.0000
01	X	0.0000	03	X	0.0000
	Y	0.0000		Y	0.0000
	Z	0.0000		Z	0.0000

ADRS. —


F3
F4
F5
EDIT
F6
F7

OFFSET

WORK

25. Jog the Tool up above the Work Piece using Z+

TOOL OFFSET



F:100% S:100%

OFFSET		00001 N0005	
NO.	DATA	NO.	DATA
001	0.0000	009	0.0000
002	0.0000	010	0.0000
003	0.0000	011	0.0000
004	0.0000	012	0.0000
005	0.0000	013	0.0000
006	0.0000	014	0.0000
007	0.0000	015	0.0000
008	0.0000	016	0.0000


ACTUAL POSITION (RELATIVE)

X 0.0000	Y 0.0000
Z 0.0000	

NO. —

EDIT

F3 OFFSET	F4	F5	F6 WORK
--------------	----	----	------------

1. Jog Tool tip down & touch the Top of the Work Piece
(Use Feed Dial or Steps to approach at a slower feed)
2. Press the MENU/OFFSET button 
3. The value in Actual Position (Relative) Z type this value in Offset NO. 001(H1) If tool is going to be T1
4. Place the Radius in the corresponding Offset 011 (H11)
 - This is for the cutter compensation when using G41 or G42
5. To set more Tools Repeat Steps 1 thru 4
 - Drills & Taps need no Radius set for them

F: 100% S: 100%

OFFSET		00001 N0005	
NO.	DATA	NO.	DATA
001	0.0000	009	0.0000
002	0.0000	010	0.0000
003	0.0000	011	0.0000
004	0.0000	012	0.0000
005	0.0000	013	0.0000
006	0.0000	014	0.0000
007	0.0000	015	0.0000
008	0.0000	016	0.0000
ACTUAL POSITION (RELATIVE)			
X	0.0000	Y	0.0000
Z	0.0000		
NO.	—		

F3
OFFSET

F4

F5

EDIT
F6
WORK


F7

NOTE: When you use a T the H = Height


When you use a G41 or G42 the H = Radius

Program Training


Program O0001




Program O0006



Program O0007



Change the Mode Dial to Edit
Press the Program Button
To do functions on this page



- **INSERT A NEW PROGRAM**

1. Press letter o then program number
2. Press insert button



Example: Q0001 OR Q1

- **CALL A EXISTING PROGRAM UP**

1. Press letter o then program number
2. Press cursor down button



- **INSERT A WORD**

1. Press letter then number
2. Press insert button



Example: press once letter Q appears press again
number 7 appears

HINT: When inserting a word place the cursor one word on
the left before the place being inserted

Example: _N5 G01 X 0.25; G01 is the word being inserted

- **INSERT END OF BLOCK**

1. Press the (EOB) button



2. Press insert button




HINT: at the end of each number line needs an End Of Block
looks like a Semicolon (;)

Example: N5 G01 X1.00 F.003;

NOTE: IN EDIT & IN PROGRAM USE INSERT ONLY.
USE **INPUT** ALL OTHER APPLICATIONS.

Change the Mode Dial to Edit
Press the Program Button
To do functions on this page

PRGRM



- **DELETE A PROGRAM**

1. Press letter o then program number
2. Press delete button

DELET

Example: O0001 OR O1

- **DELETE ALL PROGRAMS**

1. Press letter o plus the – & 9999
2. Press delete button

DELET

Example: O – 9999

- **DELETE A CODE**

1. Press letter then number
2. Press delete button

DELET

Example: press once S appears press again 0 appears

HINT: Deleting a word; place the cursor on the left side
before the word being deleted

Example: BEFORE N5_S1000; AFTER N5;

(S1000) is the word being deleted?

- **DELETE A BLOCK OR LINE NUMBER**


1. Type the number line
2. Press delete button

DELET

Example: _N10 G0 X1.0 F.003; make sure cursor is on
the line being deleted (_N10)

Change the Mode Dial to Edit
Press the Program Button
To do functions on this page

PRGRM



- **CANCEL MISTYPED CODE**

1. Press cancel button



HINT: In the ADRS. (Address) at the lower left of the screen is the code and numbers that you typed in. Before pressing insert check if what was typed in is correct. If not press cancel and retype code and numbers.

- **ALTER A CODE**

1. Type the code needed altered

2. Press alter button



Example: Make sure the cursor is to the left of the words being altered (_N5 CHANGE TO _N10)

- **SEARCH FOR NUMBER BLOCK**

1. Press letter n and the number of the block

2. Press cursor down button



Example:(N50)

HINT: The arrow button pointing down

- **SEARCH FOR CODE**

1. Type in code & number

Example: (M30)

2. Press cursor down button



- **SEARCH FOR LETTER**

1. Press letter

2. Press cursor down button



HINT: This goes to the first (G). Follow steps 1 & 2 cursor goes to the next (G)

Survey commands G CODES: Mostly used only

G00 Rapid motion

- G01 Linear interpolation in working feed
- G02 Circular interpolation, clockwise
- G03 Circular interpolation, counter-clockwise
- G04 Dwell time, active block by block
- G09 Exact hold

G17 Selection of plane X-Y

- G18 Selection of plane Z-X
- G19 Selection of plane Y-Z
- G20 Dimension in inch
- G21 Dimension in millimeter
- G28 Approach reference point

G40 Deselect miller radius compensation

- G41 Miller radius compensation left
- G42 Miller radius compensation right
- G43 Tool length compensation positive
- G44 Tool length compensation negative

G49 Deselect tool length compensation

- G53 Machine coordinate system

G54 Zero point shift 1

- G55 Zero point shift 2
- G56 Zero point shift 3
- G57 Zero point shift 4
- G58 Zero point shift 5
- G59 Zero point shift 6
- G73 Chip break cycle

G80 Delete drilling cycle (G83 to G85)

- G81 Drilling cycle
- G83 Excavation drilling cycle

G90 Absolute value programming

- G91 Incremental value programming

G94 Feed in inch/min

- G95 Speed with feed in inch/revolution

G97 Spindle speed per minute

G98 Retract to plane of start (drilling cycles)

Survey commands M-CODES: Mostly used



M00	Programmed stop, unconditional
M01	Programmed stop, conditional
M03	Spindle ON clockwise
M04	Spindle ON counter clockwise
M05	Spindle OFF
M25	Open clamping vice
M26	Close clamping vice
M30	Main program end with new start of program
M71	Blow-off ON
M72	Blow-off OFF
M98	Subroutine call-up
M99	Subroutine end

A maximum of three M commands allowed for each program block!

Used Addresses

C	Chamfer
F	Feed rate, thread pitch
G	Path function
H	Tool height, tool radius
I, J, K	Circle parameter, scale factor, K number of repetition
M	Miscellaneous function
N	Block number 1 to 9999
O	Program number 1 to 9499
P	Dwell, subroutine
Q	Cutting depth or shift value
R	Radius, retraction height
S	Spindle speed
T	Tool called out
X, Y, Z	Position data
;	Block end

Tools needed for Programs 1, 2, 3, 4, 5, 6

F1Z 010	<u>Collet holder</u>	For ESX-25 collets	
225 100	(9.0-10.0mm)Ø 3/8"	ESX 25 COLLETS	
764 308	Acc. to DIN 327, shape B cutting-Ø10 mm / shank-Ø10mm	<u>Slot end mill, HSS</u>	

Program screen & Edit mode


- To edit / change a program / insert new programs & input or output excising programs & offsets

Program screen & MDI mode

- To manually program the spindle speed / move the axis (X,Y,Z) to a specified location and or Index to a certain tool

Note: Material is 2024-T4 Alum, All feeds & speeds are programmed for this type of Aluminum

Program Q0001



N5 **G00 G17 G40 G80** (Demo 1) (2 X 2 X .5 Alum.)

N10 **G90 G94 G98**

N15 **G54**

N20 G43 T1 H1 M0 (3/8 or 10mm Endmill)

N25 S1800 M3

N30 G0 Z1

N35 X-1 Y1

N40 Z-.1

N45 G1 G41 H11 X.1 F7

N50 Y1.9

N55 X1.9

N60 Y.1

N65 X.1

N70 Y1

N75 G0 G40 X-1

N80 G28 Z3

N85 G28 X2.5 Y2.5

N90 M30

2D Simulation

1. Press **Graph** button on the Display Keys for the Graph screen to appear

F:100% S:100%

PATH GRAPHIC (PARAMETER-1) 00011 N0000

AXIS P= 0
(XY=0, XZ=1, YZ=2)

ANGLE
ROTATION A= 0
TILTING A= 0.00

SCALE K=

MAXIMUM/MINIMUM
X= 3.0000 Y= 1.5000 Z= 0.0000
I= -0.5000 J= -0.5000 K= 0.0000

START SEQ. NO. N= 0
END SEQ. NO. N= 9999

NO. _

JOG


F3 PATH	F4 SOLID	F5 AUX	F6	F7
------------	-------------	-----------	----	----

>

Note: There are only 7 values you can change on this page the rest of them change by the values you will enter. This graph only works with an active program and runs only the current program selected

2. Axis P = 0 means G17 1 means G18 2 means G19
3. Maximum/Minimum X = Overall Length of the stock in X direction this is a positive value
4. Maximum/Minimum Y = Overall Width of the stock in Y direction this is a positive value
5. Maximum/Minimum Z = Overall Height of the stock in Z direction this is a positive value
6. Maximum/Minimum I = This value is normally a negative number and this is the viewable area passed X0 going negative
7. Maximum/Minimum J = This value is normally a negative number and this is the viewable area passed Y0 going negative
8. Maximum/Minimum K = This value is normally a negative number and this is the viewable area passed Z0 going negative

9. Press the Soft key **PATH**
10. Press the Soft key **EXEC** for Execution screen



Note: If you press the AUTO on this screen this will auto scale for you. You will need to press the arrow left on the soft keys to go back and enter your values that you originally had.

11. Now press **Cycle start** or Soft Key **Start** and you will see the tool movements of the program

- **Changing I/O to floppy drive** (Only need to do this once stays default)

1. Move the Mode Dial to **EDIT**
2. Press **Parameter** on the display keys
3. Page down until you see Parameter (Setting 1)
4. Cursor down to I/O
5. Type A (for the Floppy Drive) press Input key

Other Drives useable: **B (Drive), C (Drive), P (Printer), 1, 2 (Com Ports)**

Note: If you want to use USB use C and then follow the appendix

- **Output Program from Fanuc software to Drive unit**

1. Press the **Program** on the display key
2. Type program number to be send out

Example: letter Q and program number
(Q0002) or (Q2)

3. Press (**Output Start**) key

- **Output Offsets from Fanuc software to Drive unit**

1. Press the **Menu Offset** display key
2. Press (**Output Start**) key

- **Input Program into Fanuc Software from Drive unit**

1. Press the **Program** display key
2. Type program number to be read


Example: letter Q and program number
(Q0002) or (Q2)

3. Press (**Input**) key

- **Input Offsets into Fanuc Software from Drive unit**


1. Press the **Menu Offset** display key
2. Press (**Input**) key

Running a Program

Note: If the correct program # is at the top right corner of the screen then skip step 3 only and press reset for step 3 


1. Rotate the Mode dial to Edit

2. Press the Program button



3. Call up Program to be run / cut
(Example O1 for program 1)

4. Rotate the Mode dial to Auto




5. If screen is not in **PROGRAM CHECK** then press the check soft key

6. Press the Single Block button for the program to run one line at a time.

SBL

Note: Use one hand on the feed override dial slowly increasing it and the other pressing cycle start and close to the reset button




7. Press Cycle Start and continue

(Once the program have moved in the safe called out locations for X, Z and looks right; you can take single block off and run the program)

8. Press Cycle Start one more time

(If there is more than one tool; before the next tool use single block to check the offsets locations for X, Z then continue at step 8 again)

Program Q0002 (C & R)



N5 G00 G17 G40 G80 (Demo 2) (2 X 2 X .5 Alum.)

N10 G90 G94 G98

N15 G54

N20 G43 T1 H1 M0 (3/8 or 10 mm end mill)

N25 S1800 M3

N30 G0 Z1

N35 X-1 Y1

N40 Z-.1

N45 G1 G41 H11 X.1 F7

N50 Y1.9 C.1

N55 X1.9 C.1

N60 Y.1 R.1

N65 X.1 R.1

N70 Y1


N75 G0 G40 X-1

N80 G28 Z3

N85 G28 X2.5 Y2.5

N90 M30

Program Q0003 (Deep Hole Drilling)



G83 X = Location of hole Y = location of hole

Z = Overall Depth of hole P = Dwell at bottom of hole

R = Retract after Cycle **Q = incremental peck depth per pass**

K = Incremental repeats only used with G91 **F = Feed rate**

N5 G54 (Demo 3) (2 X 2 X .5 Alum.)

N10 G43 T1 H1 M0 (3/8 or 10 mm end mill)

N15 S1500 M3

N20 G0 Z1

N25 X1 Y1

N30 Z.05

N35 G83 Z-.2 R.1 Q.05 F3


N40 G80

N45 G28 Z3

N50 G28 X2.5 Y2.5

N55 M30

Program Q0004 (I & J)



N5 G54 (Demo 4) (2 X 2 X .5 Alum.)

N10 G43 T1 H1 M0 (3/8 or 10 mm end mill)

N15 S1500 M3

N20 G0 Z1

N25 X1 Y1

N30 Z.1

N35 G1 Z-.1 F3

N40 S1800

N45 G1 G42 H11 X.5 F5

N50 G2 X.5 Y1 I.5 J0 (360 degrees)


N55 G0 G40 X1

N60 G28 Z3

N65 G28 X2.5 Y2.5

N70 M30

Program Q0005 (R)



N5 G54 (Demo 5) (2 X 2 X .5 Alum.)

N10 G43 T1 H1 M0 (3/8 or 10 mm end mill)

N15 S1500 M3

N20 G0 Z1

N25 X1 Y1

N30 Z.1

N35 G1 Z-.1 F3

N40 S1800

N45 G1 G42 H11 X.5 F5

N50 G2 X1.5 Y1 R.5 (180 Degrees)

N55 G2 X.5 Y1 R.5 (180 Degrees)


N60 G0 G40 X1

N65 G28 Z3

N65 G28 X2.5 Y2.5

N70 M30


I and J Test



Using T1 (3/8 End Mill) and cutting on the inside of the red arc starting at the SP

```

N10 G1 Z.1
N15 G1 G H X Y (SP)
N20 G1 Z-.1
N25 G X Y I J (EP)
N30 G1 Z.1
N35 G0 G
    
```



$$A^2 \text{ (K leg)} + B^2 \text{ (I leg)} = C^2 \text{ (H radius)}$$

S $\frac{O}{H}$
 C $\frac{A}{H}$
 T $\frac{O}{A}$

Degrees

Sally Can Tell Oscar Has A Hat On Always

SINE COSINE TANGENT

1. To make all programs tie together O0002, O0003, O0004 to run together. Use M98 this calls out Sub programs or Sub routines.
Example: M98 P010001
2. After M98 P is identified with 6 digits.
 - The First 2 digits is the number of times program is to be repeated
 - The next 4 digits is the program number without the letter O
3. Programs that are being used as a Sub Programs must end with M99 instead of M30.
4. All programs can be used as Sub Programs or Main Programs
M99 means program is Sub, M30 means program is a Main
5. A main Program can also use M99 at the end.
 - Program is being used to repeat without cutting multiple parts.
 - This is mainly used for Demo's for just seeing Tool movements.
6. To link all 3 programs together follow Program O0006
 - Program O0002(C/R), O0003, O0004(I,J) must all have M99 at the end to link together

TEST FOR SUB PROGRAMS

O0006 (Tie Programs)

N5

N10 (Demo 2 C/R)

N15 (Demo 3 Drilling)


N20 (Demo 5 I & J)

N25 M30

Changing Item

Note: Change the end of O0002, O0003, and O0005 to M99 for running them as SUB PROGRAMS

Program Q0007 (Pocket Milling) (Making a Cycle)



```
N5 G54 (Demo 7) (2 X 2 X .5 Alum.)  
N10 G43 T1 H1 M0 (3/8 or 10 mm end mill)  
N15 S1500 M3  
N20 G0 Z1  
N25 X1 Y1  
N30 Z.1  
N35 G1 Z0 F3  
N40 M98 P030006  
N45 G0 G28 Z3  
N50 G28 X2.5 Y2.5  
N55 M30
```


Program Q0008 (Sub for program 7)

N5 G91 (Sub Prog. for Prog. 7)

N10 G1 Z-.1 F2

N15 G90

N20 S1800

N25 G41 H11 X.4 Y1.35 F7

N30 X.2 Y1

N35 X.6 Y.3

N40 X1.4

N45 X1.8 Y1

N50 X1.4 Y1.7

N55 X.6

N60 X.2 Y1

N65 X.4

N70 X.8 Y.5

N75 X1.2

N80 X1.6 Y1

N85 X1.2 Y1.5

N90 X.8

N95 X.4 Y1

N100 G0 G40 X1

N105 M99

Shorter Program Test:

Make program O0008 shorter by using the information given during the training!

N5 G91

N10 G1 Z-.1 F2

N15 G90

N20 S1800

N25 G41 H11 X.4 Y1.35 F7

N30 X.2 Y1

N35 X.6 Y.3

N40 X1.4

N45 X1.8 Y1

N50 X1.4 Y1.7

N55 X.6

N60

N65

N70

N75

N80

N60

N65

N70

N75




N80

N85

Appendix


Changing Drive to USB Port


1. Close out the SW (software)

- Press  to allow you to exit
- Press  and  together to exit the Software



2. Make sure USB is plug into port

3. Open Explorer

- Right Click on Either My Computer, My Documents or any Folder on the Desktop
- Move mouse to  (Explorer)
- Left Click
- If you right clicked on My computer skip to step 4 if not then Left Click on My Computer




4. Copy Drive directory

- Click on you USB drive
- At the top of the active screen or page in the Address copy or remember drive info 
- Close the active screen or page using either Alt and F4 or  at top of the active screen






5. Setting up WinConfig

- Left Click on Green Start button on Desktop
- Move mouse to All Program or Programs
- Move mouse to EMCO
- Move mouse to WinNC-WinConfig WinNC or WinNC32 – Singlelicense or MultipleLicense or Mal (Machine)


- Left Click



6. In Winconfig

- Left Click on  (INI) button
- Double Left Click on **Directories** (Directories)
- Left click on white box 
- Either Press Ctrl and V (this will paste in the info) or type in USB directory
- Left Click on  (OK)
- Left Click on  (Close)
- Left Click on  (Yes) to save the changes

7. Restart SW (software)

- Left Click on Green Start button on Desktop
- Move mouse to All Program or Programs
- Move mouse to EMCO
- Move mouse to WinNC with this  icon on it
- Left Click