



GE FANUC 21 CONCEPT 155 TCM TURN TEACHERS GUIDE


5/3/08 Version 1
Made by EMCO
Authorized by Chad Hawk

Training Index

Machine Components.....	Pg 1
• Fanuc 21 Control	
• Machine Control	
Fanuc 21 Screen	Pg 2
Fanuc 21 Keys	Pg 3
• Data Input Keys	
• Change Keys	
Cursor Movement Keys	Pg 4
• Function Keys (Display Keys)	
• Soft Key Module	
Machine Keys	Pg 5
• Machine Function Keys	
Direction Keys	Pg 6
• Spindle Override Keys	
• Accessory Functions	
Mode Dial	Pg 7
• Feed Override Dial	
Pc Keyboard Keys	Pg 8
Referencing the Machine	Pg 9
Work Shift Description (Picture)	Pg 10
Work Shift (How to do Work Shift)	Pg 11
Tool Offset Description (Picture)	Pg 13
Tool Offset (How to do Tool Offsets for X)	Pg 14
• Manually programming Turret Index	
• Manually programming Spindle on	
Tool Offset (How to do Tool Offsets for Z)	Pg 16

Program Training	Pg 18
Inserting a New Program.....	Pg 19
• Calling a Existing Program up	
• Insert a word	
• Insert a End of Block	
Delete a Program	Pg 20
• Delete all Programs	
• Delete a word	
• Delete a Block	
Cancel word	Pg 21
• Alter a word	
• Search for number Block	
• Search for word	
G Groups	Pg 22
G Codes	Pg 23
M Codes	Pg 24
• Used Addresses	
Program 1	Pg 34
2D simulation (Setup)	Pg 35
Input & Output the Programs & offsets thru the Fanuc Software	Pg 37
Running a Program	Pg 40
Program 1 (C & R)	Pg 41
Program 2 (G73 and G72 Description)	Pg 42
G78 Description	Pg 43
Program 2	Pg 44
Sub Programming	Pg 45
Program 3	Pg 46

Machine Components




Fanuc 21 Keypad


Fanuc 21 Soft Keys



EMCO Machine Control



The Fanuc 21 Screen



1. Displays of Feed
2. Spindle Speed override
3. Display of Program and Number block
4. Display of active Screen
5. Entry line
6. Display of active Mode
7. Display of Soft key Functions

FANUC 21 KEYS



RESET = cancels most alarms, resets program,
interrupts programs

DATA INPUT KEYS



Press a button for a letter / number
needed. Use Shift for the second
letter or symbol on that button.

CHANGE KEYS



ALTER = alter word (replace word)



INSRT = insert word, create new program



DELETE = deletes word / block or programs



INPUT = input offsets / words or numbers



CAN = deletes entries in the address one by one




EOB = end of block

CURSOR & PAGE KEYS



Page Up = pages up in a program or additional screens

Page Down = pages down in a program or additional screens



Cursor up = moves up one line or to left in the screen

Cursor left = moves left in the screen

Cursor right = moves right in the screen

Cursor down = moves down one line or to the right in the screen, search function, and calls up programs

FUNCTION KEYS (DISPLAY KEYS)



POS = displays actual, relative, machine positions



PROG = displays program, library page



OFFSET/ SETTINGS = displays wear, geometry work pages



SYSTEM = displays parameters, diagnostic pages; use page up or down for optional pages




MESSAGE = displays operator & alarm messages











GRAPH = displays 2-d graph simulation

SOFT KEYS







EMCO MACHINE KEYS


Operator Keys

-  = Press skip for any block lines with (/) (Slash) before block number will be skipped
-  = Press for test run without spindle on and rapids only (remove raw material from vise)
-  = (Single piece) for continuous mode active only on automatic material loading
-  = (Optional stop) for programs with (m1)
-  = (Reset) cancels most alarms, resets program, interrupts programs
-  = (Single block) reads one block line at a time
-  = (Cycle stop) program hold, feed hold
-  = (Cycle start) program start

Large Buttons and Keys

-  = **Additional Chuck Button**
Hand Mode is for moving machine around with door open and works in conjunction with the (Agreement button)
-  = **(Agreement button) used for open/closing door or to jog axis with the door open**
-  = **(Mode Key) Automatic & Hand Mode**
Hand Mode is for moving machine around with door open and works in conjunction with the (Agreement button)
-  = **(Cycle start) program start**

Note: Skip, Dry Run, Optional Stop, and Single Block will show at the top of the screen when pressed. When pressed again they will disappear and turn off.




DIRECTION KEYS

These keys control axes directional movements

+4 & -4 = Additional axes

Reference all (Doesn't work for 55 Turn's)

Feed stop (Red) / Feed start (Green) works all modes but EDIT & ZRN



SPINDLE OVERRIDE KEYS


Arrow key pointing right increase the Spindle speed (120% high)

Arrow key pointing left decrease the Spindle speed (50% low)

100% key jumps speed to 100%

Spindle stop (Red) / Spindle start (Green)

Works all modes except EDIT & ZRN (Reference)



ACCESSORY FUNCTIONS

Arrow right door open

Arrow left door closed

Press once chuck open

Press again chuck closed

Press turret index's one time clockwise
Each time pressed

Press tailstock moves backward

Press tailstock moves forward


Press once coolant on

Press again coolant off

Press auxiliary drives on (Green)


Press auxiliary drives off (Red)

MODE DIAL




- (1) REF = Zero / Reference or Home mode
- (2) MEM = Automatic mode for running a program
- (3) EDIT = Edit mode for program changes or entering a new program
- (4) MDI = Manual Data Input mode for manually running the machine
- (5) JOG = Manual moving the axis in X, Z
- (6) SIEMEN MODE (Not used on Fanuc)
- (7) STEPS = .0001 or tenths
- (8) STEPS = .0010 or thousands
- (9) STEPS = .0100 or ten thousands
- (10) STEPS = .1000 or hundred thousands
- (11) STEPS = .1000 or hundred thousands
- (12) SIEMEN MODE (Not used on Fanuc)

FEED OVERRIDE DIAL





Controls feed for jogging in the X, Z Axis.
Overrides from 0% to 120% of the
programmed feed rate or the rapid rate




E Stop or Emergency Stop

Turning the Machine On/Entering Fanuc Software

Referencing the Machine


1. Press the **AUX** button  (This turns on the Auxiliary Drives)
2. Press the **Agreement** button  **Open** door then **Shut** door
(This Initialize the safety circuits on the Machine door)
3. Move the MODE dial to REF position also know as Reference make sure your feed rate is not on "0"



4. Make sure the Door is closed
5. Press the X+ (arrow pointing up) this references the X axis.
(Wait until X is fully reference)
6. Press the Z- (arrow pointing left) this references the Z axis

OR


Press this
Button



Reference all axis

Note: Every time you enter Fanuc 21 Software or Turn the Machine On you must reference the axis

WORK SHIFT



Zero offset from machine zero point M to workpiece zero point W

With EMCO lathes the machine zero "M" lies on the rotating axis and on the end face of the spindle flange. This position is unsuitable as a starting point for dimensioning. With the so-called zero offset the coordinate system can be moved to a suitable point in the working area of the machine.

The offset register offers one adjustable zero offset.

When you define a value in the offset register, this value will be considered with program start and the coordinate zero point will be shifted from the machine zero M to the workpiece zero W.


The workpiece zero point can be shifted within a program with "G92 - Coordinate system setting" in any number.

More informations see in the command description.

The Coordinate System

The X coordinate lies in the directions of the cross slide, the Z coordinate in the direction of the longitudinal slide.

Coordinate values in minus directions describe movements of the tool system towards the workpiece. Values in plus direction away from the workpiece,



Absolute coordinates refer to a fixed position, incremental coordinates to the tool position. The bracket values for X, -X, U, -U are valid for the PC TURN 50 because the tool is in front of the turning centre on this machine.

Coordinate System for Absolute Value Programming

The origin of the coordinate system lies at the machine zero "M" or at the workpiece zero "W" following a programmed zero offset.

All target points are described from the origin of the coordinate system by the indication of the respective X and Z distances.

X distances are indicated as the diameter (as dimensioned on the drawing).

Coordinate System for Incremental Value Programming

The origin of the coordinate system lies at the tool mount reference point "N" or at the cutting tip after a tool call-up.


The U coordinate lies in the direction of the cross slide, the W coordinate in the direction of the longitudinal slide. The plus and minus directions are the same as for absolute value programming.

With incremental value programming the actual paths of the tool (from point to point) are described. X distances are indicated as the diameter.

Work Shift:

Note: There are 2 main ways of doing this Education way or **Industry way**. Step 1 thru 3 is for the Education way; skip these steps if you are setting up **Industry way**; go to step 4.

1. Index to a empty ID location

- Manually index by going to Jog Mode and Pressing Index button 

OR

- Programming Index

Rotate Mode Dial to MDI

Press the PROGRAM display button

Until top left of the screen shows **PROGRAM (MDI)**

Type T0100 (if the ID location wanted is position 1)

Press Input button





Then press CYCLE START  (Door must be closed)

2. If the Dial is not in Jog rotate Mode Dial to Jog

3. Jog the TURRET to the face of the Work Piece & touch using the Direction keys.

(Use piece of paper between TURRET and Work Piece)

(Use the Feed override dial or Steps to approach at a slower feed)




4. Press the OFFSET/SETT button until Work Shift page appears
5. Make sure (Shift Value) Z is 0 if not cursor to Z under (SHIFT VALUE) and type 0 and Input

OFFSET
SETT.

Note : **Industry way** skip steps 6 thru 8 but read the red print at the bottom of the page

6. The value that is in the ACTUAL POSITION (RELATIVE) Z type this value in (SHIFT VALUE) Z as a negative number
7. Then press INPUT button
8. Jog TURRET away from WORK PIECE using Z+

This value is the distance from the Spindle Nose to the end of the Work Piece




Note: Machine 0 is the turret face touching the spindle nose.

NEVER put a value in SHIFT VALUE X

TOOL OFFSETS

T 01 01






GE Fanuc Series 0 - T

F100% S100%
O0001 N0000

OFFSET/GEOMETRY				
No.	X	Z	R	T
G 01	0.000	0.000	0.000	0
G 02	0.000	0.000	0.000	0
G 08	0.000	0.000	0.000	0

ACT. POSITION (RELATIVE)
U 0.000 W 0.000
ADRS. S 0.000
JOG

WEAR GEOM W.SHIFT



Tool Offsets

1. Index the TURRET to the tool being measured

- Move the MODE Dial to MDI position
- Press Program button until **PROGRAM (MDI)** is at the top left of the screen

- Type tool number then press INPUT button



Example: T0200

- A. For scratching type S1000 M03 press INPUT button





S = Spindle speed M03 = spindle on clockwise



- Press CYCLE START  (make sure door is closed)

2. Move the MODE Dial to JOG position

3. Jog TOOL TIP to the WORK PIECE & touch TOOL TIP to the DIAMETER of the WORK PIECE using the Direction keys.



(Use the Feed override dial or Steps to approach at a slower feed)



4. Press the OFFSET/SETT button until Geometry page appears

OFFSET
SETT.

5. Type X and the Diameter being scratched

Example: X1 (If the diameter being scratch is 1"dia.)

6. Cursor down and over to highlight the G0 X location for the tool that is being measured

(Picture below shows tool 2 is being measured)

7. Then press soft key for

F4
(MEASUR)

8. Jog TURRET away from WORK PIECE using X+

This value is the distance from an I.D. Tool Station to the Tool Tip

OF 100%

OFFSET / GEOMETRY		00000 N00000	
NO.	X	Z	R T
G01	0.0000	0.0000	0.0000 0
G02	0.0000	0.0000	0.0000 0
G03	0.0000	0.0000	0.0000 0
G04	0.0000	0.0000	0.0000 0
G05	0.0000	0.0000	0.0000 0
G06	0.0000	0.0000	0.0000 0
G07	0.0000	0.0000	0.0000 0
G08	0.0000	0.0000	0.0000 0

ACTUAL POSITION (RELATIVE)

X	0.0000	Z	0.0000
---	--------	---	--------

> 1.097_ OS100% T



JOG **** * 11:38:33

F3 F4 F5 F6 F7

(NO.SRH) (MEASUR) (INP.C.) (+INPUT) (INPUT)>

9. Jog TOOL TIP to the end of the WORK PIECE & touch TOOL TIP to the FACE of the WORK PIECE using the Direction keys.

(Use the Feed override dial or Steps to approach at a slower feed)



10. Press the OFFSET/SETT button until Geometry page appears

OFFSET
SETT.

11. Type Z and 0 for reading from work shift 0

Example: Z0

12. Cursor down and over to highlight the G0 Z location for the tool that is being measured

(Picture below shows tool 2 is being measured)

13. Then press soft key for

F4
(MEASUR)


```

OF 100%
OFFSET / GEOMETRY                                00000 N00000
NO.      X      Z      R      T
G01      0.0000  0.0000  0.0000  0
G02      0.0000  0.0000  0.0000  0
G03      0.0000  0.0000  0.0000  0
G04      0.0000  0.0000  0.0000  0
G05      0.0000  0.0000  0.0000  0
G06      0.0000  0.0000  0.0000  0
G07      0.0000  0.0000  0.0000  0
G08      0.0000  0.0000  0.0000  0
ACTUAL POSITION (RELATIVE)
X      0.0000      Z      0.0000
>
OS 100% T
JOG **** * 11:39:22
F3      F4      F5      F6      F7
( NO.SRH ) ( MEASUR ) ( INP.C. ) ( +INPUT ) ( INPUT ) >

```

Note: Industry way the value for Z will be a large value
(This is the distance from spindle nose to the program 0 / front of the work piece)

14. R is the Tool Tip Radius



Note: Most insert packages or tool holders specify this value. If cutter comp is not used then the R value is not used


Type in the value for the tip radius

Emco tooling radius


55° insert = .015 Parting Off or Groove = .003

80° insert = .032 35° insert = .010

Threading insert = .001



15. T for cutter comp cutting direction



Note: **The T is Direction that the Tool Points.**
Tool doesn't need to look like Tool in the picture

All machines that have a turret on the bottom will also use the bracket #'s. Machines with turret on top will use regular #'s

16. Jog TURRET away from WORK PIECE using Z+

17. Repeat steps for all OD tools (STEPS 1-16 starting on pg 14)

Note: The T is Direction that the Tool Points. Tool does not need to look like Tool in the Picture

Live Tool Offsets

1. Index the TURRET to a **Axial** Tool

- Move the MODE Dial to MDI position
- Press Program button until **PROGRAM (MDI)** is at the top left of the screen

- Type tool number then press INPUT button

Example: T1100



- Press CYCLE START  (make sure door is closed)

2. Move the MODE Dial to JOG position

3. Jog TOOL TIP (Z axis) to the end of the WORK PIECE & touch TOOL TIP to the FACE of the WORK PIECE using the Direction keys.



(Use the Feed override dial or Steps to approach at a slower feed)



- Press the OFFSET/SETT button until Geometry page appears
- Type Z and 0 for reading from work shift 0

OFFSET
SETT.

Example: Z0

- Cursor down and over to highlight the G0 Z location for the tool that is being measured

(Picture below shows tool 11 is being measured)

- Then press soft key for

F4
(MEASUR)

OF 100%

00000 N00000

NO.	X	Z	R	T
G09	0.0000	0.0000	0.0000	0
G10	0.0000	0.0000	0.0000	0
G11	-0.7875	0.0000	0.0000	0
G12	0.0000	0.0000	0.0000	0
G13	0.0000	0.0000	0.0000	0
G14	0.0000	0.0000	0.0000	0
G15	0.0000	0.0000	0.0000	0
G16	0.0000	0.0000	0.0000	0

ACTUAL POSITION (RELATIVE)

X	Z
3.2283	3.1890

> Z0_ OS 100% T

EDIT ***** 07:33:12

F3 F4 F5 F6 F7

(NO.SRH) (MEASUR) (INP.C.) (+INPUT) (INPUT)>

- The X will be 20mm neg. (-.7874 inch) type this in then press INPUT button this is read as a Diameter value.

(The live tool positions 1,3,5,7,9,11 are offset negative 20mm diameter from the even positions 2, 4, 6, 8, 10, 12)


Note: Both Education / Industry ways are the same in the X direction
Industry way the value for Z will be a large value

9. R is Radius for an End Mill

Note: If cutter comp is not used then the R value is not used



10. I for cutter comp cutting direction



Live tools use 0 on Emco Education Fanuc Machines


11. Jog TURRET away from WORK PIECE using Z+

12. Repeat steps for all Axial Live tools

(STEPS 1-11 starting on pg 18)

1. Index the TURRET to a **Radial** tool

- Move the MODE Dial to MDI position
- Press Program button until **PROGRAM (MDI)** is at the top left of the screen



- Type tool number then press INPUT button





Example: T1100



- Press CYCLE START  (make sure door is closed)

2. Move the MODE Dial to JOG position

3. Jog TOOL TIP to the WORK PIECE & touch TOOL TIP to the DIAMETER of the WORK PIECE using the Direction keys.



(Use the Feed override dial or Steps to approach at a slower feed)



4. Press the OFFSET/SETT button until Geometry page appears

OFFSET
SETT.

5. Type X and the Diameter being scratched

Example: X1 (If the diameter being scratch is 1"dia.)

6. Cursor down and over to highlight the G0 X location for the tool that is being measured

(Picture below shows tool 9 is being measured)

7. Then press soft key for

F4
(MEASUR)

8. Jog TURRET away from WORK PIECE using X+

This value is the distance from an I.D. Tool Station to the Tool Tip

OF 100%

OFFSET / GEOMETRY 00000 N00000

NO.	X	Z	R	T
G09	0.0000	0.0000	0.0000	0
G10	0.0000	0.0000	0.0000	0
G11	0.0000	0.0000	0.0000	0
G12	0.0000	0.0000	0.0000	0
G13	0.0000	0.0000	0.0000	0
G14	0.0000	0.0000	0.0000	0
G15	0.0000	0.0000	0.0000	0
G16	0.0000	0.0000	0.0000	0

ACTUAL POSITION (RELATIVE)

X	3.2283	Z	3.1890
---	--------	---	--------

> X0_ OS100% T

EDIT ***** 07:28:54


F3 F4 F5 F6 F7

(NO.SRH) (MEASUR) (INP.C.) (+INPUT) (INPUT)>

Industry Way Only; Education way skip steps 9-15

9. Jog TOOL TIP to the end of the WORK PIECE & touch TOOL DIAMETER to the FACE of the WORK PIECE using the Direction keys.

(Use the Feed override dial or Steps to approach at a slower feed)



10. Press the OFFSET/SETT button until Geometry page appears

OFFSET
SETT.

11. Type Z and 0 for reading from work shift 0

Example: Z0

12. Cursor down and over to highlight the G0 Z location for the tool that is being measured

(Picture below shows tool 9 is being measured)

13. Then press soft key for

F4
(MEASUR)

OF 100%

OFFSET / GEOMETRY		00000 N00000	
NO.	X	Z	R T
G09	2.1580	0.0000	0.0000 0
G10	0.0000	0.0000	0.0000 0
G11	-0.7875	3.1890	0.0000 0
G12	0.0000	0.0000	0.0000 0
G13	0.0000	0.0000	0.0000 0
G14	0.0000	0.0000	0.0000 0
G15	0.0000	0.0000	0.0000 0
G16	0.0000	0.0000	0.0000 0

ACTUAL POSITION (RELATIVE)

X	Z
3.2283	3.1890

> Z0_ OS100% T

EDIT **** ** F3 F4 F5 F6 F7

(NO.SRH) (MEASUR) (INP.C.) (+INPUT) (INPUT) >

14. Type in - and the radius of the tool being used

Example: Using a ¼ inch drill or end mill


> -.125_

15. Press the soft keys for

F6
(+ INPUT)

Education Way Only; Industry way skip step 16


16. For Z type in **2.0078 inch** which is **(51 mm)**




**Note: If you are using one of the plugs on the tool turret to set
Workshift subtract 12.1mm (.476) from the 51mm (2.0078)
Length is preset from tool manufacture (WTO), provided by
EMCO Maier**

17. R is Radius for an End Mill

Note: If cutter comp is not used then the R value is not used



18. I for cutter comp cutting direction



Live tools use 0 on Emco Education Fanuc Machines


19. Jog TURRET away from WORK PIECE using Z+

20. Repeat steps for all Radial Live tools


(STEPS 1-17 starting on pg 21)

Program Training


Program O0001




Program O0002



Program O0003



Change the Mode Dial to Edit
Press the Program Button
To do functions on this page



- **INSERT A NEW PROGRAM**

1. Press letter o then a program number between 1- 8999
2. Press insert button



Example: Q0001 OR Q1

- **CALL A EXISTING PROGRAM UP**

1. Press letter o then program number in the directory
2. Press cursor down button



- **INSERT A WORD**

1. Press letter then number
2. Press insert button



HINT: When inserting a word to the left of the highlighted word the new word will be placed

Example: N5 G01 X 0.25; G01 is the word being inserted

- **INSERT END OF BLOCK**

1. Press the (EOB) button
2. Press insert button




HINT: at the end of each number line needs an End Of Block looks like a Semicolon (;)

Example: N5 G01 X1.00 F.003;

NOTE: IN EDIT & IN PROGRAM USE INSERT

USE INPUT FOR ALL OTHER SCREENS AND MODES.

Change the Mode Dial to Edit
Press the Program Button
To do functions on this page



- **DELETE A PROGRAM**

1. Press letter o then program number
2. Press delete button

Example: O0001 OR O1

- **DELETE ALL PROGRAMS**

1. Press letter o plus the – & 9999
2. Press delete button

Example: O – 9999

- **DELETE A WORD**

1. Highlight the Word
2. Press delete button

- **DELETE A BLOCK OR LINE NUMBER**

1. Type the number line and highlight the number line
2. Press delete button


- **CANCEL MISTYPED WORD (Backspace)**

1. Press cancel button

HINT: In the ADRS. (Address) at the lower left of the screen is the word & numbers that has been typed in. Before pressing insert or input check if what was typed in is correct. If not press cancel until error is erased and retype

Change the Mode Dial to Edit
Press the Program Button
To do functions on this page

PROG



- **ALTER A WORD**

1. Highlight the word needed altered type the change
2. Press alter button

ALTER

- **SEARCH FOR NUMBER BLOCK**

1. Press letter n and the number of the block
2. Press cursor down button



- **SEARCH FOR WORD**

1. Type in word & number
2. Press cursor down button



- **SEARCH FOR LETTER**

1. Press letter
2. Press cursor down button



HINT: This goes to the first (G). Follow steps 1 & 2 cursor goes to the next (G)

Groups of G codes

There are 3 groups of G-Codes; Emco Group uses the C group of G-Codes.
In relation to the other two Groups the only differences is the # for the G-Code

Gr.	Command			Function
	A	B	C	
0	+ G04	G04	G04	Dwell
	+ G07.1	G07.1	G07.1	Cylindrical Interpolaton
	+ G10	G10	G10	Data setting
	+ G11	G11	G11	Data setting Off
	+ G28	G28	G28	Return to reference point
	+ G70	G70	G72	Finishing cycle
	+ G71	G71	G73	Stock removal in turning
	+ G72	G72	G74	Stock removal in facing
	+ G73	G73	G75	Pattern repeating
	+ G74	G74	G76	Deep hole drilling, cut-in cycle in Z
	+ G75	G75	G77	Cut in cycle in X
	+ G76	G76	G78	Multiple threading cycle
	+ G90	G92	G92	Coord.syst.set., Spindle speed limit
1	• G00	G00	G00	Positioning (rapid traverse)
	G01	G01	G01	Linear interpolation clockwise
	G02	G02	G02	Circular interpolation clockwise
	G03	G03	G03	Circular interp. counterclockwise
	G90	G77	G20	Longitudinal turning cycle
	G92	G78	G21	Thread cutting cycle
	G94	G79	G24	Face turning cycle
	G32	G33	G33	Thread cutting
2	G96	G96	G96	Constant cutting speed
	• G97	G97	G97	Direct spindle speed programming
3	• -	G90	G90	Absolute programming
	-	G91	G91	Inkremental programming
5	G98	G94	G94	Feed per minute
	• G99	G95	G95	Feed per revolution
6	G20	G20	G70	Inch data input
	G21	G21	G71	Metric data input
7	• G40	G40	G40	Cancel cutter radius compensation
	G41	G41	G41	Cutter radius compensation left
	G42	G42	G42	Cutter compensation right
10	• G80	G80	G80	Cancel cycles
	G83	G83	G83	Drilling cycle
	G84	G84	G84	Tapping cycle
	G85	G85	G85	Reaming cycle
11	• -	G98	G98	Return to initial plane
	-	G99	G99	Return to withdrawal plane
16	G17	G17	G17	Plane selection XY
	G18	G18	G18	Plane selection ZX
	G19	G19	G19	Plane selection YZ
21	G12.1	G12.1	G12.1	Polar Coordinate Interpolation ON
	G13.1	G13.1	G13.1	Polar Coordinate Interpolation OFF

Example

G70 in the C group is programming in inches

G20 in the A & B group is programming in inches

Both are exactly the same but the G #

Survey of commands G-CODES (Group C): Mostly used

Model	G00	Rapid traverse
Model	G01	Linear interpolation in working feed
Model	G02	Circular interpolation, clockwise
Model	G03	Circular interpolation, counter-clockwise
Non-Model	G04	Dwell, active block by block
Model	G7.0	Cylindrical Interpolation OFF
Model	G7.1	Cylindrical Interpolation
Model	G10	Data Setting
Model	G11	Data Setting Off
Model	G12.1	Polar Coordinate Interpolation On
Model	G13.1	Polar Coordinate Interpolation Off
Model	G17	Plane Selection XY
Model	G18	Plane Selection ZX
Model	G19	Plane Selection YZ
Non-Model	G28	Approach reference point
Model	G40	Deselect cutter radius compensation
Model	G41	Cutter radius compensation left
Model	G42	Cutter radius compensation right
Model	G70	Dimensions in inch
Model	G71	Dimension in millimeter
Non-Model	G72	Finishing cycle
Non-Model	G73	Longitudinal turning cycle
Non-Model	G78	Multiple Thread cutting cycle
Model	G80	Deselect drilling cycles
Model	G83	Drilling cycle
Model	G90	Absolute value programming
Model	G91	Incremental value programming
Model	G92	Set coordinates zero point / speed limitation
Model	G94	Feed in inch/min
Model	G95	Feed in inch/rev
Model	G96	Constant cutting speed (Surface Footage)
Model	G97	Constant speed
Model	G98	Return to start plane
Model	G99	Return to withdraw plane

Bold print = is the Default codes that are on at all times until changed

Note: Most CONTROLS only take up to 4 G codes per line

Survey of commands M- CODES : Mostly used













M00	Programmed stop unconditional
M02	Main program end, new start of program
M03	Spindle ON clockwise
M04	Spindle ON counter clockwise
M05	Spindle OFF
M13	Driven Tool On Clockwise
M14	Driven Tool On Counterclockwise
M15	Driven Tool Off
M20	Tailstock sleeve backward
M21	Tailstock sleeve forward
M25	Release clamping device
M26	Close clamping device
M30	Main program end with new start of program
M52	C-axis On
M53	C-axis Off
M71	Blow-off ON (cleaning clamping device)
M72	Blow-off OFF
M98	Subroutine called up
M99	Subroutine end

Only one M-command per Block

Used Addresses

A	Angle
C	Chamfer, Axis Position data
F	Feed rate, thread pitch
G	Path, movement function
I, K	Circle parameter
U, W	Incremental, cycle parameter
M	Miscellaneous, machine function
N	Block number 1 to 9999, macro call out
O	Program number 1 to 9499
P	Dwell, subroutine, cycle parameter
Q	Cutting depth, cycle parameter
R	Radius, retraction, cycle parameter
S	Spindle speed
T	Tool called out
X, Z	Position data in absolute

Need one of each tool and holder / collet's

Position	Part #	Discription	Picture
T0202	A8Z 240	Radial tool holder VDI 16, M4	
	271 050	Finishing tool left	
	271 056	Indexable inserts for aluminum	
T0404	A8Z 230	Radial tool holder VDI 16, M3	
	271 110	OD-threading tool right	
	271 115	Indexable inserts for OD-threading, right	
T0909	A8Z 480	Radial milling holder VDI 16	
	152 760	Ø.236" ESX 16 COLLET (6.0mm)	
	573 770	Center drill, HSS (6mm)	
T1111	A8Z 470	Axial milling holder VDI 16	
	152 760	Ø.236" ESX 16 COLLET (6.0mm)	
	764 304	ø6 mm / shank- ø6 mm	

Program screen & Edit mode


To edit / change a program / insert new programs & input or output
excising programs & offsets

Program screen & MDI mode

To manually program the spindle speed / move the axis (X,Z) to a specified
location and or Index to a certain tool

**Note: Material is 2011-T3 Alum, All feeds & speeds are
programmed for this type of Aluminum**

Program Q0001



G73 U = Depth of Cut R = Retract Value

G73 P = First Block number of the Contour (Block number after the 2nd G73)

Q = Last Block number of the Contour F = Feed rate for cycle

(Facing in a cycle)

O0001 (Demo 1).....	Label Line Only
N5 (3 x 1.25 alum).....	Part Label Optional
N10 G40 G70 G80 G90	Default G Codes
N15 G95 G96 G98	sfpm
N20 G0 G28 U0 W0.....	safe move
N25 T0202 S700 M4 (Finish Tool 55°).....	Tool, Speed, Direction
N30 G0 X1.25 Z.1.....	start point of cycle
N35 G73 U.06 R.03.....	cycle parameters
N40 G73 P45 Q65 F.004.....	cycle begin / end lines
N45 G0 X0.....	first line of cycle
N50 G1 Z0.0.....	Z to Face of part
N55 X.5.....	1 st diameter of contour
N60 Z-1.0.....	length of contour
N65 X1.25.....	diameter of contour
N70 G0 G28 U0 W0.....	safe move
N75 M30.....	end of program

2D Simulation


1. Press **Graph** button on the Display Keys for the Graph screen to appear

[illegible]

Note: There are only 4 values you can change on this page the rest of them change by the values you will enter. This graph only works with an active program and runs only the current program selected

2. Work Length W = Overall length of stock in the Z direction this is a + value
3. Work Diameter D = Overall diameter of stock in the X direction + value
4. Graphic Center X = any area you wish to see past X0. Usually only if a Drill or a Tap is being used place a – value to see the tool movements for X pasted 0
Example -.100 is a common value entered
5. Graphic Center Z = this value is always a negative number and this is the area you wish to view. The longest Z- number in the program is normally used here

6. Press the Soft key **Graph** for Simulation screen



7. Now press **Cycle start** and you will see the tool movements of the program

- **Changing I/O to floppy drive** (Only need to do this once stays default)

1. Move the Mode Dial to **EDIT**
2. Press **System** on the display keys
3. Page down until you see Parameter (Manual)
4. Cursor down to the I/O
5. Type A (for the Floppy Drive) press Input key

Other Drives useable: **B (Drive), C (Drive), P (Printer), 1, 2 (Com Ports)**

Note: If you want to use USB use C and then follow instruction in the Appendix

- **Output Program from Fanuc software to Drive unit**

1. Press the **Program** on the display key
2. Type program number to be send out
Example: letter O and program number
(O0002) or (O2)
3. Press the right Arrow key on the Soft keys
4. Press Punch then press Exec

- **Output Offsets from Fanuc software to Drive unit**

1. Press the **Offset/Sett** display key
2. Press (OPRT)
3. Press the right Arrow key on the Soft keys
4. Press Punch then press Exec


- **Input Program into Fanuc Software from Drive unit**

1. Press the **Program** display key
2. Type program number to be read
Example: letter O and program number
(O0002) or (O2)
3. Press the right Arrow key on the Soft keys
4. Press Read then press Exec

- **Input Offsets into Fanuc Software from Drive unit**

1. Press the **Offset/Sett** display key
2. Press (OPRT)
3. Press the right Arrow key on the Soft keys
4. Press Read then press Exec

Running a Program

Note: If the correct program # is at the top right corner of the screen then skip step 3 only and press reset for step 3 

1. Rotate the Mode dial to Edit

2. Press the Program button

PROG

3. Call up Program to be run / cut
(Example O1 for program 1)

4. Rotate the Mode dial to MEM


5. If screen is not in **PROGRAM CHECK** then press program button until this is at the top left of the screen

PROG

6. Press the Single Block button for the program to run one line at a time.

SBL

Note: Use one hand on the feed override dial slowly increasing it and the other pressing cycle start and close to the reset button




7. Press Cycle Start and continue

(Once the program have moved in the safe called out locations for X, Z and looks right; you can take single block off and run the program)

8. Press Cycle Start one more time

(If there is more than one tool; before the next tool use single block to check the offsets locations for X, Z then continue at step 8 again)

Program Q0001 using C/R's



G73 U = Depth of Cut R = Retract Value

G73 P = First Block number of the Contour (Block number after the 2nd G73)

Q = Last Block number of the Contour F = Feed rate for cycle

(Facing in a cycle)

O0001(Demo 1)

N5 (3.25 x 1" alum)

N10 **G40 G70 G80 G90**

N15 **G95 G96 G98**.....sfpm

N20 G0 Z2.0.....safe move

N25 T0202 S550 M3 (Finish Tool 55°)

N30 G0 X1.0 Z.1.....start point of cycle

N35 G73 U.03 R.015.....cycle parameters

N40 G73 **P45 Q65** F.004.....cycle begin and end lines

N**45** G0 X0.....first line of cycle

N50 G1 Z0.0.....movement to face of part

N55 X.5 **C.05**.....1st diameter of contour


N60 Z-1.0 **R.1**.....length of contour

N**65** X1.0.....diameter of contour

N70 G0 Z2.0.....safe move

N75 M30.....end of program

Program Q0002



G73 **U** = Depth of Cut **R** = Retract Value

G73 **P** = First Block number of the Contour (Block number after the 2nd G73)
Q = Last Block number of the Contour **U** = Allowance for Finish cut in X
W = Allowance for Finish cut in Z **F** = Feed rate for the cycle

HINT:

The X **BEFORE** G73 example (X 1.25) should be (=) to or (>) than X at the **END** of the Cycle. X at the end of the cycle determines stock size

G72 **P** = First Block number of the Contour (Block number after G73)
Q = Last Block number of the Contour

HINT:

BEFORE the G72 call a spindle **SPEED** higher and **FEED** rate lower
If possible change tool to a 55 degrees for FINISHING & 80 degree for
ROUGHING

G78 CYCLE MULTIPLE

Example for 1/2 20 thread

1ST G78

P = Is 6 Digits divided in 2 Digit groups

P = 1st two digits is number of FINISH PASSES 01

2ND two digits is PULL OUT ANGLE 00

3rd two digits is angle of the THREADS 60 degrees

Q = Minimum cutting DEPTH 0020 (Micro IN)

R = Finishing OFFSET .001

2nd G78

X = Minor DIA. X .434

Z = Length of THREAD from (0) call out Z -1.05

P = Depth of THREAD Radial 0330 (Micro IN)

Q = First cutting DEPTH 0120 (Micro IN)

F = Thread PITCH .050

Micro IN is the value without the decimal point

Example: .1000 is shown as 1000 (show all 4 place values)

HINT: Threading

$$\text{TPI} = \frac{1}{20} = \frac{1}{(F)} .05$$

$$\text{IPM} = \text{RPM} \times \text{PITCH}$$

$$\text{RPM} = \frac{\text{IPM}}{\text{PITCH}} = \frac{50}{.05} = 1000 \text{ RPM} \qquad 78 \text{ is max for a Concept 55 Machine}$$

Make sure the X value before the G78 is larger than the MAJOR Diameter and the Z is at least 2 times the PITCH before cutting threads

Example: N100 G0 X.55 Z.1 ; THIS IS THE START POINT FOR G78
N105 G78 ;

Program Q0002

O0002 (Demo 2)
N5 (Stock 3.25 x 1 alum)
N10 G0 Z2
N15 G96 T0202 S550 M3 (Finish Tool 55°)
N20 G0 X1.1 Z.1.....Safe start for Facing
N25 Z0.....Face of part
N30 G1 X-.02 F.002.....Facing past Zero
N35 G0 X1.0 Z.1.....Start point of cycle
N40 G73 U.04 R.02.....Cycle parameters
N45 G73 P50 Q115 U.01 W.005 F.004.....Cycle finish offsets
N50 G0 G42 X.2.....Turning CRC on
N55 G1 Z0.....Face of part
N60 X.35 C.05
N65 Z-.15
N70 X.5 C.05
N75 Z-.950
N80 X.35 Z-1.125
N85 Z-1.3 R.1
N90 X.6
N95 X.75 Z-1.5
N100 Z-1.6
N105 G2 X.75 Z-1.994 R.4
N110 G1 Z-2.2
N115 G1 X1.0
N120 G0 G40 X1.1.....Cancel CRC
N125 S700 F.002
N130 G72 P50 Q120
N135 G0 Z2Safe Index Pos
N140 G97 S560 M3Threading Speed in RPM
N145 T0404 (Threading Tool Right Hand)
N150 X.55 Z.1.....Start Pos. Thread Cycle
N155 G78 P010060 Q0020 R.001.....Threading cycle
N160 G78 X.434 Z-1.125 P0330 Q0120 F.05
N165 G0 Z2Safe Return
N170 M30.....End of Program

1. To make a program tie together use M98 this calls out Sub programs or Sub routines.
Example: M98 P010001
2. After M98 P is identified with 6 digits.
 - The First 2 digits is the number of times program is to be repeated
 - The next 4 digits is the program number without the letter O
3. Programs that are being used as a Sub Programs must end with M99 instead of M30.
4. All programs can be used as Sub Programs or Main Programs
M99 means program is Sub, M30 means program is a Main
5. A main Program can also use M99 at the end.
 - Program is being used to repeat without cutting multiple parts.
 - This is mainly used for Demo's for just seeing Tool movements.

TEST FOR SUB PROGRAMS

O0005 (Tie Programs)

N5 (Stock 3.25 x 1 alum)


N10

N15

N20

Changing Item

Note: Change the end of O0001 and O0002 to M99 for running them as SUB PROGRAMS



Find the I and J for the arc in the picture

$$A^2 \text{ (K leg)} + B^2 \text{ (I leg)} = C^2 \text{ (H radius)}$$



S $\frac{O}{H}$


C $\frac{A}{H}$

T $\frac{O}{A}$

Sally Can Tell Oscar Has A Hat On Always

SINE COSINE TANGENT

Program O0005



O0005 (Live Tool Demo)

N5 (3.25 x 1.25)

N10 G28 U0 W0

(SAFE POSITION)

N15 T0202

(FINISHING TOOL LEFT HAND)

N20 G96 S700 M4

N25 X1.3 Z0

(FACING)

N30 G1 X-.02 F.003

N35 G0 X1.25 Z.1

N40 G73 U.1 R.05

(ROUGHING CYCLE)

N45 G73 P50 Q110 U.01 W.005 F.004

N50 G0 G42 X.3

N55 G1 Z0

N60 G1 X.5 C.05

N65 Z-.4

N70 X.45 Z-.5

N75 X.75 R.075

N80 Z-.7

N85 X1.05 Z-1.1
 N90 Z-1.3
 N95 G2 X1.05 Z-1.8 R.400
 N100 G1 Z-1.9
 N105 X1.25 R.04
 N110 Z-2.0
 N115 G0 G40 X1.26
 N120 S900 F.002
 N125 G72 P50 Q115 (FINISHING CYCLE)
 N130 G28 U0 W0 (SAFE INDEX MOVE)
 N135 G97 T0404 S1000 M3 (THREADING TOOL RIGHT HAND)
 N140 G0 X.55 Z.2
 N145 G78 P010060 Q0020 R.001 (THREADING CYCLE)
 N150 G78 X.414 Z-.45 P0330 Q0100 F.05
 N155 G28 U0 W0

USING THE C-AXIS AS A Y-AXIS

N160 M5
 N165 T1111 (6 mm END MILL in AXIAL HOLDER)
 N170 M52 (TURN ON C AXIS)
 N175 M13 (LIVE SPINDLE ON CLOCKWISE)
 N180 G97 S1500 (DIRECT RPM)
 N185 G28 C0 (REFERENCE C AXIS)
 N190 G12.1 (PCI ON)
 N195 G0 X1.3 Z-.7 C0 (SAFE MOVE)
 N200 G1 G41 X.750 C.2 F.008 (CRC ON)
 N205 G1 C0 F.004 (POSITION 1)
 N210 X.375 C-.325 (POSITION 2)
 N215 X-.375 (POSITION 3)
 N220 X-.750 C0 (POSITION 4)
 N225 X-.375 C.325 (POSITION 5)
 N230 X.375 (POSITION 6)
 N235 X.750 C0 (POSITION 7)
 N240 C-.200 (SAFE MOVE)
 N245 G1 G40 X.9 C-.4 (CRC OFF)
 N250 G13.1 (PCI OFF)
 N255 G0 X.9 Z-.25 M15 (LIVE SPINDLE OFF)
 N260 M53 (C-AXIS OFF)




USING THE C-AXIS AS DEGREES

N265 M52	(C-AXIS ON)
N270 M13	(LIVE SPINDLE CLOCKWISE)
N275 G97 S1500	(DIRECT RPM)
N280 G28 C0	(REFERENCE C-AXIS)
N285 G0 X.8	(MAKING SLOT ON THE FRONT OF PART)
N290 C90	(TURN C IN DEGREES)
N295 G1 X0 F.003	
N300 G0 C270	(TURN C IN DEGREES)
N305 G1 X.8	
N310 G28 U0 W0	
N315 T0909	(CENTER DRILL IN RADIAL HOLDER)
N320 G97 S1800	(LIVE SPINDLE CLOCKWISE)
N325 G0 X1.1	(MAKING DRILLED HOLES AROUND PART)
N330 Z-1.2	
N335 C60	(DEGREES)
N340 G1 X.65 F.003	
N345 G0 X1.1	
N350 C120	(DEGREES)
N355 G1 X.65	
N360 G0 X1.1	
N365 C180	(DEGREES)
N370 G1 X.65	
N375 G0 X1.1	
N380 C240	(DEGREES)
N385 G1 X.65	
N390 G0 X1.1	
N395 C300	(DEGREES)
N400 G1 X.65	
N405 G0 X1.1	
N410 C360	(DEGREES)
N415 G1 X.65	
N420 G0 X1.1 M15	
N425 M53	(C-AXIS OFF)
N430 G28 U0 W0	
N435 G97	
N440 T0404 S1000 M3	(THREADING TOOL RIGHT HAND)
N445 G0 X.55 Z.2	(DEBURRING THREADS)
N450 G78 P010060 Q0330 R.001	
N455 G78 X.414 Z-.45 P0330 Q0100 F.05	
N460 G28 U0 W0	(SAFE MOVE)
N465 M30	

Appendix


Changing Drive to USB Port


1. Close out the SW (software)

- Press  to allow you to exit
- Press  and  together to exit the Software

2. Make sure USB is plug into port


3. Open Explorer

- Right Click on Either My Computer, My Documents or any Folder on the Desktop
- Move mouse to  (Explorer)
- Left Click
- If you right clicked on My computer skip to step 4 if not then Left Click on My Computer



4. Copy Drive directory

- Click on you USB drive
- At the top of the active screen or page in the Address copy or remember drive info




- Close the active screen or page using either Alt and F4 or  at top of the active screen






5. Setting up WinConfig

- Left Click on Green Start button on Desktop
- Move mouse to All Program or Programs
- Move mouse to EMCO
- Move mouse to WinNC-WinConfig WinNC or WinNC32 – Singlelicense or MultipleLicense or Mal (Machine)


- Left Click



6. In Winconfig

- Left Click on  (INI) button
- Double Left Click on **Directories** (Directories)
- Left click on white box  (Import / Export directory)
- Either Press Ctrl and V (this will paste in the info) or type in USB directory
- Left Click on  (OK)
- Left Click on  (Close)
- Left Click on  (Yes) to save the changes

7. Restart SW (software)

- Left Click on Green Start button on Desktop
- Move mouse to All Program or Programs
- Move mouse to EMCO
- Move mouse to WinNC with this  icon on it
- Left Click