



**innovative machine tools**



# **GE FANUC 21 155/325II TCM TRAINING GUIDE**


9/11/03 Version 6  
Made by EMCO  
Authorized by Chad Hawk

# Training Index


<b>Fanuc 21 Control .....</b>	<b>Pg 1</b>
• Machine Control	
<b>Fanuc 21 Screen .....</b>	<b>Pg 2</b>
<b>Fanuc 21 Keys .....</b>	<b>Pg 3</b>
• Cursor Movement Keys	
• Change Keys	
• Store Keys	
<b>Data Input Keys .....</b>	<b>Pg 4</b>
• Function Keys (Display Keys)	
• Soft Key Module	
<b>Machine Keys .....</b>	<b>Pg 5</b>
• Machine Function Keys	
<b>Direction Keys .....</b>	<b>Pg 6</b>
• Spindle Override Keys	
• Accessory Functions	
<b>Mode Dial .....</b>	<b>Pg 7</b>
• Feed Override Dial	
<b>Referencing the Machine .....</b>	<b>Pg 8</b>
<b>Work Shift Description (Picture) .....</b>	<b>Pg 9</b>
<b>Work Shift (How to do Work Shift) .....</b>	<b>Pg 10</b>
<b>Tool Offset Description (Picture) .....</b>	<b>Pg 12</b>
<b>Tool Offset (How to do Tool Offsets for X) .....</b>	<b>Pg 13</b>
• Manually programming Turret Index	
• Manually programming Spindle on	
<b>Tool Offset (How to do Tool Offsets for Z) .....</b>	<b>Pg 15</b>
<b>Live Tool Offset (Axial) .....</b>	<b>Pg 17</b>
<b>Live Tool Offset (Radial) .....</b>	<b>Pg 19</b>

<b>Program Training .....</b>	<b>Pg 22</b>
<b>Inserting a New Program .....</b>	<b>Pg 23</b>
• Calling a Existing Program up	
• Insert a word	
• Insert a End of Block	
<b>Delete a Program .....</b>	<b>Pg 24</b>
• Delete all Programs	
• Delete a word	
• Delete a Block	
<b>Cancel word .....</b>	<b>Pg 25</b>
• Alter a word	
• Search for number Block	
• Search for word	
<b>G Codes .....</b>	<b>Pg 26</b>
<b>M Codes .....</b>	<b>Pg 27</b>
• Used Addresses	
<b>Program 1 .....</b>	<b>Pg 29</b>
<b>2D simulation (Setup) .....</b>	<b>Pg 30</b>
<b>Input &amp; Output the Programs &amp; offsets thru the Fanuc Software ....</b>	<b>Pg 32</b>
<b>Program 1 (C &amp; R) .....</b>	<b>Pg 33</b>
<b>Program 2 (G73 and G72 Description) . ....</b>	<b>Pg 34</b>
<b>G78 Description .....</b>	<b>Pg 35</b>
<b>Program 2 .....</b>	<b>Pg 36</b>
<b>Sub Programming.....</b>	<b>Pg 37</b>
<b>Program O0003 .....</b>	<b>Pg 38</b>
<b>Program O0005 (Live Tooling Program).....</b>	<b>Pg 40</b>


# FANUC 21 CONTROL



# MACHINE CONTROL



# The Fanuc 21 Screen



1. **Displays of Feed**
2. **Spindle Speed override**
3. **Display of Program and Number block**
4. **Display of active Screen**
5. **Entry line**
6. **Display of active Mode**
7. **Display of Soft key Functions**

# FANUC 21 KEYS



**RESET = cancels most alarms, resets program,  
interrupts programs**

## **CURSOR MOVEMENT KEYS**



**CURSOR UP = moves cursor up**



**CURSOR DOWN = moves cursor down, search  
function, program call up**



**PAGE UP = moves one page up**



**PAGE DOWN = moves one page down**



**CURSOR RIGHT = moves cursor right**



**CURSOR LEFT = moves cursor left**

## **CHANGE KEYS**



**ALTER = alter word (replace word)**



**INSRT = insert word, create new program**



**DELET = deletes word / block or programs**



**EOB = end of block**



**CAN = deletes entries in the address one by one**



**INPUT = input offsets / words or numbers**

## DATA INPUT KEYS



Press a button for a letter / number needed. Use Shift for the second letter or symbol on that button.

## FUNCTION KEYS (DISPLAY KEYS)



**POS** = displays actual, relative, machine positions



**PROG** = displays program, library page



**OFFSET/ SETTINGS** = displays wear, geometry, work shifts pages



**SYSTEM** = displays parameters, diagnostic pages




**MESSAGE** = displays operator & alarm messages



**AUX / GRAPH** = displays 2-d graph simulation

## **SOFT KEYS**



**SCROLL BACK**

**SOFT KEYS**

**PAGES OVER**

# MACHINE KEYS

## MACHINE FUNCTION KEYS



= Press skip any block lines with ( / Slash) before block number will be skipped



= Test run without spindle on (remove raw material from chuck)



= (Single piece) for continuous mode active only on automatic material loading



= (Optional stop) for programs with (m1)



= (Reset) cancels most alarms, resets program, interrupts programs



= (Single block) reads one block line at a time



= (Cycle stop) program hold, feed hold



= (Cycle start) program start



= (Agreement button) used for open/closing door or to jog axis with the door open




= (Mode Key) Automatic & Hand Mode

Hand Mode is for moving machine around with door open and works in conjunction with the (Agreement button)



=(Cycle start) program start





## DIRECTION KEYS

These keys control axis directional movements

+4 & -4 = Additional axis

Reference all axis

Feed stop (Red) / Feed start (Green) works all modes but EDIT & ZRN



## SPINDLE OVERRIDE KEYS


Arrow key pointing right increase the Spindle speed (120% high)

Arrow key pointing left decrease the Spindle speed (50% low)

100% key jumps speed to 100%

Spindle stop (Red) / Spindle start (Green)

Works all modes except EDIT & ZRN (Reference)



## ACCESSORY FUCTIONS

Arrow right door closed

Arrow left door open

Press once chuck open

Press again chuck closed

**Press turret index's one time clockwise  
Each time pressed**

Press tailstock moves backward

Press tailstock moves forward


Press once coolant on

Press again coolant off

Press auxiliary drives on (Green)

Press auxiliary drives off (Red)

## MODE DIAL



- (1) REF = Zero / Reference or Home mode
- (2) MEM = Automatic mode for running a program
- (3) EDIT = Edit mode for program changes or entering a new program
- (4) MDI = Manual Data Input mode for manually running the machine
- (5) JOG = Manual moving the axis in x or z
- (6) STEPS = Incremental feed movements
- (7) STEPS = .0001 or tenths
- (8) STEPS = .001 or thousands
- (9) STEPS = .010 or ten thousands
- (10) STEPS = .100 or hundred thousands
- (11) STEPS = .100 or hundred thousands



## FEED OVERRIDE DIAL




Controls feed for jogging in the X Axis and the Z Axis. Overrides from 0% to 120% of the programmed feed rate or the rapid rate


# Turning the Machine On/Entering Fanuc Software

## Referencing the Machine

1. Press the **AUX** button  (This turns on the Auxiliary Drives)
2. Press the **Agreement** button  and hold then **Open** door then **Shut** door (This Initialize the safety circuits on the Machine door)
3. Move the MODE dial to REF position also know as Reference make sure your feed rate is not on "0"




4. Press the X+ (arrow pointing up) this references the X axis.
5. Press the Z+ (arrow pointing left) this references the Z axis
6. For all axis press the Reference key



**Note:** Every time you enter Fanuc 21 Software or Turn the Machine On you must reference the axis

# WORK SHIFT



Zero offset from machine zero point M to workpiece zero point W

With EMCO lathes the machine zero "M" lies on the rotating axis and on the end face of the spindle flange. This position is unsuitable as a starting point for dimensioning. With the so-called zero offset the coordinate system can be moved to a suitable point in the working area of the machine.

The offset register offers one adjustable zero offset.

When you define a value in the offset register, this value will be considered with program start and the coordinate zero point will be shifted from the machine zero M to the workpiece zero W.


The workpiece zero point can be shifted within a program with "G92 - Coordinate system setting" in any number.

More informations see in the command description.

## The Coordinate System

The X coordinate lies in the directions of the cross slide, the Z coordinate in the direction of the longitudinal slide.

Coordinate values in minus directions describe movements of the tool system towards the workpiece. Values in plus direction away from the workpiece,



Absolute coordinates refer to a fixed position, incremental coordinates to the tool position. The bracket values for X, -X, U, -U are valid for the PC TURN 50 because the tool is in front of the turning centre on this machine.

### Coordinate System for Absolute Value Programming

The origin of the coordinate system lies at the machine zero "M" or at the workpiece zero "W" following a programmed zero offset.

All target points are described from the origin of the coordinate system by the indication of the respective X and Z distances.

X distances are indicated as the diameter (as dimensioned on the drawing).

### Coordinate System for Incremental Value Programming

The origin of the coordinate system lies at the tool mount reference point "N" or at the cutting tip after a tool call-up.

The U coordinate lies in the direction of the cross slide, the W coordinate in the direction of the longitudinal slide. The plus and minus directions are the same as for absolute value programming.

With incremental value programming the actual paths of the tool (from point to point) are described. X distances are indicated as the diameter.

## Work Shift:

1. Move the MODE dial to JOG position
2. Jog the TURRET to the face of the Work Piece & touch using the Direction keys.




3. Use piece of paper between TURRET and Work Piece

A. Turn the key to hand position



B. Press the  and hold while pressing the direction keys




4. Press the OFFSET/SETT button until Work Shift page appears
5. Make sure the (Shift value) Z is 0 if not highlight Z (Shift Value) type in 0 & press Input button
6. The value that is in the ACTUAL POSITION (RELATIVE) Z type this value in (SHIFT VALUE) Z as a negative number
7. Then press INPUT button
8. Jog TURRET away from WORK PIECE using Z+

OFFSET  
SETT.

INPUT

INPUT

This value is the distance from the Spindle Nose to the end of the  
Work Piece




**Note:** Machine 0 is the turret face touching the spindle nose.

**NEVER put a value in SHIFT VALUE X**



# TOOL OFFSETS



## Tool Offsets

1. Index the TURRET to a tool to be measured


- Move the MODE Dial to MDI position
- Press Program button
- Type tool number then press INPUT button




Example: T0200

1. For Scratching type S1000 then M04 press INPUT button

This is for Spindle speed & spindle on clockwise

2. Then press CYCLE START  (make sure door is closed)
3. Move the MODE Dial to JOG position
4. Jog TOOL TIP (X axis) to the WORK PIECE & touch TOOL TIP to the DIAMETER of the WORK PIECE using the Direction keys.





5. Press the OFFSET/SETT button until Offset / Geometry page appears



6. Actual Position (Relative) X subtract the Diameter of the Work Piece being scratched

7. Type value in G02 for X (If the tool being use is T0202)

8. Then press INPUT



9. Jog TURRET away from WORK PIECE using X+

Example: X is 2.962 Type 1.962 (If stock is 1"dia.)

---

OF 100%

OFFSET / GEOMETRY		00001		N00020	
NO.	X	Z	R	T	
G01	0.0000	0.0000	0.0000	0	
G02	0.0000	0.0000	0.0000	0	
G03	0.0000	0.0000	0.0000	0	
G04	0.0000	0.0000	0.0000	0	
G05	0.0000	0.0000	0.0000	0	
G06	0.0000	0.0000	0.0000	0	
G07	0.0000	0.0000	0.0000	0	
G08	0.0000	0.0000	0.0000	0	

ACTUAL POSITION (RELATIVE)  
X 0.0000      Z 0.0000

> \_
OS 100% T

EDIT
\*\*\*
\*\*\*
\*\*\*
22:15:51


F3
F4
F5
F6
F7

[ WEAR ]
[ GEOM ]
[
)]
[ (OPRT) ]

---

This value is the distance from the center of the Tool Station to the  
Tool Tip


10. Jog TOOL TIP (Z axis) to the end of the WORK PIECE & touch TOOL TIP to the FACE of the WORK PIECE using the Direction keys.
11. Press the OFFSET/SETT button until Offset / Geometry page appears



12. The Value in the Actual Position (Relative) Z type this value in G02 for Z (If the tool being use is T0202)

13. Then press INPUT button



Example: Z is .062 Type .062



14. Jog TURRET away from WORK PIECE using Z+

15. The R will be Tool Tip Radius

16. The I is the Tool Direction or Tool Type



Note: Direction that the Tool is pointing.

Tool doesn't need to look like Tool in the Picture

17. Repeat steps for all OD tools (STEPS 1-16 under Tool Offset)

# Live Tools Offset


1. Index the TURRET to a **Axial Tool**


- Move the MODE Dial to MDI position
- To do this press Program button
- Type tool number then press INPUT button

PROG

INPUT

Example: T1100

2. Then press CYCLE START  (make sure door is closed)
3. Move the MODE Dial to JOG position
4. Jog TOOL TIP (Z axis) to the end of the WORK PIECE & touch TOOL TIP to the FACE of the WORK PIECE using the Direction keys.



5. Press the OFFSET/SETT button until Offset / Geometry page

appears



6. The Value in the Actual Position (Relative) Z type this value in

G11 for Z (If the tool being use is T1111)

7. Then press INPUT button



Example: Z is 3.125 Type 3.125

---

OF 100%

OFFSET / GEOMETRY		00001 N00020	
NO.	X	Z	R T
G09	0.0000	0.0000	0.0000 0
G10	0.0000	0.0000	0.0000 0
G11	0.0000	0.0000	0.0000 0
G12	0.0000	0.0000	0.0000 0
G13	0.0000	0.0000	0.0000 0
G14	0.0000	0.0000	0.0000 0
G15	0.0000	0.0000	0.0000 0
G16	0.0000	0.0000	0.0000 0

ACTUAL POSITION (RELATIVE)  

X 0.0000
Z 0.0000

> \_
OS 100% T

EDIT \*\*\*\*
22:21:03

F3
F4
F5
F6
F7

[ WEAR ]
[ GEOM ]
[ ]
[ (OPRT) ]

---

8. The X will be 20mm neg. (-.7874 inch) type this in then press

INPUT button





this is read as a Diameter value.

(The live tool positions 1,3,5,7,9,11 are offset 10mm negative from the even positions 2,4,6,8,10,12.)

9. The R is the radius of the End Mill being used. If drill is used no radius is needed.


10. The T will always be 0 for live tools


1. Index the TURRET to a **Radial Tool**

- Move the MODE Dial to MDI position
- To do this press Program button 
- Type tool number then press INPUT button 



Example: T0900

2. Then press CYCLE START  (make sure door is closed)
3. Move the MODE Dial to JOG position
4. Jog TOOL TIP (X axis) to the WORK PIECE & touch TOOL TIP to the diameter of the WORK PIECE using the Direction keys.



5. Press the OFFSET/SETT button until Offset / Geometry page appears



6. Actual Position (Relative) X subtract the Diameter of the Work Piece being scratched

7. Type value in G09 for X (If the tool being use is T0909)

8. Then press INPUT



9. Jog TURRET away from WORK PIECE using X+

Example: X is 2.962 Type 1.962 (If stock is 1"dia.)

---

OF 100%

OFFSET / GEOMETRY		00001 N00020	
NO.	X	Z	R T
G01	0.0000	0.0000	0.0000 0
G02	0.0000	0.0000	0.0000 0
G03	0.0000	0.0000	0.0000 0
G04	0.0000	0.0000	0.0000 0
G05	0.0000	0.0000	0.0000 0
G06	0.0000	0.0000	0.0000 0
G07	0.0000	0.0000	0.0000 0
G08	0.0000	0.0000	0.0000 0

ACTUAL POSITION (RELATIVE)  
X      0.0000
Z      0.0000

> \_
OS 100% T

EDIT
\*\*\*
\*\*\*
\*\*\*
22:15:51

F3
F4
F5
F6
F7

[ WEAR ]
[ GEOM ]
[
)]
[ (OPRT) ]


---

This value is the distance from the center of the Tool Station to the Tool Tip

10. For Z type in **2.0078 inch** which is **(51 mm)**

11. The R is the radius of the End Mill that is used. If a Drill or Tap is used no radius is needed.

12. The T will always be 0 for live tools.




**Note: Length is preset from tool manufacture (WTO), provided by EMCO Maier**




# Program Training


**Program O0001**



**Program O0002**




**Program O0003**




Change the Mode Dial to Edit & Press the  to do functions below  
& on the next 2 Pages

- **INSERT A NEW PROGRAM**



1. Press letter o then program number
2. Press insert button 

Example: Q0001 OR Q1

- **CALL A EXISTING PROGRAM UP**

1. Press letter o then program number
2. Press cursor down button 




- **INSERT A WORD**

1. Press letter then number
2. Press insert button  or input 

**HINT:** When inserting a word to the left of the highlighted word the new word will be placed

Example: **N5** G01 X 0.25; G01 is the word being inserted

- **INSERT END OF BLOCK**


1. Press the (EOB) button 
2. Press insert button  or input 

**HINT:** at the end of each number line needs an End Of Block looks like a Semicolon (;)

Example: N5 G01 X1.00 F.003;


**NOTE:** IN EDIT & IN PROGRAM USE INSERT OR INPUT.  
USE **INPUT** FOR ALL OTHER APPLICATIONS.

- **DELETE A PROGRAM**

1. Press letter o then program number
2. Press delete button 


**Example: O0001 OR O1**

- **DELETE ALL PROGRAMS**

1. Press letter o plus the – & 9999
2. Press delete button 

**Example: O – 9999**

- **DELETE A WORD**

1. Highlight the Word
2. Press delete button 

- **DELETE A BLOCK OR LINE NUMBER**

1. Type the number line and highlight the number line
2. Press delete button 

- **CANCEL MISTYPED WORD (Backspace)**


1. Press cancel button 

**HINT:** In the ADRS. (Address) at the lower left of the screen is the word & numbers that has been typed in. Before pressing insert or input check if what was typed in is correct. If not press cancel until error is erased and retype


- **ALTER A WORD**

1. Highlight the word needed altered type the change
2. Press alter button 


- **SEARCH FOR NUMBER BLOCK**

1. Press letter n and the number of the block
2. Press cursor down button 

- **SEARCH FOR WORD**

1. Type in word & number
2. Press cursor down button 

- **SEARCH FOR LETTER**

1. Press letter
2. Press cursor down button 

**HINT:** This goes to the first (G). Follow steps 1 & 2 cursor goes to the next (G)

## Survey of commands G-GODES (Group C): Mostly used

G00 Rapid traverse  
G01 Linear interpolation in working feed  
G02 Circular interpolation, clockwise  
G03 Circular interpolation, counter-clockwise  
G04 Dwell, active block by block  
G7.0 Cylindrical Interpolation OFF  
G7.1 Cylindrical Interpolation  
G10 Data Setting  
G11 Data Setting Off  
G12.1 Polar Coordinate Interpolation On  
G13.1 Polar Coordinate Interpolation Off  
G17 Plane Selection XY  
G18 Plane Selection ZX  
G19 Plane Selection YZ  
G28 Approach reference point  
G40 Deselect cutter radius compensation  
G41 Cutter radius compensation left  
G42 Cutter radius compensation right  
G70 Dimensions in inch  
G71 Dimension in millimeter  
G72 Finishing cycle  
G73 Longitudinal turning cycle  
G78 Multiple Thread cutting cycle  
G80 Deselect drilling cycles  
G83 Drilling cycle  
G90 Absolute value programming  
G91 Incremental value programming  
G92 Set coordinates zero point / speed limitation  
G94 Feed in inch/min  
G95 Feed in inch/rev  
G96 Constant cutting speed (Surface Footage)  
G97 Constant speed  
G98 Return to start plane  
G99 Return to withdrawal plane

**Bold print = is the Default codes that are on at all times until changed**

## Survey of commands M- CODES: Mostly used













M00	Programmed stop unconditional
M02	Main program end, no new start of program
M03	Spindle ON clockwise
M04	Spindle ON counter clockwise
<b>M05</b>	<b>Spindle OFF</b>
M08	Coolant On
M09	Coolant Off
M13	Driven Tool On Clockwise
M14	Driven Tool On Counterclockwise
M15	Driven Tool Off
M20	Tailstock sleeve backward
M21	Tailstock sleeve forward
M23	Collection Tray Backward
M24	Collection Tray Forward
M25	Release clamping device
M26	Close clamping device
M30	Main program end with new start of program
M52	C-axis On
M53	C-axis Off
M98	Subroutine called up
M99	Subroutine end

**Only one M-command for one Block authorized**

## Used Addresses

C	Chamfer
F	Feed rate, thread pitch
G	Path function
I, K	Circle parameter
M	Miscellaneous function
N	Block number 1 to 9999
O	Program number 1 to 9499
P	Dwell, subroutine, cycle parameter
Q	Cutting depth
R	Radius, retraction, cycle parameter
S	Spindle speed
T	Tool called out
X, Z	Position data in absolute
;	Block end

**Need one of each tool and holder / collet's**

<b>Position</b>	<b>Part #</b>	<b>Discription</b>	<b>Picture</b>
T0202	A8Z 240	Radial tool holder VDI 16, M4	
	271 050	Finishing tool left	
	271 056	Indexable inserts for aluminum	
T0404	A8Z 230	Radial tool holder VDI 16, M3	
	271 110	OD-threading tool right	
	271 115	Indexable inserts for OD-threading, right	
T0909	A8Z 480	Radial milling holder VDI 16	
	152 760	Ø.236" ESX 16 COLLET (6.0mm)	
	573 770	Center drill, HSS (6mm)	
T1111	A8Z 470	Axial milling holder VDI 16	
	152 760	Ø.236" ESX 16 COLLET (6.0mm)	
	764 304	ø6 mm / shank- ø6 mm	

**Program screen & Edit mode**


To edit / change a program / insert new programs & input or output  
excising programs & offsets

**Program screen & MDI mode**

To manually program the spindle speed / move the axis (X,Z) to a specified  
location and or Index to a certain tool

**Note: Material is 2011-T3 Alum, All feeds & speeds are  
programmed for this type of Aluminum**

## Program Q0001



**G73** U = Depth of Cut R = Retract Value

**G73** P = First Block number of the Contour (Block number after the 2<sup>nd</sup> G73)

Q = Last Block number of the Contour F = Feed rate for cycle

### (Facing in a cycle)

O0001 (Demo 1)

N5 (3.25 x 1 alum)

N10 G40 G70 G80 G90.....active codes

N15 G95 **G96** G98.....active codes

N20 G0 G28 U0 W0.....safe move

N25 T0202 S700 M4.....(Right Hand Finish Tool 55°)

N30 G0 X1.0 Z.1.....start point of cycle

N35 G73 U.06 R.02.....cycle parameters

N40 G73 **P45** **Q65** F.004.....cycle begin and end lines

**N45** G0 X0.....first line of cycle

N50 G1 Z0.0.....movement to face of part

N55 X.5.....1<sup>st</sup> diameter of contour

N60 Z-1.0.....length of contour

**N65** X1.0.....diameter of contour

N70 G0 G28 U0 W0.....safe move

N75 M30.....end of program



## 2D Simulation

1. Press **Graph** button on the Display Keys for the Graph screen to appear

```

OF 100%
GRAPHIC PARAMETER      00001  N00000

WORK LENGTH            W =  0.0000
WORK DIAMETER          D =  0.0000
PROGRAM STOP           N =    0
AUTO ERASE             A =    1
LIMIT                  L =    0
GRAPHIC CENTER         X =  0.0000
                       Z =  0.0000
SCALE                  S =  0.000
GRAPHIC MODE           M =    0


> _
JOG  ****   ***   ***      20:21:13      OS100% T
      F3          F4          F5          F6          F7
( G.PRM ) (          ) ( GRAPH ) (          ) (          ) >

```

Note: There are only 4 values you can change on this page the rest of them change by the values you will enter. This graph only works with an active program and runs only the current program selected

2. Work Length W = Overall length of stock in the Z direction this is a + value
3. Work Diameter D = Overall diameter of stock in the X direction + value
4. Graphic Center X = any area you wish to see past X0. Usually only if a Drill or a Tap is being used place a – value to see the tool movements for X pasted 0  
Example -.100 is a common value entered
5. Graphic Center Z = this value is always a negative number and this is the area you wish to view. The longest Z- number in the program is normally used here

6. Press the Soft key **Graph** for Simulation screen



7. Now press **Cycle start** and you will see the tool movements of the program

- **Changing I/O to floppy drive** (Only need to do this once stays default)

1. Move the Mode Dial to **EDIT**
2. Press **System** on the display keys
3. Page down until you see Parameter (Manual)
4. Cursor down to the I/O
5. Type A (for the Floppy Drive) press Input key

Other Drives useable: **B (Drive), C (Drive), P (Printer), 1 , 2 (Com Ports)**

- **Output Program from Fanuc software to Drive unit**

1. Press the **Program** on the display key
2. Type program number to be send out  
Example: letter O and program number  
(O0002) or (O2)
3. Press the right Arrow key on the Soft keys
4. Press Punch then press Exec

- **Output Offsets from Fanuc software to Drive unit**

1. Press the **Offset/Sett** display key
2. Press (OPRT)
3. Press the right Arrow key on the Soft keys
4. Press Punch then press Exec


- **Input Program into Fanuc Software from Drive unit**

1. Press the **Program** display key
2. Type program number to be read  
Example: letter O and program number  
(O0002) or (O2)
3. Press the right Arrow key on the Soft keys
4. Press Read then press Exec

- **Input Offsets into Fanuc Software from Drive unit**

1. Press the **Offset/Sett** display key
2. Press (OPRT)
3. Press the right Arrow key on the Soft keys
4. Press Read then press Exec

## Program Q0001 using C/R's



**G73** U = Depth of Cut R = Retract Value

**G73** P = First Block number of the Contour (Block number after the 2<sup>nd</sup> G73)

Q = Last Block number of the Contour F = Feed rate for cycle

**(Facing in a cycle)**

O0001 (Demo 1)

N5 (3.25 x 1 alum)

N10 **G40 G70 G80 G90**

N15 **G95 G96 G98**

N20 G0 G28 U0 W0.....safe move

N25 T0202 S700 M4 (Left Hand Finish Tool 55°)

N30 G0 X1.0 Z.1.....start point of cycle

N35 G73 U.06 R.02.....cycle parameters

N40 G73 **P45 Q65** F.004.....cycle begin and end lines

**N45** G0 X0.....first line of cycle

N50 G1 Z0.0.....movement to face of part

N55 X.5 **C.05**.....1<sup>st</sup> diameter of contour


N60 Z-1.0 **R.1**.....length of contour

**N65** X1.0.....diameter of contour

N70 G0 G28 U0 W0.....safe move

N75 M30.....end of program

## Program Q0002



**G73**    **U** = Depth of Cut    **R** = Retract Value

**G73**    **P** = First Block number of the Contour (Block number after the 2<sup>nd</sup> G73)  
           **Q** = Last Block number of the Contour    **U** = Allowance for Finish cut in X  
           **W** = Allowance for Finish cut in Z    **F** = Feed rate for the cycle

### HINT:

The X **BEFORE** G73 example (X 1.25) should be (=) to or (>) than X at the **END** of the Cycle. X at the end of the cycle determines stock size

**G72**    **P** = First Block number of the Contour (Block number after G73)  
           **Q** = Last Block number of the Contour

### HINT:

**BEFORE** the G72 call a spindle **SPEED** higher and **FEED** rate lower

If possible change tool to a 55 degrees for FINISHING & 80 degree for ROUGHING

## G78 CYCLE MULTIPLE

### Example for 1/2 20 thread

#### 1<sup>ST</sup> G78

P = Is 6 Digits divided in 2 Digit groups

P = 1<sup>st</sup> two digits is number of FINISH PASSES      01

2<sup>ND</sup> two digits is PULL OUT ANGLE      00

3<sup>rd</sup> two digits is angle of the THREADS      60 degrees

Q = Minimum cutting DEPTH      0020 (Micro IN)

R = Finishing OFFSET      .001

#### 2<sup>nd</sup> G78

X = Minor DIA.      X .434

Z = Length of THREAD from (0) call out      Z -1.05

P = Depth of THREAD Radial      0330 (Micro IN)

Q = First cutting DEPTH      0120 (Micro IN)

F = Thread PITCH      .050

**Micro IN is the value without the decimal point**

**Example: .1000 is shown as 1000 (show all 4 place values)**

## HINT: Threading

$$\frac{1}{\text{TPI}} = \frac{1}{20} = (F) .05$$

$$\text{IPM} = \text{RPM} \times \text{PITCH}$$

$$\text{RPM} = \frac{\text{IPM}}{\text{PITCH}} = \frac{50}{.05} = 1000 \text{ RPM}$$

300 is max for a 155 machine  
315 is max for a 325II Machine

Make sure the X value before the G78 is larger than the MAJOR Diameter and the Z is at least 2 times the PITCH before cutting threads

Example: N100 G0 X.55 Z.1 ;    THIS IS THE START POINT FOR G78  
N105 G78;


## Program Q0002

O0002 (Demo 2)  
N5 (Stock 3.25 x 1)  
N10 G0 G28 U0 W0  
N15 G96 T0202 S700 M4 (Left Hand Finish Tool 55°)  
N20 G0 X1.1 Z.1.....Safe start for Facing  
N25 Z0.....Face of part  
N30 G1 X-.02 F.002.....Facing past Zero  
N35 G0 X1.0 Z.1.....Start point of cycle  
N40 G73 U.06 R.02.....Cycle parameters  
N45 G73 P50 Q115 U.01 W.005 F.004.....Cycle finish offsets  
N50 G0 G42 X.2.....Turning CRC on  
N55 G1 Z0.....Face of part  
N60 X.35 C.05  
N65 Z-.15  
N70 X.5 C.05  
N75 Z-.950  
N80 X.35 Z-1.125  
N85 Z-1.3 R.1  
N90 X.6  
N95 X.75 Z-1.5  
N100 Z-1.6  
N105 G2 X.75 Z-1.994 R.4  
N110 G1 Z-2.2  
N115 G1 X1.0  
N120 G0 G40 X1.1.....Cancel CRC  
N125 S1000 F.002  
N130 G72 P50 Q120  
N135 G0 G28 U0 W0.....Safe Index Pos  
N140 G97 S1000 M3 .....Threading Speed in RPM  
N145 T0404 (Threading Tool Right Hand)  
N150 X.55 Z.1.....Start Pos. Thread Cycle  
N155 G78 P010060 Q0020 R.001.....Threading cycle  
N160 G78 X.434 Z-1.125 P0330 Q0120 F.05  
N165 G0 G28 U0 W0.....Safe Return  
N170 M30.....End of Program

1. To make a program tie together use M98 this calls out Sub programs or Sub routines.  
Example: M98 P010001
2. After M98 P is identified with 6 digits.
  - The First 2 digits is the number of times program is to be repeated
  - The next 4 digits is the program number without the letter Q
3. Programs that are being used as a Sub Programs must end with M99 instead of M30.
4. All programs can be used as Sub Programs or Main Programs  
M99 means program is Sub, M30 means program is a Main
5. A main Program can also use M99 at the end.
  - Program is being used to repeat without cutting multiple parts.
  - This is mainly used for Demo's for just seeing Tool movements.



## Program O0003



O0003 (Ball Hitch)

N5 (Stock 2.5625 x 1.25)

N10 G0 G28 U0 W0

N15 G96 T0202 S700 M4 (Left Hand Finish Tool 55°)

N20 G0 Z.1

N25 Z0

N30 G1 X-.02 F.003

N35 G0 X1.25 Z.1

N40 G73 U.06 R.02

N45 G73 P50 Q95 U.01 W.005 F.004

N50 G0 G42 X.24

N55 G1 Z0

N60 X.5 C.08

N65 Z-.6

N70 X.43 Z-.69

N75 Z-.770

N80 X.7 C.04

N85 Z-1.413

N90 G3 X1.2 Z-1.92 R.6

N95 G1 X1.25

N100 G0 G40 X1.3

N105 S1000 F.002

N110 G72 P50 Q100

N115 G0 G28 U0 W0  
N120 G97 S1000 M3  
N125 T0404 (Threading tool Right hand)  
N130 X.55 Z.1  
N135 G78 P010060 Q0020 R.001  
N140 G78 X.434 Z-.69 P0330 Q0100 F.05  
N145 G0 G28 U0 W0  
N150 M30 (Flip Part around) **Note: change M30 to M00 after touch off**  
**Then start back at line N150 to run the back side**  
N155 M98 P010004 (SUB PROGRAM FOR BACK SIDE)  
N160 M30

### **Program O0004**

O0004 (Back side of Ball Hitch)

N5 G96

N10 G10 P0 Z- \_\_\_\_\_

**Need to touch with turret to the face of stock to get the number for the (Z-) after you cut the first side. Now press Position and the number that is in Machine for (Z) place this number on line N10 for Z as (-).**

N15 T0202 S700 M4 (Left Hand Finish Tool 55°)

N20 X1.25 Z.200

N25 G73 U.06 R.02

N30 G73 P35 Q55 U.01 W.005 F.004

N35 G0 G42 X0

N40 G1 Z0

N45 G3 X1.2 Z-.6 R.6

N50 G1 Z-.69

N55 X1.25

N60 G0 G40 X1.3

N65 S1000 F.002

N70 G72 P35 Q60

N75 G28 U0 W0


N80 G10 P0 Z- **(the original work shift)**

N85 M99

**Might need to subtract from the Z- on line N10 at least .0625**

**This is the difference between the Stock size on the print and the Stock size recommended. This way the ball will blend together in the middle of the part. The other thing that can be done is to face .03125 on each side of the part as it is being machined**

# Program O0005



O0005 (Live Tool Demo)

N5 (3.25 x 1.25)

N10 G28 U0 W0

N15 T0202

N20 G96 S700 M4

N25 X1.3 Z0

N30 G1 X-.02 F.003

N35 G0 X1.25 Z.1

N40 G73 U.1 R.05 (ROUGHING CYCLE)

N45 G73 P50 Q110 U.01 W.005 F.004

N50 G0 G42 X.3

N55 G1 Z0

N60 G1 X.5 C.05

N65 Z-.4

N70 X.45 Z-.5

N75 X.75 R.075

N80 Z-.7

(SAFE POSITION)

(FINISHING TOOL LEFT HAND)

(FACING)

N85 X1.05 Z-1.1  
 N90 Z-1.3  
 N95 G2 X1.05 Z-1.8 R.400  
 N100 G1 Z-1.9  
 N105 X1.25 R.04  
 N110 Z-2.0  
 N115 G0 G40 X1.26  
 N120 S900 F.002  
 N125 G72 P50 Q115 (FINISHING CYCLE)  
 N130 G28 U0 W0 (SAFE INDEX MOVE)  
 N135 G97 T0404 S1000 M3 (THREADING TOOL RIGHT HAND)  
 N140 G0 X.55 Z.2  
 N145 G78 P010060 Q0020 R.001 (THREADING CYCLE)  
 N150 G78 X.414 Z-.45 P0330 Q0100 F.05  
 N155 G28 U0 W0

### USING THE C-AXIS AS A Y-AXIS

N160 M5  
 N165 T1111 (6 mm END MILL in AXIAL HOLDER)  
 N170 M52 (TURN ON C AXIS)  
 N175 M13 (LIVE SPINDLE ON CLOCKWISE)  
 N180 G97 S1500 (DIRECT RPM)  
 N185 G28 C0 (REFERENCE C AXIS)  
 N190 G12.1 (PCI ON)  
 N195 G0 X1.3 Z-.7 C0 (SAFE MOVE)  
 N200 G1 G41 X.750 C.2 F.008 (CRC ON)  
 N205 G1 C0 F.004 (POSITION 1)  
 N210 X.375 C-.325 (POSITION 2)  
 N215 X-.375 (POSITION 3)  
 N220 X-.750 C0 (POSITION 4)  
 N225 X-.375 C.325 (POSITION 5)  
 N230 X.375 (POSITION 6)  
 N235 X.750 C0 (POSITION 7)  
 N240 C-.200 (SAFE MOVE)  
 N245 G1 G40 X.9 C-.4 (CRC OFF)  
 N250 G13.1 (PCI OFF)  
 N255 G0 X.9 Z-.25 M15 (LIVE SPINDLE OFF)  
 N260 M53 (C-AXIS OFF)

## USING THE C-AXIS AS DEGREES

N265 M52	(C-AXIS ON)
N270 M13	(LIVE SPINDLE CLOCKWISE)
N275 G97 S1500	(DIRECT RPM)
N280 G28 C0	(REFERENCE C-AXIS)
N285 G0 X.8	(MAKING SLOT ON THE FRONT OF PART)
N290 C90	(TURN C IN DEGREES)
N295 G1 X0 F.003	
N300 G0 C270	(TURN C IN DEGREES)
N305 G1 X.8	
N310 G28 U0 W0	
N315 T0909	(CENTER DRILL IN RADIAL HOLDER)
N320 G97 S1800	(LIVE SPINDLE CLOCKWISE)
N325 G0 X1.1	(MAKING DRILLED HOLES AROUND PART)
N330 Z-1.2	
N335 C60	(DEGREES)
N340 G1 X.65 F.003	
N345 G0 X1.1	
N350 C120	(DEGREES)
N355 G1 X.65	
N360 G0 X1.1	
N365 C180	(DEGREES)
N370 G1 X.65	
N375 G0 X1.1	
N380 C240	(DEGREES)
N385 G1 X.65	
N390 G0 X1.1	
N395 C300	(DEGREES)
N400 G1 X.65	
N405 G0 X1.1	
N410 C360	(DEGREES)
N415 G1 X.65	
N420 G0 X1.1 M15	
N425 M53	(C-AXIS OFF)
N430 G28 U0 W0	
N435 G97	
N440 T0404 S1000 M3	(THREADING TOOL RIGHT HAND)
N445 G0 X.55 Z.2	(DEBURRING THREADS)
N450 G78 P010060 Q0330 R.001	
N455 G78 X.414 Z-.45 P0330 Q0100 F.05	
N460 G28 U0 W0	(SAFE MOVE)
N465 M30	