



Operating Elements Control Elements CNC-Operation




1. Main switch with removable key. Memory is being cleared when switching off.
2. Control lamp shows the power supply of machine and control unit.
3. Emergency stop button with interlock. Unlocking of button: turn button to the left. To switch on machine, turn main switch to zero and to 1 again. When switching off also memory will be cleared.

4. Optional switch for axis system and for metric or inch mode of operation.



5. Switch for main spindle



Position 1 (main spindle ON, without MO3)

Position CNC: main spindle is switched on by programming MO3 and switched off by MO5, MO6 (with F#0) and M30.

6. Ammeter

7. Magnetic tape

8. **H/C** switch key
Manual/CNC operation

9. Control lamp CNC operation


10. **START** key
The program is being worked off

12. VDU (display):
Indicates values for address letters and modes of operation

13. Control lamp address letters

14. Control of milling spindle speed

11. Keys for program input, correction, storing of program on tape, V24 operation etc. (see detailed explanations)



11.1. Number keys **0** - **9**

11.2. **-** The minus sign key
To enter minus values the minus sign **-** has to be pressed after input of numbers.

11.3. **INP** key (INPUT = storing)
Storing key

11.4. **DEL** key (DELETE = erase)
Erasing key

11.5. **FWD** key (FORWARD)
Program jumps forward block by block

11.6. **REV** key (REVERSE)
Program jumps backwards block by block

11.7. **→** Arrow key
Display jumps word by word

11.8. **M** key: key for entering of miscellaneous functions.

Survey

Preparatory Functions, G-Codes (metric)

Note: Formats inch: all X,Y,Z values have 4 digits
(No differences in horizontal and vertical
Axis system)

G00 Rapid traverse

V: N3/G00/X[±]5/Y[±]4/Z[±]5

H: N3/G00/X[±]4/Y[±]5/Z[±]5

G01 Linear interpolation

V: N3/G01/X[±]5/Y[±]4/Z[±]5/F3

H: N3/G01/X[±]4/Y[±]5/Z[±]5/F3

G02 Circular interpolation clockwise

G03 Circular interpolation counterclockwise

Quadrants:

V: N3/^{G02}/_{G03}/X[±]5/Y[±]4/Z[±]5/F3

H: N3/^{G02}/_{G03}/X[±]4/Y[±]5/Z[±]5/F3

N3/M99/J2/K2 (Partial circles)

G04 Dwell

N3/G04

G21 Empty block

N3/G21

G25 Sub-routine program call

N3/G25/L(F) 3

G27 Jump instruction

N3/G27/L(F) 3

G40 Tool radius compensation cancelled

N3/G40

G45 Add tool radius

N3/G45

G46 Subtract tool radius

N3/G46

G47 Add tool radius twice

N3/G47

G48 Subtract tool radius twice

N3/G48

G64 Feed motors without current (switching function)

N3/G64

G65 Magnetic tape operation (switching function)

N3/G65

G66 Activating RS 232 Interface

N3/G66

G72 Pocket milling cycle

V: N3/G72/X[±]5/Y[±]4/Z[±]5/F3

H: N3/G72/X[±]4/Y[±]5

G74 Thread-cutting cycle (left-hand)

N3/G74/K3/Z[±]5/F3

G81 Fixed boring cycle

N3/G81/Z[±]5/F3

G82 Fixed boring cycle with dwell

N3/G82/Z[±]5/F3

G83 Fixed boring cycle with chip removal

N3/G83/Z[±]5/F3

G84 Thread-cutting cycle

N3/G84/K3/Z⁺5/F3

G85 Fixed reaming cycle

N3/G85/Z⁺5/F3

G89 Fixed reaming cycle with dwell

N3/G89/Z⁺5/F3

G90 Absolute value programming

N3/G90

G91 Incremental value programming

N3/G91

G92 Offset of reference point

V: N3/G92/X⁺5/Y⁺4/Z⁺5

H: N3/G92/X⁺4/Y⁺5/Z⁺5

V = Vertical

H = Horizontal

Miscellaneous or Switching Functions

M00 — Dwell
N3/M00

M03 — Milling spindle ON, clockwise
N3/M03

M05 — Milling spindle OFF
N3/M05

M06 — Tool offset, milling cutter radius input
N3/M06/D5/S4/Z[±]5/T3

M17 — Return to main program
N3/M17

M08 }
M09 }
M20 } Switching exits
M21 } N3/M2
M22 }
M23 }

M26 — Switching exit — impulse
N3/M26/H3

M30 — Program end
N3/M30

M99 — Parameters circular interpolation
(in connection with G02/03)
N3/M99/J2/K2

Alarm Signs

AOO: Wrong G/M code
AO1: Wrong radius / M99
AO2: Wrong X-value
AO3: Wrong F-value
AO4: Wrong Z-value
AO5: M30 code missing
AO6: M03 code missing
AO7: No significance
AO8: Tape end with cassette operation
SAVE
AO9: Program not found
A10: Writing protection
A11: Loading mistake
A12: Checking mistake
A13: Inch/mm switching with full program memory
A14: Wrong mill head position/path increment with LOAD \perp /M or \dashv /M
A15: Wrong Y-value
A16: Value of milling cutter radius missing
A17: Wrong sub-routine
A18: Path milling cutter compensation smaller zero

**Possible Inputs
(Otherwise alarm signs)**

	Metric		Inch	
	Values	Unit (mm)	Values	Unit (inch)
X _V	0-19999	1/100 mm	0-7999	1/1000"
X _H	0-9999	1/100 mm	0-3999	1/1000"
Y _V	0-9999	1/100 mm	0-3999	1/1000"
Y _H	0-19999	1/100 mm	0-7999	1/1000"
Z _{VH}	0-19999	1/100 mm	0-7999	1/1000"
Radii	0-9999	1/100 mm	0-3999	1/1000"
D(X) milling cutter radius with MO6	0-9999	1/100 mm	0-3999	1/1000"
F	2-499	mm/min	2-199	1/10"/min
T(F) tool address MO6	0-499	1	0-199	1
L(F) jump instruc- tions	0-221			
H(F) exit signs M26	0-299			
J/K circular para- meter	0-90			

Adresses

N, G, X, Y, Z, F, D, J, K, L, M, T, S, H

Operation CNC

INP	Storing of word contents
DEL	Deleting of word contents
FWD	Forward in program block by block
REV	Backward in program block by block
→	Forward in block word by word
M	Input of M-functions

Program hold:

INP + **FWD**

Program interruption

INP + **REV**

Delete program

DEL + **INP**

First **DEL** then **INP**

DEL remains pressed.

Delete alarm

INP + **REV**

Insert block

~ + **INP**

Delete block

~ + **DEL**

Single block mode

1**2****3** etc. + **START**

Testrun:

M

Operation – Magnetic tape

Storing of program on tape

G65 **INP** → **FWD** → Put in program
number → **INP**

Transmit program from tape to memory

G65 **INP** → **INP** → Select program
number → **INP**

Delete tape contents

G65 **INP**
↓
→ + **DEL**