



Software Release Notes

USB Power Delivery Software Framework (PSF)

3THIS DOCUMENT IS UNCONTROLLED UNLESS OTHERWISE STAMPED. It is the user's responsibility to ensure this is the latest revision prior to using or referencing this document.	Page	Spec. No.	Rev.
© Microchip Technology Inc. CONFIDENTIAL AND PROPRIETARY	1 of 34	FRM-50381-001	1.11

Information contained in this publication regarding device applications and the like is provided only for your convenience and can be superseded by updates. It is your responsibility to ensure that your application meets with your specifications. MICROCHIP MAKES NO REPRESENTATIONS OR WARRANTIES OF ANY KIND WHETHER EXPRESS OR IMPLIED, WRITTEN OR ORAL, STATUTORY OR OTHERWISE, RELATED TO THE INFORMATION, INCLUDING BUT NOT LIMITED TO ITS CONDITION, QUALITY, PERFORMANCE, MERCHANTABILITY OR FITNESS FOR PURPOSE.

Microchip disclaims all liability arising from this information and its use. Use of Microchip devices in life support and/or safety applications is entirely at the buyer's risk, and the buyer agrees to defend, indemnify and hold harmless Microchip from any and all damages, claims, suits, or expenses resulting from such use. No licenses are conveyed, implicitly or otherwise, under any Microchip intellectual property rights.

3THIS DOCUMENT IS UNCONTROLLED UNLESS OTHERWISE STAMPED. It is the user's responsibility to ensure this is the latest revision prior to using or referencing this document.	Page	Spec. No.	Rev.
© Microchip Technology Inc. CONFIDENTIAL AND PROPRIETARY	2 of 34	FRM-50381-001	1.11



MICROCHIP
Microchip Technology, Inc.

Microchip Technology, Incorporated
2355 W. Chandler Boulevard
Chandler, Arizona 85224
480/792-7200

REV	DATE	DESCRIPTION OF CHANGE
0.90	Oct 24, 2019	First Web release
0.91	Nov 11, 2019	Bug fix release
0.92	Dec 12, 2019	Documentation release
0.95	Jan 09, 2020	Release with complete documentation and Bug fix
1.00	Feb 25, 2020	Source only feature complete release
1.01	Mar 19, 2020	Phase 2 Alpha release
1.02	Apr 8, 2020	Phase 3 Alpha release
1.03	Apr 21, 2020	Bug fix release
1.04	June 19, 2020	Phase 2 Beta Release
1.05	July 24, 2020	Bug fix release
1.06	Aug 20, 2020	Phase 4 Alpha Release
1.07	Sep 11, 2020	Phase 5 Interim Release
1.08	Nov 11, 2020	Phase 5 Alpha Release
1.09	Dec 31, 2020	Phase 5 Beta Release
1.11	Mar 06, 2021	Beta Release

Table of Contents

1	Introduction	6
2	Release notes	6
2.1	Version 1.11.....	6
2.1.1	Not implemented / Limited functionality requirements	6
2.1.2	Bug Fixes.....	7
2.1.3	Features Added.....	9
2.1.4	Notes.....	9
2.2	Version 1.09.....	9
2.2.1	Not implemented / Limited functionality requirements	9
2.2.2	Bug Fixes.....	11
2.2.3	Features Added.....	11
2.2.4	Notes.....	12
2.3	Version 1.08.....	12
2.3.1	Not implemented / Limited functionality requirements	12
2.3.2	Bug Fixes.....	14
2.3.3	Features Added.....	15
2.3.4	Notes.....	15
2.4	Version 1.07.....	15
2.4.1	Not implemented / Limited functionality requirements	15
2.4.2	Bug Fixes.....	17
2.4.3	Features Added.....	18
2.4.4	Notes.....	18
2.5	Version 1.06.....	18
2.5.1	Not implemented / Limited functionality requirements	18
2.5.2	Bug Fixes.....	19
2.5.3	Features Added.....	20
2.5.4	Notes.....	20
2.6	Version 1.05.....	21
2.6.1	Not implemented / Limited functionality requirements	21
2.6.2	Bug Fixes.....	22
2.6.3	Features Added.....	23
2.6.4	Notes.....	23
2.7	Version 1.04.....	23
2.7.1	Not implemented / Limited functionality requirements	23
2.7.2	Bug Fixes.....	24
2.7.3	Features Added.....	25
2.7.4	Notes.....	25
2.8	Version 1.03.....	26
2.8.1	Not implemented / Limited functionality requirements	26
2.8.2	Bug Fixes.....	27
2.8.3	Features added.....	27
2.8.4	Notes.....	27
2.9	Version 1.02.....	27
2.9.1	Not implemented / Limited functionality requirements	27
2.9.2	Bug Fixes.....	29

2.9.3	Features added	29
2.9.4	Notes.....	29
2.10	Version 1.01	30
2.10.1	Not implemented / Limited functionality requirements	30
2.10.2	Bug Fixes.....	30
2.10.3	Features added	30
2.10.4	Notes.....	31
2.11	Version 1.00	31
2.11.1	Not implemented / Limited functionality requirements	31
2.11.2	Bug Fixes.....	31
2.11.3	Features added	31
2.11.4	Notes.....	31
2.12	Version 0.95	32
2.12.1	Not implemented / Limited functionality requirements	32
2.12.2	Bug Fixes.....	32
2.12.3	Features added	32
2.12.4	Notes.....	32
2.13	Version 0.92	33
2.13.1	Not implemented / Limited functionality requirements	33
2.13.2	Bug Fixes.....	33
2.13.3	Features added	33
2.13.4	Notes.....	33
2.14	Version 0.91	33
2.14.1	Not implemented / Limited functionality requirements	33
2.14.2	Bug Fixes.....	33
2.14.3	Features added	33
2.14.4	Notes.....	34
2.15	Version 0.90	34
2.15.1	Not implemented / Limited functionality requirements	34
2.15.2	Bug Fixes.....	34
2.15.3	Features added	34
2.15.4	Notes.....	34

1 Introduction

USB Power Delivery Software Framework (PSF) – a software-based Power Delivery stack along with UPD350 Type-C Port Controller (Maverick) is a USB-PD solution. It is a generic user-friendly that can be ported across various hardware platform.

Component Type	USB Power Delivery Software Framework (PSF)
Target Silicon	SAMD20 + UPD350
Where can an end user see the version number	Version number appended with filename ../PSF/Source/include/ProjectVersion.h

2 Release notes

2.1 Version 1.11

Release date	06-Mar-2021
Release Type	Beta release
Pre-requisites (if any)	PSF EVB
Source Tag	Tag: PSF_STACK_V1.11

2.1.1 Not implemented / Limited functionality requirements

1. PSF-262: [Ellisys] TD.PD.FRSISNK3.E1. Normal Conditions - vSafe5V not applied within tSrcFRSwap
2. PSF-261: [Ellisys] TD.PD.FRSISNK3.E1. Normal Conditions - Sink_Cap not detected by PSF
3. PSF-18: CLONE - Absence of power negotiation on ports of the DUT when VDD33 is set to 2.80V
4. PSF-21: VBUS OCS Power fault handling not working
5. PSF-229: PD Firmware does not support the PMPD-MCP19119 Rev C with UCS3205 load switch
6. PSF-247: eMCHP_PSF_TYPEC_DETACH_EVENT triggered on attach as well
7. PSF-187: SenderResponseTimer Timeout Request Compliance test Failed
8. PSF-215: Firmware gets stuck after negotiating with Port partner in DRP Port
9. PSF-237: Interoperability issues seen between PSF DRP device and PSF SOURCE Only device

10. PSF-240: Repeated Type C Detach event observed in DRP port with open ended Type C to Type A cable
11. PSF-235: Chain of Soft-Resets Observed during Power Negotiation
12. PSF-236: Source sends Soft-Reset during Power Negotiation
13. PSF-182: tVCONNON should be 2ms as per Type- C specification but it is 10ms as inherited from Amazon
14. PSF-180: Updating PSF documentation to add more inclusive terminology as per new guidelines
15. PSF-154: CLONE - Workaround for OLYMPUS_DEV-3217
16. PSF-78: Clarification On MCU Idle Timeout Configuration
17. PSF-94: [MPQ] Handle I2C read/write failures
18. PSF-51: [Sink][LeCroy] TD.4.10.2 Sink Power Precedence Test Fails When PUT configured as Sink
19. PSF-50: [Sink][LeCroy] TDA 2.3.3.1 PDO Transition, Current Draw and Suspend Test - Sink, Consumer or Consumer/Provider Test Fails when PUT acts as Sink Partner
20. PSF-49: [Sink][LeCroy] TDA 2.1.3.2 BMC PHY Level Message Test Fails when PUT is Configured as sink
21. PSF-44: [Lecroy] TDA 2.3.1.1 Source Dynamic Load Test, Provider or Provider/Consumer Test Fails When PUT is configured as Source

2.1.2 Bug Fixes

1. PSF-246: [PR_Swap] Source to Sink PR_Swap fails when Plugable Dock acts as port partner
2. PSF-243: PSF rejects asynchronous request from Sink when a renegotiation client request is pending
3. PSF-195: [Teton PSF][Ellisys Comp]SRC.E16 PDO Transition (Testing Dfp) fails
4. PSF-153: VBUS Discharge handling inside Type C ISR
5. PSF-170: VCONN Source to reset the Cable Plug's Protocol Layer in order to ensure MessageID synchronization
6. PSF-85: [MPQ]Ellisys Compliance fails when
INCLUDE_POWER_MANAGEMENT_CTRL = 1

7. PSF-18: CLONE - Absence of power negotiation on ports of the DUT when VDD33 is set to 2.80V
8. PSF-244: [VCONN_Swap] Port0 when attached as source (and so sources VCONN), inconsistently 'Rejects' VCONN_Swap
9. PSF-242: Option to have infinite retries in case of faults
10. PSF-241: CLONE - Teton PSF: Notifications from ISR handler to be revisited
11. PSF-239: Interoperability issues seen between PSF DRP UFP port and Power OFF SOURCE Only DFP
12. PSF-222: Get Sink Cap Extended support for Sink only and DRP ports
13. PSF-207: [PSF_SINK] - UPD 350 failed to come out from reset
14. PSF-187: SenderResponseTimer Timeout Request Compliance test Failed
15. PSF-186: [Sink] Hard Reset is sent after negotiation with Dell XPS as partner
16. PSF-173: Port0 when acts as DRP as Source or fixed source, runs into error recovery after turning on VBUS
17. PSF-98: [Field]Implement the requested software hooks
18. PSF-160: Trace support at lower UART frequencies
19. PSF-150: [Ellisys] [Sink] Ellisys compliance tests failed with sink demo firmware
20. PSF-132: [SNK][Phase3] List of features not tested for PSF phase 3 alpha release
21. PSF-161: [Cfg&Sts] Power fault counter status parameter needs to be implemented.
22. PSF-141: [Document] Source Pro Demo Read Me Limitations
23. PSF-53: [Sink][Ellisys] TD.4.1.2 Unpowered CC Voltage Test fails when PUT Configured as Sink
24. PSF-101: [PSF User Guide] Capture the 8-bit memory requirement details under section "Software Requirements"
25. PSF-221: UART Trace messages cleanup
26. PSF-259: [DR_Swap] Port Data Role field of Good_CRC packet is changed before the completion of DR_Swap AMS
27. PSF-254: Sink - VBUS Threshold to be configured only after the Source partner accepts the request

3THIS DOCUMENT IS UNCONTROLLED UNLESS OTHERWISE STAMPED. It is the user's responsibility to ensure this is the latest revision prior to using or referencing this document.	Page	Spec. No.	Rev.
© Microchip Technology Inc. CONFIDENTIAL AND PROPRIETARY	8 of 34	FRM-50381-001	1.11

28. PSF-253: MCHP_PSF_HOOK_HW_PORTPWR_INIT return type to be corrected in comments
29. PSF-248: Need separate PSF demos for DRP and FRS

2.1.3 Features Added

- None.

2.1.4 Notes

None

2.2 Version 1.09

Release date	31-Dec-2020
Release Type	Phase 5 Beta release
Pre-requisites (if any)	PSF EVB
Source Tag	Tag: PSF_STACK_V1.09

2.2.1 Not implemented / Limited functionality requirements

22. PSF-184: UART trace using onboard debugger not working
23. PSF-246: [PR_Swap] Source to Sink PR_Swap fails when Plugable Dock acts as port partner
24. PSF-243: PSF rejects asynchronous request from Sink when a renegotiation client request is pending
25. PSF-235: Chain of Soft-Resets Observed during Power Negotiation
26. PSF-236: Source sends Soft-Reset during Power Negotiation
27. PSF-195: [Teton PSF][Ellisys Comp]SRC.E16 PDO Transition (Testing Dfp) fails
28. PSF-153: VBUS Discharge handling inside Type C ISR
29. PSF-170: VCONN Source to reset the Cable Plug's Protocol Layer in order to ensure MessageID synchronization
30. PSF-85: [MPQ]Ellisys Compliance fails when
INCLUDE_POWER_MANAGEMENT_CTRL = 1

31. PSF-18: CLONE - Absence of power negotiation on ports of the DUT when VDD33 is set to 2.80V
32. PSF-21: VBUS OCS Power fault handling not working
33. PSF-244: [VCONN_Swap] Port0 when attached as source (and so sources VCONN), inconsistently 'Rejects' VCONN_Swap
34. PSF-242: Option to have infinite retries in case of faults
35. PSF-241: CLONE - Teton PSF: Notifications from ISR handler to be revisited
36. PSF-239: Interoperability issues seen between PSF DRP UFP port and Power OFF SOURCE Only DFP
37. PSF-240: Repeated Type C Detach event observed in DRP port with open ended Type C to Type A cable
38. PSF-215: Firmware gets stuck after negotiating with Port partner in DRP Port
39. PSF-237: Interoperability issues seen between PSF DRP device and PSF SOURCE Only device
40. PSF-229: PD Firmware does not support the PMPD-MCP19119 Rev C with UCS3205 load switch
41. PSF-222: Get Sink Cap Extended support for Sink only and DRP ports
42. PSF-207: [PSF_SINK] - UPD 350 failed to come out from reset
43. PSF-187: SenderResponseTimer Timeout Request Compliance test Failed
44. PSF-186: [Sink] Hard Reset is sent after negotiation with Dell XPS as partner
45. PSF-182: tVCONNON should be 2ms as per Type- C specification but it is 10ms as inherited from Amazon
46. PSF-180: Updating PSF documentation to add more inclusive terminology as per new guidelines
47. PSF-154: CLONE - Workaround for OLYMPUS_DEV-3217
48. PSF-173: Port0 when acts as DRP as Source or fixed source, runs into error recovery after turning on VBUS
49. PSF-98: [Field]Implement the requested software hooks
50. PSF-160: Trace support at lower UART frequencies

51. PSF-78: Clarification On MCU Idle Timeout Configuration
52. PSF-150: [Ellisys] [Sink] Ellisys compliance tests failed with sink demo firmware
53. PSF-132: [SNK][Phase3] List of features not tested for PSF phase 3 alpha release
54. PSF-94: [MPQ] Handle I2C read/write failures
55. PSF-51: [Sink][LeCroy] TD.4.10.2 Sink Power Precedence Test Fails When PUT configured as Sink
56. PSF-50: [Sink][LeCroy] TDA 2.3.3.1 PDO Transition, Current Draw and Suspend Test - Sink, Consumer or Consumer/Provider Test Fails when PUT acts as Sink Partner
57. PSF-49: [Sink][LeCroy] TDA 2.1.3.2 BMC PHY Level Message Test Fails when PUT is Configured as sink
58. PSF-44: [Lecroy] TDA 2.3.1.1 Source Dynamic Load Test, Provider or Provider/Consumer Test Fails When PUT is configured as Source
59. PSF-161: [Cfg&Sts] Power fault counter status parameter needs to be implemented.
60. PSF-141: [Document] Source Pro Demo Read Me Limitations
61. PSF-53: [Sink][Ellisys] TD.4.1.2 Unpowered CC Voltage Test fails when PUT Configured as Sink
62. PSF-101: [PSF User Guide] Capture the 8-bit memory requirement details under section "Software Requirements"
63. PSF-221: UART Trace messages cleanup

2.2.2 Bug Fixes

1. PSF-86: [Field] VBUS drop observed during Voltage transitions when the sink load is higher
2. PSF-219: [DRP] DR Swap gets rejected because of corruption in Port Data Role
3. PSF-233: Initial Power Source should always Accept VCONN Source irrespective of Active Cable presence or not
4. PSF-234: Soft-reset observed during Power Negotiation
5. PSF-238: Source capabilities are corruptly transmitted
6. PSF-245: Extend VDM support to Source Lite, Pro and Sink Demos

2.2.3 Features Added

- Fast Role Swap (FRS)

3THIS DOCUMENT IS UNCONTROLLED UNLESS OTHERWISE STAMPED. It is the user's responsibility to ensure this is the latest revision prior to using or referencing this document.	Page	Spec. No.	Rev.
© Microchip Technology Inc. CONFIDENTIAL AND PROPRIETARY	11 of 34	FRM-50381-001	1.11

2.2.4 Notes

None

2.3 Version 1.08

Release date	11-Nov 2020
Release Type	Phase 5 alpha release
Pre-requisites (if any)	PSF EVB
Source Tag	Tag: PSF_STACK_V1.08

2.3.1 Not implemented / Limited functionality requirements

1. PSF-234: Soft Reset observed during Power Negotiation
2. PSF-233: Initial Power Source should always Accept VCONN Source irrespective of Active Cable presence or not
3. PSF-215: Firmware gets stuck after negotiating with Port partner in DRP Port
4. PSF-219: [DRP] DR Swap gets rejected because of corruption in Port Data Role
5. PSF-184: UART trace using onboard debugger not working
6. PSF-153: VBUS Discharge handling inside Type C ISR
7. PSF-170: VCONN Source to reset the Cable Plug's Protocol Layer in order to ensure MessageID synchronization
8. PSF-195: [Teton PSF][Ellisys Comp]SRC.E16 PDO Transition (Testing Dfp) fails
9. PSF-85: [MPQ]Ellisys Compliance fails when
INCLUDE_POWER_MANAGEMENT_CTRL = 1
10. PSF-18: CLONE - Absence of power negotiation on ports of the DUT when VDD33 is set to 2.80V
11. PSF-21: VBUS OCS Power fault handling not working
12. PSF-229: PD Firmware does not support the PMPD-MCP19119 Rev C with UCS3205 load switch
13. PSF-224: SM IDLE Status reporting - DPM, SINK and DRP SMs
14. PSF-222: Get Sink Cap Extended support for Sink only and DRP ports
15. PSF-207: [PSF_SINK] - UPD 350 failed to come out from reset

3THIS DOCUMENT IS UNCONTROLLED UNLESS OTHERWISE STAMPED. It is the user's responsibility to ensure this is the latest revision prior to using or referencing this document.	Page	Spec. No.	Rev.
© Microchip Technology Inc. CONFIDENTIAL AND PROPRIETARY	12 of 34	FRM-50381-001	1.11

16. PSF-187: SenderResponseTimer Timeout Request Compliance test Failed
17. PSF-186: [Sink] Hard Reset is sent after negotiation with Dell XPS as partner
18. PSF-182: tVCONNON should be 2ms as per Type- C specification but it is 10ms
19. PSF-180: Updating PSF documentation to add more inclusive terminology as per new guidelines
20. PSF-86: [Field] VBUS drop observed during Voltage transitions when the sink load is higher
21. PSF-154: CLONE - Workaround for OLYMPUS_DEV-3217
22. PSF-173: Port0 when acts as DRP as Source or fixed source, runs into error recovery after turning on VBUS
23. PSF-98: [Field]Implement the requested software hooks
24. PSF-160: Trace support at lower UART frequencies
25. PSF-78: Clarification On MCU Idle Timeout Configuration
26. PSF-150: [Ellisys] [Sink] Ellisys compliance tests failed with sink demo firmware
27. PSF-132: [SNK][Phase3] List of features not tested for PSF phase 3 alpha release
28. PSF-94: [MPQ] Handle I2C read/write failures
29. PSF-51: [Sink][LeCroy] TD.4.10.2 Sink Power Precedence Test Fails When PUT configured as Sink
30. PSF-50: [Sink][LeCroy] TDA 2.3.3.1 PDO Transition, Current Draw and Suspend Test - Sink, Consumer or Consumer/Provider Test Fails when PUT acts as Sink Partner
31. PSF-49: [Sink][LeCroy] TDA 2.1.3.2 BMC PHY Level Message Test Fails when PUT is Configured as sink
32. PSF-44: [Lecroy] TDA 2.3.1.1 Source Dynamic Load Test, Provider or Provider/Consumer Test Fails When PUT is configured as Source
33. PSF-161: [Cfg&Sts] Power fault counter status parameter needs to be implemented.
34. PSF-53: [Sink][Ellisys] TD.4.1.2 Unpowered CC Voltage Test fails when PUT Configured as Sink
35. PSF-221: UART Trace messages cleanup

2.3.2 Bug Fixes

1. PSF-202: PSF v1.07 Port enabled before DPM_CLIENT_REQ_PORT_ENABLE Client req issued
2. PSF-213: SPI Write APIs shall be generic to support all Hardware platforms
3. PSF-208: Current limit should be set before Driving Power for Implicit contract entry
4. PSF-228: SRC.E11 Accept Requests can be met fails - when client request is active
5. PSF-223: PSF Sends Not supported for Get_sink_caps for a DRP Port
6. PSF-220: [DRP] Sink to Source PR Swap fails occasionally in Port Loopback
7. PSF-201: Port 2 DRP Dock fails to renegotiate after detach
8. PSF-199: [Ellisys Comp]SRC3.E23 Vconn Swap(Testing Dfp) fails
9. PSF-188: PSF should not go into Type C Error Recovery without Client intervention
10. PSF-217: [Sink] CC thresholds corresponding to DFP proprietary current not handled as Type-C attach
11. PSF-183: Hard Reset occurs when renegotiation is triggered via client request
12. PSF-200: Discover identity for SOP' is sent 63 times[nDiscoverIdentityCount] - PD Spec limit is 20
13. PSF-196: [Ellisys Comp]SRC3.E14 Status Fields Checks fails
14. PSF-203: [GRL] DUT doesn't respond with Not supported for Reserved message
15. PSF-177: [VCONN_Swap and DR_Swap] Continuous Role Swap did not occur even when both Auto Request policies are enabled
16. PSF-211: VDM: Callback notification for Not supported Response
17. PSF-209: Hard Reset Complete Notification
18. PSF-210: [Sink] PSF Sink fails to establish explicit contract with Galaxy Note 10
19. PSF-168: [Swap Notification] Swap completion notification to be posted after sending Reject to swap request
20. PSF-157: Implement the FW changes needed to address PSF-148
21. PSF-204: [Ellisys Comp]SRC.E16 PDO Transition (Testing Dfp) fails because of Collision avoidance

- 22. PSF-179: Require modifications in PSF IDLE Status reporting
- 23. PSF-232: HPD hardware queue interrupt handler Changes
- 24. PSF-231: HPD interrupt doesn't fire

2.3.3 Features Added

- Alternate Mode
- Hot Plug Detect
- DPM support to handle the following at run time:
 - Renegotiate with either default PDOs or new PDOs
 - Initiate the following swaps:
 - VCONN swap
 - Power role swap
 - Data role swap

2.3.4 Notes

None

2.4 Version 1.07

Release date	11-Sep 2020
Release Type	Phase 5 interim release
Pre-requisites (if any)	PSF EVB
Source Tag	Tag: PSF_STACK_V1.07

2.4.1 Not implemented / Limited functionality requirements

1. PSF-184: UART trace using onboard debugger not working
2. PSF-188: PSF should not go into Type C Error Recovery without Client intervention
3. PSF-183: Hard Reset occurs when renegotiation is triggered via client request
4. PSF-170: VCONN Source to reset the Cable Plug's Protocol Layer in order to ensure MessageID synchronization
5. PSF-85: [MPQ]Ellisys Compliance fails when
INCLUDE_POWER_MANAGEMENT_CTRL = 1
6. PSF-153: VBUS Discharge handling inside Type C ISR

3THIS DOCUMENT IS UNCONTROLLED UNLESS OTHERWISE STAMPED. It is the user's responsibility to ensure this is the latest revision prior to using or referencing this document.	Page	Spec. No.	Rev.
© Microchip Technology Inc. CONFIDENTIAL AND PROPRIETARY	15 of 34	FRM-50381-001	1.11

7. PSF-18: CLONE - Absence of power negotiation on ports of the DUT when VDD33 is set to 2.80V
8. PSF-21: VBUS OCS Power fault handling not working
9. PSF-187: SenderResponseTimer Timeout Request Compliance test Failed
10. PSF-186: [Sink] Hard Reset is sent after negotiation
11. PSF-182: tVCONNON should be 2ms as per Type- C specification but it is 10ms as inherited from Amazon
12. PSF-179: Require modifications in PSF IDLE Status reporting
13. PSF-180: Updating PSF documentation to add more inclusive terminology as per new guidelines
14. PSF-177: [VCONN_Swap and DR_Swap] Continuous Role Swap did not occur even when both Auto Request policies are enabled
15. PSF-168: [Swap Notification] Swap completion notification to be posted after sending Reject to swap request
16. PSF-157: Implement the FW changes needed to address PSF-148
17. PSF-86: [Field] VBUS drop observed during Voltage transitions when the sink load is higher
18. PSF-154: CLONE - Workaround for OLYMPUS_DEV-3217
19. PSF-173: Port0 when acts as DRP as Source or fixed source, runs into error recovery after turning on VBUS
20. PSF-98: [Field]Implement the requested software hooks
21. PSF-160: Trace support at lower UART frequencies
22. PSF-78: Clarification On MCU Idle Timeout Configuration
23. PSF-150: [Ellisys] [Sink] Ellisys compliance tests failed with sink demo firmware
24. PSF-132: [SNK][Phase3] List of features not tested for PSF phase 3 alpha release
25. PSF-94: [MPQ] Handle I2C read/write failures
26. PSF-51: [Sink][LeCroy] TD.4.10.2 Sink Power Precedence Test Fails When PUT configured as Sink

27. PSF-50: [Sink][LeCroy] TDA 2.3.3.1 PDO Transition, Current Draw and Suspend Test - Sink, Consumer or Consumer/Provider Test Fails when PUT acts as Sink Partner
28. PSF-49: [Sink][LeCroy] TDA 2.1.3.2 BMC PHY Level Message Test Fails when PUT is Configured as sink
29. PSF-44: [Lecroy] TDA 2.3.1.1 Source Dynamic Load Test, Provider or Provider/Consumer Test Fails When PUT is configured as Source
30. PSF-161: [Cfg&Sts] Power fault counter status parameter needs to be implemented.
31. PSF-53: [Sink][Ellisys] TD.4.1.2 Unpowered CC Voltage Test fails when PUT Configured as Sink
32. PSF-155: PSF does not respond to VDM:Disc Identity command from port partner
33. PSF-141: [Document] Source Pro Demo Read Me Limitations
34. PSF-101: [PSF User Guide] Capture the 8-bit memory requirement details under section "Software Requirements"

2.4.2 Bug Fixes

1. PSF-176: Any AMS followed by VCONN_Swap leads to Soft Reset when Negotiated PD Spec Rev is 2.0
2. PSF-178: PSF Sends Reject for a valid Request
3. PSF-185: [DR_Swap] Port fails to negotiate after first detach
4. PSF-175: CONFIG_PORT_UPD_IDLE_TIMEOUT_MS should be moved inside the stack since it is determined by the stack
5. PSF-189: 'Not Supported' response is not handled in PE Receive msg handler
6. PSF-190: DR and PR Swap should be treated as Unsupported when DRD/DRP bits are 0
7. PSF-191: [Sink] When port partner(src) gets disabled, sink detects UV fault and becomes inactive for further PD transaction
8. PSF-192: When PSF Sink acts as VCONN source, VCONN discharge is not complete when the port gets disabled
9. PSF-193: [Sink] When source partner is disabled and enabled again, PSF sink does not re-negotiate
10. PSF-194: Port2 configurations and application code may be restricted under a macro to enable a demo to be configured for single port

2.4.3 Features Added

1. PSF-136: Dynamic Port Control (Port Enable/Disable) Client request
2. PSF-137: Power Delivery Disabled notification
3. PSF-147: Discover identity support for Teton PSF

2.4.4 Notes

- Only 2 Port solution has been tested at 8MHz SPI clock speed.
- System level PD communication between PSF and UPD350 through I2C interface is untested.
- For Source Pro application,
 - Ellisys compliance has been tested with
INCLUDE_POWER_MANAGEMENT_CTRL = 0
- For DRP application, Ellisys compliance testing is not done.

2.5 Version 1.06

Release date	20-Aug 2020
Release Type	Phase 4 alpha release
Pre-requisites (if any)	PSF EVB
Source Tag	Tag: PSF_STACK_V1.06

2.5.1 Not implemented / Limited functionality requirements

1. PSF-136: Dynamic Port Control(Port Enable/Disable) Client request
2. PSF-153: VBUS Discharge handling inside Type C ISR
3. PSF-18: CLONE - Absence of power negotiation on ports of the DUT when VDD33 is set to 2.80V
4. PSF-147: Discover identity support for Teton PSF
5. PSF-21: VBUS OCS Power fault handling not working
6. PSF-98: [Field]Implement the requested software hooks
7. PSF-137: Power Delivery Disabled notification
8. PSF-160: Trace support at lower UART frequencies
9. PSF-78: Clarification On MCU Idle Timeout Configuration
10. PSF-150: [Ellisys] [Sink] Ellisys compliance tests failed with sink demo firmware

11. PSF-132: [SNK][Phase3] List of features not tested for PSF phase 3 alpha release
12. PSF-85: [MPQ]Ellisys Compliance fails when
INCLUDE_POWER_MANAGEMENT_CTRL = 1
13. PSF-86: [Field] VBUS drop observed during Voltage transitions when the sink load is higher
14. PSF-170: VCONN Source to reset the Cable Plug's Protocol Layer to ensure MessageID synchronization
15. PSF-168: [Swap Notification] Swap completion notification to be posted after sending Reject to swap request
16. PSF-157: Implement the FW changes needed to address PSF-148
17. PSF-94: [MPQ] Handle I2C read/write failures
18. PSF-51: [Sink][LeCroy] TD.4.10.2 Sink Power Precedence Test Fails When PUT configured as Sink
19. PSF-50: [Sink][LeCroy] TDA 2.3.3.1 PDO Transition, Current Draw and Suspend Test - Sink, Consumer or Consumer/Provider Test Fails when PUT acts as Sink Partner
20. PSF-49: [Sink][LeCroy] TDA 2.1.3.2 BMC PHY Level Message Test Fails when PUT is Configured as sink
21. PSF-44: [Lecroy] TDA 2.3.1.1 Source Dynamic Load Test, Provider or Provider/Consumer Test Fails When PUT is configured as Source
22. PSF-161: [Cfg&Sts] Power fault counter status parameter needs to be implemented.
23. PSF-53: [Sink][Ellisys] TD.4.1.2 Unpowered CC Voltage Test fails when PUT Configured as Sink
24. PSF-155: PSF does not respond to VDM:Disc Identity command from port partner
25. PSF-141: [Document] Source Pro Demo Read Me Limitations
26. PSF-101: [PSF User Guide] Capture the 8-bit memory requirement details under section "Software Requirements"
27. PSF-173: Port0 when acts as DRP as Source or fixed source, runs into error recovery after turning on VBUS
28. PSF-54: [Sink][Ellisys] TD.4.1.2 Unpowered CC Voltage Test fails when PUT Configured as Sink

2.5.2 Bug Fixes

1. PSF-172: When VCONN swap is not supported, respond with "reject" and not with "not supported" for the VCONN swap message

3THIS DOCUMENT IS UNCONTROLLED UNLESS OTHERWISE STAMPED. It is the user's responsibility to ensure this is the latest revision prior to using or referencing this document.	Page	Spec. No.	Rev.
© Microchip Technology Inc. CONFIDENTIAL AND PROPRIETARY	19 of 34	FRM-50381-001	1.11

2. PSF-145: [Sink] Power fault occurs when source partner is detached
3. PSF-167: [Snk] UV Fault is triggered during detach when the port is Sourcing VCONN
4. PSF-134: [Field] VCONN Swap not working with HP laptop
5. PSF-156 - Client notification to be added to indicate port powered off due to power fault
6. PSF-162 - [Cfg&Stst] In port identity, manufacturer string and its length needs to be implemented and product ID should be set with proper default value
7. PSF-164 -[Src] New PDOs to be cleared only when renegotiation is triggered by DPM
8. PSF-55: [Sink][Ellisys] Errors Encountered while Executing TD.4.3.1 Sink Connect Source Test Case
9. PSF-109: [SINK] When Gotomin was issued from source, sinkoperatingcurrent does not retain minimum operating current.
10. PSF-163: Organise defines in bootcfg.h file in all demos, so that, it is easy for user to configure.

2.5.3 Features Added

- Dual Role Power
- Data Role Swap
- Power Role Swap

New application for DRP configuration is added with this release.

First port of DRP application is configured as Notebook port with Role Swap Policy set to accept and request DR_Swap when acting as UFP, accept and request PR_Swap when acting as Source, request VCONN_Swap when not acting as VCONN source and accept VCONN_Swap when acting as both VCONN Source and Not as VCONN Source.

Second port of DRP application is configured as Dock type port with Role Swap Policy set to accept and request DR_Swap when acting as DFP, accept and request PR_Swap when acting as Sink and accept VCONN_Swap when acting as both VCONN Source and Not as VCONN Source.

2.5.4 Notes

- Only 2 Port solution has been tested at 8MHz SPI clock speed.
- System level PD communication between PSF and UPD350 through I2C interface is untested.
- For Source Pro application,
 - Ellisys compliance has been tested with
INCLUDE_POWER_MANAGEMENT_CTRL = 0
- For DRP application, Ellisys compliance testing is not done.

3THIS DOCUMENT IS UNCONTROLLED UNLESS OTHERWISE STAMPED. It is the user's responsibility to ensure this is the latest revision prior to using or referencing this document.	Page	Spec. No.	Rev.
© Microchip Technology Inc. CONFIDENTIAL AND PROPRIETARY	20 of 34	FRM-50381-001	1.11

2.6 Version 1.05

Release date	24-July 2020
Release Type	Bug fix release
Pre-requisites (if any)	PSF EVB
Source Tag	Tag: PSF_STACK_V1.05

2.6.1 Not implemented / Limited functionality requirements

Source existing issues:

1. PSF-44: TDA 2.3.1.1 Source Dynamic Load Test, Provider or Provider/Consumer Test Fails when PUT is configured as Source.
2. PSF-86: [Field] VBUS drop observed during Voltage transitions when the sink load is higher
3. PSF-79: Clarification on VSEL Configuration
4. PSF-90: Continuous PD re-negotiation when number of source PDOs is 7
5. PSF-134: [Field] VCONN Swap not working with HP laptop
6. PSF-21: VBUS OCS Power fault handling not working
7. PSF-85: [MPQ]Ellisys Compliance fails when
INCLUDE_POWER_MANAGEMENT_CTRL = 1
8. PSF-135: PSF Control/Status Data Memory Management
9. PSF-136: Dynamic Port Control(Port Enable/Disable) Client request
10. PSF-137: Power Delivery Disabled notification
11. PSF-94: [MPQ] Handle I2C read/write failures
12. PSF-78: Clarification On MCU Idle Timeout Configuration
13. PSF-95: PSF 8-bit MCU porting Feedback
14. PSF-118: Phase 2 FW does not support PB and PT on PPS Ports
15. PSF-98: [Field]Implement the requested software hooks
16. PSF-64: [Field] Un explained 20V toggling plus 5V,14V steps on the way to reaching 20V
17. PSF-153: VBUS Discharge handling inside Type C ISR
18. PSF-147: Discover identity support for Teton PSF

19. PSF-18: CLONE - Absence of power negotiation on ports of the DUT when VDD33 is set to 2.80V
20. PSF-156: Client notification to be added to indicate port powered off due to power fault
21. PSF-154: CLONE - Workaround for OLYMPUS_DEV-3217
22. PSF-155: PSF does not respond to VDM:Disc Identity command from port partner

Sink existing issues:

1. PSF-55: [Sink][Ellisys] Errors Encountered while Executing TD.4.3.1 Sink Connect Source Test Case
2. PSF-54: [Sink][Ellisys] TD.4.1.2 Unpowered CC Voltage Test fails when PUT Configured as Sink
3. PSF-51: [Sink][LeCroy] TD.4.10.2 Sink Power Precedence Test Fails When PUT configured as Sink
4. PSF-50: [Sink][LeCroy] TDA 2.3.3.1 PDO Transition, Current Draw and Suspend Test - Sink, Consumer or Consumer/Provider Test Fails when PUT acts as Sink Partner
5. PSF-49: [Sink][LeCroy] TDA 2.1.3.2 BMC PHY Level Message Test Fails when PUT is Configured as sink
6. PSF-132: [SNK][Phase3] List of features not tested for PSF phase 3 alpha release
7. PSF-109: [SINK] When Gotomin was issued from source, sinkoperatingcurrent does not retain minimum operating current.
8. PSF-150: [Ellisys] [Sink] Ellisys compliance tests failed with sink demo firmware

2.6.2 Bug Fixes

1. PSF-140: [PPS] TD.PD.SRC.E16 PDO Transition Failure
2. PSF-144: [PPS] More than one alert sent for cable limitation
3. PSF-142: [CSR] Advertised PDOs to be cleared after detach
4. PSF-151: Hooks to notify PSF stack Idle waiting for an event
5. PSF-149: [Sink] Evaluating source capabilities needs to be done based on advertised PDOs, not sink PDOs
6. PSF-139: [Sink] After a board reset, PD negotiation fails

7. PSF-146: [Src] Code Review comments
8. PSF-152: Orientation pin is not initialised in V1.04 Release
9. PSF-121: CONFIG_DCDC_CTRL in Sink Mode

2.6.3 Features Added

- None.

2.6.4 Notes

- Only 2 Port Source and Sink solution has been tested at 8MHz SPI clock speed.
- System level PD communication between PSF and UPD350 through I2C interface is untested.
- For Source Pro application,
 - Ellisys compliance has been tested with
INCLUDE_POWER_MANAGEMENT_CTRL = 0
 - Power Balancing and Power Throttling are supported only on non-PPS ports.

2.7 Version 1.04

Release date	19-June-2020
Release Type	Phase 2 Beta release
Pre-requisites (if any)	PSF EVB Rev A
Source Tag	Tag: PSF_STACK_V1.04

2.7.1 Not implemented / Limited functionality requirements

Source existing issues:

1. PSF-44: TDA 2.3.1.1 Source Dynamic Load Test, Provider or Provider/Consumer Test Fails when PUT is configured as Source.
2. PSF-86: [Field] VBUS drop observed during Voltage transitions when the sink load is higher
3. PSF-79: Clarification on VEL Configuration
4. PSF-90: Continuous PD re-negotiation when number of source PDOs is 7
5. PSF-134: [Field] VCONN Swap not working with HP laptop
6. PSF-21: VBUS OCS Power fault handling not working
7. PSF-85: [MPQ]Ellisys Compliance fails when

INCLUDE_POWER_MANAGEMENT_CTRL = 1

3THIS DOCUMENT IS UNCONTROLLED UNLESS OTHERWISE STAMPED. It is the user's responsibility to ensure this is the latest revision prior to using or referencing this document.	Page	Spec. No.	Rev.
© Microchip Technology Inc. CONFIDENTIAL AND PROPRIETARY	23 of 34	FRM-50381-001	1.11

8. PSF-135: PSF Control/Status Data Memory Management
9. PSF-136: Dynamic Port Control(Port Enable/Disable) Client request
10. PSF-137: Power Delivery Disabled notification
11. PSF-121: CONFIG_DCDC_CTRL in Sink Mode
12. PSF-94: [MPQ] Handle I2C read/write failures
13. PSF-78: Clarification On MCU Idle Timeout Configuration
14. PSF-95: PSF 8-bit MCU porting Feedback
15. PSF-118: Phase 2 FW does not support PB and PT on PPS Ports
16. PSF-98: [Field]Implement the requested software hooks
17. PSF-64: [Field] Un explained 20V toggling plus 5V,14V steps on the way to reaching 20V
18. PSF-140: [PPS] TD.PD.SRC.E16 PDO Transition Failure
19. PSF-141: [Document] Source Pro Demo Read Me Limitations

Sink existing issues:

1. [Sink][Ellisys] Errors Encountered while Executing TD.4.3.1 Sink Connect Source Test Case
2. [Sink][Ellisys] TD.4.1.2 Unpowered CC Voltage Test fails when PUT Configured as Sink
3. [Sink][LeCroy] TD.4.10.2 Sink Power Precedence Test Fails When PUT configured as Sink
4. [Sink][LeCroy] TDA 2.3.3.1 PDO Transition, Current Draw and Suspend Test - Sink, Consumer or Consumer/Provider Test Fails when PUT acts as Sink Partner
5. [Sink][LeCroy] TDA 2.1.3.2 BMC PHY Level Message Test Fails when PUT is Configured as sink
6. [SNK][Phase3] List of features not tested for PSF phase 3 alpha release
7. [SINK] When Gotomin was issued from source, sinkoperatingcurrent does not retain minimum operating current.

2.7.2 Bug Fixes

1. PSF-83: Complete the listed tasks in CSR, I2C DC/DC, PPM and PB modules
2. PSF-88: Complete the listed tasks in Control and Status registers implementation
3. PSF-30: [Sink]PD Sink Negotiation was not Proper for Certain PDO

3THIS DOCUMENT IS UNCONTROLLED UNLESS OTHERWISE STAMPED. It is the user's responsibility to ensure this is the latest revision prior to using or referencing this document.	Page	Spec. No.	Rev.
© Microchip Technology Inc. CONFIDENTIAL AND PROPRIETARY	24 of 34	FRM-50381-001	1.11

4. PSF-120: Negotiation is inconsistent when INCLUDE_POWER_FAULT_HANDLING = 1
5. PSF-119: 20V Negotiation fails with I2C DC/DC
6. PSF-114: Negotiation fails with I2C DC/DC from FW commit #1a020c212d5
7. PSF-138: Source Lite and Pro - Inconsistent behaviour observed
8. PSF-110: [MPQ] Port Power is not driven when PDO Count > 4
9. PSF-96: PC Lint for Alpha FW v1.01
10. PSF-97: [CSR] Struct and Stack versions should be updated by the stack, not by user application
11. PSF-112: [CSR] gasCfgStatusData to be passed as an argument in Configuration APIs of all the sample applications
12. PSF-117: Source Pro FW with Debug messages is non functional
13. PSF-116: [CSR] Following parameters are not getting updated during a valid PD contract
14. PSF-105: [CSR] New PDO registers should be cleared after a successful explicit contract is established
15. PSF-103: [CSR] EN_VBUS status bit should be updated for I2C based DC/DC controllers also
16. PSF-91: Build failure when INCLUDE_UPD_PIO_OVERRIDE_SUPPORT is set to 0
17. PSF-71: PSF feedback for porting to 16-bit MCUs
18. PSF-87: Handle Unexpected message when Sink capabilities message is received in wrong PE State
19. PSF-115: Implement DPM Client Request Handler based on Configuration Register settings

2.7.3 Features Added

- Power Throttling
- Source only Programmable Power Supply

2.7.4 Notes

- Only 2 Port Source and Sink solution has been tested at 8MHz SPI clock speed.
- System level PD communication between PSF and UPD350 through I2C interface is untested.

3THIS DOCUMENT IS UNCONTROLLED UNLESS OTHERWISE STAMPED. It is the user's responsibility to ensure this is the latest revision prior to using or referencing this document.	Page	Spec. No.	Rev.
© Microchip Technology Inc. CONFIDENTIAL AND PROPRIETARY	25 of 34	FRM-50381-001	1.11

- For Source Pro application,
 - Ellisys compliance has been tested with
INCLUDE_POWER_MANAGEMENT_CTRL = 0
 - Power Balancing and Power Throttling are supported only on non-PPS ports.

2.8 Version 1.03

Release date	21-April-2020
Release Type	Bug fix release
Pre-requisites (if any)	PSF EVB Rev A
Source Tag	Tag: PSF_STACK_V1.03

2.8.1 Not implemented / Limited functionality requirements

Source existing Issues:

1. PSF-44: TDA 2.3.1.1 Source Dynamic Load Test, Provider or Provider/Consumer Test Fails when PUT is configured as Source.
2. PSF-85: Ellisys Compliance fails with MPQ4230 I2C DC/DC Converter when
INCLUDE_POWER_MANAGEMENT_CTRL = 1
3. PSF-86: VBUS drop observed during Voltage transitions when the sink load is higher
4. PSF-89: No activity seen on Port 2 when MPQ I2C DC/DC controller is used with PSF
5. PSF-90: Continuous PD re-negotiation when number of source PDOs is 7
6. PSF-88: u16PortIntMask and u16PortStatusChange of Status registers need to be implemented.
7. PSF-110 [MPQ DC/DC] Port Power is not driven when PDO Count > 4
8. PSF-112 gasCfgStatusData to be passed as an argument in Configuration APIs of all the sample applications
9. PSF-97 Struct and Stack versions should be updated by the stack, not by user application
10. PSF-114 Negotiation fails with I2C DC/DC from FW commit #1a020c212d5
11. PSF-115 Implement DPM Client Request Handler based on Configuration Register settings

Sink Issues:

Due to lack of Lecroy and Ellisys availability following JIRAs could not be tested

1. PSF-49 [Sink][LeCroy] TDA 2.1.3.2 BMC PHY Level Message Test Fails when PUT is Configured as sink

3THIS DOCUMENT IS UNCONTROLLED UNLESS OTHERWISE STAMPED. It is the user's responsibility to ensure this is the latest revision prior to using or referencing this document.	Page	Spec. No.	Rev.
© Microchip Technology Inc. CONFIDENTIAL AND PROPRIETARY	26 of 34	FRM-50381-001	1.11

2. PSF-50 [Sink][LeCroy] TDA 2.3.3.1 PDO Transition, Current Draw and Suspend Test - Sink, Consumer or Consumer/Provider Test Fails when PUT acts as Sink Partner
3. PSF-51[Sink][LeCroy] TD.4.10.2 Sink Power Precedence Test Fails When PUT configured as Sink
4. PSF -53 [Sink][Ellisys] TD.4.1.2 Unpowered CC Voltage Test fails when PUT Configured as Sink
5. PSF-55 [Sink][Ellisys] Errors Encountered while Executing TD.4.3.1 Sink Connect Source Test Case
6. PSF-109 [SINK] When Gotomin was issued from source, sinkoperatingcurrent does not retain minimum operating current.

Sink Board issue:

1. PSF – 99 [SNK] [Hades] SAMD20 code does not boot when board is configured for bus-power

2.8.2 Bug Fixes

1. PSF-111 - [SYS_DOS] [SINK] EN_SNK, DC_DC_EN and VBUS_EN functionality clarification

2.8.3 Features added

1. Functional implementation for EN_SINK pin.

Sink demo project can be found under Demo folder in the name PSF_EVB_Sink.

2.8.4 Notes

The release is only for Sink application. For Source and Source Pro application use the V1.01 version of PSF.

2.9 Version 1.02

Release date	8-April-2020
Release Type	PSF Phase 3 Alpha release
Pre-requisites (if any)	PSF EVB Rev A
Source Tag	Tag: PSF_STACK_V1.02

2.9.1 Not implemented / Limited functionality requirements**Source existing Issues:**

1. PSF-44: TDA 2.3.1.1 Source Dynamic Load Test, Provider or Provider/Consumer Test Fails when PUT is configured as Source.

3THIS DOCUMENT IS UNCONTROLLED UNLESS OTHERWISE STAMPED. It is the user's responsibility to ensure this is the latest revision prior to using or referencing this document.	Page	Spec. No.	Rev.
© Microchip Technology Inc. CONFIDENTIAL AND PROPRIETARY	27 of 34	FRM-50381-001	1.11

2. PSF-85: Ellisys Compliance fails with MPQ4230 I2C DC/DC Converter when INCLUDE_POWER_MANAGEMENT_CTRL = 1
3. PSF-86: VBUS drop observed during Voltage transitions when the sink load is higher
4. PSF-89: No activity seen on Port 2 when MPQ I2C DC/DC controller is used with PSF
5. PSF-90: Continuous PD re-negotiation when number of source PDOs is 7
6. PSF-88: u16PortIntMask and u16PortStatusChange of Status registers need to be implemented.
7. PSF-110 [MPQ DC/DC] Port Power is not driven when PDO Count > 4
8. PSF-112 gasCfgStatusData to be passed as an argument in Configuration APIs of all the sample applications
9. PSF-97 Struct and Stack versions should be updated by the stack, not by user application

Sink Issues:

Due to lack of Lecroy and Ellisys availability following JIRAs could not be tested

1. PSF-49 [Sink][LeCroy] TDA 2.1.3.2 BMC PHY Level Message Test Fails when PUT is Configured as sink
2. PSF-50 [Sink][LeCroy] TDA 2.3.3.1 PDO Transition, Current Draw and Suspend Test - Sink, Consumer or Consumer/Provider Test Fails when PUT acts as Sink Partner
3. PSF-51[Sink][LeCroy] TD.4.10.2 Sink Power Precedence Test Fails When PUT configured as Sink
4. PSF -53 [Sink][Ellisys] TD.4.1.2 Unpowered CC Voltage Test fails when PUT Configured as Sink
5. PSF-55 [Sink][Ellisys] Errors Encountered while Executing TD.4.3.1 Sink Connect Source Test Case
6. PSF-109 [SINK] When Gotomin was issued from source, sinkoperatingcurrent does not retain minimum operating current.
7. PSF-111 - [SYS_DOS] [SINK] EN_SNK, DC_DC_EN and VBUS_EN functionality clarification

Sink Board issue:

1. PSF – 99 [SNK] [Hades] SAMD20 code does not boot when board is configured for bus-power

2.9.2 Bug Fixes

Sink Bug fixes:

1. PSF-36: CONFIG_PORT_n_SINK_USB_SUSPEND Field is not there in Fixed PDO fields of Sink Port – Removed CONFIG_PORT_n_SINK_USB_SUSPEND configuration which is not required and added NO_USB_SUSPEND flag implementation in u8SinkConfigSel.
2. PSF-30: PD Sink Negotiation was not proper for certain PDO – There was logical comparison error while comparing source and sink PDO list.
3. PSF-46 - [Sink][Ellisys] TD.PD.PHY.E16 Valid Hard Reset Framing Test Fails When PUT is Configured as sink - Hardreset handling in sink state machine had issue.
4. PSF-47 -[Sink][Ellisys] TD.PD.SNK.E1 SinkWaitCapTimer Deadline Test Fails When PUT Configured as Sink – Due to timer precision issue
5. PSF-54 [Sink][Ellisys] Errors Encountered while Executing TD.PD.LL.E4 Hard Reset Usage Test Case – Failure due to hard reset handling

Source Bug fixes:

1. PSF-91: Build failure when INCLUDE_UPD_PIO_OVERRIDE_SUPPORT is set to 0
2. PSF-108: UART needs to be added in SAMD20_PSFHarmonyConfiguration.xml in sink, source lite and source pro projects

Common to Source and Sink:

1. PSF-93 - Precision of software timers(PDTIMER) is erroneous to a max of 0.5ms time difference – Precision is fixed by timer providing value of Time value or +0.5ms.

2.9.3 Features added

New Demo USB PD Sink functionality is added with following supports

- Mode A (High Wattage with high voltage)
- Mode B (High wattage with low voltage)
- Goto_Min support
- VCONN swap support
- DAC and GPIO current indicators.

Sink demo project can be found under Demo folder in the name PSF_EVB_Sink.

2.9.4 Notes

The release is only for Sink application. For Source and Source Pro application use the V1.01 version of PSF.

3THIS DOCUMENT IS UNCONTROLLED UNLESS OTHERWISE STAMPED. It is the user's responsibility to ensure this is the latest revision prior to using or referencing this document.	Page	Spec. No.	Rev.
© Microchip Technology Inc. CONFIDENTIAL AND PROPRIETARY	29 of 34	FRM-50381-001	1.11

2.10 Version 1.01

Release date	19-Mar-2020
Release Type	PSF Phase 2 Alpha release
Pre-requisites (if any)	PSF EVB Rev A
Source Tag	Tag: PSF_STACK_V1.01

2.10.1 Not implemented / Limited functionality requirements

1. PSF-44: TDA 2.3.1.1 Source Dynamic Load Test, Provider or Provider/Consumer Test Fails when PUT is configured as Source.
2. PSF-85: Ellisys Compliance fails with MPQ4230 I2C DC/DC Converter when INCLUDE_POWER_MANAGEMENT_CTRL = 1
3. PSF-86: VBUS drop observed during Voltage transitions when the sink load is higher
4. PSF-89: No activity seen on Port 2 when MPQ I2C DC/DC controller is used with PSF
5. PSF-90: Continuous PD re-negotiation when number of source PDOs is 7
6. PSF-91: Build failure when INCLUDE_UPD_PIO_OVERRIDE_SUPPORT is set to 0
7. PSF-88: u16PortIntMask and u16PortStatusChange of Status registers need to be implemented.

2.10.2 Bug Fixes

1. PSF-70: "Data" Configurable Parameter cannot be Configured to Other Options mentioned in the System DOS – Bits 8:6 of u32CfgData in PORT_CFG_STATUS structure holds the option to configure USB Data parameters.
2. PSF-71: PSF feedback for porting to 16-bit MCU – Suggested type casts are taken care and a new Hook function is introduced for enable/disable of DC_DC_EN.
3. PSF-82: tVCONNSourceOn timer value exceeds the Max Limit given in USB PD Specification – VCONN On and Off timer values are updated as per the PD Specification.
4. PSF-87: Handle Unexpected message when Sink capabilities message is received in wrong PE State – Unexpected message handling is fixed by sending soft reset in case sink caps message is received in wrong PE state.

2.10.3 Features added

- Boot time Configuration parameters and Run time Status registers
- Support for MPQ4230 I2C DC/DC controller
- Power Balancing

2.10.4 Notes

- Only 2 Port Source and Sink solution has been tested at 8MHz SPI clock speed.
- System level PD communication between PSF and UPD350 through I2C interface is untested.
- For Source Pro application, Ellisys compliance has been tested only in Port 1 with INCLUDE_POWER_MANAGEMENT_CTRL = 0 and INCLUDE_POWER_BALANCING = 0 whereas for Source Lite application, 2 port Ellisys compliance has been tested.

2.11 Version 1.00

Release date	26-Feb-2020
Release Type	PD Source only feature complete release
Pre-requisites (if any)	PSF EVB Rev A
Source Tag	Tag: PSF_STACK_V1.00

2.11.1 Not implemented / Limited functionality requirements

1. PSF-44: TDA 2.3.1.1 Source Dynamic Load Test, Provider or Provider/Consumer Test Fails when PUT is configured as Source

2.11.2 Bug Fixes

1. PSF-21: VBUS OCS Power fault handling not working – Max Power Fault Count check is included for implicit contract also.
2. PSF-26: Build Fails When INCLUDE_POWER_FAULT_HANDLING Macro is set to 0 – Fixed the error thrown by the compiler.
3. PSF-43: TD.PD.SRC.E16 PDO Transition Test fails inconsistently in Port 1 Alone when Configured as Source – There was a difference in actual voltage threshold values and those calculated by FW due to the improper float to int conversions handled in FW. This is fixed.
4. PSF-45: TDA 2.3.2.1 PDO Transition Test - Source, Provider or Provider/Consumer Test Fails on both Ports – The fix is same as that of PSF-43

2.11.3 Features added

NA

2.11.4 Notes

- This is PD Source only feature complete release with bug fixes reported in v0.95
- Only 2 Port Source and Sink solution has been tested at 8MHz SPI clock speed.
- System level PD communication between PSF and UPD350 through I2C interface is untested, whereas basic I2C read/writes are tested.

2.12 Version 0.95

Release date	09-Jan-2020
Release Type	Beta Release
Pre-requisites (if any)	PSF EVB Rev A
Source Tag	Tag: PSF_STACK_V0.95

2.12.1 Not implemented / Limited functionality requirements

1. PSF-44: TDA 2.3.1.1 Source Dynamic Load Test, Provider or Provider/Consumer Test Fails when PUT is configured as Source
2. PSF-41: SPT.5 Over Current QuadraMAX Test Fails on Both Ports

2.12.2 Bug Fixes

1. PSF-21: VBUS OCS Power fault handling not working – DC_DC_EN was toggled twice to reset the fault occurred. Since DC_DC was set and reset immediately, DC-DC controller did not have enough time to reset itself. PIO Override drive was not reset after a Fault. Both the issues are fixed.
2. PSF-7: HiByte has potential error – Fixed the warning generated by PC Lint
3. PSF-65: PD Source tests in Ellisys compliance fails when MchpPSF_Run() is called for every 3ms – This issue is fixed by setting PE_PDCONNECTED_STS_MASK in ePE_SRC_NEGOTIATE_CAPABILITY state.
4. PSF-61: Unable to charge HP-Laptop - Possible Bug with VCONN SWAP response (Reject/Not Supported) - For source only operation, INCLUDE_VCONN_SWAP_SUPPORT should be defined as '1'. Same is updated in the PSF_Config.h file description.
5. PSF-69: When INCLUDE_UPD_PIO_OVERRIDE_SUPPORT defined as 0, negotiation is not happening - Undervoltage was detected by FW without considering whether under voltage power fault detection was enabled; Which caused undervoltage detection and follow up power shutdown. It is fixed now.

2.12.3 Features added

NA

2.12.4 Notes

- Only 2 Port Source and Sink solution has been tested at 8MHz SPI clock speed.
- System level PD communication between PSF and UPD350 through I2C interface is untested, whereas basic I2C read/writes are tested.

2.13 Version 0.92

Release date	12-Dec-2019
Release Type	Documentation Release
Pre-requisites (if any)	PSF EVB Rev A
Source Tag	Tag: PSF_STACK_V0.92

2.13.1 Not implemented / Limited functionality requirements

Firmware Bug fixes are not made for this release. All the bugs observed with V0.91 release is applicable for V0.92 release too.

2.13.2 Bug Fixes

No Bug fixes made

2.13.3 Features added

This release is made to mark the release of following documents

- PSF User Guide
- Getting Started with PSF
- Demo Read me

2.13.4 Notes

None.

2.14 Version 0.91

Release date	11-Nov-19
Release Type	Bug fix release
Pre-requisites (if any)	PSF EVB Rev A
Source Tag	Tag: PSF_STACK_V0.91

2.14.1 Not implemented / Limited functionality requirements

1. PSF-7 - HiByte has potential error

2.14.2 Bug Fixes

1. PSF-19 -FW has build issue when CONFIG_PD_PORT_COUNT set to 1
2. PSF-21 - VBUS OCS Power fault handling not working
3. PSF-26 - Build Fails When INCLUDE_POWER_FAULT_HANDLING Macro is set to 0
4. PSF-31 - Build Fails When INCLUDE_PDFU Macro is set to 1
5. PSF-32 - Configuring CONFIG_PORT_n_SINK_USB_COM macro Field is not Effective
6. PSF-33 - Configuring CONFIG_PORT_n_SINK_UNCONSTRAINED_PWR macro Field is not Effective
7. PSF-34 - Build Fails When INCLUDE_PD_3_0 Macro is set to 0

2.14.3 Features added

NA

2.14.4 Notes

Following JIRA reported marked invalid after developing from developer's side:

1. PSF-22 - VCONN OCS handling not working
2. PSF 23 - PD Negotiation Fails when PDOs are Configured more than 5 with certain values
3. PSF-25 - The PUT is not Disabled Even After the Under Voltage Count Exceeds the Maximum Fault Count

2.15 Version 0.90

Release date	24-Oct-2019
Release Type	Initial Web release
Pre-requisites (if any)	PSF EVB Rev A
Source Tag	Tag: PSF_STACK_V0.91

2.15.1 Not implemented / Limited functionality requirements

1. PSF-7 - HiByte has potential error
2. PSF-21 - VBUS Power fault handling not working
3. PSF-22 - VCONN OCS handling not working
4. PSF-23 - PD Negotiation Fails when PDOs are Configured more than 5 with certain values
5. PSF-25 - The PUT is not Disabled Even After the Under Voltage Count Exceeds the Maximum Fault Count

2.15.2 Bug Fixes

Not Applicable

2.15.3 Features added

Initial revision of PSF for Source only operation.

2.15.4 Notes

Not Applicable