



# Software Release Notes

## *USB Power Delivery Software Framework (PSF)*

3THIS DOCUMENT IS UNCONTROLLED UNLESS OTHERWISE STAMPED. It is the user's responsibility to ensure this is the latest revision prior to using or referencing this document.	Page	Spec. No.	Rev.
© Microchip Technology Inc. <b>CONFIDENTIAL AND PROPRIETARY</b>	1 of 22	FRM-50381-001	1.06

Information contained in this publication regarding device applications and the like is provided only for your convenience and can be superseded by updates. It is your responsibility to ensure that your application meets with your specifications. MICROCHIP MAKES NO REPRESENTATIONS OR WARRANTIES OF ANY KIND WHETHER EXPRESS OR IMPLIED, WRITTEN OR ORAL, STATUTORY OR OTHERWISE, RELATED TO THE INFORMATION, INCLUDING BUT NOT LIMITED TO ITS CONDITION, QUALITY, PERFORMANCE, MERCHANTABILITY OR FITNESS FOR PURPOSE.

Microchip disclaims all liability arising from this information and its use. Use of Microchip devices in life support and/or safety applications is entirely at the buyer's risk, and the buyer agrees to defend, indemnify and hold harmless Microchip from any and all damages, claims, suits, or expenses resulting from such use. No licenses are conveyed, implicitly or otherwise, under any Microchip intellectual property rights.

3THIS DOCUMENT IS UNCONTROLLED UNLESS OTHERWISE STAMPED. It is the user's responsibility to ensure this is the latest revision prior to using or referencing this document.	Page	Spec. No.	Rev.
© Microchip Technology Inc. <b>CONFIDENTIAL AND PROPRIETARY</b>	2 of 22	FRM-50381-001	1.06



**MICROCHIP**  
Microchip Technology, Inc.

Microchip Technology, Incorporated  
2355 W. Chandler Boulevard  
Chandler, Arizona 85224  
480/792-7200

REV	DATE	DESCRIPTION OF CHANGE
0.90	Oct 24, 2019	First Web release
0.91	Nov 11,2019	Bug fix release
0.92	Dec 12,2019	Documentation release
0.95	Jan 09, 2020	Release with complete documentation and Bug fix
1.00	Feb 25, 2020	Source only feature complete release
1.01	Mar 19,2020	Phase 2 Alpha release
1.02	Apr 8, 2020	Phase 3 Alpha release
1.03	Apr 21, 2020	Bug fix release
1.04	June 19,2020	Phase 2 Beta Release
1.05	July 24, 2020	Bug fix release
1.06	Aug 20, 2020	Phase 4 Alpha Release

## Table of Contents

1	Introduction .....	6
2	Release notes .....	6
2.1	Version 1.06.....	6
2.1.1	Not implemented / Limited functionality requirements .....	6
2.1.2	Bug Fixes.....	7
2.1.3	Features Added.....	8
2.1.4	Notes.....	8
2.2	Version 1.05.....	9
2.2.1	Not implemented / Limited functionality requirements .....	9
2.2.2	Bug Fixes.....	10
2.2.3	Features Added.....	11
2.2.4	Notes.....	11
2.3	Version 1.04.....	11
2.3.1	Not implemented / Limited functionality requirements .....	11
2.3.2	Bug Fixes.....	12
2.3.3	Features Added.....	13
2.3.4	Notes.....	14
2.4	Version 1.03.....	14
2.4.1	Not implemented / Limited functionality requirements .....	14
2.4.2	Bug Fixes.....	15
2.4.3	Features added.....	15
2.4.4	Notes.....	15
2.5	Version 1.02.....	15
2.5.1	Not implemented / Limited functionality requirements .....	16
2.5.2	Bug Fixes.....	17
2.5.3	Features added.....	17
2.5.4	Notes.....	18
2.6	Version 1.01.....	18
2.6.1	Not implemented / Limited functionality requirements .....	18
2.6.2	Bug Fixes.....	18
2.6.3	Features added.....	19
2.6.4	Notes.....	19
2.7	Version 1.00.....	19
2.7.1	Not implemented / Limited functionality requirements .....	19
2.7.2	Bug Fixes.....	19
2.7.3	Features added.....	19
2.7.4	Notes.....	20
2.8	Version 0.95.....	20
2.8.1	Not implemented / Limited functionality requirements .....	20
2.8.2	Bug Fixes.....	20
2.8.3	Features added.....	20
2.8.4	Notes.....	21
2.9	Version 0.92.....	21
2.9.1	Not implemented / Limited functionality requirements .....	21
2.9.2	Bug Fixes.....	21

---

2.9.3	Features added .....	21
2.9.4	Notes.....	21
2.10	Version 0.91 .....	21
2.10.1	Not implemented / Limited functionality requirements .....	21
2.10.2	Bug Fixes.....	21
2.10.3	Features added .....	22
2.10.4	Notes.....	22
2.11	Version 0.90 .....	22
2.11.1	Not implemented / Limited functionality requirements .....	22
2.11.2	Bug Fixes.....	22
2.11.3	Features added .....	22
2.11.4	Notes.....	22

## 1 Introduction

USB Power Delivery Software Framework (PSF) – a software-based Power Delivery stack along with UPD350 Type-C Port Controller (Maverick) is a USB-PD solution. It is a generic user-friendly that can be ported across various hardware platform.

<b>Component Type</b>	USB Power Delivery Software Framework (PSF)
<b>Target Silicon</b>	SAMD20 + UPD350
<b>Where can an end user see the version number</b>	Version number appended with filename ../PSF/Source/include/ProjectVersion.h

## 2 Release notes

### 2.1 Version 1.06

<b>Release date</b>	20-Aug 2020
<b>Release Type</b>	Phase 4 alpha release
<b>Pre-requisites (if any)</b>	<b>PSF EVB</b>
<b>Source Tag</b>	<b>Tag: PSF_STACK_V1.06</b>

#### 2.1.1 Not implemented / Limited functionality requirements

1. PSF-136: Dynamic Port Control(Port Enable/Disable) Client request
2. PSF-153: VBUS Discharge handling inside Type C ISR
3. PSF-18: CLONE - Absence of power negotiation on ports of the DUT when VDD33 is set to 2.80V
4. PSF-147: Discover identity support for Teton PSF
5. PSF-21: VBUS OCS Power fault handling not working
6. PSF-98: [Field]Implement the requested software hooks
7. PSF-137: Power Delivery Disabled notification
8. PSF-160: Trace support at lower UART frequencies
9. PSF-78: Clarification On MCU Idle Timeout Configuration
10. PSF-150: [Ellisys] [Sink] Ellisys compliance tests failed with sink demo firmware
11. PSF-132: [SNK][Phase3] List of features not tested for PSF phase 3 alpha release
12. PSF-85: [MPQ]Ellisys Compliance fails when

INCLUDE\_POWER\_MANAGEMENT\_CTRL = 1

3THIS DOCUMENT IS UNCONTROLLED UNLESS OTHERWISE STAMPED. It is the user's responsibility to ensure this is the latest revision prior to using or referencing this document.	Page	Spec. No.	Rev.
© Microchip Technology Inc. <b>CONFIDENTIAL AND PROPRIETARY</b>	6 of 22	FRM-50381-001	1.06

13. PSF-86: [Field] VBUS drop observed during Voltage transitions when the sink load is higher
14. PSF-170: VCONN Source to reset the Cable Plug's Protocol Layer to ensure MessageID synchronization
15. PSF-168: [Swap Notification] Swap completion notification to be posted after sending Reject to swap request
16. PSF-157: Implement the FW changes needed to address PSF-148
17. PSF-94: [MPQ] Handle I2C read/write failures
18. PSF-51: [Sink][LeCroy] TD.4.10.2 Sink Power Precedence Test Fails When PUT configured as Sink
19. PSF-50: [Sink][LeCroy] TDA 2.3.3.1 PDO Transition, Current Draw and Suspend Test - Sink, Consumer or Consumer/Provider Test Fails when PUT acts as Sink Partner
20. PSF-49: [Sink][LeCroy] TDA 2.1.3.2 BMC PHY Level Message Test Fails when PUT is Configured as sink
21. PSF-44: [Lecroy] TDA 2.3.1.1 Source Dynamic Load Test, Provider or Provider/Consumer Test Fails When PUT is configured as Source
22. PSF-161: [Cfg&Sts] Power fault counter status parameter needs to be implemented.
23. PSF-53: [Sink][Ellisys] TD.4.1.2 Unpowered CC Voltage Test fails when PUT Configured as Sink
24. PSF-155: PSF does not respond to VDM:Disc Identity command from port partner
25. PSF-141: [Document] Source Pro Demo Read Me Limitations
26. PSF-101: [PSF User Guide] Capture the 8-bit memory requirement details under section "Software Requirements"
27. PSF-173: Port0 when acts as DRP as Source or fixed source, runs into error recovery after turning on VBUS
28. PSF-54: [Sink][Ellisys] TD.4.1.2 Unpowered CC Voltage Test fails when PUT Configured as Sink

## 2.1.2 Bug Fixes

1. PSF-172: When VCONN swap is not supported, respond with "reject" and not with "not supported" for the VCONN swap message
2. PSF-145: [Sink] Power fault occurs when source partner is detached
3. PSF-167: [Snk] UV Fault is triggered during detach when the port is Sourcing VCONN

3THIS DOCUMENT IS UNCONTROLLED UNLESS OTHERWISE STAMPED. It is the user's responsibility to ensure this is the latest revision prior to using or referencing this document.	Page	Spec. No.	Rev.
© Microchip Technology Inc. <b>CONFIDENTIAL AND PROPRIETARY</b>	7 of 22	FRM-50381-001	1.06

4. PSF-134: [Field] VCONN Swap not working with HP laptop
5. PSF-156 - Client notification to be added to indicate port powered off due to power fault
6. PSF-162 - [Cfg&Stst] In port identity, manufacturer string and its length needs to be implemented and product ID should be set with proper default value
7. PSF-164 -[Src] New PDOs to be cleared only when renegotiation is triggered by DPM
8. PSF-55: [Sink][Ellisys] Errors Encountered while Executing TD.4.3.1 Sink Connect Source Test Case
9. PSF-109: [SINK] When Gotomin was issued from source, sinkoperatingcurrent does not retain minimum operating current.
10. PSF-163: Organise defines in bootcfg.h file in all demos, so that, it is easy for user to configure.

### 2.1.3 Features Added

- Dual Role Power
- Data Role Swap
- Power Role Swap

New application for DRP configuration is added with this release.

First port of DRP application is configured as Notebook port with Role Swap Policy set to accept and request DR\_Swap when acting as UFP, accept and request PR\_Swap when acting as Source, request VCONN\_Swap when not acting as VCONN source and accept VCONN\_Swap when acting as both VCONN Source and Not as VCONN Source.

Second port of DRP application is configured as Dock type port with Role Swap Policy set to accept and request DR\_Swap when acting as DFP, accept and request PR\_Swap when acting as Sink and accept VCONN\_Swap when acting as both VCONN Source and Not as VCONN Source.

### 2.1.4 Notes

- Only 2 Port solution has been tested at 8MHz SPI clock speed.
- System level PD communication between PSF and UPD350 through I2C interface is untested.
- For Source Pro application,
  - Ellisys compliance has been tested with  
INCLUDE\_POWER\_MANAGEMENT\_CTRL = 0
- For DRP application, Ellisys compliance testing is not done.



## 2.2 Version 1.05

Release date	24-July 2020
Release Type	Bug fix release
Pre-requisites (if any)	<b>PSF EVB</b>
Source Tag	<b>Tag: PSF_STACK_V1.05</b>

### 2.2.1 Not implemented / Limited functionality requirements

Source existing issues:

1. PSF-44: TDA 2.3.1.1 Source Dynamic Load Test, Provider or Provider/Consumer Test Fails when PUT is configured as Source.
2. PSF-86: [Field] VBUS drop observed during Voltage transitions when the sink load is higher
3. PSF-79: Clarification on VSEL Configuration
4. PSF-90: Continuous PD re-negotiation when number of source PDOs is 7
5. PSF-134: [Field] VCONN Swap not working with HP laptop
6. PSF-21: VBUS OCS Power fault handling not working
7. PSF-85: [MPQ]Ellisys Compliance fails when  
INCLUDE\_POWER\_MANAGEMENT\_CTRL = 1
8. PSF-135: PSF Control/Status Data Memory Management
9. PSF-136: Dynamic Port Control(Port Enable/Disable) Client request
10. PSF-137: Power Delivery Disabled notification
11. PSF-94: [MPQ] Handle I2C read/write failures
12. PSF-78: Clarification On MCU Idle Timeout Configuration
13. PSF-95: PSF 8-bit MCU porting Feedback
14. PSF-118: Phase 2 FW does not support PB and PT on PPS Ports
15. PSF-98: [Field]Implement the requested software hooks
16. PSF-64: [Field] Un explained 20V toggling plus 5V,14V steps on the way to reaching 20V
17. PSF-153: VBUS Discharge handling inside Type C ISR

18. PSF-147: Discover identity support for Teton PSF
19. PSF-18: CLONE - Absence of power negotiation on ports of the DUT when VDD33 is set to 2.80V
20. PSF-156: Client notification to be added to indicate port powered off due to power fault
21. PSF-154: CLONE - Workaround for OLYMPUS\_DEV-3217
22. PSF-155: PSF does not respond to VDM:Disc Identity command from port partner

#### Sink existing issues:

1. PSF-55: [Sink][Ellisys] Errors Encountered while Executing TD.4.3.1 Sink Connect Source Test Case
2. PSF-54: [Sink][Ellisys] TD.4.1.2 Unpowered CC Voltage Test fails when PUT Configured as Sink
3. PSF-51: [Sink][LeCroy] TD.4.10.2 Sink Power Precedence Test Fails When PUT configured as Sink
4. PSF-50: [Sink][LeCroy] TDA 2.3.3.1 PDO Transition, Current Draw and Suspend Test - Sink, Consumer or Consumer/Provider Test Fails when PUT acts as Sink Partner
5. PSF-49: [Sink][LeCroy] TDA 2.1.3.2 BMC PHY Level Message Test Fails when PUT is Configured as sink
6. PSF-132: [SNK][Phase3] List of features not tested for PSF phase 3 alpha release
7. PSF-109: [SINK] When Gotomin was issued from source, sinkoperatingcurrent does not retain minimum operating current.
8. PSF-150: [Ellisys] [Sink] Ellisys compliance tests failed with sink demo firmware

## 2.2.2 Bug Fixes

1. PSF-140: [PPS] TD.PD.SRC.E16 PDO Transition Failure
2. PSF-144: [PPS] More than one alert sent for cable limitation
3. PSF-142: [CSR] Advertised PDOs to be cleared after detach
4. PSF-151: Hooks to notify PSF stack Idle waiting for an event
5. PSF-149: [Sink] Evaluating source capabilities needs to be done based on advertised PDOs, not sink PDOs
6. PSF-139: [Sink] After a board reset, PD negotiation fails

<small>THIS DOCUMENT IS UNCONTROLLED UNLESS OTHERWISE STAMPED. It is the user's responsibility to ensure this is the latest revision prior to using or referencing this document.</small> <small>© Microchip Technology Inc. <b>CONFIDENTIAL AND PROPRIETARY</b></small>	Page 10 of 22	Spec. No. FRM-50381-001	Rev. 1.06
---	------------------	----------------------------	--------------

7. PSF-146: [Src] Code Review comments
8. PSF-152: Orientation pin is not initialised in V1.04 Release
9. PSF-121: CONFIG\_DCDC\_CTRL in Sink Mode

### 2.2.3 Features Added

- None.

### 2.2.4 Notes

- Only 2 Port Source and Sink solution has been tested at 8MHz SPI clock speed.
- System level PD communication between PSF and UPD350 through I2C interface is untested.
- For Source Pro application,
  - Ellisys compliance has been tested with  
INCLUDE\_POWER\_MANAGEMENT\_CTRL = 0
  - Power Balancing and Power Throttling are supported only on non-PPS ports.

## 2.3 Version 1.04

Release date	19-June-2020
Release Type	Phase 2 Beta release
Pre-requisites (if any)	<b>PSF EVB Rev A</b>
Source Tag	<b>Tag: PSF_STACK_V1.04</b>

### 2.3.1 Not implemented / Limited functionality requirements

Source existing issues:

1. PSF-44: TDA 2.3.1.1 Source Dynamic Load Test, Provider or Provider/Consumer Test Fails when PUT is configured as Source.
2. PSF-86: [Field] VBUS drop observed during Voltage transitions when the sink load is higher
3. PSF-79: Clarification on VEL Configuration
4. PSF-90: Continuous PD re-negotiation when number of source PDOs is 7
5. PSF-134: [Field] VCONN Swap not working with HP laptop
6. PSF-21: VBUS OCS Power fault handling not working

3THIS DOCUMENT IS UNCONTROLLED UNLESS OTHERWISE STAMPED. It is the user's responsibility to ensure this is the latest revision prior to using or referencing this document.	Page	Spec. No.	Rev.
© Microchip Technology Inc. <b>CONFIDENTIAL AND PROPRIETARY</b>	11 of 22	FRM-50381-001	1.06

7. PSF-85: [MPQ]Ellisys Compliance fails when  
INCLUDE\_POWER\_MANAGEMENT\_CTRL = 1
8. PSF-135: PSF Control/Status Data Memory Management
9. PSF-136: Dynamic Port Control(Port Enable/Disable) Client request
10. PSF-137: Power Delivery Disabled notification
11. PSF-121: CONFIG\_DCDC\_CTRL in Sink Mode
12. PSF-94: [MPQ] Handle I2C read/write failures
13. PSF-78: Clarification On MCU Idle Timeout Configuration
14. PSF-95: PSF 8-bit MCU porting Feedback
15. PSF-118: Phase 2 FW does not support PB and PT on PPS Ports
16. PSF-98: [Field]Implement the requested software hooks
17. PSF-64: [Field] Un explained 20V toggling plus 5V,14V steps on the way to reaching  
20V
18. PSF-140: [PPS] TD.PD.SRC.E16 PDO Transition Failure
19. PSF-141: [Document] Source Pro Demo Read Me Limitations

#### Sink existing issues:

1. [Sink][Ellisys] Errors Encountered while Executing TD.4.3.1 Sink Connect Source Test Case
2. [Sink][Ellisys] TD.4.1.2 Unpowered CC Voltage Test fails when PUT Configured as Sink
3. [Sink][LeCroy] TD.4.10.2 Sink Power Precedence Test Fails When PUT configured as Sink
4. [Sink][LeCroy] TDA 2.3.3.1 PDO Transition, Current Draw and Suspend Test - Sink, Consumer or Consumer/Provider Test Fails when PUT acts as Sink Partner
5. [Sink][LeCroy] TDA 2.1.3.2 BMC PHY Level Message Test Fails when PUT is Configured as sink
6. [SNK][Phase3] List of features not tested for PSF phase 3 alpha release
7. [SINK] When Gotomin was issued from source, sinkoperatingcurrent does not retain minimum operating current.

### 2.3.2 Bug Fixes

1. PSF-83: Complete the listed tasks in CSR, I2C DC/DC, PPM and PB modules

3THIS DOCUMENT IS UNCONTROLLED UNLESS OTHERWISE STAMPED. It is the user's responsibility to ensure this is the latest revision prior to using or referencing this document.	Page	Spec. No.	Rev.
© Microchip Technology Inc. <b>CONFIDENTIAL AND PROPRIETARY</b>	12 of 22	FRM-50381-001	1.06

2. PSF-88: Complete the listed tasks in Control and Status registers implementation
3. PSF-30: [Sink]PD Sink Negotiation was not Proper for Certain PDO
4. PSF-120: Negotiation is inconsistent when INCLUDE\_POWER\_FAULT\_HANDLING = 1
5. PSF-119: 20V Negotiation fails with I2C DC/DC
6. PSF-114: Negotiation fails with I2C DC/DC from FW commit #1a020c212d5
7. PSF-138: Source Lite and Pro - Inconsistent behaviour observed
8. PSF-110: [MPQ] Port Power is not driven when PDO Count > 4
9. PSF-96: PC Lint for Alpha FW v1.01
10. PSF-97: [CSR] Struct and Stack versions should be updated by the stack, not by user application
11. PSF-112: [CSR]gasCfgStatusData to be passed as an argument in Configuration APIs of all the sample applications
12. PSF-117: Source Pro FW with Debug messages is non functional
13. PSF-116: [CSR] Following parameters are not getting updated during a valid PD contract
14. PSF-105: [CSR] New PDO registers should be cleared after a successful explicit contract is established
15. PSF-103: [CSR] EN\_VBUS status bit should be updated for I2C based DC/DC controllers also
16. PSF-91: Build failure when INCLUDE\_UPD\_PIO\_OVERRIDE\_SUPPORT is set to 0
17. PSF-71: PSF feedback for porting to 16-bit MCUs
18. PSF-87: Handle Unexpected message when Sink capabilities message is received in wrong PE State
19. PSF-115: Implement DPM Client Request Handler based on Configuration Register settings

### 2.3.3 Features Added

- Power Throttling
- Source only Programmable Power Supply

3THIS DOCUMENT IS UNCONTROLLED UNLESS OTHERWISE STAMPED. It is the user's responsibility to ensure this is the latest revision prior to using or referencing this document.	Page	Spec. No.	Rev.
© Microchip Technology Inc. <b>CONFIDENTIAL AND PROPRIETARY</b>	13 of 22	FRM-50381-001	1.06

## 2.3.4 Notes

- Only 2 Port Source and Sink solution has been tested at 8MHz SPI clock speed.
- System level PD communication between PSF and UPD350 through I2C interface is untested.
- For Source Pro application,
  - Ellisys compliance has been tested with  
INCLUDE\_POWER\_MANAGEMENT\_CTRL = 0
  - Power Balancing and Power Throttling are supported only on non-PPS ports.

## 2.4 Version 1.03

Release date	21-April-2020
Release Type	Bug fix release
Pre-requisites (if any)	<b>PSF EVB Rev A</b>
Source Tag	<b>Tag: PSF_STACK_V1.03</b>

### 2.4.1 Not implemented / Limited functionality requirements

#### Source existing Issues:

1. PSF-44: TDA 2.3.1.1 Source Dynamic Load Test, Provider or Provider/Consumer Test Fails when PUT is configured as Source.
2. PSF-85: Ellisys Compliance fails with MPQ4230 I2C DC/DC Converter when  
INCLUDE\_POWER\_MANAGEMENT\_CTRL = 1
3. PSF-86: VBUS drop observed during Voltage transitions when the sink load is higher
4. PSF-89: No activity seen on Port 2 when MPQ I2C DC/DC controller is used with PSF
5. PSF-90: Continuous PD re-negotiation when number of source PDOs is 7
6. PSF-88: u16PortIntMask and u16PortStatusChange of Status registers need to be implemented.
7. PSF-110 [MPQ DC/DC] Port Power is not driven when PDO Count > 4
8. PSF-112 gasCfgStatusData to be passed as an argument in Configuration APIs of all the sample applications
9. PSF-97 Struct and Stack versions should be updated by the stack, not by user application
10. PSF-114 Negotiation fails with I2C DC/DC from FW commit #1a020c212d5

## 11. PSF-115 Implement DPM Client Request Handler based on Configuration Register settings

### Sink Issues:

Due to lack of Lecroy and Ellisys availability following JIRAs could not be tested

1. PSF-49 [Sink][LeCroy] TDA 2.1.3.2 BMC PHY Level Message Test Fails when PUT is Configured as sink
2. PSF-50 [Sink][LeCroy] TDA 2.3.3.1 PDO Transition, Current Draw and Suspend Test - Sink, Consumer or Consumer/Provider Test Fails when PUT acts as Sink Partner
3. PSF-51[Sink][LeCroy] TD.4.10.2 Sink Power Precedence Test Fails When PUT configured as Sink
4. PSF -53 [Sink][Ellisys] TD.4.1.2 Unpowered CC Voltage Test fails when PUT Configured as Sink
5. PSF-55 [Sink][Ellisys] Errors Encountered while Executing TD.4.3.1 Sink Connect Source Test Case
6. PSF-109 [SINK] When Gotomin was issued from source, sinkoperatingcurrent does not retain minimum operating current.

### Sink Board issue:

1. PSF – 99 [SNK] [Hades] SAMD20 code does not boot when board is configured for bus-power

## 2.4.2 Bug Fixes

1. PSF-111 - [SYS\_DOS] [SINK] EN\_SNK, DC\_DC\_EN and VBUS\_EN functionality clarification

## 2.4.3 Features added

1. Functional implementation for EN\_SINK pin.

Sink demo project can be found under Demo folder in the name PSF\_EVB\_Sink.

## 2.4.4 Notes

The release is only for Sink application. For Source and Source Pro application use the V1.01 version of PSF.

## 2.5 Version 1.02

Release date	8-April-2020
Release Type	PSF Phase 3 Alpha release
Pre-requisites (if any)	PSF EVB Rev A

3THIS DOCUMENT IS UNCONTROLLED UNLESS OTHERWISE STAMPED. It is the user's responsibility to ensure this is the latest revision prior to using or referencing this document.	Page	Spec. No.	Rev.
© Microchip Technology Inc. <b>CONFIDENTIAL AND PROPRIETARY</b>	15 of 22	FRM-50381-001	1.06

## 2.5.1 Not implemented / Limited functionality requirements

### Source existing Issues:

1. PSF-44: TDA 2.3.1.1 Source Dynamic Load Test, Provider or Provider/Consumer Test Fails when PUT is configured as Source.
2. PSF-85: Ellisys Compliance fails with MPQ4230 I2C DC/DC Converter when INCLUDE\_POWER\_MANAGEMENT\_CTRL = 1
3. PSF-86: VBUS drop observed during Voltage transitions when the sink load is higher
4. PSF-89: No activity seen on Port 2 when MPQ I2C DC/DC controller is used with PSF
5. PSF-90: Continuous PD re-negotiation when number of source PDOs is 7
6. PSF-88: u16PortIntMask and u16PortStatusChange of Status registers need to be implemented.
7. PSF-110 [MPQ DC/DC] Port Power is not driven when PDO Count > 4
8. PSF-112 gasCfgStatusData to be passed as an argument in Configuration APIs of all the sample applications
9. PSF-97 Struct and Stack versions should be updated by the stack, not by user application

### Sink Issues:

Due to lack of Lecroy and Ellisys availability following JIRAs could not be tested

1. PSF-49 [Sink][LeCroy] TDA 2.1.3.2 BMC PHY Level Message Test Fails when PUT is Configured as sink
2. PSF-50 [Sink][LeCroy] TDA 2.3.3.1 PDO Transition, Current Draw and Suspend Test - Sink, Consumer or Consumer/Provider Test Fails when PUT acts as Sink Partner
3. PSF-51[Sink][LeCroy] TD.4.10.2 Sink Power Precedence Test Fails When PUT configured as Sink
4. PSF -53 [Sink][Ellisys] TD.4.1.2 Unpowered CC Voltage Test fails when PUT Configured as Sink
5. PSF-55 [Sink][Ellisys] Errors Encountered while Executing TD.4.3.1 Sink Connect Source Test Case
6. PSF-109 [SINK] When Gotomin was issued from source, sinkoperatingcurrent does not retain minimum operating current.



7. PSF-111 - [SYS\_DOS] [SINK] EN\_SNK, DC\_DC\_EN and VBUS\_EN functionality clarification

**Sink Board issue:**

1. PSF – 99 [SNK] [Hades] SAMD20 code does not boot when board is configured for bus-power

**2.5.2 Bug Fixes****Sink Bug fixes:**

1. PSF-36: CONFIG\_PORT\_n\_SINK\_USB\_SUSPEND Field is not there in Fixed PDO fields of Sink Port – Removed CONFIG\_PORT\_n\_SINK\_USB\_SUSPEND configuration which is not required and added NO\_USB\_SUSPEND flag implementation in u8SinkConfigSel.
2. PSF-30: PD Sink Negotiation was not proper for certain PDO – There was logical comparison error while comparing source and sink PDO list.
3. PSF-46 - [Sink][Ellisys] TD.PD.PHY.E16 Valid Hard Reset Framing Test Fails When PUT is Configured as sink - Hardreset handling in sink state machine had issue.
4. PSF-47 -[Sink][Ellisys] TD.PD.SNK.E1 SinkWaitCapTimer Deadline Test Fails When PUT Configured as Sink – Due to timer precision issue
5. PSF-54 [Sink][Ellisys] Errors Encountered while Executing TD.PD.LL.E4 Hard Reset Usage Test Case – Failure due to hard reset handling

**Source Bug fixes:**

1. PSF-91: Build failure when INCLUDE\_UPD\_PIO\_OVERRIDE\_SUPPORT is set to 0
2. PSF-108: UART needs to be added in SAMD20\_PSFHarmonyConfiguration.xml in sink, source lite and source pro projects

**Common to Source and Sink:**

1. PSF-93 - Precision of software timers(PDTIMER) is erroneous to a max of 0.5ms time difference – Precision is fixed by timer providing value of Time value or +0.5ms.

**2.5.3 Features added**

New Demo USB PD Sink functionality is added with following supports

- Mode A (High Wattage with high voltage)
- Mode B (High wattage with low voltage)
- Goto\_Min support
- VCONN swap support

3THIS DOCUMENT IS UNCONTROLLED UNLESS OTHERWISE STAMPED. It is the user's responsibility to ensure this is the latest revision prior to using or referencing this document.	Page	Spec. No.	Rev.
© Microchip Technology Inc. <b>CONFIDENTIAL AND PROPRIETARY</b>	17 of 22	FRM-50381-001	1.06

- DAC and GPIO current indicators.

Sink demo project can be found under Demo folder in the name PSF\_EVB\_Sink.

## 2.5.4 Notes

The release is only for Sink application. For Source and Source Pro application use the V1.01 version of PSF.

## 2.6 Version 1.01

Release date	19-Mar-2020
Release Type	PSF Phase 2 Alpha release
Pre-requisites (if any)	<b>PSF EVB Rev A</b>
Source Tag	<b>Tag: PSF_STACK_V1.01</b>

### 2.6.1 Not implemented / Limited functionality requirements

1. PSF-44: TDA 2.3.1.1 Source Dynamic Load Test, Provider or Provider/Consumer Test Fails when PUT is configured as Source.
2. PSF-85: Ellisys Compliance fails with MPQ4230 I2C DC/DC Converter when INCLUDE\_POWER\_MANAGEMENT\_CTRL = 1
3. PSF-86: VBUS drop observed during Voltage transitions when the sink load is higher
4. PSF-89: No activity seen on Port 2 when MPQ I2C DC/DC controller is used with PSF
5. PSF-90: Continuous PD re-negotiation when number of source PDOs is 7
6. PSF-91: Build failure when INCLUDE\_UPD\_PIO\_OVERRIDE\_SUPPORT is set to 0
7. PSF-88: u16PortIntMask and u16PortStatusChange of Status registers need to be implemented.

### 2.6.2 Bug Fixes

1. PSF-70: "Data" Configurable Parameter cannot be Configured to Other Options mentioned in the System DOS – Bits 8:6 of u32CfgData in PORT\_CFG\_STATUS structure holds the option to configure USB Data parameters.
2. PSF-71: PSF feedback for porting to 16-bit MCU – Suggested type casts are taken care and a new Hook function is introduced for enable/disable of DC\_DC\_EN.
3. PSF-82: tVCONNSourceOn timer value exceeds the Max Limit given in USB PD Specification – VCONN On and Off timer values are updated as per the PD Specification.

4. PSF-87: Handle Unexpected message when Sink capabilities message is received in wrong PE State – Unexpected message handling is fixed by sending soft reset in case sink caps message is received in wrong PE state.

### 2.6.3 Features added

- Boot time Configuration parameters and Run time Status registers
- Support for MPQ4230 I2C DC/DC controller
- Power Balancing

### 2.6.4 Notes

- Only 2 Port Source and Sink solution has been tested at 8MHz SPI clock speed.
- System level PD communication between PSF and UPD350 through I2C interface is untested.
- For Source Pro application, Ellisys compliance has been tested only in Port 1 with INCLUDE\_POWER\_MANAGEMENT\_CTRL = 0 and INCLUDE\_POWER\_BALANCING = 0 whereas for Source Lite application, 2 port Ellisys compliance has been tested.

## 2.7 Version 1.00

Release date	26-Feb-2020
Release Type	PD Source only feature complete release
Pre-requisites (if any)	PSF EVB Rev A
Source Tag	Tag: PSF_STACK_V1.00

### 2.7.1 Not implemented / Limited functionality requirements

1. PSF-44: TDA 2.3.1.1 Source Dynamic Load Test, Provider or Provider/Consumer Test Fails when PUT is configured as Source

### 2.7.2 Bug Fixes

1. PSF-21: VBUS OCS Power fault handling not working – Max Power Fault Count check is included for implicit contract also.
2. PSF-26: Build Fails When INCLUDE\_POWER\_FAULT\_HANDLING Macro is set to 0 – Fixed the error thrown by the compiler.
3. PSF-43: TD.PD.SRC.E16 PDO Transition Test fails inconsistently in Port 1 Alone when Configured as Source – There was a difference in actual voltage threshold values and those calculated by FW due to the improper float to int conversions handled in FW. This is fixed.
4. PSF-45: TDA 2.3.2.1 PDO Transition Test - Source, Provider or Provider/Consumer Test Fails on both Ports – The fix is same as that of PSF-43

### 2.7.3 Features added

NA

3THIS DOCUMENT IS UNCONTROLLED UNLESS OTHERWISE STAMPED. It is the user's responsibility to ensure this is the latest revision prior to using or referencing this document.	Page	Spec. No.	Rev.
© Microchip Technology Inc. <b>CONFIDENTIAL AND PROPRIETARY</b>	19 of 22	FRM-50381-001	1.06

## 2.7.4 Notes

- This is PD Source only feature complete release with bug fixes reported in v0.95
- Only 2 Port Source and Sink solution has been tested at 8MHz SPI clock speed.
- System level PD communication between PSF and UPD350 through I2C interface is untested, whereas basic I2C read/writes are tested.

## 2.8 Version 0.95

Release date	09-Jan-2020
Release Type	Beta Release
Pre-requisites (if any)	<b>PSF EVB Rev A</b>
Source Tag	<b>Tag: PSF_STACK_V0.95</b>

### 2.8.1 Not implemented / Limited functionality requirements

1. PSF-44: TDA 2.3.1.1 Source Dynamic Load Test, Provider or Provider/Consumer Test Fails when PUT is configured as Source
2. PSF-41: SPT.5 Over Current QuadraMAX Test Fails on Both Ports

### 2.8.2 Bug Fixes

1. PSF-21: VBUS OCS Power fault handling not working – DC\_DC\_EN was toggled twice to reset the fault occurred. Since DC\_DC was set and reset immediately, DC-DC controller did not have enough time to reset itself. PIO Override drive was not reset after a Fault. Both the issues are fixed.
2. PSF-7: HiByte has potential error – Fixed the warning generated by PC Lint
3. PSF-65: PD Source tests in Ellisys compliance fails when MchpPSF\_Run() is called for every 3ms – This issue is fixed by setting PE\_PDCONNECTED\_STS\_MASK in ePE\_SRC\_NEGOTIATE\_CAPABILITY state.
4. PSF-61: Unable to charge HP-Laptop - Possible Bug with VCONN SWAP response (Reject/Not Supported) - For source only operation, INCLUDE\_VCONN\_SWAP\_SUPPORT should be defined as '1'. Same is updated in the PSF\_Config.h file description.
5. PSF-69: When INCLUDE\_UPD\_PIO\_OVERRIDE\_SUPPORT defined as 0, negotiation is not happening - Undervoltage was detected by FW without considering whether under voltage power fault detection was enabled; Which caused undervoltage detection and follow up power shutdown. It is fixed now.

### 2.8.3 Features added

NA

## 2.8.4 Notes

- Only 2 Port Source and Sink solution has been tested at 8MHz SPI clock speed.
- System level PD communication between PSF and UPD350 through I2C interface is untested, whereas basic I2C read/writes are tested.

## 2.9 Version 0.92

Release date	12-Dec-2019
Release Type	Documentation Release
Pre-requisites (if any)	<b>PSF EVB Rev A</b>
Source Tag	<b>Tag: PSF_STACK_V0.92</b>

### 2.9.1 Not implemented / Limited functionality requirements

Firmware Bug fixes are not made for this release. All the bugs observed with V0.91 release is applicable for V0.92 release too.

### 2.9.2 Bug Fixes

No Bug fixes made

### 2.9.3 Features added

This release is made to mark the release of following documents

- PSF User Guide
- Getting Started with PSF
- Demo Read me

### 2.9.4 Notes

None.

## 2.10 Version 0.91

Release date	11-Nov-19
Release Type	Bug fix release
Pre-requisites (if any)	<b>PSF EVB Rev A</b>
Source Tag	<b>Tag: PSF_STACK_V0.91</b>

### 2.10.1 Not implemented / Limited functionality requirements

1. PSF-7 - HiByte has potential error

### 2.10.2 Bug Fixes

1. PSF-19 -FW has build issue when CONFIG\_PD\_PORT\_COUNT set to 1
2. PSF-21 - VBUS OCS Power fault handling not working
3. PSF-26 - Build Fails When INCLUDE\_POWER\_FAULT\_HANDLING Macro is set to 0
4. PSF-31 - Build Fails When INCLUDE\_PDFU Macro is set to 1
5. PSF-32 - Configuring CONFIG\_PORT\_n\_SINK\_USB\_COM macro Field is not Effective

6. PSF-33 - Configuring CONFIG\_PORT\_n\_SINK\_UNCONSTRAINED\_PWR macro Field is not Effective
7. PSF-34 - Build Fails When INCLUDE\_PD\_3\_0 Macro is set to 0

### 2.10.3 Features added

NA

### 2.10.4 Notes

Following JIRA reported marked invalid after developing from developer's side:

1. PSF-22 - VCONN OCS handling not working
2. PSF 23 - PD Negotiation Fails when PDOs are Configured more than 5 with certain values
3. PSF-25 - The PUT is not Disabled Even After the Under Voltage Count Exceeds the Maximum Fault Count

## 2.11 Version 0.90

Release date	24-Oct-2019
Release Type	Initial Web release
Pre-requisites (if any)	<b>PSF EVB Rev A</b>
Source Tag	<b>Tag: PSF_STACK_V0.91</b>

### 2.11.1 Not implemented / Limited functionality requirements

1. PSF-7 - HiByte has potential error
2. PSF-21 - VBUS Power fault handling not working
3. PSF-22 - VCONN OCS handling not working
4. PSF-23 - PD Negotiation Fails when PDOs are Configured more than 5 with certain values
5. PSF-25 - The PUT is not Disabled Even After the Under Voltage Count Exceeds the Maximum Fault Count

### 2.11.2 Bug Fixes

Not Applicable

### 2.11.3 Features added

Initial revision of PSF for Source only operation.

### 2.11.4 Notes

Not Applicable