

# Drawing instruction



**Sayma Sultana**

**Lecturer**

**Dept. of CSE**



**Dhaka International University, Dhaka**

# MECHANICAL ENGINEERING



CORRECT

(a)




POOR PRACTICE

(b)


**Fig. 11.32 Locating Holes.**

# MECHANICAL ENGINEERING




**Fig. 11.13 Dimensions and Section Lines.**

# MECHANICAL ENGINEERING



PREFERRED  
(a)





POOR PRACTICE  
(b)

**Fig. 11.14 Staggered Numerals.**

# MECHANICAL ENGINEERING

**Arrows** – 3 mm wide and should be 1/3rd as wide as they are long - symbols placed at the end of dimension lines to show the limits of the dimension. Arrows are uniform in size and style, regardless of the size of the drawing.





Thank You