


Pre Plane Assembly Summary

Pre Plane Assembly Summary										Panel Pre- Assy gas leak test
Panel No	Plane No	Cleaned/ Prepped	Blocked straws	Missing wires	Missing wires confirmed	PFN & std. off epoxy	Ear install	Ear leak test	Prep Finished	
MN221	26	✓	none	5, 44		✓	grey ✓ clear ✓	✓ ✓		✓
Repairs	Straw 44 cut out due to double patch, flooded both sides PFN cleared, #4 at 2.5 turns									LT post Straw cut out and PFN repair ✓
HV issues	wire g2 high current 31 FeSS test - (✓) hv test - (✓) gain test - (✓) pass a.c. test.									
Notes	Air tested for blocked straws - ✓ DMB gap test w/ 5 mil kapton air - ✓ backside PFN check - #4 at 2 turns ear flooding - ✓ Patched straws: 16, 44, 68, 69 (44 patched twice), 44 removed.									

MN221 cal side connector
drilled 3/19/25



x = drilled

• = not drilled