

| Panel No | Plane No | Cleaned/ Prepped | Air test | Blocked straws | Missing wires | Missing wires confirmed | PFN ^{prev. done} epoxy | DMB Id | ear install | |
|--------------|---|---------------------|----------|-------------------|---------------|----------------------------|------------------------------------|---|----------------|----------------|
| MN073 | 4 | ✓ | ✓ | ○ | | | Stand-offs ✓ | | ear install | ✓ |
| Repairs | ear flooded. can't clean 21 because it is slanted out of reach, can't clean 38 RHS due to epoxy cleaned 8, 9, 26, 33, 38, 61 | | | | | | | | pass | leak test ✓ |
| HV issues | Brass ring (20) + Omega reattached 20/21 + 8/9 • HV test 8 • gas test 8 • FESS test 8 wire 8, 9, 21, 26, 33, 38, 61 high current no pan & test | | | | | | | After 1st repaired • wires high currents: 21, 26, 33, 61 • pass ac test | | |
| Notes | Lots of Apiezon on orings & even on cover screws & recesses of cover holes. what a mess!! • Re epoxied stand off threads • Omega missing 20/21 Rt side, 8/9 Left side | | | | | | | brass ring missing 20 rt side brass ring & w-pieces reattached ✓ | | |