

Pre Plane Assembly Summary

Panel No	Plane No	Cleaned/ Prepped	Blocked straws	Missing wires	Missing wires confirmed	PFN & std. off epoxy	Ear install	Ear leak test	Prep Finished
MN2606	31	✓	none			✓	grey ✓ clean ✓	✓	
Repairs	drilled straw #15 Straw pos 32, hole 31cm. Patch 2cm @ 30cm from left, < 0.1g epoxy 12/13/23								
HV issues	<div style="display: flex;"> <ul style="list-style-type: none"> - Ear card problem → check again → OK - Ω piece ch 4 HV side missing off RT HVAC - blocked straw at cathode channel 7 - Fe55 test - Ⓢ pass A test but need to repair blocked straw, - HU test - Ⓢ earcard and Ω piece missing - gain test - Ⓢ <div style="flex-grow: 1; border-left: 1px solid black; padding-left: 10px;"> <p>After drilling, wire 15% cover.</p> <p>pass a test</p> <hr/> <p>earcard test again 11/02/2023 OK</p> </div> </div>								
Notes	<ul style="list-style-type: none"> - Air test for blocked straws ✓ - DMBS gap test w/ 5mil Kapton + air ✓ - Backside pfn check - ✓ - ear flooding - ✓ - patched straws - #73 - Lots of metal shavings near Rt DMBS conn. + along outer ring crease - cleared of - Backside Center 5mm hole has epoxy in it - needs to be removed? NO 								