

# Wind Energy Conversion Systems

## Assignment 2

Muhammad Shamaas

ID # 2018-MS-EE-4

### Introduction

This case study investigates the Induction machine modeling in Complex Vector. The first example analyzes the free acceleration of a singly excited, 6 pole, 3 phase, 220V (line-to-line), 10hp, 60 Hz induction machine. The machine is at standstill state with no load torque applied. Nominal voltage will be applied at its stator. The machine will accelerate to reach a nominal speed. This process of acceleration is call “free acceleration”. The second example illustrates the consequence of DFIG stator voltage drop in rotor currents.

The dq0-axis model of the induction generator can be obtained by decomposing the voltage, current and flux linkage space-vectors into their corresponding d-, q- and 0-axis components. This is known as Park’s Transformation.

$$\begin{bmatrix} x_d \\ x_q \\ x_0 \end{bmatrix} = \frac{2}{3} \begin{bmatrix} \cos\theta & \cos\left(\theta - \frac{2\pi}{3}\right) & \cos\left(\theta - \frac{4\pi}{3}\right) \\ -\sin\theta & -\sin\left(\theta - \frac{2\pi}{3}\right) & -\sin\left(\theta - \frac{4\pi}{3}\right) \\ \frac{1}{2} & \frac{1}{2} & \frac{1}{2} \end{bmatrix} \begin{bmatrix} x_a \\ x_b \\ x_c \end{bmatrix}$$

The  $\alpha\beta\gamma$  stationary reference frame is derived from dq0-axis rotating reference frame by putting  $\theta = 0$  and  $\frac{d\theta}{dt} = \omega = 0$ . The transformation of three-phase variables in the stationary reference frame into the two-phase variables also in the stationary frame is often referred to as abc/ $\alpha\beta\gamma$  transformation:

$$\begin{bmatrix} x_\alpha \\ x_\beta \\ x_\gamma \end{bmatrix} = \frac{2}{3} \begin{bmatrix} 1 & \frac{-1}{2} & \frac{-1}{2} \\ 0 & \frac{\sqrt{3}}{2} & \frac{-\sqrt{3}}{2} \\ \frac{1}{2} & \frac{1}{2} & \frac{1}{2} \end{bmatrix} \begin{bmatrix} x_a \\ x_b \\ x_c \end{bmatrix}$$

Similarly, the two-phase to three-phase transformation in the stationary reference frame, known as  $\alpha\beta\gamma$ /abc transformation, can be performed by:

$$\begin{bmatrix} x_a \\ x_b \\ x_c \end{bmatrix} = \begin{bmatrix} 1 & 0 & \sqrt{\frac{1}{2}} \\ \frac{-1}{2} & \frac{\sqrt{3}}{2} & \sqrt{\frac{1}{2}} \\ \frac{-1}{2} & \frac{-\sqrt{3}}{2} & \sqrt{\frac{1}{2}} \end{bmatrix} \begin{bmatrix} x_\alpha \\ x_\beta \\ x_\gamma \end{bmatrix}$$

### Example 1: Free Acceleration

A simulation complex vector-based model was built in Matlab/Simulink to demonstrate the dynamics of free acceleration of an induction machine. A complex vector was treated as two real variables with the q-axis is leading the d-axis by 90°. A complex vector can be expressed as:

$$\mathbf{f} = f_q - jf_d$$

Since zero-sequence currents do not introduce magnetic field, the zero-sequence circuits of stator and rotor are decoupled. All variables are in per unit.

#### Induction Machine dq0-axis Reference Frame Model Equations

##### 1. Voltage Equations:

$$\begin{bmatrix} v_{qs} \\ v_{ds} \\ v_{0s} \\ v_{qr} \\ v_{dr} \\ v_{0r} \end{bmatrix} = \begin{bmatrix} R_s + \frac{p}{\omega_b} X_s & \frac{\omega_s}{\omega_b} X_s & 0 & \frac{p}{\omega_b} X_m & \frac{\omega_s}{\omega_b} X_s & 0 \\ -\frac{\omega_s}{\omega_b} X_s & R_s + \frac{p}{\omega_b} X_s & 0 & -\frac{\omega_s}{\omega_b} X_m & \frac{p}{\omega_b} X_m & 0 \\ 0 & 0 & R_s + \frac{p}{\omega_b} X_{ls} & 0 & 0 & 0 \\ \frac{p}{\omega_b} X_m & \frac{\omega_s - \omega_r}{\omega_b} X_m & 0 & R_r + \frac{p}{\omega_b} X_r & \frac{\omega_s - \omega_r}{\omega_b} X_r & 0 \\ -\frac{\omega_s - \omega_r}{\omega_b} X_m & \frac{p}{\omega_b} X_m & 0 & -\frac{\omega_s - \omega_r}{\omega_b} X_r & R_r + \frac{p}{\omega_b} X_r & 0 \\ 0 & 0 & 0 & 0 & 0 & R_r + \frac{p}{\omega_b} X_{lr} \end{bmatrix} \begin{bmatrix} i_{qs} \\ i_{ds} \\ i_{0s} \\ i_{qr} \\ i_{dr} \\ i_{0r} \end{bmatrix}$$

##### 2. Current Equations

$$\begin{bmatrix} pi_{qs} \\ pi_{ds} \\ pi_{0s} \\ pi_{qr} \\ pi_{dr} \\ pi_{0r} \end{bmatrix} = B \begin{bmatrix} v_{qs} \\ v_{ds} \\ v_{0s} \\ v_{qr} \\ v_{dr} \\ v_{0r} \end{bmatrix} + A \begin{bmatrix} i_{qs} \\ i_{ds} \\ i_{0s} \\ i_{qr} \\ i_{dr} \\ i_{0r} \end{bmatrix}$$

where

$$B = \begin{bmatrix} \frac{1}{\omega_b} X_s & 0 & 0 & \frac{1}{\omega_b} X_m & 0 & 0 \\ 0 & \frac{1}{\omega_b} X_s & 0 & 0 & \frac{1}{\omega_b} X_m & 0 \\ 0 & 0 & \frac{1}{\omega_b} X_{ls} & 0 & 0 & 0 \\ \frac{1}{\omega_b} X_m & 0 & 0 & \frac{1}{\omega_b} X_r & 0 & 0 \\ 0 & \frac{1}{\omega_b} X_m & 0 & 0 & \frac{1}{\omega_b} X_r & 0 \\ 0 & 0 & 0 & 0 & 0 & \frac{1}{\omega_b} X_{lr} \end{bmatrix}^{-1}$$

$$A = -B \begin{bmatrix} R_s & \frac{\omega_s}{\omega_b} X_s & 0 & 0 & \frac{\omega_s}{\omega_b} X_s & 0 \\ -\frac{\omega_s}{\omega_b} X_s & R_s & 0 & -\frac{\omega_s}{\omega_b} X_m & 0 & 0 \\ 0 & 0 & R_s & 0 & 0 & 0 \\ 0 & \frac{\omega_s - \omega_r}{\omega_b} X_m & 0 & R_r & \frac{\omega_s - \omega_r}{\omega_b} X_r & 0 \\ -\frac{\omega_s - \omega_r}{\omega_b} X_m & 0 & 0 & -\frac{\omega_s - \omega_r}{\omega_b} X_r & R_r & 0 \\ 0 & 0 & 0 & 0 & 0 & R_r \end{bmatrix}$$


$$A = -B \left( \begin{bmatrix} R_s & \frac{\omega_s}{\omega_b} X_s & 0 & 0 & \frac{\omega_s}{\omega_b} X_s & 0 \\ -\frac{\omega_s}{\omega_b} X_s & R_s & 0 & -\frac{\omega_s}{\omega_b} X_m & 0 & 0 \\ 0 & 0 & R_s & 0 & 0 & 0 \\ 0 & \frac{\omega_s}{\omega_b} X_m & 0 & R_r & \frac{\omega_s}{\omega_b} X_r & 0 \\ -\frac{\omega_s}{\omega_b} X_m & 0 & 0 & -\frac{\omega_s}{\omega_b} X_r & R_r & 0 \\ 0 & 0 & 0 & 0 & 0 & R_r \end{bmatrix} + \begin{bmatrix} 0 & 0 & 0 & 0 & 0 & 0 \\ 0 & 0 & 0 & 0 & 0 & 0 \\ 0 & 0 & 0 & 0 & 0 & 0 \\ 0 & \frac{\omega_r}{\omega_b} X_m & 0 & 0 & 0 & \frac{\omega_r}{\omega_b} X_r \\ -\frac{\omega_r}{\omega_b} X_m & 0 & 0 & -\frac{\omega_r}{\omega_b} X_r & 0 & 0 \\ 0 & 0 & 0 & 0 & 0 & 0 \end{bmatrix} \right)$$

### 3. Motion and Torque Equations

$$\frac{\omega_r}{\omega_b} = \frac{1}{2HS} (T_e - T_m)$$

$$T_e = X_m (i_{qs} i_{dr} - i_{ds} i_{qr})$$

### 4. Arbitrary Reference Frame d-, q- and 0-axis circuits for 3-phase Induction Machine



## SCIG Machine Constants

1. Rated Line-Line Voltage

$$V_{rated,LL} = 220 \text{ V}(rms)$$

2. Number of Poles

$$P = 6$$

3. Rated Stator Frequency

$$f_e = 60 \text{ Hz}$$

4. Stator Winding Resistance

$$R_s = 0.0453 \text{ p.u.}$$

5. Rotor Winding Resistance

$$R_r = 0.0222 \text{ p.u.}$$

6. Stator Leakage Reactance

$$X_{ls} = 0.0775 \text{ p.u.}$$

7. Rotor Leakage Reactance

$$X_{lr} = 0.0322 \text{ p.u.}$$

8. Magnetizing Reactance

$$X_m = 2.042 \text{ p.u.}$$

$$X_s = X_{ls} + X_m = 0.0775 + 2.042 \text{ mH} = 2.1195 \text{ p.u.}$$

$$X_r = X_{lr} + X_m = 0.0322 + 2.042 = 2.0742 \text{ p.u.}$$

9. Inertia Constant

$$H = 0.5 \text{ s}$$

10. Base Speed

$$\omega_b = 2\pi f_e = 376.9911184307752 \text{ rad/s}$$

11. Synchronous Speed

$$\omega_s = \frac{2}{P} 2\pi f_e = 125.6637061435917 \text{ rad/s}$$

### Initial Conditions (t = 0-)

In this case, the IG model in the synchronous reference frame should be used, which was realized by setting the speed of the arbitrary reference frame to zero ( $\omega = \omega_s$ ). The dq-axis rotor voltages are set to zero for simulation of squirrel-cage induction generators.

1. The reference frame is rotating at synchronous speed

$$\omega = \omega_s$$

2. Electrical Frequency

$$f_e = 60 \text{ Hz}$$

3. Rotor Speed

$$\omega_r = 0 \text{ rad/s}$$

4. Stator Voltages

$$v_{ds} = 0 \text{ p.u.}$$

$$v_{qs} = 1 \text{ p.u.}$$

5. Rotor voltages are zero

$$v_{dr} = v_{qr} = 0 \text{ p.u.}$$

6. Stator and Rotor Currents

$$i_{dr} = i_{qr} = i_{ds} = i_{qs} = 0 \text{ p.u.}$$

7. Electromagnetic Torque is zero

$$T_e = X_m (i_{qs} i_{dr} - i_{ds} i_{qr}) = 0$$

8. The rotor is not loaded


$$T_m = 0$$

$$\frac{d\omega_r}{dt} = 0$$


## Simulink Model

The input variables of the model include the dq-axis stator voltages  $v_{ds}$  and  $v_{qs}$ , rotor voltages  $v_{dr}$  and  $v_{qr}$ , the mechanical torque  $T_m$ . The output variables are dq-axis stator currents,  $i_{ds}$  and  $i_{qs}$ , dq-axis rotor currents,  $i_{dr}$  and  $i_{qr}$ , the electromagnetic torque  $T_e$ , and the rotor speed  $\omega_r$  of the generator.

1. Block diagram for dynamic simulation of SCIG in free acceleration.



2. Block diagram for dynamic simulation of an induction generator in the synchronous reference frame



### 3. WECSConstants.m


```

WECSConstants.m
1 - Xls=0.0775;
2 - Xm=2.042;
3 - Xs=Xls+Xm;
4 - Xlr=0.0322;
5 - Xr=Xlr+Xm;
6 - Rs=0.0453;
7 - Rr=0.0222;
8 - P=6;
9 - f=60;
10 - wb=2*pi*f;
11 - ws=(12*pi*f)/P;
12 - H=0.5;
13 - B=inv([
14     (Xs/wb) 0 0 (Xm/wb) 0 0;
15     0 (Xs/wb) 0 0 (Xm/wb) 0;
16     0 0 (Xls/wb) 0 0 0;
17     (Xm/wb) 0 0 (Xr/wb) 0 0;
18     0 (Xm/wb) 0 0 (Xr/wb) 0;
19     0 0 0 0 0 (Xlr/wb)
20 ]);
21
22 - Z=[
23     Rs ((ws/wb)*Xs) 0 0 ((ws/wb)*Xm) 0;
24     -((ws/wb)*Xs) Rs 0 -((ws/wb)*Xm) 0 0;
25     0 0 Rs 0 0 0;
26     0 ((ws/wb)*Xm) 0 Rr ((ws/wb)*Xr) 0;
27     -((ws/wb)*Xm) 0 0 -((ws/wb)*Xr) Rr 0;
28     0 0 0 0 0 Rr
29 ];


```

## Results

### 1. Currents ( $i_{qs}$ , $i_{ds}$ , $i_{qr}$ , $i_{dr}$ )




### 2. Electromagnetic Torque





### 3. Rotor Speed ( $\omega_r/\omega_b$ )



During the system transients, a high inrush current flows into the induction generator. As a rotating magnetic field is being built and generator core is being magnetized by the stator current, an electromagnetic torque  $T_e$  is produced. Since the generator operates below synchronous speed in motoring mode, it produces a positive torque that accelerates the turbine. The generator finally reaches the synchronous speed of 376.99 rpm (1 pu) at  $t = 0.6$  sec, at which it enters the steady-state operation with  $T_e = T_m = 0$ . The direct connection of the generator to the grid during the system start-up causes excessive inrush currents with peak values of 7.6 per unit (pu), high electromagnetic torque (3.75 pu, peak), as well as high torque oscillations.

## Example 2: DFIG Stator Voltage Drop to zero

### SCIG Machine Constants

1. Rated Line-Line Voltage

$$V_{rated,LL} = 380 \text{ V}(rms)$$

2. Number of Poles

$$P = 4$$

3. Rated Stator Frequency

$$f_e = 50 \text{ Hz}$$

4. Stator Winding Resistance

$$R_s = 1.2$$

5. Stator Leakage Inductance

$$L_{ls} = 0.0022 \text{ H}$$

6. Magnetizing Inductance

$$L_m = 0.127 \text{ H}$$

### Initial Conditions (t = 0-)

In this case, the IG model in the synchronous reference frame should be used, which was realized by setting the speed of the arbitrary reference frame to zero ( $\omega = \omega_s$ ).

1. The reference frame is rotating at synchronous speed

$$\omega = \omega_s$$

2. Electrical Frequency

$$f_e = 50 \text{ Hz}$$

3. Rotor Speed

$$\omega_r = 0 \text{ rad/s}$$

4. Stator Voltages

$$v_{ds} = 1 \text{ p.u.}$$

$$v_{qs} = 1 \text{ p.u.}$$

5. Rotor voltages are zero

$$v_{dr} = v_{qr} = 1 \text{ p.u.}$$

6. Stator and Rotor Currents

$$i_{dr} = i_{qr} = i_{dr} = i_{qr} = 0 \text{ p.u.}$$

7. Electromagnetic Torque is zero

$$T_e = X_m (i_{qs} i_{dr} - i_{ds} i_{qr}) = 0$$


8. The rotor is loaded

$$T_m = 1$$

## Simulink Model

The input variables of the model include the dq-axis stator voltages  $v_{ds}$  and  $v_{qs}$ , rotor voltages  $v_{dr}$  and  $v_{qr}$ , the mechanical torque  $T_m$ . The output variables are dq-axis stator currents,  $i_{ds}$  and  $i_{qs}$ , dq-axis rotor currents,  $i_{dr}$  and  $i_{qr}$ , the electromagnetic torque  $T_e$ , and the rotor speed  $w_r$  of the generator.

### 1. Block diagram for dynamic simulation of SCIG for stator voltage drop.




### 2. WECSConstants.m


```
WECSConstants.m
1 - Xls=0.0022*2*pi*50;
2 - Xm=0.127*2*pi*50;
3 - Xs=Xls+Xm;
4 - Xlr=0.0022*2*pi*50;
5 - Xr=Xlr+Xm;
6 - Rs=1.2;
7 - Rr=1.2;
8 - P=4;
9 - f=50;
10 - wb=2*pi*f;
11 - ws=pi*f;
12 - H=1;
13 - B=inv([
14     (Xs/wb) 0 0 (Xm/wb) 0 0;
15     0 (Xs/wb) 0 0 (Xm/wb) 0;
16     0 0 (Xls/wb) 0 0 0;
17     (Xm/wb) 0 0 (Xr/wb) 0 0;
18     0 (Xm/wb) 0 0 (Xr/wb) 0;
19     0 0 0 0 0 (Xlr/wb)
20 ]);
21
22 - Z=[
23     Rs ((ws/wb)*Xs) 0 0 ((ws/wb)*Xm) 0;
24     -((ws/wb)*Xs) Rs 0 -((ws/wb)*Xm) 0 0;
25     0 0 Rs 0 0 0;
26     0 ((ws/wb)*Xm) 0 Rr ((ws/wb)*Xr) 0;
27     -((ws/wb)*Xm) 0 0 -((ws/wb)*Xr) Rr 0;
28     0 0 0 0 0 Rr
29 ];
```

## Results


### 1. Stator Voltages (vas, vbs, vcs)



### 2. Stator Currents (ias, ibs, ics)



### 3. Rotor Currents



The Stator voltage drop of the generator causes decay in stator currents. It however, causes excessive rotor currents and voltages.