

SSP v1.5.2

Additional Usage Note

Renesas Synergy™ Platform
Synergy Software
Synergy Software Package

All information contained in these materials, including products and product specifications, represents information on the product at the time of publication and is subject to change by Renesas Electronics Corp. without notice. Please review the latest information published by Renesas Electronics Corp. through various means, including the Renesas Electronics Corp. website (<http://www.renesas.com>).

Notice

1. Descriptions of circuits, software and other related information in this document are provided only to illustrate the operation of semiconductor products and application examples. You are fully responsible for the incorporation or any other use of the circuits, software, and information in the design of your product or system. Renesas Electronics disclaims any and all liability for any losses and damages incurred by you or third parties arising from the use of these circuits, software, or information.
2. Renesas Electronics hereby expressly disclaims any warranties against and liability for infringement or any other claims involving patents, copyrights, or other intellectual property rights of third parties, by or arising from the use of Renesas Electronics products or technical information described in this document, including but not limited to, the product data, drawings, charts, programs, algorithms, and application examples.
3. No license, express, implied or otherwise, is granted hereby under any patents, copyrights or other intellectual property rights of Renesas Electronics or others.
4. You shall not alter, modify, copy, or reverse engineer any Renesas Electronics product, whether in whole or in part. Renesas Electronics disclaims any and all liability for any losses or damages incurred by you or third parties arising from such alteration, modification, copying or reverse engineering.
5. Renesas Electronics products are classified according to the following two quality grades: "Standard" and "High Quality". The intended applications for each Renesas Electronics product depends on the product's quality grade, as indicated below.

"Standard": Computers; office equipment; communications equipment; test and measurement equipment; audio and visual equipment; home electronic appliances; machine tools; personal electronic equipment; industrial robots; etc.

"High Quality": Transportation equipment (automobiles, trains, ships, etc.); traffic control (traffic lights); large-scale communication equipment; key financial terminal systems; safety control equipment; etc.

Unless expressly designated as a high reliability product or a product for harsh environments in a Renesas Electronics data sheet or other Renesas Electronics document, Renesas Electronics products are not intended or authorized for use in products or systems that may pose a direct threat to human life or bodily injury (artificial life support devices or systems; surgical implantations; etc.), or may cause serious property damage (space system; undersea repeaters; nuclear power control systems; aircraft control systems; key plant systems; military equipment; etc.). Renesas Electronics disclaims any and all liability for any damages or losses incurred by you or any third parties arising from the use of any Renesas Electronics product that is inconsistent with any Renesas Electronics data sheet, user's manual or other Renesas Electronics document.

6. When using Renesas Electronics products, refer to the latest product information (data sheets, user's manuals, application notes, "General Notes for Handling and Using Semiconductor Devices" in the reliability handbook, etc.), and ensure that usage conditions are within the ranges specified by Renesas Electronics with respect to maximum ratings, operating power supply voltage range, heat dissipation characteristics, installation, etc. Renesas Electronics disclaims any and all liability for any malfunctions, failure or accident arising out of the use of Renesas Electronics products outside of such specified ranges.
7. Although Renesas Electronics endeavors to improve the quality and reliability of Renesas Electronics products, semiconductor products have specific characteristics, such as the occurrence of failure at a certain rate and malfunctions under certain use conditions. Unless designated as a high reliability product or a product for harsh environments in a Renesas Electronics data sheet or other Renesas Electronics document, Renesas Electronics products are not subject to radiation resistance design. You are responsible for implementing safety measures to guard against the possibility of bodily injury, injury or damage caused by fire, and/or danger to the public in the event of a failure or malfunction of Renesas Electronics products, such as safety design for hardware and software, including but not limited to redundancy, fire control and malfunction prevention, appropriate treatment for aging degradation or any other appropriate measures. Because the evaluation of microcomputer software alone is very difficult and impractical, you are responsible for evaluating the safety of the final products or systems manufactured by you.
8. Please contact a Renesas Electronics sales office for details as to environmental matters such as the environmental compatibility of each Renesas Electronics product. You are responsible for carefully and sufficiently investigating applicable laws and regulations that regulate the inclusion or use of controlled substances, including without limitation, the EU RoHS Directive, and using Renesas Electronics products in compliance with all these applicable laws and regulations. Renesas Electronics disclaims any and all liability for damages or losses occurring as a result of your noncompliance with applicable laws and regulations.
9. Renesas Electronics products and technologies shall not be used for or incorporated into any products or systems whose manufacture, use, or sale is prohibited under any applicable domestic or foreign laws or regulations. You shall comply with any applicable export control laws and regulations promulgated and administered by the governments of any countries asserting jurisdiction over the parties or transactions.
10. It is the responsibility of the buyer or distributor of Renesas Electronics products, or any other party who distributes, disposes of, or otherwise sells or transfers the product to a third party, to notify such third party in advance of the contents and conditions set forth in this document.
11. This document shall not be reprinted, reproduced or duplicated in any form, in whole or in part, without prior written consent of Renesas Electronics.
12. Please contact a Renesas Electronics sales office if you have any questions regarding the information contained in this document or Renesas Electronics products.

(Note 1) "Renesas Electronics" as used in this document means Renesas Electronics Corporation and also includes its directly or indirectly controlled subsidiaries.

(Note 2) "Renesas Electronics product(s)" means any product developed or manufactured by or for Renesas Electronics.

(Rev.4.0-1 November 2017)

1. Introduction

This document describes additional usage notes for **Synergy Software Package (SSP) version 1.5.2**.

2. Release Information

SSP Release Version	v1.5.2
Release Date	Nov 16, 2018

The intended audience for this release is Renesas Synergy™ customers, prospective customers, partners, and support staff. This document lists additional information on SSP v1.5.2 usage. See the SSP v1.5.2 Release Note for enhancements, bug fixes, and known issues that were identified since the last release for SSP v1.5.1.

3. SSP v1.5.2 Additional Usage Note

3.1 BSP for SSP Supported Platforms

Issue ID: 2625

Unaligned access across the memory map boundary 0x20000000 (between SRAMHS and SRAM0) results in a data read/write failure due to the Synergy hardware restriction. However, user applications might cause an unaligned access across the boundary, since linker script files for S7 or S5 MCU parts define the single 'RAM' section across SRAMHS and SRAM0. For details on this hardware restriction, see the *Arm® Cortex®-M4 Technical Reference Manual*, section 3.4.3

http://infocenter.arm.com/help/topic/com.arm.doc.100166_0001_00_en/arm_cortexm4_processor_trm_100166_0001_00_en.pdf.

Applies to: S7 and S5 MCU Series

Workaround: Users need to modify their linker script manually to ensure that objects do not cross the memory map boundary, 0x20000000.

Issue ID: 10664

If a user is using the trace buffer for debugging and has data stored in RAM at addresses above 0x20004000, that data will be overwritten by the trace buffer when debugging.

Applies to: S128 and S1JA MCU Groups

Workaround: The S128 linker script currently allocates 1K for the Trace buffer at 0x20000000. This allocation could be removed, freeing up the 1K mistakenly reserved for the Trace Buffer. Using e² studio, Trace Buffer function will store 1K of the trace buffer data beginning at 0x20004000. Therefore, 1K of RAM must not be used by the application if the Trace Buffer is to be used for debugging.

3.2 Crypto/r_sce

Issue ID: 11147

Only data input lengths that are multiples of the AES block size are supported for AES encryption/decryption APIs for XTS chaining mode.

Applies to: S7, S5, and S3 MCU Series

Workaround: None

3.3 MCU Implementation/ SW Architecture

Issue ID: 6399

If control structures are not all zeros, then, function calls to other than the open() function may incorrectly determine that the module has already been opened. If this occurs, then the module may cause undefined behavior, since it has not been properly initialized. Statically allocated control structures will be zeroed-out as part of the C runtime initialization by the BSP. An example of when a control structure should be explicitly zeroed-out is if it was allocated off the stack.

Applies to: All MCUs

Workaround:

- Follow SSP rules and ensure that the open() function is always called before the other APIs.
- Ensure that control structures are all zeros before first use.

Issue ID: 10864

The pin configuration tab in the configurator cannot be used to configure the opamp or analog comparators for every use case.

Applies to: S7G2, S5D9, S5D5, S5D3, S3A7, S3A3, S128, and S124 MCU Groups

Workaround: Configure the pins manually in the user-defined code.

3.4 nxd_tls_secure

Issue ID: 10694

NetX Crypto Hardware Accelerator Error occurs for GCC-O3 during TLS handshake process. For GCC-O2, there is no such issue.

Applies to: S7 and S5 MCU Series

Workaround: Use GCC-O2

3.5 r_ctsu

Issue ID: 6927

R_CTSU_Update_Parameters() returns error. Not all return codes are described in the function header. Some return codes are as follows:

- SSP_ERR_NOT_OPEN when mode is set to CTSU_MODE_UNCONFIGURED
- SSP_ERR_IN_USE, when the Measurement Status Counter is set to non-zero value, or the CTSU Data Transfer Status flag is set
- SSP_ERR_CTSU_RC_OVERFLOW, when CTSUROVF flag is set
- SSP_ERR_CTSU_SC_OVERFLOW, when CTSUSOVF flag is set
- SSP_ERR_CTSU_ICOMP, when TSCAP Voltage Error Monitor flag is set.

Applies to: All MCUs

Workaround: In cases where the returned error code is not described in the function header, see the return code description in the ssp_common_api.h file.

Issue ID: 6928

If the customer calls R_CTSU_Read while the driver is in an uninitialized state, then the documented return code is SSP_SUCCESS, but the actual return code is SSP_ERR_NOT_OPEN. When calling R_CTSU_Read while the driver is uninitialized, the application should expect a return code of SSP_ERR_NOT_OPEN.

The R_CTSU_Read() function is not sufficiently tested with the CTSU_READ_FILTERED_REF_ICO_VALUES_SEL and CTSU_READ_FILTERED_REF_ICO_VALUES_ALL options.

Applies to: All MCUs

Workaround: None

Issue ID: 6929

Auto-calibration, auto-scan, and auto-drift compensation features are not available in the r_ctsu driver.

Applies to: All MCUs

Workaround: None

Issue ID: 6931

Parameter checking for NULL parameters is not implemented. Passing in a NULL parameter to the r_ctsu API will result in undefined system operation.

Applies to: S7G2, S5D5, S3A7, S128, and S124 MCU Groups

Workaround: When using this driver, make sure that the control structure passed to the r_ctsu API is not NULL.

3.6 r_flash_lp, r_flash_hp

Issue ID: 10820

The Flash API for both Flash LP and Flash HP currently disables the Flash cache for the duration that the Flash module is open. This reduces ROM performance during that period. The Flash cache only needs to be disabled during Code Flash operations, not Data Flash operations, and only for the duration of the Code Flash operation.

Applies to: S7, S5, and S3 MCU Series for both Flash LP and Flash HP.

Workaround: The cache can be manually enabled or disabled by calling the R_BSP_CacheSet() and R_BSP_CacheOff() functions respectively.

3.7 r_lpmv2

Issue ID: 9223

When entering Software Standby mode, while the PLL clock is being used as the clock source, there is a risk that some through-current flows in the PLL circuit.

Applies to: S5 MCU Series

Workaround:

This workaround is for user application.

Prior to entering Software Standby mode:

- Select a clock other than the PLL clock as clock source (MOCO is recommended. It is OK to use HOCO if you are already using it.)
- Stop the PLL clock.
- Wait at least 83 µs.
- Request that the MCU enter Software Standby mode.

After returning from Software Standby mode:

- Start the PLL clock.
- Select the PLL clock as clock source.

3.8 r_qspi

Issue ID: 9809

QSPI operations should be performed with valid address range. Invalid address operations will not result in warning or error.

Applies to: All MCUs

Workaround: Check for the valid address range before calling QSPI APIs.

3.9 r_sci_i2c

Issue ID: 9601

Applications with SCI_I2C module that have high performance requirement communication.

Applies to: All MCUs

Workaround: None

3.10 sf_audio_playback_hw_dac

Issue ID: 9308

sf_audio_playback is not tested with the DMAC module as a transfer driver.

Applies to: All boards except S1JA, S124, and S128 boards

Workaround: sf_audio_playback module can use DTC module as a transfer driver, instead of DMAC.

3.11 sf_cellular

Issue ID: 9475

Applications using the cellular framework will not be able to upgrade module firmware over the air (FOTA) since FOTA is not supported by the cellular framework.

Applies to: Cellular framework CAT3 and CAT1 implementation on all Synergy MCUs

Workaround: None

3.12 sf_el_fx

Issue ID: 12753

The warning "control reaches end of non-void function" will be seen if code is configured to reach fx_fault_tolerant_transaction_fail().

Applies to: S7, S5, and S3 MCU Series

Workaround: None

3.13 sf_el_gx

Issue ID: 12704

The GUIX Studio crashes while opening an incorrectly configured project file (.gxp). There should not be any configurations for unsupported formats in the GUIX Studio project.

Applies to: GUIX Studio project files

Workaround: None

3.14 sf_el_nx

Issue ID: 7513

The current sf_el_nx (NetX Port driver) is hard-coded to use the RMMI interface (a Micrel Ethernet PHY chip mounted on Renesas kits which does not support other PHY chips or MMI interfaces). The customer defines an Ethernet PHY chip driver when using a different PHY chip than the one mounted on Renesas kits, or when using a PHY chip with a MII interface.

Workaround: There is no plan to provide support for additional Ethernet PHY chip drivers included in SSP; users are required to create their own PHY chip driver.

To create a PHY chip driver, users can use the sf_el_nx module under `/ssp/src/framework/sf_el_nx/` as a template and modify it for the target Ethernet PHY chip. Source files under sf_el_nx are in plain text; you can copy the file to other directories, such as `/src/` directory, and exclude the original sf_el_nx module from being built to avoid 'multiple definition' compile-error.

The following steps give high-level guidance:

1. Copy the directory `/ssp/src/framework/sf_el_nx/` including all the files under the directory to `/src/`.
2. Exclude original SF_EL_NX module in SSP from your build. Right click on the directory `/ssp/src/framework/sf_el_nx/` and select 'Exclude from build...'. Then click the 'Select All' button.
3. Modify `/src/sf_el_nx/nx_hw_init.c`. Modify `nx_synergy_ethernet_init()` as indicated below, and select the MII interface. Change `IOPORT_ETHERNET_MODE_RMII` to `IOPORT_ETHERNET_MODE_MII`.
`g_ioport_on_ioport.pinEthernetModeCfg(IOPORT_ETHERNET_CHANNEL_n,
IOPORT_ETHERNET_MODE_RMII);`
4. Modify `/src/sf_el_nx/phy/ether_phy.c` and `ether_phy.h`. Modify these files to match to your Ethernet PHY chip.
5. Be sure to select MII pins under the 'Pins' tab in the Synergy Configurator. Check the pin configuration setting; **Peripherals > Connectivity:ETHERC**.

Notes:

- Source files under `/ssp/src/framework/sf_el_nx/` are overwritten by the tool when building a project. Be sure to copy the files before editing.
- To exclude files from building, right-click on the files and select '**Exclude from build**' (as is the case for e² studio).

3.15 sf_el_ux

Issue ID: 7687

USBX HID Host API to get mouse events, or keyboard events may not work and may return 'no data,' even though the actual HID reports were received from a HID device. The issue happens if the application does not allocate adequate memory for USBX.

Applies to: All MCUs

Workaround: Specify enough memory size for USBX. (Set the value to “USBX Pool Memory Size” in the Properties of “USBX on ux” component). The following examples show the USBX Pool Memory Size setting (minimum). The values are obtained through measurements on a Synergy target board.

HID Mouse:

- 35 KB if USBX Host Class HID Pre-built library is used.
- 28 KB if USBX Host Class HID Source module is used.

HID Keyboard:

- 43 KB if USBX Host Class HID Pre-built library is used.
- 33 KB if USBX Host Class HID Source module is used.

The following fixed configurations are used for USBX Host Class HID Pre-built library:

- `UX_HOST_CLASS_HID_DECOMPRESSION_BUFFER`: 4096 (in bytes, default value).
- `UX_HOST_CLASS_HID_USAGE`: 1024 (in WORDs, default value).

The following configurations are used for USBX Host Class HID Source module:

- `UX_HOST_CLASS_HID_DECOMPRESSION_BUFFER`: 128 (in bytes).
- `UX_HOST_CLASS_HID_USAGE`: 256 (in WORDs).

Issue ID: 8574

The current `SF_EL_UX` HCD driver does not enable the Double Buffer feature for Bulk OUT PIPEs, which is supported by the USB hardware. Therefore, USB data throughput for Data Write through a Bulk OUT PIPE will be less than the value for Double Buffer-Enabled. This issue is only for Data Write (Bulk OUT). Double buffering is supported for Data Read (Bulk IN).

Applies to: S7, S5, and S3 MCU Groups

Workaround: None

3.16 sf_touch_ctsu

Issue ID: 6858

When channel is set to NULL, the `SF_TOUCH_CTSU_Read()` returns `SSP_ERR_INTERNAL`. Return values from the ThreadX API calls are not checked in the framework, which can lead to functional issues in the framework when ThreadX APIs return errors. The framework may not work as expected in such error cases, since errors are not handled. With valid callback and context if `callback_index` is set to `SF_TOUCH_CTSU_CFG_MAX_WIDGET_TYPES (= 3)`, `SF_TOUCH_CTSU_Open()` returns `SSP_ERR_OUT_OF_MEMORY`.

Applies to: All MCUs

Workaround: None

Issue ID: 6859

`SF_TOUCH_CTSU_Read()` returns the error value `SSP_ERR_INTERNAL` if the semaphore **get** or **put** are not successful.

Applies to: All MCUs

Workaround: None

3.17 sf_touch_ctsu_button

Issue ID: 6882

1. Valid range for button_count is 0 to less than SF_TOUCH_CTSU_BUTTON_CFG_USER_SUPPORTED_BUTTONS (= 12).
2. For button_count values outside the range, SF_TOUCH_CTSU_Button_Open() returns error SSP_ERR_ASSERTION.

Applies to: All MCUs

Workaround: None

Issue ID: 6883

For button_count values outside the range, SF_TOUCH_CTSU_Button_Open() returns the error SSP_ERR_ASSERTION, and buttons outside the range cannot be operated.

Applies to: All MCUs

Workaround: The button_count values must be set to value 0 to less than SF_TOUCH_CTSU_BUTTON_CFG_USER_SUPPORTED_BUTTONS (= 12).

Issue ID: 12742

The GT202 module supported by the WiFi Framework is affected by the WPA2 KRACK issue.

Applies to: GT202 module supported by the WiFi Framework

Workaround: None

3.18 SSP XMLs for ISDE

Issue ID: 10695

The configurator does not warn about the limitation on the RSPI bit rate if the bit rate is less than or equal to 30 MHz.

Applies to: All MCUs

Workaround: The RSPI bit rate must be a positive integer that is less than or equal to 30 MHz or PCLK/2, whichever is the smaller value.

3.19 Synergy Software Configurator

Issue ID: 7665

When using the Synergy Software Configurator in e² studio/SSC, if you rename a thread on the Threads tab and generate code, a new thread_entry.c file is created with template content, and the old thread_entry.c file remains in the project. If you have edited the thread_entry.c file, your changes are not moved to the new file. It will not be called; it causes a build error if the old thread_entry.c file is not removed from the project manually.

Applies to: All MCUs

Workaround: Manually move any edits (if made) from the old thread_entry.c file to the new thread_entry.c file, then manually delete the old thread_entry.c file from your project.

3.20 Synergy Tools

Issue ID: 12863

Support for ID byte programming for S5D3 and S5D5 devices is not available in SEGGER J-Link DLL version 6.32.

Applies to: S5D5 and S5D3 MCU Groups

Workaround: None

3.21 USBX

Issue ID: 6389

Public header files for USBX Device RNDIS Class and USBX Network Driver are not stored in SSP public header file directory for X-wares \synergy\ssp\inc\framework\el, so the user application would not build with such USBX components.

Applies to: All MCUs

Workaround: Add `ux_device_class_rndis_src` or `ux_network_driver_src` module to your project through the Synergy Configurator **Components** tab. Use populated header files and move them to path `\synergy\ssp\inc\framework\el\`, or add the file include paths to the e² studio project property settings (**Cross Arm C Compiler - Includes - Include paths**) to make them compile.

Note: The USBX Device RNDIS Class and USBX Network Driver are experimental modules. These modules are not yet tested and may not work.

Issue ID: 8505

Users need to set the 'requested_length' of the USBX Device CDC API `ux_device_class_cdc_acm_read` large enough compared to the expected reception data length. If length of the reception data from a USB Host is larger than 'requested_length', the API returns `UX_SUCCESS` but reception data will not be stored in a user buffer and 'actual_length' is set to '0'.

Applies to: All MCUs

Workaround: Set 'requested_length' of the USBX Device CDC API `ux_device_class_cdc_acm_read` large enough compared to the expected reception data length.

Issue ID: 10027

USBX Device Class HID does not support Interrupt-Out endpoint. The use of Interrupt-Out endpoint is optional in the USB HID specification. It would not often be the case in embedded applications, but Synergy customers may require the feature for their production.

Applies to: All MCUs

Workaround: Ask Synergy customer support for a custom HID class example that enables Interrupt-In and Interrupt-Out endpoints.

Issue ID: 13036

In the user guide from Express Logic, the return error code 0x91 is not defined for `ux_host_class_video_transfer_buffer_add()`, and the example code sequence for the UVC application is incorrect.

Applies to: None

Workaround: None

4. Additional Technical Notes

- Subscribe to the Synergy Technical Bulletin Board to receive the latest technical news and notifications about new features, known issues, workarounds, and release announcements. To subscribe, visit http://renesasrulz.com/synergy/synergy_tech_notes/f/214.aspx. Sign in to Renesas Rulz, and press **Email Subscribe to this forum**.
- Additional technical information, including informative papers and articles on SSP and Synergy can be found at Synergy Knowledge Base, www.renesassynergy.com/knowledgebase

Website and Support

Visit the following vanity URLs to learn about key elements of the Synergy Platform, download components and related documentation, and get support.

Synergy Software	renesas-synergy.com/software
Synergy Software Package	renesas-synergy.com/ssp
Software add-ons	renesas-synergy.com/addons
Software glossary	renesas-synergy.com/softwareglossary
Development tools	renesas-synergy.com/tools
Synergy Hardware	renesas-synergy.com/hardware
Microcontrollers	renesas-synergy.com/mcus
MCU glossary	renesas-synergy.com/mcuglossary
Parametric search	renesas-synergy.com/parametric
Kits	renesas-synergy.com/kits
Synergy Solutions Gallery	renesas-synergy.com/solutionsgallery
Partner projects	renesas-synergy.com/partnerprojects
Application projects	renesas-synergy.com/applicationprojects
Self-service support resources:	
Documentation	renesas-synergy.com/docs
Knowledgebase	renesas-synergy.com/knowledgebase
Forums	renesas-synergy.com/forum
Training	renesas-synergy.com/training
Videos	renesas-synergy.com/videos
Chat and web ticket	renesas-synergy.com/support

Revision History

Rev.	Date	Description	
		Page	Summary
1.00	Nov 16, 2018	-	Initial release

All trademarks and registered trademarks are the property of their respective owners.

SSP v1.5.2 Additional Usage Note

Publication Date: Rev.1.00 Nov 16, 2018

Published by: Renesas Electronics Corporation



SALES OFFICES

Renesas Electronics Corporation

<http://www.renesas.com>

Refer to "<http://www.renesas.com/>" for the latest and detailed information.

Renesas Electronics Corporation

TOYOSU FORESIA, 3-2-24 Toyosu, Koto-ku, Tokyo 135-0061, Japan

Renesas Electronics America Inc.

1001 Murphy Ranch Road, Milpitas, CA 95035, U.S.A.

Tel: +1-408-432-8888, Fax: +1-408-434-5351

Renesas Electronics Canada Limited

9251 Yonge Street, Suite 8309 Richmond Hill, Ontario Canada L4C 9T3

Tel: +1-905-237-2004

Renesas Electronics Europe Limited

Dukes Meadow, Millboard Road, Bourne End, Buckinghamshire, SL8 5FH, U.K

Tel: +44-1628-651-700

Renesas Electronics Europe GmbH

Arcadiastrasse 10, 40472 Düsseldorf, Germany

Tel: +49-211-6503-0, Fax: +49-211-6503-1327

Renesas Electronics (China) Co., Ltd.

Room 1709 Quantum Plaza, No.27 ZhichunLu, Haidian District, Beijing, 100191 P. R. China

Tel: +86-10-8235-1155, Fax: +86-10-8235-7679

Renesas Electronics (Shanghai) Co., Ltd.

Unit 301, Tower A, Central Towers, 555 Langao Road, Putuo District, Shanghai, 200333 P. R. China

Tel: +86-21-2226-0888, Fax: +86-21-2226-0999

Renesas Electronics Hong Kong Limited

Unit 1601-1611, 16/F., Tower 2, Grand Century Place, 193 Prince Edward Road West, Mongkok, Kowloon, Hong Kong

Tel: +852-2265-6688, Fax: +852 2886-9022

Renesas Electronics Taiwan Co., Ltd.

13F, No. 363, Fu Shing North Road, Taipei 10543, Taiwan

Tel: +886-2-8175-9600, Fax: +886 2-8175-9670

Renesas Electronics Singapore Pte. Ltd.

80 Bendemeer Road, Unit #06-02 Hyflux Innovation Centre, Singapore 339949

Tel: +65-6213-0200, Fax: +65-6213-0300

Renesas Electronics Malaysia Sdn.Bhd.

Unit 1207, Block B, Menara Amcorp, Amcorp Trade Centre, No. 18, Jln Persiaran Barat, 46050 Petaling Jaya, Selangor Darul Ehsan, Malaysia

Tel: +60-3-7955-9390, Fax: +60-3-7955-9510

Renesas Electronics India Pvt. Ltd.

No.777C, 100 Feet Road, HAL 2nd Stage, Indiranagar, Bangalore 560 038, India

Tel: +91-80-67208700, Fax: +91-80-67208777

Renesas Electronics Korea Co., Ltd.

17F, KAMCO Yangjae Tower, 262, Gangnam-daero, Gangnam-gu, Seoul, 06265 Korea

Tel: +82-2-558-3737, Fax: +82-2-558-5338

Renesas Synergy™ Platform SSP v1.5.2 Additional Usage Note