

UNIT-III


AC MACHINES

Construction of Transformers: -


static machine.

Magnetically coupled

Electrically isolated



Principle Electro



classification:

construction

windings

phase

1. Core

1. step Up

1. 1 ϕ

2. Shell

2. step down

2. 3 ϕ

3. Berry

Principle: Faraday's laws of electromagnetic induction,
mutual induction b/w 2 coils:

Working principle of transformer:

The basic principle behind working of transformer is mutual induction b/w two windings linked by common magnetic flux. Basically

a transformer consists of two inductive coils


primary & secondary these are electrically separated but magnetically coupled when

primary winding is connected to source of alternating voltage (AC), Alternating magnetic flux is produced around the winding.

The core provides magnetic path for the flux to get link with the secondary winding. Most of the flux gets linked with secondary is called useful flux or main flux. & the flux which doesnot link with secondary winding is called leakage flux. The flux which is produced is alternating in nature.

Emf gets induced in the secondary winding according to faraday's laws of electro magnetic inductⁿ. This emf is called mutually induced Emf & this frequency is same as supply emf. If the secondary winding is closed then mutually induced current flows through it & hence electrical energy is transferred from 1 circuit (primary) to another circuit (secondary)

Emf eqⁿ of a transformer:



According to faraday's laws of electromagnetic induction:

$$\boxed{E = N \frac{d\phi}{dt}}$$

$N = \text{no of turns}$

$$N = 1$$

$$E = \frac{d\phi}{dt}$$

change in flux

$$d\phi = \phi_m - 0$$

$$dt = \frac{1}{4f}$$

$$E = \frac{\phi_m}{\frac{1}{4f}}$$

$$E = 4f\phi_m$$

$$\text{form factor} = \frac{\text{Rms value}}{\text{avg value}}$$

$$\text{form factor} = 1.11 (\sin)$$

$$E = 4f\phi_m \times 1.1$$

$$= 4.4f\phi_m$$

E_{mf} induced in primary winding

$$\boxed{E_1 = 4.44f\phi_m N_1}$$

E_{mf} induced in secondary winding

$$\boxed{E_2 = 4.44f\phi_m N_2}$$

turns ratio

$$k = \frac{N_2}{N_1} = \frac{E_2}{E_1} = \frac{V_2}{V_1} = \frac{I_1}{I_2}$$

- 8) A 40 kVA single phase ideal transformer has 400 turns on primary & 100 turns on secondary the primary is connected to 2000V, 50 Hz (i) supply determine secondary voltage on \uparrow open circuit.
(ii) current flowing through 2 windings on full load.
(iii) max value of ϕ .

$$P = 40 \text{ kVA}:$$

$$N_1 = 400.$$

$$N_2 = 100.$$

$$E_1 = 2000 \text{ V}.$$

$$f = 50 \text{ Hz}.$$

$$\frac{V_2}{40 \times 2000} = 4,$$

$$V_2 = 8000.$$

$$\frac{V_2}{2000} = \frac{1}{4}$$

$$V_2 = 500 \text{ V}.$$

$$V_2 = ?$$

$$I_1 = ?, I_2 = ?$$

$$\phi = ?$$

max.

$$\frac{V_2}{V_1} = \frac{N_2}{N_1}$$

$$P = 40 \text{ kVA}$$

$$N_1 = 400$$

$$N_2 = 100$$

$$E_1 = 2000 \text{ V}, f = 50 \text{ Hz}$$

$$E_2 = V_2 = ? \quad I_1 = ? \quad I_2 = ? \quad \phi_m = ?$$

$$\frac{E_2}{E_1} = \frac{N_2}{N_1}$$

$$P_1 = V_1 \times I_1$$

$$40 \times 10^3 = (2000) I_1$$

$$I_1 = \frac{40 \times 10^3}{2000}$$

$$I_1 = 20 \text{ A}$$

$$40 \times 10^3 = (500) I_2$$

$$I_2 = \frac{40 \times 10^3}{500}$$

$$I_2 = 80 \text{ A}$$

$$E_1 = 4.44 f \phi_m N_1$$

$$2000 = 4.44 \phi_m (400) (50)$$

$$\phi_m = 0.022$$

8) the number of load ratio required to a single phase 50 Hz transformer is $\frac{6600}{600}$ 6600/600V if the max value of ϕ in core is to be about 0.08 Wb find no of turns in each winding.
 $f = 50 \text{ Hz}$.

$$\frac{V_2}{V_1} = \frac{6600}{600}$$

$$\phi_m = 0.08$$

$$N = ?$$

$$E = 4.4 f \phi_m$$

$$= 4.4 \times 50 \times 0.08$$

$$E = 17.6$$

$$E_2 = 6600$$

$$E_1 = 4.4 f \phi_m N_1$$

$$E_1 = 600$$

$$\frac{600}{4.4 \times 50 \times 0.08} = N_1$$

$$6600 = 4.4 f \phi_m N_2$$

$$\frac{6600}{4.4 \times 50 \times 0.08} = N_2$$

$$\frac{600}{17.76} = 33.78$$

$$\frac{6600}{17.76} \Rightarrow 371.62$$

$$= 371.62$$

losses in transformer:

$$1) \text{ Cu } \begin{cases} \text{primary} \rightarrow I_1^2 R_1 \\ \text{secondary} \rightarrow I_2^2 R_2 \end{cases}$$

$$2) \text{ Iron loss } \begin{cases} \text{hysteresis} \rightarrow w_h = \eta_h B_m^{1.6} f_v \\ \text{Eddy current losses} \rightarrow w_e = \eta_e B_m^2 f^2 \end{cases}$$

$f_v \Rightarrow$ volume of core

$t \Rightarrow$ thickness of transformer.

Efficiency (η): ratio of output power & input power

$$\eta = \frac{P_o}{P_i} \text{ is called } \eta.$$

$$P_o = P_i$$

$$P_i = P_o + \text{losses}$$

$$\text{losses} = w_{cu} + w_{\text{iron losses (P)}}$$

$$\% = \frac{P_o}{P_o + \text{losses}} \times 100$$

Q) A single phase transformer is connected to a 230V, 50Hz supply the net cross sectional area of the core is 60 cm^2 the no of turns

efficiency in primary is 100% in secondary is 100 determine transformation ratio.

2) Max value of flux density in the core

3) Emf induced in secondary winding.

$$f = 50 \text{ Hz}$$

$$V_1 \Rightarrow E_1 = 230 \text{ V} \quad \Phi_m = B_m A$$

$$A = 60 \text{ cm}^2 \quad B_m = ?$$

$$N_1 = 500$$

$$N_2 = 100$$

$$\frac{N_2}{N_1} = \frac{100}{500} = 0.2$$

~~$$\Phi_m = B_m A$$~~

$$k = \frac{E_2}{E_1}$$

$$E_2 = ?$$

$$5) 230 \left(\frac{46}{3} \right)$$

$$\frac{E_2}{E_1} = \frac{N_2}{N_1}$$

$$E_2 = \frac{100}{500} \times 230 \times \frac{46}{3}$$

$$\frac{23}{1332.5}$$

$$\Phi_m = B_m A$$

$$E_1 = 4.44 f \Phi_m N_1$$

$$E_1 = 4.44 f B_m A N_1$$

$$B_m = \frac{230}{4.44 \times 50 \times 60 \times 10^{-4} \times 500}$$

$$B_m = 0.345 \text{ wb/m}^2 \text{ (or) Tesla.}$$

$$E_2 = 4.44 f \Phi_m N_2 = 459.5 \text{ V.}$$

$$\Phi_m = B_m A = 2.07 \text{ mwb}$$

Q) A 500 kVA transformer is desired to have a 4.13 mwb maximum core flux in a transformer at 110V & 50 Hz determine the required no of turns in primary $N_1 = ?$

$$P = 500 \times 10^3$$

$$\Phi_m = 4.13 \times 10^{-3}$$

$$V_1 = E_1 = 110 \text{ V} \quad f = 50 \text{ Hz.}$$

$$E_2 = 4.44 f \Phi_m N_2$$

$$110 = 4.44 \times 4.13 \times 10^{-3} \times 50 \times N_2$$

$$110 = 916.86 \times 10^{-3}$$

$$110 = 0.916 N_1$$

$$N_1 = 120.08$$

$$\frac{6400}{10.5}$$

$$320 \times 1362.5$$

Q) A 400 KVA transformer has a primary winding resistance of 0.5Ω & a secondary winding resistance of 0.001Ω & the iron loss is 2.5 kW & primary & secondary voltages are 5 kV & 320 V respectively if the power factor of the load is 0.85 determine the efficiency of transformer on full load & half full load.

$$E_1 = 5 \times 10^3 \text{ V } P = 400 \text{ KVA.}$$

$$E_2 = 320 \text{ V.}$$

$$r_1 = 0.5 \Omega$$

$$r_2 = 0.001 \Omega$$

$$\cos \phi = 0.85$$

$$\eta_{FL} = ?$$

$$\eta_{H.FL} = ?$$

$$\boxed{\text{Power factor} = \cos \phi}$$

$$W_p = 2.5 \text{ kW} = 2.5 \times 10^3$$

$$\eta = \frac{P_o}{P_o + \text{losses}}$$

$$P_o = \text{rating} \times \text{power factor}$$

$$P_o = 400 \times 10^3 \times 0.85$$

$$= 340 \text{ kW}$$

$$\text{losses} = W_{cu} + W_i$$

$$W_{cu} = I_1^2 R_1 + I_2^2 R_2$$

$$P = V_2 I_2$$

$$I_2 = \frac{400 \times 10^3}{320}$$

$$P = V_1 I_1$$

$$= 1250 \text{ A}$$

$$400 \times 10^3 = 80 \times 10^3 \times I_1$$

$$I_1 = 80 \text{ A}$$

$$W_{cu} = (80)^2 \times 0.5 \times (1250)^2 \times 0.001$$

$$= 4762.5 \text{ W}$$

$$\eta_{HFL} = \frac{\frac{1}{2} P_0}{\frac{1}{2} P_0 + \left(\frac{1}{2}\right)^2 w_{cu} + w_i}$$

$$\eta_{FL} = \frac{340 \times 10^3}{340 \times 10^3 + 4762.5 + 2.5 \times 10^3}$$

$$= \frac{340000}{340000 + 4762.5 + 2500} \times 100$$

$$= \frac{340000}{347262.5} \times 100$$

$$= 97.9$$

$$\eta_{HFL} = \frac{\frac{1}{2} P_0}{\frac{1}{2} P_0 + \frac{1}{4} w_{cu} + w_i}$$

$$\frac{12.5 \times 10^3}{12.5 \times 10^3 + 450} = \frac{125 \times 100}{12500 + 450} = 96.52$$

8) In a 25 kVA, 2000/200V power transformer, the Iron loss & full load copper loss are 350 & 400W respectively calculate the η at unity power factor at full load & HFL

$$P = 25 \text{ kVA}$$

$$\cos \phi = 1$$

$$\eta_{FL} = ?$$

$$\frac{V_2}{V_1} = \frac{2000}{200}$$

$$W_i = 350$$

$$W_{cu} = 400 \quad \eta_{HFL} = ?$$

$$P_0 = \text{rating} \times \text{power factor}$$

$$P_0 = 25 \times 10^3$$

$$\text{losses} = 350 + 400 = 750$$

$$\eta_{HFL} = \frac{P_0}{P_0 + \text{losses}} \times 100$$

$$\eta_{HFL} = \frac{25 \times 10^3}{25 \times 10^3 + 750} \times 100$$

$$\frac{25 \times 10^3 + \frac{1}{4}(750)}{25 \times 10^3 + 750} = \frac{25 \times 10^3}{25 \times 10^3 + 750} \times 100$$

$$= 12.5 \times 10^3$$

$$12.5 \times 10^3 + 187.5$$

$$= \frac{125 \times 10^4}{125000 + 187.5}$$

$$= \frac{25 \times 10^3}{25750}$$

$$\times = 97.087$$

Q) calculate the current drawn by the primary of transformer which steps down 200 to 20V to operate a device of resistance 20Ω assume η of transformer to be 80%.

$$V_1 = 200V$$

$$I_1 = ?$$

$$V_2 = 20V$$

$$R_2 = 20\Omega$$

$$\eta = 80\%$$

$$I_2$$

$$80\% = \frac{V_2 \times I_2}{V_1 \times I_1} \times 100$$

$$\frac{V_2}{R_2} = I_2$$

$$80 = \frac{200 \times I_2}{20 \times I_1} \times 100$$

$$I_2 = \frac{200}{20}$$

$$0.8 = \frac{2000}{20 I_1}$$

$$I_2 = 10$$

$$20 I_1 = \frac{20000}{8}$$

$$I_1 = \frac{20000}{8 \times 20}$$


$$= \frac{1000}{8}$$

$$I_1 = 125$$



Induction Motors:

It consists of two parts stator, rotor & has air gap in b/w them & due to current in R, Y, B a magnetic flux is generated & due to the interaction b/w these fluxes a rotating field is produced in the air gap

(i)



(i) Rotating Magnetic field:



$$\phi_1 = \phi_m \sin \omega t$$

$$\phi_2 = \phi_m \sin(\omega t - 120^\circ)$$

$$\phi_3 = \phi_m \sin(\omega t - 240^\circ)$$

a) at position 1; $\omega t = 0$

$$\phi_1 = \phi_m \sin(0) = 0$$

$$\phi_2 = \phi_m \sin(0 - 120^\circ)$$

$$= -\phi_m \sin 120^\circ$$

$$= -\phi_m \sin(90 + 30)$$

$$= -\phi_m \cos 30^\circ$$

$$\phi_2 = -\frac{\sqrt{3}}{2} \phi_m$$

$$\phi_3 = \phi_m \sin(0 - 240)$$

$$= -\phi_m \sin(180 + 60^\circ)$$

$$= +\phi_m \sin 60^\circ$$


$$\phi_3 = \phi_m \frac{\sqrt{3}}{2}$$

at position ②

$$\phi_1 = \frac{\sqrt{3}}{2} \phi_m$$

$$\phi_2 = -\frac{\sqrt{3}}{2} \phi_m$$

$$\phi_3 = 0$$



According to parallelogram law resultant phasor magnitude:

$$\text{flux } \phi_y = 2a \cos \frac{\alpha}{2}$$

$$= 2 \frac{\sqrt{3}}{2} \phi_m \cos \frac{60}{2}$$

($\alpha = 60^\circ \because \phi_2, \phi_3$
angle is 60°)

$$= 2 \frac{\sqrt{3}}{2} \phi_m \cos 30^\circ$$

$$= 2 \left(\frac{\sqrt{3}}{2} \times \frac{\sqrt{3}}{2} \right) \phi_m$$

$$= \frac{3}{2} \phi_m$$


$$\boxed{\phi_y = 1.5 \phi_m}$$

a) at position ②

$$\phi_1 = \frac{\sqrt{3}}{2} \phi_m$$

$$\phi_2 = -\frac{\sqrt{3}}{2} \phi_m$$


$$\phi_3 = 0$$



$$\phi_r = 2a \cos 30^\circ$$

$$= \left| \frac{\sqrt{3}}{2} \phi_m \right|$$

$$\boxed{\phi_r = 1.5 \phi_m}$$




3) $\text{rot} = 120^\circ$

$$\phi_1 = \frac{\sqrt{3}}{2} \phi_m$$

$$\phi_2 = 0$$

$$\phi_3 = -\frac{\sqrt{3}}{2} \phi_m$$



$$\phi_r = 2a \cos 30^\circ$$

$$= \left| \frac{\sqrt{3}}{2} \phi_m \right|$$


$$\boxed{\phi_r = 1.5 \phi_m}$$

at (A) position. $\omega t = 180^\circ$

$$\phi_1 = 0$$

$$\phi_2 = \frac{\sqrt{3}}{2} \phi_m$$

$$\phi_3 = -\frac{\sqrt{3}}{2} \phi_m$$



$$\phi_r = 2a \cos \frac{\alpha}{2}$$


$$\phi_r = 1.5 \phi_m$$

at position (B) $\omega t = 240^\circ$

$$\phi_1 = -\frac{\sqrt{3}}{2} \phi_m$$

$$\phi_2 = \frac{\sqrt{3}}{2} \phi_m$$

$$\phi_3 = 0$$



$$\phi_r = 2a \cos \frac{\alpha}{2}$$


$$\phi_r = 1.5 \phi_m$$

at position (C) $\omega t = 300^\circ$

$$\phi_1 = -\frac{\sqrt{3}}{2} \phi_m$$

$$\phi_2 = 0$$

$$\phi_3 = \frac{\sqrt{3}}{2} \phi_m$$




at position $\theta = 360^\circ$

$$\phi_1 = 0$$

$$\phi_2 = -\frac{\sqrt{3}}{2} \phi_m$$

$$\phi_3 = \frac{\sqrt{3}}{2} \phi_m$$




Whenever three phase (3 ϕ) input AC voltage given to the induction motor three phase currents starts flowing which produce magnetic flux &

Definition of rotating magnetic field (RMF):

The magnetic field due to three phase flux interaction the magnetic rotates in the air gap with a fixed speed & constant magnitude is known as rotating magnetic field!

Working principle of 3 ϕ induction motor: 3 ϕ



$$N_s = \frac{120f}{P}$$

rotating transformer

1 ϕ I.M \Rightarrow fan

Whenever a 3 ϕ ac (AC) voltage is applied to the induction motor due to 3 ϕ flux interaction an rotating magnetic field produced in the air gap which cuts the rotor conductors due to relative speed according to Faraday's laws of Electromagnetic induction. an EMF gets induced in the conductor due to this current starts flowing through rotor

winding which acts as current carrying conductor now. Whenever a current carrying conductor placed in the magnetic field it will experience a mechanical force. This twisting or turning movement of force is called Torque. Because of this torque the rotor starts in the direction of EMF. Rotor always tries to catch the synchronous speed but it can never catch the N_s (^{synchronous} speed) and will always run less than synchronous speed.

3 ϕ Induction motor:

Principle: B.H

Induction motor works on the principle of electromagnetic induction when three phase supply is given to stator winding. RMF is produced and the induction motor will rotate with synchronous speed (N_s). The induction motor is also called as rotating transformer.

$$N_s = \frac{120f}{P}$$

f = frequency


P = Poles.

Units of N_s is r.p.m

Construction of Induction motor:

- 1) Stator
- 2) Rotor {
 - squirrel cage rotor
 - or slip ring motor.

stator:



silicon
laminated
steel.


or delta

stator has laminated type of construction and made up of stampings and thickness of each stamping is 0.4 to 0.5mm. And these stampings are slotted to carry stator winding. Stator core carries a 3 phase winding connected either in star or delta. So, this winding is excited by 3 ϕ supply produces rotating magnetic field.

2) Rotor!

low torque appli

(i) squirrel cage rotor: low cost due to no use of resistance.
(to provide good mechanical strength)
↑




increasing low starting torque! we use it for

The rotor consisting of copper and aluminium bar conductor these are the rotor conductors
the copper bars are permanently

shorted at each end with the help of end rings. These end rings provide good mechanical strength.

~~2) (ii)~~ (ii) slip Ring rotor: To limit the starting current & are also used in lifts.



$$T \propto \frac{R_2}{X_2}$$

External resistance box


in case of High torque applications

High $\cos \phi$ due to the use of resistances & brushes.

The construction of rotor is similar to that of stator. Here the R, Y, B phases are brought outside & are connected to three slip rings with the help of brushes & then external resistances will be added in each phase to improve the starting Torque.

shorted at each end with the help of end rings. These end rings provide good mechanical strength.

(ii) slip Ring rotor: To limit the starting current & are also used in lifts.



External resistance box

in case of High torque applications High cost due to the use of resistances & brushes. The construction of rotor is similar to that of stator. Here the R, Y, B phases are brought outside & are connected to three slip rings with the help of brushes & then external resistances will be added in each phase to improve the starting Torque.

Under running condition the brushes will be removed & now 3 slip rings form closed path that is joined together to form a simple bar. Now, it will act similar to that of squirrel cage rotor (motor) to limit losses.

Slip (s):

$$s = \frac{N_s - N_r}{N_s}$$

N_s = synchronous speed.

N_r = rotor speed / (motor) actual speed.

$$N_s = \frac{120f}{P}$$

$$sN_s = N_s - N_r$$

$$N_r = N_s - sN_s$$

$$N_r = N_s(1-s)$$

$$\% s = \frac{N_s - N_r}{N_s} \times 100$$

It is defined as the ratio of difference b/w synchronous speed & motor speed to the synchronous speed.

And it is denoted by s .

Rotor frequency (f_r):

$$\text{Slip speed} = N_s - N_r$$

dividing with N_s on both sides.

$$\frac{\text{slip speed}}{N_s} = \frac{N_s - N_r}{N_s}$$

$$\frac{120f_r}{P} = s$$

$$\frac{120f}{P}$$

$$\boxed{f_r = sf}$$

f_r = rotor frequency.


f = supplied frequency.

s = slip.

Rotor EMF (E_{2r}):
 EMF induced $\propto N_s$ (synchronous speed)
 in rotor.

E_{2r} = rotor emf at running condⁿ.

$$I = \frac{V}{R} \Rightarrow \text{for DC circuits}$$



$$I = \frac{V}{Z} \Rightarrow \text{for AC}$$

$Z \Rightarrow$ Impedance.

$$= \frac{V}{R + jX}$$

$$= \frac{V}{\sqrt{R^2 + X^2}} \quad \sqrt{R^2 + X^2} \Rightarrow \text{magnitude}$$

$$E_2 \propto N_s$$

$$E_{2r} \propto N_s - N_r$$

$$\frac{E_{2r}}{E_2} \propto \frac{N_s - N_r}{N_s}$$

$$\frac{E_{2r}}{E_2} = s$$

$$\boxed{E_{2r} = sE_2}$$

→ Rotor resistance (R_2):

$$\boxed{R_{2r} = R_2}$$

→ Rotor reactance X_2 :

$$X_2 = \omega L \quad [\because \omega = 2\pi f]$$
$$= 2\pi f_r L$$

$$X_{2r} = 2\pi(f_s s) L \quad f_r = s f_s$$
$$= (2\pi f_s) \cdot s \cdot L$$

$$\boxed{X_{2r} = s \cdot X_2}$$

→ Rotor Impedance Z_2

$$Z_2 = \sqrt{R_2^2 + X_2^2}$$

$$Z_{2r} = \sqrt{R_{2r}^2 + (X_{2r})^2} \quad [\because R_{2r} = R_2]$$

$$\boxed{Z_{2r} = \sqrt{R_2^2 + (sX_2)^2}}$$

Z_{2r} = Impedance of rotor at running condition

R_2 = Resistance of rotor.

X_2 = rotor reactance

s = slip

Rotor current (I_{2r}):

$$I_2 = \frac{E_2}{Z_2}$$
$$= \frac{E_2}{\sqrt{R_2^2 + X_2^2}}$$

E_{2r} = Emf induced in rotor under running condition.


$$I_{2r} = \frac{E_{2r}}{Z_{2r}} = \frac{SE_2}{\sqrt{R_2^2 + (SX_2)^2}}$$

Rotor power factor:

$$\cos \phi_2 = \frac{R_2}{Z_2}$$
$$= \frac{R_2}{\sqrt{R_2^2 + X_2^2}}$$

$$\cos \phi_{2r} = \frac{R_{2r}}{Z_{2r}}$$

Impedance triangle.



$$OB^2 = OA^2 + AB^2$$

$$OB = \sqrt{OA^2 + AB^2}$$

$$\cos \phi_{2r} = \frac{R_2}{\sqrt{R_2^2 + (SX_2)^2}}$$

$$Z = \sqrt{R^2 + X^2}$$
$$\cos \phi = \frac{\text{adj}}{\text{Hypotenuse}}$$
$$= \frac{R}{\sqrt{R^2 + X^2}}$$

★★ Torque Equation of 3phase I.M:

$$T \propto \phi I$$

$$T \propto \phi_2 I_{2r} \cos \phi_{2r}$$

I_{2r} = rotor current at running condition.

$$T \propto E_2 \cdot \frac{E_{2Y}}{Z_{2Y}} \cdot \frac{B_{2Y}}{Z_{2Y}}$$

$$T \propto E_2 \cdot \frac{SE_2}{\sqrt{R_2^2 + (SX_2)^2}} \cdot \frac{R_2}{\sqrt{R_2^2 + (SX_2)^2}}$$

$$T \propto \frac{SE_2^2 R_2}{R_2^2 + (SX_2)^2}$$

$$T = \frac{k \cdot SE_2^2 R_2}{R_2^2 + (SX_2)^2}$$

$$k = \frac{3}{2\pi N_s}$$

$$T = \frac{3SE_2^2 R_2}{2\pi N_s (R_2^2 + (SX_2)^2)}$$

$$T = \frac{3}{2\pi N_s} \frac{SE_2^2 R_2}{R_2^2 + (SX_2)^2}$$

N_s = synchronous speed

E_2 = Emf induced in rotor

R_2 = rotor resistance.

X_2 = rotor reactance

s = slip

T = Torque

I_2 = current induced in rotor

$I_2 \rightarrow$ stand still.

$\cos\phi_2$ = Power factor of rotor.

X_{2r} = rotor reactance at running condition.

$\cos\phi_{2r}$ = Power factor of rotor at running condition.

Q) A 10 pole, 50 Hz, 3 ϕ I.M runs at 485 rpm what will be the rotor frequency of rotor current.

$$\begin{array}{r} 600 \\ - 485 \\ \hline 115 \end{array}$$

$$P = 10 \quad f = 50 \text{ Hz} \quad N_r = 485$$

$$f_r = sf$$

$$s = \frac{600 - 485}{600} = \frac{115}{600} = 0.191$$

$$N_s = \frac{120f}{P} = \frac{120(50)}{10} = 600 \text{ rpm}$$

$N_s = 600 \text{ rpm}$

$$s = 0.191$$

$$f_r = s \cdot f$$

$$= 0.191 \times 50$$

$$f_r = 9.55 \text{ Hz}$$

Q) A 3ϕ induction motor is wound for 4 poles & is supplied from 50Hz system calculate:

(i) N_s

(ii) speed of motor at 4% of slip.

(iii) Rotor current frequency when motor runs at 600 rpm.

$$P = 4, f = 50 \text{ Hz}$$

$$s = 0.04$$

$$N_r = N_s(1 - s)$$

(i)

$$N_s = \frac{120f}{P}$$

$$= \frac{120 \times 50}{4}$$

$$= 1500 \text{ rpm}$$

$$s = \frac{N_s - N_r}{N_s} \times 100$$

$$\begin{aligned}
 \text{(ii)} \quad N_r &= N_s(1-s) \\
 &= 1500(1-0.04) \\
 &= 1500(0.96) \\
 &= 1440 \text{ rpm}
 \end{aligned}$$

$$\begin{aligned}
 \text{(iii)} \quad f_r &= s \cdot f \\
 s &= \frac{N_s - N_r}{N_s} \\
 &= \frac{1500 - 600}{1500} \\
 &= \frac{700}{1500} = 0.6 \\
 f_r &= 0.6 \times 50 \\
 &= 30 \text{ Hz}
 \end{aligned}$$

Q) A 3Ø 6 pole 50Hz induction motor is running with a slip of 4% find

(i) N_s (ii) Motor speed (iii) slip speed
(iv) frequency of Induction motor

$$P = 6 \quad f = 50 \text{ Hz} \quad s = 0.04$$

$$\text{(i)} \quad N_s = \frac{120 \times 50}{6} = 1000 \text{ rpm}$$

$$\text{(ii)} \quad N_r = N_s(1-s) = 1000(0.96) = 960 \text{ rpm}$$

$$N_r = 960 \text{ Hz rpm}$$

$$\text{slip speed} = 1000 - 960$$

$$= 40.$$

$$f_r = s \cdot f_s$$

$$s = \frac{N_s - N_r}{N_s}$$

$$= \frac{1000 - 960}{960}$$

$$= \frac{40}{960}$$

$$= 0.041$$

$$= 0.04 \times 50$$

$$= 0.4 \times 5$$

$$= 2 \text{ Hz}$$

Q) A 6 pole 3 ϕ 50Hz induction motor is running at a full load with slip of 4% the rotor is star connected its resistance

$$p = 6 \quad f_s = 50 \text{ Hz} \quad s = 0.04 \quad \left. \begin{array}{l} \text{reactances are} \\ 0.25 \times 1.5 \Omega \end{array} \right\}$$

$$R_2 = 0.25 \quad X_2 = 1.5 \Omega \quad \text{the emf } E_2 = 100 \text{ V}$$

rotor is 100 V find $I_2 = ?$

$$I_{2Y} = \frac{S E_2}{\sqrt{R_2^2 + (S X_2)^2}}$$

$$NS = \frac{120f}{P}$$

$$= \frac{120 \times 50}{6} = 1000 \text{ Hz}$$

$$S = 0.04 \quad I_{2Y} = \frac{0.04 \times 100}{\sqrt{(0.2)^2 + (0.04 \times 1.5)^2}}$$

$$= \frac{4}{\sqrt{0.0625 + 3.6 \times 10^{-3}}}$$

$$= \frac{4}{\sqrt{0.06286}} = \frac{4}{\sqrt{0.25041}}$$

0.06

$$= 15.5 \text{ A}$$

Q) A 6 pole 3 ϕ 50 Hz induction motor is running at full load with a slip of 4%. rotor is star connected & its resistances & reactance are 0.45 Ω & 2.5 Ω

$f = 50 \text{ Hz}$ $s = 0.04$ $R_2 = 0.45$, $X_2 = 2.5$

the emf b/w slip rings is 120V. Determine rotor current & Power factor assuming the slip rings are short circuited.

$$E_2 = 120V$$

$$\cos \phi_{2r} = \frac{R_2}{\sqrt{R_2^2 + (S X_2)^2}}$$

$$= \frac{0.45}{\sqrt{(0.45)^2 + (0.04 \times 2.5)^2}}$$

$$= \frac{0.45}{\sqrt{0.2125}}$$


$$= \frac{0.45}{0.4609}$$

$$\cos \phi_{2r} = 0.976$$

$$I_{2r} = \frac{0.04 \times 120}{\sqrt{(0.45)^2 + (0.04 \times 2.5)^2}}$$

$$= \frac{4.8}{0.4609} = 10.41A$$

44. Torque-slip characteristics of 3 phase induction motor:



The performance curve drawn b/w torque against slip known as torque slip characteristics of an induction motor.

Torque expression:

$$T \propto \frac{s E_2^2 R_2}{(R_2)^2 + (s X_2)^2}$$

The relation b/w Torque and slip, the entire operating region b/w 0 & 1 is divided into two 1 is lower slip

region & higher slip region!

lower slip region!

$$N_s = N_r$$

$$s = 0$$

$$T = 0.$$

$$s = \frac{N_s - N_r}{N_s}$$

$$T \propto \frac{s E_2^2 R_2}{(R_2)^2 + (s X_2)^2}$$

$$R_2 \gg (s X_2)^2$$

$$T \propto \frac{s E_2^2 R_2}{R_2^2}$$

$$T \propto s$$

$$\text{as } T \uparrow \quad s \uparrow$$

Under the lower slip region Torque is directly proportional to slip. Hence, the curve is a straight line.

Higher slip region!

When the slip further rises beyond $s = s_m$ then the term R_2^2 is very smaller than

$$sX_2^2$$

$$T \propto \frac{SE_2^2 R_2}{R_2^2 + (sX_2)^2}$$

$$(sX_2)^2 \gg R_2^2$$

$$T \propto \frac{SE_2^2 R_2}{s^2 X_2^2}$$

$$\downarrow T \propto \frac{1}{s} \downarrow$$

Under the Higher slip region Torque is inversely proportional to slip. Hence, the curve is a rectangular hyperbola.

losses in 3 ϕ induction motor:

losses are classified into two types

- (i) constant losses
- (ii) variable losses.

(i) constant losses:

These are classified into two types

- (a) Iron losses
- (b) Mechanical losses

(a) Iron losses: The losses which occur in the core of stator & rotor. Iron losses

includes hysteresis & eddy current losses

Iron losses are also known as core losses


(i) Mechanical losses:

losses which occurs in shaft of induction motor. losses includes friction & windage losses

(ii) Variable losses: These are also called as copper losses which occur at winding of stator & rotor. Power wasted in the form of $I^2 R$ losses known as variable losses.

cu losses usually occur in windings.


star connection



$$V_L = \sqrt{3} V_{ph}$$

$$I_L = I_{ph}$$

Delta connection



$$V_L = V_{ph}$$

$$I_L = \sqrt{3} I_{ph}$$