


For the angle range of:  $30^\circ \sim 150^\circ$

(as an example)



$$\lambda_{pm} = \lambda_{pmi} \cdot \left[ 1 - \frac{\theta}{\pi/3} \right]$$

$$\Rightarrow \frac{d\lambda_{pm}}{dt} = \frac{d\lambda_{pm}}{d\theta} \cdot \frac{d\theta}{dt} = -\frac{3}{\pi} \cdot \lambda_{pmi} \cdot \omega$$

$$V = Ri + \frac{d\lambda}{dt}$$

Because  $\lambda = \lambda_{pm} + \lambda_a = \lambda_{pmi} \left[ 1 - \frac{\theta}{\pi/3} \right] + L_a i$

So:  $V = Ri + L_a \frac{di}{dt} + \frac{d\lambda_{pm}}{dt}$   
 $= Ri + L_a \frac{di}{dt} + \left( -\frac{3}{\pi} \cdot \lambda_{pmi} \right) \cdot \omega$ , where  $\omega = \frac{d\theta}{dt}$

input power

Power:  $P_i = Ri^2 + L_a i \frac{di}{dt} + i \cdot \frac{d\lambda_{pm}}{dt}$

mechanical power

$$P_{mec} = i \cdot \frac{d\lambda_{pm}}{dt} = i \cdot \left( -\frac{3}{\pi} \cdot \lambda_{pmi} \right) \cdot \omega \quad \dots \dots (1)$$

Torque:  $\tau = \frac{P_{mec}}{\omega} = \frac{1}{\omega} \cdot i \cdot \left( -\frac{3}{\pi} \lambda_{pmi} \right) = \underbrace{p}_{\substack{\uparrow \\ \text{mechanical speed}}} \cdot i \cdot \underbrace{\left( -\frac{3}{\pi} \right)}_{\substack{\uparrow \\ \text{Number of pole pairs}}} \cdot \lambda_{pmi}$

Therefore:  $i$  should be a negative, constant value, the instantaneous torque will be constant and greater than 0.

(This is for the angle range  $30^\circ \sim 150^\circ$ ).

For other angle ranges: \* when the PM flux linkage is constant, according to (1), the output power will be zero, independent of the current, so the current should also be zero to save the loss.

\* when the PM flux linkage is not constant, similar analysis as above may be carried out.