


EVENT ANALYSIS REPORT				
UNIT NO : 01	TPS : Khaperkheda TPS		Unit Capacity : 210 MW	
1. *HO Code :	Station Code : T003	Time - 14:54 Hrs	Date - 14/05/2016	No. of days from last sync. : 45 days
2. Operating conditions at the time of Event :-				
Load 70 MW		Coal Cycles in service A & C		Oil Support Nil
3. Nature of Event: T.A. Set withdrawn due to boiler tube leakage at steam cooled wall.				
4. Name of First Up , Main Protections & Protection on which GCB tripped : Hand Tripped, (First Up) Loss of all fuel, Boiler Tripped, Generator Protection Operated.				
5A) Observations: On dt. 14/05/2016 at 14.00 hrs, set was on load at 165 MW with five coal cycles in service (B-U/P) and no oil support. At 14.30 hrs, boiler tube leakage suspected due to disturbance in boiler parameters. Drum level found dropped to low level with sudden increase in DM make-up. So, load started reducing by withdrawing coal cycles-F, E & D, one by one. Set hand tripped at 14:54 hrs when the load was 70 MW with coal mills-A & C in service and no oil support, to attend boiler tube leakage.				
5 B) Remedial Action/work done : <u>Primary Failure</u> - Front steam cooled wall header SHH-5 stub no. 4 found punctured. <u>Secondary failure</u> - Front steam cooled wall header SHH-5 stub no. 5 found punctured and external surface of SHH-5 header between stub no. 4 & 5 found damaged due to steam erosion approx. 100mm x100 mm x 15 mm depth. Replacement of stub no. 4 & 5 of front SCW header SHH-5 is carried out. Repairing of external surface of SHH-5 header by preheating, welding & post heating process. Total 04 Nos. HP weld joints. (02 Nos. of butt joint and 02 Nos. of stub joints)				
2. Root Cause Analysis : Thermal stress ruptured due to load variations and cyclic loading & unloading might be the root cause of failure of stub no. 4 of front steam cooled wall header SHH-5 which resulted into stub joint cracks.				
7. Preventive action suggested (Short Term) : (1) DP test & ultrasonic test of all stubs connection joints of front steam cooled wall header SHH 5 will be carried out during forthcoming AOH of Unit no. 1. (2) Checking of mirror image of stub joints of LHS of SHH 5 and strengthening the same. (3) Strengthening stub joint 1, 2 & 3 of SHH 5 header RHS side.				
8. Preventive action suggested (Long Term) :-				
9. Similar event occurred last time:-	Unit No # 1, 210 MW	Time : 16:27 hrs	Date : 01/10/2015	
Event: - T.A. Set withdrawn due to boiler tube leakage at economizer side & Water Wall.				
9A. Implementation Status of Long Term/Short Term measures stated at Sr No 7 & 8 :- The above corrective action will be implemented in July-16 by BM-I section.				
10. Boiler lighted up	Time - 23:30 Hrs		Date- 15/05/2016	
11. T-A Set Synchronized	Time - 05:26 Hrs		Date- 16/05/2016	
12. Remark: -				
 Chief Engineer				
13. Recommendations of Works Section:				
1. Procurement/Replacement Plan:				
2. Operational Error:				
3. Delay in Maintenance:				
4. Delay in bringing back the Unit:				
5. Training of Staff:				
6. Whether remedial action is completed satisfactory & point is closed:				
C E/Dy C E (Works)				