


Module 2 Chapter 3 Map.

Understanding variation in process


- Variation is what customer doesn't like
- Statistical Tools used to calculate variation



Seven Tools of quality

- help in visual presentation of the data.
- Ishikawa :- 95% of quality related problem can be resolved with these Basic Tools

- ① Flow chart (non statistical)
- ① describe process in graphically displaying (visual steps) with proper sequence.
 - ② The Below can be analyzed:-
 - 1 identify critical process points need control so it's useful for Appraisal and prevention
 - 2 looking for missing steps
 - 3 check the value added by each steps




- ② Check sheet
- ① helps in organization data by category (Data record)
 - ② show how many times each particular value occurs.
 - ③ help to spot the problem
- Problem description
- | Reason | Mon | Tues | Wed | Thurs | Fri | Total |
|---------|-----|------|-----|-------|-----|-------|
| cause 1 | +++ | +++ | | | | 16 |
| cause 2 | | | +++ | | | |
| Total | 7 | | | | | |
- ④ attributed / Count Data

- ③ PARETO chart
- ① Prioritization Tool & (Count data)
 - ② Vital few / Trivial many.
 - ③ help to find Root causes
 - ④ help to find CTQ, CTPs
-
- CTQ = No Causes
- CTP = process level to make cause (1, 2, 3) in critical

- ④ Histogram
- Display the frequency of distribution of continuous / variable data.
-
- Strong Central Tendency (Mean, Median and Mode close to each other) indicate less assignable cause variation
- if bar are more spread out mean that range is higher, so i.e. presence of non assignable causes
- More than one mode indicate assignable causes.
- Curve sharp means more stable
- Curve flat means more variation


work as LCO
→ check
→ capability of the process
→ check process running
→ observe the behaviour
of process over
period of time.

- ⑦ Control chart
- To calculate Process Capability (Analyze in DMAIC)
 - To study nature of Variation (non assignable cause)
 - Monitor The Process if it is important (Control in DMAIC)
 - To monitor The process performance on an ongoing basis (assignable causes)






- ⑥ Co-relation diagram or Scatter diagram
- relation between CTPs X & Y
 - Correlation ~~Coefficient~~
 - if Y increase as X increase (Positive correlation)
 - if Y decrease as X increase (negative correlation)
 - Correlation Coefficient (r)
 - Points are very close (CTPs) to the best fit line = strong correlation
 $r \Rightarrow -0.7 \text{ to } -1.0$ or $0.7 \text{ to } 1.0$
 - Weak correlation (NOT CTPs)
 Points are far from the best fit line
 $r = -0.3 \text{ to } -0.69$ or $0.3 \text{ to } 0.69$
 - No correlation (NOT CTP)
 You cannot draw any best fit line
 $r = -0.0 \text{ to } -0.29$ or $0.0 \text{ to } 0.29$

⑤ Fish Bone / Ishikawa Diagram / Cause and effect Diagram



Use SPC (Statistical Process Control)
in Six Sigma.
Control chart.

④ → *
next page
[15]



⊕ Count data → DPMO Table → Process Capability is Calculated from Sigma level.

⊕ Variable data → CP → Process Capability is Calculated as $3 \times CP$.

⊕ If $CP = 1$ of certain process
So the Sigma level of this process
 $= 3 \times 1 = 3$ sigma level