

Representing Curves and Surfaces

Introduction

- We need smooth curves and surfaces in many applications:
 - model real world objects
 - computer-aided design (CAD)
 - high quality fonts
 - data plots
 - artists sketches

Introduction

- The need to present curves and surfaces arises in two cases:
 - In modeling **existing objects** (a face, a mountain).
 - In modeling “from scratch” where **no preexisting physical object** is being presented.

Introduction

- Most common representation for surfaces:
 - polygon mesh
 - parametric surfaces
 - quadric surfaces
- Solid modeling

Introduction

- Polygon mesh:
 - Is a collection of edges, vertices and polygons connected such that each edge is shared by at most two polygons.
 - An edge connects two vertices, and a polygon is a closed sequence of edges.
 - good for boxes, cabinets, building exteriors.
 - bad for curved surfaces.
 - errors can be made arbitrarily small at the cost of space and execution time

Representing Polygon Meshes

- explicit representation
- by a list of vertex coordinates


$$P = ((x_1, y_1, z_1), (x_2, y_2, z_2), \dots, (x_n, y_n, z_n))$$

- pointers to a vertex list
- pointers to an edge list

Explicit representation

- Advantages:
 - It is space efficient for a single polygon.
- Disadvantages:
 - In polygon mesh representation much space is lost because the coordinates of shared vertices are duplicated
 - There is no explicit representation of shared edges and vertices.
 - If edges are being drawn, each shared edge is drawn twice.

Pointers to a Vertex List



$$V = (V_1, V_2, V_3, V_4)$$

$$= ((x_1, y_1, z_1), \dots, (x_4, y_4, z_4))$$


$$P_1 = (1, 2, 4)$$

$$P_2 = (4, 2, 3)$$

Pointers to a Vertex List

- Advantages:
 - Since each vertex is stored once, considerable space is saved.
 - Coordinates of a vertex can be changed easily
- Disadvantages:
 - It is difficult to find polygons that share an edge.
 - Shared polygon edges are drawn twice when polygons outlines are displayed.

Pointers to an Edge List



$$V = (V_1, V_2, V_3, V_4)$$

$$= ((x_1, y_1, z_1), \dots, (x_4, y_4, z_4))$$

$$E_1 = (V_1, V_2, P_1, \lambda)$$

$$E_2 = (V_2, V_3, P_2, \lambda)$$

$$E_3 = (V_3, V_4, P_2, \lambda)$$

$$E_4 = (V_4, V_2, P_1, P_2)$$

$$E_5 = (V_4, V_1, P_1, \lambda)$$

$$P_1 = (E_1, E_4, E_5)$$

$$P_2 = (E_2, E_3, E_4)$$

Pointers to a Edge List

- Advantages:
 - Redundant clipping, transformation and scan conversion are avoided
 - Filled polygons are displayed easily
- Disadvantages:
 - It is not easy to determine which edges are incident to a vertex.

Introduction

- Parametric polynomial curves:
 - point on 3D curve = $(x(t), y(t), z(t))$
 - $x(t)$, $y(t)$, and $z(t)$ are polynomials
 - usually cubic: cubic curves

Parametric cubic curves

- Polylines and polygons:
 - large amounts of data to achieve good accuracy
 - interactive manipulation of the data is tedious
- Higher-order curves:
 - more compact (use less storage)
 - easier to manipulate interactively
- Possible representations of curves:
 - explicit, implicit, and parametric

Parametric cubic curves

- General form:

$$x(t) = a_x t^3 + b_x t^2 + c_x t + d_x$$

$$y(t) = a_y t^3 + b_y t^2 + c_y t + d_y$$

$$z(t) = a_z t^3 + b_z t^2 + c_z t + d_z$$

$$C = \begin{bmatrix} a_x & a_y & a_z \\ b_x & b_y & b_z \\ c_x & c_y & c_z \\ d_x & d_y & d_z \end{bmatrix} \quad T = [t^3 \quad t^2 \quad t \quad 1]$$

$$Q(t) = [x(t) \quad y(t) \quad z(t)] = T \cdot C = T \cdot M \cdot G$$

Tangent Vector

$$\begin{aligned}\frac{d}{dt}Q(t) &= Q'(t) = \left[\frac{d}{dt}x(t) \quad \frac{d}{dt}y(t) \quad \frac{d}{dt}z(t) \right]^T \\ &= \frac{d}{dt}C \bullet T = C \bullet \begin{bmatrix} 3t^2 & 2t & 1 & 0 \end{bmatrix}^T \\ &= \begin{bmatrix} 3a_x t^2 + 2b_x t + c_x & 3a_y t^2 + 2b_y t + c_y & 3a_z t^2 + 2b_z t + c_z \end{bmatrix}^T\end{aligned}$$

Parametric Cubic Curves

- $Q(t) = C \bullet T$
- Rewrite the coefficient matrix as $C = G \bullet M$
 - where M is a 4×4 **basis matrix**, G is called the **geometry matrix**
 - so

$$Q(t) = \begin{bmatrix} x(t) \\ y(t) \\ z(t) \end{bmatrix} = \begin{bmatrix} G_1 & G_2 & G_3 & G_4 \end{bmatrix} \begin{bmatrix} m_{11} & m_{21} & m_{31} & m_{41} \\ m_{12} & m_{22} & m_{32} & m_{42} \\ m_{13} & m_{23} & m_{33} & m_{43} \\ m_{14} & m_{24} & m_{34} & m_{44} \end{bmatrix} \begin{bmatrix} t^3 \\ t^2 \\ t \\ 1 \end{bmatrix}$$

4 endpoints or tangent vectors

Parametric Cubic Curves

- $Q(t) = G \bullet M \bullet T = G \bullet B$
where $B = M \bullet T$ is called the **blending function**

Why Parametric Cubic Curves?

- Why cubic?
 - lower-degree polynomials give too little flexibility in controlling the shape of the curve
 - higher-degree polynomials can introduce unwanted wiggles and require more computation
 - lowest degree that allows specification of endpoints and their derivatives
 - lowest degree that is not planar in 3D

Continuity between curve segments

- G^0 geometric continuity
 - two curve segments join together
- G^1 geometric continuity
 - the directions (*but not necessarily the magnitudes*) of the two segments' tangent vectors are equal at a join point

Continuity between curve segments

- C^1 continuous
 - the tangent vectors of the two cubic curve segments are equal (*both directions and magnitudes*) at the segments' join point
- C^n continuous
 - the direction and magnitude of
through the n th derivative are equal at the join point
 $\underline{\underline{d^n / dt^n [Q(t)]}}$

Measure of Smoothness

G^0 Geometric Continuity \Leftrightarrow C^0 Parametric Continuity

If two curve segments join together.

G^1 Geometric Continuity

If the **directions** (but not necessarily the magnitudes) of the two segments' tangent vectors are equal at a join point.

C^1 Parametric Continuity




If the **directions and magnitudes** of the two segments' tangent vectors are equal at a join point.

C^2 Parametric Continuity


If the direction and magnitude of $Q^2(t)$ (curvature or **acceleration**) are equal at the join point.

C^n Parametric Continuity


If the direction and magnitude of $Q^n(t)$ through the n th derivative are equal at the join point.




Continuity between curve segments



Continuity between curve segments




Measure of Smoothness



- By increasing parametric continuity we can increase smoothness of the curve.


- Q_1 & Q_2 are C^1 and G^1 continuous
- Q_1 & Q_3 are G^1 continuous only as Tangent vectors have different magnitude.
- Observe the effect of increasing in magnitude of TV



Three Types of Parametric Cubic Curves

- Hermite Curves
 - defined by two **endpoints** and two endpoint **tangent vectors**
- Bézier Curves
 - defined by two **endpoints** and two **control points** which control the endpoint' **tangent vectors**
- Splines
 - defined by four **control points**

Hermit Curves



A cubic Hermite curve segment interpolating the endpoints P_1 and P_4 is determined by constraints on

the endpoints P_1 and P_4 and

tangent vectors at the endpoints R_1 and R_4

Hermite Curves

- Given the endpoints P_1 and P_4 and tangent vectors at R_1 and R_4
- What are
 - Hermite basis matrix M_H
 - Hermite geometry vector G_H
 - Hermite blending functions B_H
- By definition

$$G_H = [P_1 \quad P_4 \quad R_1 \quad R_4]$$

Hermit Curves (Continue)

The Hermite Geometry Vector: $G_H = \begin{bmatrix} P_1 \\ P_4 \\ R_1 \\ R_4 \end{bmatrix}$

$$\begin{aligned} x(t) &= a_x t^3 + b_x t^2 + c_x t + d_x = T \cdot C_x = T \cdot M_H \cdot G_{H_x} \\ &= \begin{bmatrix} t^3 & t^2 & t & 1 \end{bmatrix} M_H \cdot G_{H_x} \end{aligned}$$

The constraints on $x(0)$ and $x(1)$:

$$x(0) = P_{1x} = \begin{bmatrix} 0 & 0 & 0 & 1 \end{bmatrix} M_H \cdot G_{H_x}$$

$$x(1) = P_{4x} = \begin{bmatrix} 1 & 1 & 1 & 1 \end{bmatrix} M_H \cdot G_{H_x}$$

Hermit Curves (Continue)

$$x'(t) = \begin{bmatrix} 3t^2 & 2t & 1 & 0 \end{bmatrix} M_H \cdot G_{H_x}$$

Hence the tangent-vector constraints:

$$x'(0) = R_{1x} = \begin{bmatrix} 0 & 0 & 1 & 0 \end{bmatrix} M_H \cdot G_{H_x}$$

$$x'(1) = R_{4x} = \begin{bmatrix} 3 & 2 & 1 & 0 \end{bmatrix} M_H \cdot G_{H_x}$$

The 4 constraints can be written as:

$$\begin{bmatrix} P_1 \\ P_4 \\ R_1 \\ R_4 \end{bmatrix}_x = G_{H_x} = \begin{bmatrix} 0 & 0 & 0 & 1 \\ 1 & 1 & 1 & 1 \\ 0 & 0 & 1 & 0 \\ 3 & 2 & 1 & 0 \end{bmatrix} M_H \cdot G_{H_x}$$

Hermit Curves (Continue)

$$M_H = \begin{bmatrix} 0 & 0 & 0 & 1 \\ 1 & 1 & 1 & 1 \\ 0 & 0 & 1 & 0 \\ 3 & 2 & 1 & 0 \end{bmatrix}^{-1} = \begin{bmatrix} 2 & -2 & 1 & 1 \\ -3 & 3 & -2 & -1 \\ 0 & 0 & 1 & 0 \\ 1 & 0 & 0 & 0 \end{bmatrix}$$

$$\begin{aligned} Q(t) &= \begin{bmatrix} x(t) & y(t) & z(t) \end{bmatrix} = T \cdot M_H \cdot G_H = B_H \cdot G_H \\ &= (2t^3 - 3t^2 + 1)P_1 + (-2t^3 + 3t^2)P_4 \\ &\quad + (t^3 - 2t^2 + t)R_1 + (t^3 - t^2)R_4 \end{aligned}$$

Bezier Curves




Figure 4.14




Figure 4.15




Figure 4.16

P_1, P_2, P_4, P_3




Figure 4.17

P_1, P_3, P_4, P_2





Figure 4.18

P_3, P_1, P_4, P_2

Bézier Curves



Indirectly specifies the endpoint tangent vectors by specifying two intermediate points that are not on the curve.

$$R_1 = Q'(0) = P_1P_2 = 3(P_2 - P_1)$$

$$R_4 = Q'(1) = P_3P_4 = 3(P_4 - P_3)$$

Bézier Curves (Continue)

The Bézier Geometry Vector: $G_B = \begin{bmatrix} P_1 \\ P_2 \\ P_3 \\ P_4 \end{bmatrix}$

$$G_H = \begin{bmatrix} P_1 \\ P_4 \\ R_1 \\ R_4 \end{bmatrix} = \begin{bmatrix} 1 & 0 & 0 & 0 \\ 0 & 0 & 0 & 1 \\ -3 & 3 & 0 & 0 \\ 0 & 0 & -3 & 3 \end{bmatrix} \begin{bmatrix} P_1 \\ P_2 \\ P_3 \\ P_4 \end{bmatrix} = M_{HB} \cdot G_B$$

$$\begin{aligned} Q(t) &= T \cdot M_H \cdot G_H = T \cdot M_H \cdot (M_{HB} \cdot G_B) \\ &= T \cdot (M_H \cdot M_{HB}) \cdot G_B = T \cdot M_B \cdot G_B \end{aligned}$$

Bézier Curves (Continue)

$$M_B = M_H \cdot M_{HB} = \begin{bmatrix} -1 & 3 & -3 & 1 \\ 3 & -6 & 3 & 0 \\ -3 & 3 & 0 & 0 \\ 1 & 0 & 0 & 0 \end{bmatrix}$$

$$Q(t) = T \cdot M_B \cdot G_B$$

$$= (1-t)^3 P_1 + 3t(1-t)^2 P_2 + 3t^2(1-t)P_3 + t^3 P_4$$

The 4 polynomials in $B_B = T \cdot M_B$ are called the Bernstein polynomials.

B-Spline Curves

- Most shapes are simply too complicated to define using a single Be'zier curve.
- A spline curve is a sequence of curve segments that are connected together to form a single continuous curve.
- For example, a piecewise collection of B'ezier curves, connected end to end, can be called a spline curve.
- The word “spline” can also be used as a verb, as in “Spline together some cubic B'ezier curves.”

B-Spline Curves...

- While C^1 continuity is straightforward to attain using Be'zier curves, C^2 and higher continuity is cumbersome. This is where B-spline curves come in.
- In practical terms, B-spline curves can be thought of as a method for defining a sequence of degree n Be'zier curves that join automatically with C^{n-1} continuity, regardless of where the control points are placed.
- An open string of m Be'zier curves of degree n involve $(nm + 1)$ distinct control points (shared control points counted only once), that same string of Be'zier curves can be expressed using only $(m + n)$ B-spline control points (assuming all neighboring curves are C^{n-1}).

Polar Form

- All of the important algorithms for Be'zier and B-spline curves can be derived from the following rules for polar values.
- For degree n Be'zier curves over the parameter interval $[a, b]$, the control points are relabeled

$$P_i = P(u_i, u_2, \dots, u_n) \text{ where } u_j = a, (j \leq n - i) \text{ otherwise}$$

$$u_j = b$$

- For a degree two curve over the interval $[a, b]$,


$$P_0 = P(a, a); P_1 = P(a, b); P_2 = P(b, b).$$

- For a degree three Be'zier curve,

$$P_0 = P(a, a, a); P_1 = P(a, a, b);$$

$$P_2 = P(a, b, b); P_3 = P(b, b, b);$$

Be'zier curves in Polar Form



- Figure shows two cubic Be'zier curves labeled using polar values. The first curve is defined over the parameter interval $[0, 2]$ and the second curve is defined over the parameter interval $[2, 3]$.


B-Spline curves in Polar Form

- For a degree n B-spline with a knot vector (explained later) of $[t_1, t_2, t_3, t_4, \dots]$, the arguments of the polar values consist of groups of n adjacent knots from the knot vector, with the i^{th} polar value being $P(t_i, \dots, t_{i+n-1})$, as shown in the next slide.
- A polar value is symmetric in its arguments. This means that the order of the arguments can be changed without changing the polar value. For example,
$$P(1, 0, 0, 2) = P(0, 1, 0, 2) = P(0, 0, 1, 2) = P(2, 1, 0, 0), \text{ etc.}$$

knot vector

- A knot vector is a list of parameter values, or knots, that specify the parameter intervals for the individual Be'zier curves that make up a B-spline.
- For example, if a cubic B-spline is comprised of four Be'zier curves with parameter intervals $[1, 2]$, $[2, 4]$, $[4, 5]$, and $[5, 8]$, the knot vector would be $[t_0, t_1, 1, 2, 4, 5, 8, t_7, t_8]$.
- Notice that there are two (one less than the degree) extra knots prepended and appended to the knot vector. These knots control the end conditions of the B-spline curve.

B-spline curve labeled using polar form



References

- J. D. Foley, A. V. Van Dam, S. K. Van Dam and J. F. Hughes, Computer Graphics, Principles & Practice, Second Edition.
- T. W. Sederberg, An Introduction to B-Spline Curves, March 14, 2005.