

BMXNOE0100 Firmware History

Version #	Date of Publication	Internal reference	Description
SV3.2	10/2017	PEP0399812R	A loss of connection would occur if both Unity and SoMove (used as an Ethernet/CANOpen gateway) were connected through the BMXNOE01x0.
SV3.1	12/2015	PEP0309176R	Removed a Remote Code Execution vulnerability in the websSecurityHandler (ICS-VU-587471)
		PEP0300706R	Removed a web server vulnerability to a remote file inclusion attack. (ICS-ALERT-15-224-02)
SV3.0	01/2015		<p>Note: The wrong V3.0 Exec file (BMXNOE0100_v30.idx) was posted for the BMXNOE0100 on Feb 18, 2015. The correct file was posted on March 16, 2015 with the new filename (BMXNOE0100_v300.idx). Do not install the firmware with the filename BMXNOE0100_v30.idx as it could make the BMXNOE0100 inoperable and unrecoverable.</p> <p>The correct firmware is identified as follows:</p> <ol style="list-style-type: none"> The filename was changed <ul style="list-style-type: none"> - Correct filename BMXNOE0100_v300.idx - Incorrect filename BMXNOE0100_v30.idx The .idx file sizes are different <ul style="list-style-type: none"> - Correct v3.00 file size: 3,102 KB - Incorrect v3.0 file size: 5,367 KB If using Unity Loader: <ul style="list-style-type: none"> - The correct file is identified as a BMXNOE0100 V3.00 - The incorrect file is identified as a BMXNOE0110 V6.10
		PEP0259556R	There is a possibility the data in an I/O scanner message could be corrupted. The receive buffer was overwritten by an incoming message as it was being read. Interrupts are now disabled while data is being read and the issue is resolved.
		PEP0279419R	Code was corrected to restore the Graphics Viewer password button.
		PEP0271221R	Disabling FTP or HTTP in the Security tab of the Ethernet Configuration page in Unity, did not work if the PLC was reset or power cycled. At power up, the enabled/disabled state was set before the web server started. Then when the server started, the ports were enabled. Services are now disabled after the web server is started.
		PEP0273473R	The Function Block ETH-PORT-CTRL was not able to control the enable/disable state of FTP and HTTP. FTP/HTTP enable/disable bits were incorrectly implemented.
SV2.9	06/2014	PEP0228870R	Under very rare conditions, the device would not recover if power is switched on and off.
		PEP0234061R	The module experiences ARP and connection problems after 497 days of continuous operation. The 497 consecutive days powered on relates to an internal clock value within the BMXNOE0100 and is not accessible by the user. When this specific clock value is reached, the ARP cache stops updating and is no longer flushed or updated. Any connections already established would continue, but if any were closed or any new connection attempts were made, they would be refused. If the issue occurred, a reboot of the module was required to reset it. A power cycle within the 497 days would prevent the issue from occurring and reset the clock back to day 1. This can be done during any scheduled maintenance period within the 497 day time frame to avoid this event.
		PEP0241427R	Cyber Security vulnerabilities with FTP and HTTP. Option added to prevent FTP/HTTP access.

		PEP0250560R	In HTTP, using directory traversals, an attacker can bypass the basic authentication mechanism. Security Alert - ICS-VU-529542.
		PEP0251116R	Web page issue with Java Version 1.7. Files did not have security Signature. The Java dialog box provides a warning indicating that this is a unsigned application. The files all have been properly signed.
SV2.8	10/2013	OPR20051029	Daylight Savings Time 'auto' selection adjustment did not work.
		PEP0139716R	Under certain conditions, the web page may return a "Null Reference Exception" error. File fixed so the application will not return an exception when navigating from page to page.
SV2.7	01/2013		Ethernet Port Becomes Non-responsive after repeated Link Up/Down events, when it is getting its IP address through a DHCP request. There were problems with task priority handling in the DHCP. The task priorities were corrected and the link now becomes reestablished after all link-down/link-up events.
SV2.6	06/2012		If the user entered a new password as 17 characters in the http password web page, the NOE returned a page saying that the password change was successful. When the user tried use the new password, it failed. The password field was corrected to limit the user to 16 characters and no more will be accepted.
			Enhancement: Time To Live (TTL) was increased to 32.
			Changing pages very quickly causes an exception error getting returned. An incorrect function returned from the stack, combined with multiple timeout values, resulted in loss of communication resources. Function call was corrected and a single timeout replacing the previous ones resolved the issue.
			The time between READ_VAR queries increases over time if 1 or 2 of unrelated devices are disconnected. Improved handling of the Port 502 client's send message resolved the issue.
			Cyber Security services disabled and changes: 1) Removed Telnet service. 2) Removed Wind River debug service port. 3) Removed unused logins/passwords from firmware.
SV2.3	06/2011		DHCP Server did not provide Option 17 in the OFFER when it is included in the DISCOVER or REQUEST PDU's. The DHCP Server now provides the path data in all DHCP OFFERs. Option 17 is a parameter in the DHCP OFFER from the Server indicating the path of the .prm parameter file.
			A BMXNOE may not initially respond to a SYN from an XBT if both BMXNOE0100 and XBT are powered on at same time. SYN Requests are now ignored until the BMXNOE0100 is completely booted.
			BMXNOE0100 fails to recover from a serial disconnection through a Serial/Ethernet Gateway. The retransmission mechanism was modified to improve robustness against sync errors.
SV2.2	12/2010		The BMXNOE0100 may stop functioning as a DHCP Server. If the device being IO scanned has a slow response time (110-120ms), then the IO scanner was not able to open a connection. The Round Trip time algorithm for retransmission was corrected.