


How to use Actuator Function Tester

2017-12-03

<http://OpenActuator.org> (zgitae@gmail.com)

Program Composition

Main Window




Move Page

Function Buttons

Main Window

➤ Monitoring Window

- View real time Current, Stroke and magnetic force data



➤ Settings Window

- Correction and setting of physical values

1. Hardware Setting

DAQ Board Number : (Arduino : ComPort, NI : Device Number)

P/Supply Com Port :

2. Compensation Setting

가. 전류 [mA]

측정전류	측정레벨
0	-0.02037
13	0.055365
26	0.131411
38	0.208536
51	0.284299
64	0.361372
77	0.436227
89	0.512062
102	0.588154
115	0.664068

기울기 167.5298
절편 3.5366

나. 변위 [mm]

측정변위	측정레벨
0	-5.0012
0.2	-4.89975
0.4	-4.79865
0.6	-4.70083
0.8	-4.60115
1	-4.50046
1.2	-4.39908
1.4	-4.29969
1.6	-4.20152
1.8	-4.09975

기울기 1.9998
절편 9.9995

다. 자기력 [N]

측정힘	측정레벨
0	-0.00213
1	0.064998
2	0.132023
3	0.198246
4	0.265771
5	0.333349
6	0.399559
7	0.466565
8	0.535808
9	0.603774

기울기 14.8739
절편 0.0409

- Y 축인 측정물리량 범위는 해당 물리량의 동작범위와 유사하게 맞추어라.
- 물리량의 동작범위에 대한 측정레벨이 2,000 등분이상 되도록 증폭비를 조정하라.

3. Measurement Setting

Sampling Period : ms Max Current : mA

Moving average Count : Max Voltage : V

가. 전류 측정

Initial Current : mA

Final Current : mA

나. 변위 측정


Initial Stroke : mm

Final Stroke : mm

Main Window


➤ Current Window

- Examination of Current-Magnetic force



➤ Stroke Window

- Examination of Stroke-Magnetic Force



Program Setting

➤ Method of Program Setting

1. Refer the AFT Installation Manual

1. Hardware Setting

DAQ Board Number : (Arduino : ComPort, NI : Device Number)

P/Supply Com Port :

2. Compensation Setting

가. 전류 [mA]

측정전류	측정레벨	레벨
0	-0.02037	측정
13	0.055365	
26	0.131411	
38	0.208536	
51	0.284299	
64	0.361372	
77	0.436227	
89	0.512062	
102	0.588154	
115	0.664068	

기울기	167.5298
절편	3.5366

나. 변위 [mm]

측정변위	측정레벨	레벨
0	-5.0012	측정
0.2	-4.89975	
0.4	-4.79865	
0.6	-4.70083	
0.8	-4.60115	
1	-4.50046	
1.2	-4.39908	
1.4	-4.29969	
1.6	-4.20152	
1.8	-4.09975	

기울기	1.9998
절편	9.9995

다. 자기력 [N]

측정힘	측정레벨	레벨
0	-0.00213	측정
1	0.064998	
2	0.132023	
3	0.198246	
4	0.265771	
5	0.333349	
6	0.399559	
7	0.466565	
8	0.535808	
9	0.603774	

기울기	14.8739
절편	0.0409

- Y 축인 측정물리량 범위는 해당 물리량의 동작범위와 유사하게 맞추어라.

- 물리량의 동작범위에 대한 측정레벨이 2,000 등분이상 되도록 증폭비를 조정하라.

3. Measurement Setting

Sampling Period : ms Max Current : mA

Moving average Count : Max Voltage : V

가. 전류 측정

Initial Current : mA

Final Current : mA

나. 변위 측정



Initial Stroke : mm

Final Stroke : mm


Data Monitoring

➤ Measurement Explanation

1. Move to Monitoring Window
2. Open indicator window
3. View real time measured data and stop
4. Current Output
5. Continuous Current output
6. Measurement of real time data



⑥



Current Measurement

➤ Measurement orders

1. Set Zero Point prior to Actuator stroke Zero Point
 - The position of Zero is the start of the moving parts or the final location
 - The Zero point is sensed by confirming the contact via power sensor
2. Move to Current Window
3. Click Measurement.
4. Move sensor part to the measured Stroke
5. Input measurement of Initial Current, final current and current divisions
6. Set Series No. (Supports total five Series)
7. Click Measure button

The screenshot shows the 'Current-Force' software window. At the top, there are three digital displays for 'Current : 0.0', 'Stroke : 0.0', and 'Force : 0.0', each with a yellow '0.0' on a black background. To the right of these displays is an 'Update' button. Below the displays, on the left, are input fields for 'Initial Current : 0 mA', 'Final Current : 315 mA', and 'Step Count : 8'. A blue circle with the number '5' is next to the 'Initial Current' field. To the right of these fields is a 'Series No : 1' dropdown menu, with a blue circle and the number '6' next to it. Below the dropdown are two buttons: a play button (triangle) and a square button. A blue circle with the number '7' is next to the play button. At the bottom right of the window is an 'Exit' button.

A vertical menu bar on the right side of the screen. It contains seven buttons arranged vertically: 'Main', 'Current' (with a blue circle and the number '2' next to it), 'Stroke', 'Setup', 'Measurement' (with a blue circle and the number '3' next to it), 'Delete', and 'Print'.

Current Measurement

➤ Measurement orders

1. Set Zero Point prior to Actuator stroke Zero Point
 - The position of Zero is the start of the moving parts or the final location
 - The Zero point is sensed by confirming the contact via power sensor
2. Move to Stroke Window
3. Click Measurement.
4. Input measurement of Initial Stroke, final Stroke and Stroke divisions
5. Move Sensor part below initial stroke
6. Set Series No. and input permitted current(Supports total five Series)
7. Click Measure button

Stroke-Force

Current :	Stroke :	Force :	
0.0	0.0	0.0	Update

Initial Stroke :	0	mm	Series No : 1
Final Stroke :	1	mm	
Step Count :	20		
			Test Current : 250 mA
			▶ ■
			Exit

⑤

⑦

⑥

Main

Current

② Stroke

Setup

③ Measurement

Delete

Print



– Thank You –
