

**Arm® Cortex®-M0**  
**32-bit Microcontroller**

# **NUC121/NUC125 Series CMSIS BSP**

## **Revision History**

*The information described in this document is the exclusive intellectual property of Nuvoton Technology Corporation and shall not be reproduced without permission from Nuvoton.*

*Nuvoton is providing this document only for reference purposes of NuMicro microcontroller and microprocessor based system design. Nuvoton assumes no responsibility for errors or omissions.*

*All data and specifications are subject to change without notice.*

For additional information or questions, please contact: Nuvoton Technology Corporation.

[www.nuvoton.com](http://www.nuvoton.com)

### Revision 3.01.006 (Released 2020-05-21)

---

- IAR startup\_NUC121.s
  1. Fixed build issue with IAR V7.5.
- Standard driver
  1. UART driver
    - Updated UART\_DisableInt, UART\_EnableInt: Removed NVIC IRQ control.
- Sample code
  1. New sample code: USCI\_SPI\_SlaveModeINT.
  2. Updated all UART sample codes: Added NVIC IRQ control.
  3. Fixed I2C\_PDMA\_TRX: Unused \_\_ALIGNED macro.
  4. Fixed PDMA, PDMA\_Scatter\_Gather: Missing word alignment.
  5. Fixed USB\_D\_MassStorage\_CDRom: Removed 2KB file size limit.
  6. Fixed all USB\_D\_VCOM sample codes: Potential UART Tx FIFO overflow issue.
  7. Fixed USB\_D\_VCOM\_DualPort: Wrong baudrate issue.

### Revision 3.01.005 (Released 2020-09-14)

---

- Added Apache-2.0 license declaration.
- Standard driver
  1. retarget.c
    - Fixed \_write, SendChar\_ToUART: '\r' issue.
    - Fixed SendChar: Uninitialized pointer.
  2. SPI driver
    - New API: SPI\_DISABLE\_TX\_RX\_PDMA, SPI\_TRIGGER\_TX\_RX\_PDMA.
  3. TIMER driver
    - New API: TIMER\_SET\_OPMODE.
  4. UART driver
    - New API: UART\_PDMA\_DISABLE, UART\_PDMA\_ENABLE
- Sample code
  1. Improved I2C\_Wakeup\_Slave: Wakeup robustness.
  2. Fixed USB\_D\_VCOM\_DualPort: Only one VCOM port in Linux.
  3. Fixed USCI\_UART\_TxRx\_Function, all UART samples: '\r' issue.

### Revision 3.01.004 (Released 2019-10-02)

---

- Standard driver
  1. TIMER driver
    - Fixed TIMER\_Open: Return value.

- 2. USCI\_SPI driver
  - Fixed USPI\_SET\_SS\_HIGH: Implementation.
- Sample code
  - 1. New sample code: I2C\_PDMA\_TRX, ISP\_DFU, ISP\_I2C, ISP\_RS485, ISP\_SPI.
  - 2. Improved FMC\_ExecInSRAM: Add IAR and GCC projects.
  - 3. Fixed UART\_TxRx\_Function: Data lost.

---

**Revision 3.01.003** (Released 2019-06-19)

- Standard driver
  - 1. I2C driver
    - Added error handling for new transfer.
  - 2. TIMER driver
    - Fixed TIMER\_GetModuleClock: Correct PCLK.
  - 3. USB\_Driver
    - Fixed potential issue.
- Sample code
  - 1. New sample code: ISP samples.
  - 2. Updated USB\_Driver\_Audio\_NAU8822, USB\_Driver\_Audio\_HID\_NAU8822: Clear FIFO before play / record.
  - 3. Fixed TIMER\_Delay: Correct PCLK.
  - 4. Fixed all USB\_Driver samples: Potential issue.

---

**Revision 3.01.002** (Released 2018-12-28)

- CMSIS
  - 1. Upgraded to v5.1.1.
- Standard driver
  - 1. CLK driver
    - Updated CLK\_PowerDown: Require HIRC / MIRC auto trim disabled.
  - 2. PDMA driver
    - Improved PDMA\_Open: Support multiple open.
- Sample code
  - 1. Updated all samples: Keil projects use “NULink Debugger” instead of “Nuvoton Nu-Link Debugger”.
  - 2. Fixed all samples: Semihost build failure with GCC toolchain 7-2018-q2.
  - 3. Fixed I2S\_PDMA\_PlayRecord: Race condition.

4. Fixed TIMER\_CaptureCounter: Array access overflow.
5. Fixed USB\_D\_VCOM samples: UART baud rate calculation.
6. Fixed USB\_D\_VCOM\_And\_HID\_Transfer: Buffer overflow.

### Revision 3.01.001 (Released 2018-06-27)

---

- NuMicro.h
  1. New header file.
- NUC121.h
  1. Separated register declarations of each IP into distinct header files.
- Standard driver
  1. Fixed USB\_D driver: USB Control-In packet with the same size as endpoint limit.
- Sample code
  1. New sample code: USCI\_I2C\_Monitor.
  2. Improved PDMA\_ScatterGather\_PingPongBuffer: Add PDMA error handling.
  3. Improved UART\_PDMA: Add UART error handling.
  4. Updated all samples: Add Eclipse projects for GCC toolchain.
  5. Updated CLK\_ClockDetector, HIRC\_Trim, UART\_Wakeup\_LXT, ADC samples: Set analog pins as input mode and disabled digital input function.

### Revision 3.00.003 (Released 2017-12-13)

---

- NUC121.h
  1. Removed TIMER\_CTL\_TRGDAC\_Pos, TIMER\_CTL\_TRGDAC\_Msk.
- Standard driver
  1. I2C driver
    - Fixed I2C\_ReadByteTwoRegs, I2C\_ReadMultiBytesTwoRegs, I2C\_WriteByteTwoRegs, I2C\_WriteMultiBytesTwoRegs: High byte lost.
  2. SPI driver
    - Improved I2S\_Open: I2S sample rate accuracy.
  3. TIMER driver
    - Replaced TIMER\_TRG\_TO\_EADC with TIMER\_TRG\_TO\_ADC.
  4. USB\_D driver
    - Replaced USB\_D\_L1RESUME with USB\_D\_STATE\_L1RESUME.
    - Replaced USB\_D\_L1SUSPEND with USB\_D\_STATE\_L1SUSPEND.
  5. USCI-I2C driver
    - Fixed UI2C\_ReadByteTwoRegs, UI2C\_ReadMultiBytesTwoRegs, UI2C\_WriteByteTwoRegs, UI2C\_WriteMultiBytesTwoRegs: High byte lost.

6. USCI-UART driver
  - Fixed UART\_Open, UART\_SetLine\_Config: Wrong baud rate.

### Revision 3.00.002 (Released 2017-03-09)

---

- NUC121.h
  1. New definition: BPWM0\_IRQn, BPWM1\_IRQn.
- Standard driver
  1. BPWM driver
    - Fixed BPWM\_ConfigOutputChannel: 100% duty issue.
  2. CLK driver
    - Replaced CLK\_CLKSEL1\_ADCSEL\_HIRC\_DIV2 with CLK\_CLKSEL1\_ADCSEL\_HIRC.
    - Fixed definition: GPIOA\_MODULE, GPIOB\_MODULE, GPIOC\_MODULE, GPIOD\_MODULE, GPIOE\_MODULE, GPIOF\_MODULE.
  3. I2C driver
    - Removed I2C\_CLEAR\_WAKEUP\_WR\_STATUS.
  4. PWM driver
    - Fixed PWM\_ConfigOutputChannel: 100% duty issue.
  5. SYS driver
    - New definition: SYS\_GPF\_MFPL\_PF0MFP\_XT1\_OUT, SYS\_GPF\_MFPL\_PF0MFP\_X32\_OUT, SYS\_GPF\_MFPL\_PF1MFP\_XT1\_IN, SYS\_GPF\_MFPL\_PF1MFP\_X32\_IN.
    - Replaced SYS\_GPD\_MFPL\_PD3MFP\_UART0\_CTS with SYS\_GPD\_MFPL\_PD3MFP\_UART0\_nCTS.
    - Replaced SYS\_GPD\_MFPL\_PD3MFP\_UART0\_RTS with SYS\_GPD\_MFPL\_PD3MFP\_UART0\_nRTS.
- Sample code
  1. New sample code: LED\_Toggle, UART\_Wakeup\_LXT.
  2. Updated all USB samples: Reply USB 2.1 version only if SUPPORT\_LPM defined.
  3. Fixed BPWM\_DutySwitch: 100% duty issue.
  4. Fixed FMC\_IAP: Wrong project setting.
  5. Fixed PWM\_DutySwitch: 100% duty issue.
  6. Fixed USB\_Audio\_HID\_NAU8822: PD11 issue.
  7. Fixed USCI\_UART\_TxRx\_Function: Compilation error.

### Revision 3.00.001 (Released 2016-10-07)

---

- Primary release version.

### Important Notice

Nuvoton Products are neither intended nor warranted for usage in systems or equipment, any malfunction or failure of which may cause loss of human life, bodily injury or severe property damage. Such applications are deemed, "Insecure Usage".

Insecure usage includes, but is not limited to: equipment for surgical implementation, atomic energy control instruments, airplane or spaceship instruments, the control or operation of dynamic, brake or safety systems designed for vehicular use, traffic signal instruments, all types of safety devices, and other applications intended to support or sustain life.

All Insecure Usage shall be made at customer's risk, and in the event that third parties lay claims to Nuvoton as a result of customer's Insecure Usage, customer shall indemnify the damages and liabilities thus incurred by Nuvoton.

---

*Please note that all data and specifications are subject to change without notice.  
All the trademarks of products and companies mentioned in this datasheet belong to their respective owners.*