

Arm® Cortex®-M0
32-bit Microcontroller

NUC121/NUC125 Series CMSIS BSP

Revision History

The information described in this document is the exclusive intellectual property of Nuvoton Technology Corporation and shall not be reproduced without permission from Nuvoton.

Nuvoton is providing this document only for reference purposes of NuMicro microcontroller based system design. Nuvoton assumes no responsibility for errors or omissions.

All data and specifications are subject to change without notice.

For additional information or questions, please contact: Nuvoton Technology Corporation.

www.nuvoton.com

Revision 3.01.003 (Released 2019-6-19)

- I²C driver
 - Added error handling for new transfer.
- Timer driver
 - TIMER_GetModuleClock
 - Fixed correct PCLK.
- USB driver
 - Fixed potential issue.
- Sample code
 - ISP_HID, ISP_UART
 - New sample code for ISP Tool.
 - TIMER_Delay
 - Fixed correct PCLK.
 - USB_Audio_NAU8822, USB_Audio_HID_NAU8822
 - Clear FIFO before play / record.
 - All USB samples
 - Fixed potential issue.

Revision 3.01.002 (Released 2018-12-28)

- CMSIS
 - Upgraded to v5.1.1.
- CLK driver
 - CLK_PowerDown
 - Required HIRC/MIRC auto trim disabled.
- PDMA driver
 - PDMA_Open
 - Revised to support multi-open.
- Sample code
 - Fixed semihost build failure with GCC toolchain 7-2018-q2.
 - Keil projects use "NULink Debugger" instead of "Nuvoton Nu-Link Debugger".
 - I2S_PDMA_PlayRecord
 - Fixed race condition.
 - TIMER_CaptureCounter
 - Fixed array access overflow issue.
 - USB_VCOM samples
 - Fixed UART baud rate calculation.
 - USB_VCOM_And_HID_Transfer
 - Fixed buffer overflow issue.

Revision 3.01.001 (Released 2018-06-27)

- NuMicro.h
 - New header file.
- NUC121.h
 - Separated register declarations of each IP into distinct header files.

- USB driver
 - Fixed the issue of USB Control-In packet with the same size as endpoint limit.
- Sample code
 - Added Eclipse projects for GCC toolchain.
 - CLK_ClockDetector, HIRC_Trim, UART_Wakeup_LXT, ADC samples
 - Set analog pins as input mode and disabled digital input function.
 - PDMA_ScatterGather_PingPongBuffer
 - Added PDMA error handling.
 - UART_PDMA
 - Added UART error handling.
 - USCI_I2C_Monitor
 - New sample code.

Revision 3.00.003 (Released 2017-12-13)

- NUC121.h
 - TIMER_CTL_TRGDAC_Pos, TIMER_CTL_TRGDAC_Msk
 - Removed.
- I2C driver
 - I2C_ReadByteTwoRegs, I2C_ReadMultiBytesTwoRegs, I2C_WriteByteTwoRegs, I2C_WriteMultiBytesTwoRegs
 - Fixed high byte lost issue.
- SPI driver
 - I2S_Open
 - Improved I2S sample rate accuracy.
- TIMER driver
 - TIMER_TRG_TO_EADC
 - Replaced with TIMER_TRG_TO_ADC.
- USB driver
 - USBD_L1RESUME
 - Replaced with USBD_STATE_L1RESUME.
 - USBD_L1SUSPEND
 - Replaced with USBD_STATE_L1SUSPEND.
- USCI-I2C driver
 - UI2C_ReadByteTwoRegs, UI2C_ReadMultiBytesTwoRegs, UI2C_WriteByteTwoRegs, UI2C_WriteMultiBytesTwoRegs
 - Fixed high byte lost issue.
- USCI-UART driver
 - UART_Open, UART_SetLine_Config
 - Fixed wrong baud rate issue.

Revision 3.00.002 (Released 2017-03-09)

- NUC121.h
 - BPWM0_IRQn, BPWM1_IRQn
 - New definition.
- BPWM driver
 - BPWM_ConfigOutputChannel
 - Fixed 100% duty issue.

- CLK driver
 - CLK_CLKSEL1_ADCSEL_HIRC_DIV2
 - Replaced with CLK_CLKSEL1_ADCSEL_HIRC.
 - GPIOA_MODULE, GPIOB_MODULE, GPIOC_MODULE, GPIOD_MODULE, GPIOE_MODULE, GPIOF_MODULE
 - Fixed definition.
- I²C driver
 - I2C_CLEAR_WAKEUP_WR_STATUS
 - Redundant, removed.
- PWM driver
 - PWM_ConfigOutputChannel
 - Fixed 100% duty issue.
- SYS driver
 - SYS_GPD_MFPL_PD3MFP_UART0_CTS
 - Replaced with SYS_GPD_MFPL_PD3MFP_UART0_nCTS.
 - SYS_GPD_MFPL_PD3MFP_UART0_RTS
 - Replaced with SYS_GPD_MFPL_PD3MFP_UART0_nRTS.
 - SYS_GPF_MFPL_PF0MFP_XT1_OUT, SYS_GPF_MFPL_PF0MFP_X32_OUT, SYS_GPF_MFPL_PF1MFP_XT1_IN, SYS_GPF_MFPL_PF1MFP_X32_IN
 - New definition for backward compatible.
- Sample code
 - BPWM_DutySwitch
 - Fixed 100% duty issue.
 - FMC_IAP
 - Fixed wrong project setting.
 - LED_Toggle
 - New sample code.
 - PWM_DutySwitch
 - Fixed 100% duty issue.
 - UART_Wakeup_LXT
 - New sample code split from UART_Wakeup due to NUC121-B tiny board removed LXT.
 - USB_D_Audio_HID_NAU8822
 - Fixed PD11 issue.
 - All USB samples
 - Replied USB 2.1 version only if SUPPORT_LPM defined.
 - USCI_UART_TxRx_Function
 - Fixed compilation error.

Revision 3.00.001 (Released 2016-10-07)

- Primary release version.

Important Notice

Nuvoton Products are neither intended nor warranted for usage in systems or equipment, any malfunction or failure of which may cause loss of human life, bodily injury or severe property damage. Such applications are deemed, "Insecure Usage".

Insecure usage includes, but is not limited to: equipment for surgical implementation, atomic energy control instruments, airplane or spaceship instruments, the control or operation of dynamic, brake or safety systems designed for vehicular use, traffic signal instruments, all types of safety devices, and other applications intended to support or sustain life.

All Insecure Usage shall be made at customer's risk, and in the event that third parties lay claims to Nuvoton as a result of customer's Insecure Usage, customer shall indemnify the damages and liabilities thus incurred by Nuvoton.

*Please note that all data and specifications are subject to change without notice.
All the trademarks of products and companies mentioned in this datasheet belong to their respective owners.*