

ARM[®] Cortex[®]-M0
32-bit Microcontroller

NuMicro[®] Family
NANO100BN Series CMSIS BSP
Revision History

The information described in this document is the exclusive intellectual property of Nuvoton Technology Corporation and shall not be reproduced without permission from Nuvoton.

Nuvoton is providing this document only for reference purposes of NuMicro microcontroller based system design. Nuvoton assumes no responsibility for errors or omissions.

All data and specifications are subject to change without notice.

For additional information or questions, please contact: Nuvoton Technology Corporation.

www.nuvoton.com

Revision 3.03.000 (Released 2018-05-30)

1. Added Eclipse project support.
2. Minor bug fix.

Revision 3.02.002 (Released 2017-03-10)

1. Fixed INTR_T structure base address definition error.
2. Fixed smartcard driver and library behaviors that do not comply with EMV2000 spec.
3. Fixed CCID sample bug that incorrect error code is returned.
4. Fixed the bug that time-out interrupt flag is cleared at wrong time in I2C_Loopback sample code.
5. Fixed USBD_Audio_Speaker sample code interrupt control error.
6. Added Interface Association Descriptor(IAD) in USBD_Audio_Speaker_And_HID_Transfer sample code.
7. Updated SC_ReadSimPhoneBook sample code to support SIM card with CHV1 disabled.

Revision 3.02.001 (Released 2016-07-28)

1. Updated CMSIS to v4.5.0.
2. Added sample codes including USBD_HID_Transfer_CTRL, USBD_Vendor_LBK, and USBD_Mass_Storage_SDCard.
3. Fixed the HIDTransferTest.exe bug to use correct sector size to compare data.
4. Updated HIDTransferTest.exe to support the connection of the composite device with HID interface number other than 0.
5. Fixed the USBD_VCOM_SerialEmulator, USBD_VCOM_DualPort, USBD_VCOM_And_Mass_Storage, USBD_VCOM_And_HID_Transfer, and USBD_VCOM_And_HID_Keyboard samples bug to ensure SET_LINE_CODE command is properly handled.
6. Minor bug fixes.

Revision 3.02.000 (Released 2015-08-07)

1. Removed FMC driver's FMC_SetBootSource(),FMC_DisableAPUpdate(),FMC_DisableConfigUpdate(),FMC_DisableLDUpdate(),FMC_EnableAPUpdate(),FMC_EnableConfigUpdate(),FMC_EnableLDUpdate() in fmc.h, because there exist functionally identical macros.
2. Removed SYS_IRCTRIMCTL_SEL_MASK, SYS_IRCTRIMCTL_LOOP_MASK and SYS_IRCTRIMCTL_RETRY_COUNT in sys.h.
3. Removed SPI_ENABLE_DUAL_MODE() in spi.h.
4. Modified SPI_ENABLE_DUAL_INPUT_MODE() and SPI_ENABLE_DUAL_OUTPUT_MODE() to enable dual I/O with direction.
5. Modified USBD driver to pass USB Command Verify test in usbd.c and usbd.h.
6. Modified UART_SelectIrDAMode() to reload UART clock before calculating baudrate, in uart.c.
7. Modified SD card clock speed from 24 MHz to 5 MHz to make SPI operations stable in SDCard.c.

8. Modified MMC_FLASH_Init() to retry SD CMD0 command until success in SDCard.c.
9. Modified TIMER_Open() to not start timer in timer.c.
10. Updated TIMER_Open() and TIMER_Delay() to support extreme high clock input, in timer.c.
11. Renamed sample CRC to CRC_CCITT in StdDriver.
12. Renamed sample GPIO to GPIO_IOTest in StdDriver.
13. Renamed sample PDMA to PDMA_Memory in StdDriver.
14. Renamed sample SYS to SYS_Control in StdDriver.
15. Renamed SYS_Int_xxx_Msk to SYS_xxx_Msk in sys.h.
16. Renamed GP_DBNCECON_PUEN_* to GP_DBNCECON_DBCLKSEL_* in Nano100Series.h.
17. Renamed SYS_IRCTRIMINT_32KERR_ENNT to SYS_IRCTRIMINT_32KERR_INT in sys.h.
18. Fixed the bug that RTC_AER enable flow may be interrupted by interrupt service routine in rtc.c.
19. Fixed the bug that PWM_ENABLE_OUTPUT_INVERTER() does not clear register field before writing input parameter to it in pwm.h.
20. Fixed the bug that TIMER_Delay() sets prescale to wrong register in timer.c.
21. Fixed SCUART_Open() and SCUART_SetLineConfig() baudrate calculation prescale setting error in scuart.c.
22. Fixed bugs of SPI_EnableAutoSS () and SPI_SetBusClock () in spi.c, and cleared bit mask of register field before writing input parameter to it.
23. Fixed the CLK_SysTickDelay() bug that continuously calling CLK_SysTickDelay() may imply an incorrect delay time by clearing control register on each call in clk.c.
24. Fixed implementation errors of CLK_PLLCTL_FB_DV_Msk and CLK_APBCLK_I2C0_EN in Nano100Series.h.
25. Fixed SYS_CLEAR_RST_SOURCE implementation error in sys.h.
26. Fixed CLK_WK_INTSTS_IS implementation error in clk.h.
27. Fixed "GPIO_DISABLE_DOUT_MASK" and "GPIO_ENABLE_DOUT_MASK" implementation errors in gpio.h.
28. Fixed SC_SET_STOP_BIT_LEN implementation error in sc.h.
29. Fixed PDMA_IS_CH_BUSY implementation error in pdma.h.
30. Fixed LCD_CPUMP_DIV128 implementation error in lcd.h.
31. Fixed RTC_CLEAR_TAMPER_FLAG() implementation bug in rtc.h.
32. Fixed ADC_SET_DMOF() implementation error in adc.h.
33. Fixed CRC_SET_SEED ()implementation error in crc.h.
34. Disabled Rx before raising RST high during cold reset in SmartCardLib library.
35. Checked SC_RST and SC_DAT_O pin status during deactivation in SmartCardLib library.
36. Added SYS_PA_H_MFP_PA9_MFP_LCD_S7 macro in sys.h.
37. Added I2C_ClearIntFlag() and I2S_SetFIFO() functions in i2c.c.
38. Added bit definitions of MCLKO (Module Clock CKO) register in clk.h.
39. Added LCD_MODULE and DAC_MODULE macro sets in clk.c.
40. Added CLK_EnableSysTick() and CLK_DisableSysTick() in clk.c.
41. Added macros CLK_PLLCTL_*MHz_HXT and CLK_PLL_*MHz_HIRC for setting PLLCTL value in clk.c.
42. Added SYS_EnableIRCTrim() and SYS_DisableIRCTrim() functions in sys.c, and added macros SYS_GET_IRCTRIM_INT_FLAG() and SYS_CLEAR_IRCTRIM_INT_FLAG() in sys.h.
43. Added UART_SelectLINMode() in uart.c, and added UART_FUNC_SEL_LIN in uart.h.
44. Added a sample USBDAudio_Speaker_And_HID_Transfer to Nu-LB-NANO130.

45. Added samples SYS_MCLKO, SYS_PLLClockOutput, and SYS_TrimIRC to StdDriver.
46. Added a sample Timer_Wakeup to StdDriver.
47. Added samples USBD_HID_Keyboard, USBD_HID_MouseKeyboard, USBD_HID_Touch, USBD_HID_Transfer_And_Keyboard, USBD_HID_Transfer_And_MSC, USBD_Mass_Storage_CDRom, USBD_Micro_Printer, USBD_Printer_And_HID_Transfer, USBD_VCOM_And_HID_Keyboard, USBD_VCOM_And_HID_Transfer, USBD_VCOM_And_Mass_Storage, USBD_VCOM_DualPort, and USBD_VCOM_SerialEmulator to StdDriver.

Revision 3.01.000 (Released 2014-09-19)

1. Renamed register TESTCLK to MCLKO.
2. Renamed registers PDSSR0 and PDSSR1 to DSSR0 and DSSR1.
3. Renamed UBSD_ENABLE_INT() to USBD_ENABLE_INT().
4. Renamed I2S_Enable_MCLK()/I2S_Disable_MCLK() to I2S_EnableMCLK()/I2S_DisableMCLK().
5. Renamed
CLK_CLKSEL1_PWM1_CH01_S_Msk/CLK_CLKSEL1_PWM1_CH23_S_Msk to
CLK_CLKSEL2_PWM1_CH01_S_Msk/CLK_CLKSEL2_PWM1_CH23_S_Msk.
6. Renamed RTC_RIIR_SNOOPIS_Msk to RTC_RIIR_SNOOPIF_Msk.
7. Renamed PDMA_IER_BLKD_IE_Msk to PDMA_IER_TD_IE_Msk.
8. Modified PWM_EnablePDMA() function prototype, and added one more parameter to select captured edge.
9. Modified PWM capture interrupt flag relative macro definitions to improve performance.
10. Added ADC clock source bit position and mask definition.
11. Added ADC_SET_REF_VOLTAGE() macro and RES/REF definitions.
12. Added DAC driver.
13. Added ADC_Compare, ADC_TimerTrigger, ADC_PDMA, DAC_PDMATrigger, DAC_SoftwareTrigger, DAC_TimerTrigger, GPIO_PowerDown, Hard_Fault_Sample, PWM_CapturePDMA, SPI_LoopbackPDMA, UART_FlowCtrl, UART_TxRxDMA, and USBD_HID_Transfer samples.

Revision 3.00.000 (Released 2014-02-20)

1. Update major version number from 2 to 3.
2. Renamed RTC_GetDatAndTime() to RTC_GetDateAndTime().

Revision 2.00.000 (Released 2014-01-11)

1. Primary release version.

Important Notice

Nuvoton Products are neither intended nor warranted for usage in systems or equipment, any malfunction or failure of which may cause loss of human life, bodily injury or severe property damage. Such applications are deemed, "Insecure Usage".

Insecure usage includes, but is not limited to: equipment for surgical implementation, atomic energy control instruments, airplane or spaceship instruments, the control or operation of dynamic, brake or safety systems designed for vehicular use, traffic signal instruments, all types of safety devices, and other applications intended to support or sustain life.

All Insecure Usage shall be made at customer's risk, and in the event that third parties lay claims to Nuvoton as a result of customer's Insecure Usage, customer shall indemnify the damages and liabilities thus incurred by Nuvoton.

*Please note that all data and specifications are subject to change without notice.
All the trademarks of products and companies mentioned in this datasheet belong to their respective owners.*