


COLUMBIA CHIMNEY SERVICES
8630 - M Guilford Rd.
Suite #301
Columbia, MD 21046
Phone: 410-997-3181
Email: rob@columbiachimney.com

Name: Arny Marshall
Address: 5451 El Camino
City Columbia State MD Zip 21044-1111
Phone (410) 971-0797
E-mail bjmar867@gmail.com
Technician Robert Waid
Service Date 12/17/2024 Time 10:11 AM

Fireplace:	<input type="checkbox"/> Masonry	<input checked="" type="checkbox"/> Prefab	<input type="checkbox"/> FPO	<input type="checkbox"/> Model #	Heatlitor EL 36
Appliance:	<input type="checkbox"/> F-S Stove	<input type="checkbox"/> Insert	<input type="checkbox"/> Furnace	B.T.U.	Collar <input type="text"/>
Type of Fuel:	<input checked="" type="checkbox"/> Wood	<input type="checkbox"/> Pellet	<input type="checkbox"/> Oil	<input type="checkbox"/> Gas	<input type="checkbox"/> Other: <input type="text"/>
Chimney:	<input type="checkbox"/> Masonry	<input checked="" type="checkbox"/> Prefab	<input type="checkbox"/> Other	<input checked="" type="checkbox"/> Flue Height	Approximately 25'
Liner:	<input checked="" type="checkbox"/> Stainless	<input type="checkbox"/> Tile	<input type="checkbox"/> Cast	<input type="checkbox"/> Unlined	<input type="checkbox"/> Serial # AL 958759
Flue Size:	<input type="checkbox"/> 8x8	<input type="checkbox"/> 6"R	<input type="checkbox"/> 8x13	<input type="checkbox"/> 13x13	<input type="checkbox"/> I.D. <input type="text"/>
HE:	<input type="checkbox"/> HEH	<input checked="" type="checkbox"/> 8"R	<input type="checkbox"/> 10"R	<input type="checkbox"/> 11"R	<input type="checkbox"/> Other: <input type="text"/>



12/17/24...PREFAB FACTORY BUILT WOOD BURNING FIREPLACE ; Laid out flooring protection, swept up deposits in firebox and performed a level 1 inspection. Chimney flue system does not require sweeping at this time. Smoke stains above fireplace opening indicate spillage of heated gases during operation. Cause may be due to user error / failure to open damper prior to operating. The unattached 3 panel mesh spark screen located in front of fireplace opening may be a contributing factor, is potentially restrictive and not approved for use by the fireplace manufacturer. Operation with 3 panel mesh spark screen is a potential health hazard. The log grate is warped with loss of material, condition may adversely affect intended operation and will likely contribute to further deterioration of hearth and rear refractory panels. Damper is now closed. We will acquire and review fireplace install manual to verify if any venting grills are concealed or restricted.

The National Fire Protection Association (NFPA) recommends annual inspection of all fireplaces, chimneys, and vents. The next inspection of your system is scheduled for:

This report is the result of a visual inspection done at the time of cleaning. It is intended as a convenience to our customer, not as certification of fire worthiness or safety. Since conditions of use and hidden construction defects are beyond our control, no warranty is made for the safety or function of any appliance and none is to be implied.

I have read this form and understand the apparent condition of my fireplace, appliance, chimney, and/or vent system. Furthermore I understand the limitations of this report as given in the paragraph above.

Description	Price
Level 1 Inspection	\$349.00
Credit fee \$ 10.47	
Paid \$359.47	
Invoices unpaid after 30 days will be charged 1.5% interest per month (18% APR).	Subtotal \$359.47
	Total \$359.47