

# Engine Health Report

Generated on: 2025-02-06 03:19:42

```markdown

## Executive Summary

This report details a critical health assessment of the aircraft engine, revealing a significant anomaly detected in the blade analysis and corroborated by sensor data indicating imminent engine failure. A blade fracture was identified, accompanied by an elevated anomaly score. Real-time sensor measurements at cycle 263 further confirm this concerning state, displaying values that align with known pre-failure patterns, as indicated by the "VERY BAD" prediction. Immediate intervention is required to prevent catastrophic engine failure.

## Blade Condition Analysis

The blade analysis returned a concerning Anomaly Score of 0.475, indicating a deviation from expected operational parameters. This score, in conjunction with the confirmed **fracture** observed in the blade condition, represents a severe structural integrity compromise. Anomaly scores approaching or exceeding 0.5 typically correlate with significant damage and increased risk of failure. The presence of a physical fracture necessitates immediate engine shutdown and thorough inspection. This combination of a high anomaly score and a confirmed fracture unequivocally points to a critical engine health issue.

## Sensor Data Analysis

The following sensor data was recorded at cycle 263:

- **Operating Settings:** Stable operating settings were observed, with ``operating_setting_1`` at 10.0077 and ``operating_setting_2`` at 0.2501. ``operating_setting_3`` was at a constant 100. These readings, while seemingly normal, must be considered in the context of the blade fracture.
- **Temperature Measurements:** ``Primary_temperature`` at 489.05°C, ``secondary_temperature`` at 604.86°C, ``tertiary_temperature`` at 1507.7°C, and

`quaternary\_temperature` at 1318.06°C. While individually within nominal ranges, potential fluctuations may not be evident in a single snapshot, the tertiary and quaternary temperatures should be monitored closely, these can reflect reduced compressor efficiency associated with blade degradation.

- **Pressure Measurements:** `Primary\_pressure` at 10.52 kPa, `secondary\_pressure` at 15.47 kPa, `tertiary\_pressure` at 401.91 kPa, and `quaternary\_pressure` at 2319.43 kPa. The downstream pressures may be showing signs of instability with the fractured blade.
- **Speed Measurements:** `Primary\_speed` at 8816.35 RPM, `secondary\_speed` at 1.27, `tertiary\_speed` at 45.7, and `quaternary\_speed` at 379.16. These speeds show no immediate red flags, however deviations can occur rapidly with structural failure
- **Vibration Measurements:** `Primary\_vibration` at 2388.61 Hz and `secondary\_vibration` at 8170.26 Hz. The secondary vibration reading is notably elevated and a very large anomaly. High vibration levels are commonly observed preceding or during blade failures, confirming the blade fracture findings.
- **Flow Measurements:** `Primary\_flow` at 8.4897 kg/s, `secondary\_flow` at 0.03, `tertiary\_flow` at 372, `pressure\_ratio` is 2319, `efficiency\_indicator` at 100%, `power\_setting` at 28.85, `fuel\_flow\_rate` at 17.3519 kg/s. These parameters do not indicate any major deviations from normal operation given the recorded cycle.

The provided sensor data, particularly the elevated secondary vibration and the "VERY BAD" prediction reinforces the critical nature of the blade fracture. The "VERY BAD" prediction derived from a sophisticated predictive model leveraging historical data, strongly suggests an imminent failure if corrective action is not taken.

## Health Status Assessment

Based on the combined analysis of blade condition and sensor data, the engine's health status is critically compromised. The confirmed blade fracture and elevated anomaly score, coupled with sensor readings flagging high vibration and a "VERY BAD" prediction indicate a high probability of catastrophic engine failure in the near term. The engine is considered unsafe for continued operation.

## Recommendations

Immediate actions are required:

1. **Immediate Engine Shutdown:** The engine must be shut down immediately to prevent further damage and potential catastrophic failure.

2. **Comprehensive Inspection:** A thorough borescope inspection and physical examination of the engine, including all blades, is mandatory.

3. **Blade Replacement/Engine Overhaul:** Depending on the extent of the damage identified during the inspection, blade replacement or a complete engine overhaul is recommended.

4. **Data Review and Model Recalibration:** Re-evaluate historical sensor data in light of this failure to improve the accuracy of the predictive model and identify potential precursor indicators.

5. **Vibration Monitoring System Enhancement:** Investigate the possibility of enhanced real-time vibration monitoring systems to improve early detection capabilities.

...