

# QorIQ LS1046A Reference Design Board

## Errata

This document lists and describes all known errata for the LS1046ARDB. It also provides available workaround with detailed explanation, wherever required, for each erratum.

The table below lists the revision history of this document.

**Table 1. Revision history**

Revision	Date	Description
Rev. 0	10/2018	Initial public release

This table summarizes all known errata and their workarounds for the LS1046ARDB.

**Table 2. LS1046ARDB errata summary**

Errata	Name	Workaround	Applicable PCB revision	Applicable schematics (SCH-29142) revision
<a href="#">E-00001</a>	AQR107-ES2 MDIO voltage configuration changed as per ES2 part requirements	Remove R70 (0 $\Omega$ ) and populate R69 (4.99 K $\Omega$ )	Rev. B	Rev. B
<a href="#">E-00002</a>	When SFP+ module is inserted, its I2C address conflicts with that of SPD	Cut SFP cage's I2C traces	Rev. B	Rev. B
<a href="#">E-00003</a>	FA_VL pin is connected to VDD	Remove the J13 shunt	Rev. B	Rev. B or B1

The table below lists the additional documents that you can refer to, for more information about the LS1046ARDB. Some of the documents listed below may be available only under a non-disclosure agreement (NDA). To request access to such documents, contact your local field applications engineer or sales representative.



**Table 3. Related documentation**

Document	Description	Web link
QorIQ LS1046A Reference Design Board Reference Manual (LS1046ARDBRM)	Explains the LS1046ARDB interfaces and configuration	<a href="#">LS1046ARDB product summary page - Documentation tab</a>
QorIQ LS1046A Reference Design Board Getting Started Guide (LS1046ARDBGSG)	Describes the LS1046ARDB hardware kit, provides settings for the onboard switches, connectors, jumpers, and LEDs, and explains the basic board operations in a step-by-step manner	
Updating SDK Images on QorIQ LS1046ARDB Application Note (AN5340)	Describes how to deploy U-Boot, Linux kernel, and root file system on the QorIQ LS1046ARDB using QorIQ SDK images	
QorIQ LS1046A BSP v0.4 (QORIQ-LS1046A-BSP)	Provides detailed information about QorIQ LS1046A BSP v0.4	
QorIQ LS1046ARDB Schematics (SCH-29142)	Provides detailed information about the LS1046ARDB circuitry	<a href="#">LS1046ARDB product summary page - Software and Tools tab</a> (bundled with the LS1046ARDB design file package)
QorIQ LS1046A Reference Manual (LS1046ARM)	Provides a detailed description of the LS1046A multicore processor and its features, such as the memory map, serial interfaces, power supply, chip features, and clock information	<a href="#">LS1046A product summary page</a>
QorIQ LS1046A Data Sheet (LS1046A)	Contains information on LS1046A pin assignments, electrical characteristics, hardware design considerations, package information, and ordering information	
QorIQ LS1046A Design Checklist (AN5252)	Provides recommendations for new designs based on the LS1046A/LS1026A processor	This document is currently under NDA. After it becomes public, it will be posted at the <a href="#">LS1046A product summary page</a> .

**NOTE**

In case of any mismatch between the board schematics and SoC datasheet, the SoC datasheet is recommended to be followed.

## E-00001: AQR107-ES2 MDIO voltage configuration changed as per ES2 part requirements

**Description:** As per AQR107-ES2 revision A0, the polarity of MDIO\_1P2\_SELECT\_N is inverted as follows:

- When pulled low, the voltage level is 1.8 V - 2.1 V
- When pulled high, the voltage level is 2.5 V - 3.3 V

**Impact:** AQR107 firmware cannot be programmed and MDIO cannot work.

**Workaround:** Remove R70 (0  $\Omega$ ) and populate R69 (4.99 K $\Omega$ ).




Figure 1. E-00001 workaround

**Fix plan:** The above mentioned rework has been implemented on all revision B boards. Starting board revision B1, no rework is needed.

## E-00002: When SFP+ module is inserted, its I2C address conflicts with that of SPD

**Description:** When SFP+ module is inserted into the LS1046ARDB, then an I2C address conflict happens between SFP+ module and SPD.

**Impact:** Board stops booting if SFP+ module is inserted.

**Workaround:** Follow these steps:

1. Cut off top layer trace I2C1\_SDA and I2C1\_SCL before and after vertical interconnect access (via) (1900.60 4402.20) and via (1947.42 4375.42).
2. Fly wire from via (2100.20 3702.90) to pin 5 of U22.
3. Fly wire from via (2065.00 3748.60) to pin 4 of U22.

E-00002: When SFP+ module is inserted, its I2C address conflicts with that of SPD




Figure 2. Rework demonstrated on PCB layout




Figure 3. Rework implemented on PCB assembly (PCBA)

After the rework, SFP+ module cannot be accessed through I2C1.



**Fix plan:** The above mentioned rework needs to be implemented on all revision B boards. Starting board revision B1, no rework is needed. On the PCB Gerber file, I2C connection is disconnected from the SFP slot.

## E-00003: FA\_VL pin is connected to VDD

**Description:** The FA\_VL pin has a jumper (J13) to select GND or VDD. On some early-shipped boards, J13 is shorted. The J13 shunt needs to be removed to select GND.

**Impact:** This may impact Linux kernel stability.

**Workaround:** Remove the J13 shunt.




Figure 4. E-00003 workaround

**Fix plan:** The J13 shunt must be removed from all boards with revision B or later.

## **How To Reach Us**

### **Home Page:**

[nxp.com](http://nxp.com)

### **Web Support:**

[nxp.com/support](http://nxp.com/support)

Information in this document is provided solely to enable system and software implementers to use NXP products. There are no express or implied copyright licenses granted hereunder to design or fabricate any integrated circuits based on the information in this document. NXP reserves the right to make changes without further notice to any products herein.

NXP makes no warranty, representation, or guarantee regarding the suitability of its products for any particular purpose, nor does NXP assume any liability arising out of the application or use of any product or circuit, and specifically disclaims any and all liability, including without limitation consequential or incidental damages. "Typical" parameters that may be provided in NXP data sheets and/or specifications can and do vary in different applications, and actual performance may vary over time. All operating parameters, including "typicals," must be validated for each customer application by customer's technical experts. NXP does not convey any license under its patent rights nor the rights of others. NXP sells products pursuant to standard terms and conditions of sale, which can be found at the following address: [nxp.com/SalesTermsandConditions](http://nxp.com/SalesTermsandConditions).

While NXP has implemented advanced security features, all products may be subject to unidentified vulnerabilities. Customers are responsible for the design and operation of their applications and products to reduce the effect of these vulnerabilities on customer's applications and products, and NXP accepts no liability for any vulnerability that is discovered. Customers should implement appropriate design and operating safeguards to minimize the risks associated with their applications and products.

NXP, the NXP logo, Freescale, the Freescale logo, CodeWarrior, Layerscape, and QorIQ are trademarks of NXP B.V. All other product or service names are the property of their respective owners. Arm and Cortex are trademarks or registered trademarks of Arm Limited (or its subsidiaries) in the US and/or elsewhere. The related technology may be protected by any or all of patents, copyrights, designs and trade secrets. All rights reserved.

© NXP B.V. 2019.

All rights reserved.

For more information, please visit: <http://www.nxp.com>

For sales office addresses, please send an email to: [salesaddresses@nxp.com](mailto:salesaddresses@nxp.com)

Date of release: 15 October 2018

Document identifier: LS1046ARDBE

The logo for Arm, consisting of the word "arm" in a lowercase, blue, sans-serif font.