

08/06/21

Welding.

Parth Tohra
2K20/B17/33

The process of joining different metals:->

• Arc Welding: Process in which source of heat is electricity i.e. coalescence is brought about heating the workplace with an electric arc struck b/w an electrode and the work piece.

The filler material has similar composition & melting point temp. as the base metal. It is used to fill gap b/w the joint surfaces.

• Resistance Welding: Process which is coalescence is produced by the heat obtained from resistance of the work to the flow of electric current in a circuit of which work is a part and by application of pressure.

Practical Applications of Welding:

★ Aircraft Construction

★ Automobile

★ Pippings & pipelines

★ Ships

★ Repair of broken & damaged components of machinery


★ Bridges

★ Buildings

★ Storage tanks

Welding Terminology

Parth Johri
2K20/BI7/33



Base metal → Original metal being joined.

Bead metal → Deposited Metal

Weld metal → Part of Base metal that has melted

Flux → Providing shielding to keep gases out.

Ripple → Shape of the bead.

Pass → Each layer of bead weld deposited

Crater → Depression in the base metal.

Penetration → Depth of fusion with metal

Arc Length → Distance from electrode to metal


Weldface → Exposed surface of weld.

Porosity → Voids of gas pockets in the weld.


Spatter → Metal particles expelled during welding.

Welded joints


Bull joint = a joint b/w two members aligned appear in same plane




Corner joint = a joint b/w two members located at right angles to each other







T joint = a joint between two members located appear at right angles to each other in the form of T.



Lap joint = a joint b/w two overlapping members



Edge joint = A joint between the edges of two or more parallel or nearly parallel members



(Square-Groove)



(U-Groove)

Fig (vi)