



# G12 Circular Pocket Milling CW / G13 Circular Pocket Milling CCW (Group 00)

These G-codes mill circular shapes. They are different only in that *G12* uses a clockwise direction and *G13* uses a counterclockwise direction. Both G-codes use the default *XY* circular plane (*G17*) and imply the use of *G42* (cutter compensation) for *G12* and *G41* for *G13*. *G12* and *G13* are non-modal.

\* **D** - Tool radius or diameter selection\*\*

**F** - Feedrate

**I** - Radius of first circle (or finish if no *K*). *I* value must be greater than Tool Radius, but less than *K* value.

\* **K** - Radius of finished circle (if specified)

\* **L** - Loop count for repeating deeper cuts

\* **Q** - Radius increment, or stepover (must be used with *K*)

**Z** - Depth of cut or increment

\*indicates optional

\*\*To get the programmed circle diameter, the control uses the selected *D* code tool size. To program tool centerline select *D0*.

NOTE	Specify <i>D00</i> if you do not want to use cutter compensation. If you do not specify a <i>D</i> value in the <i>G12</i> / <i>G13</i> block, the control uses the last commanded <i>D</i> value, even if it was previously canceled with a <i>G40</i> .
------	---

Rapid-position the tool to the center of the circle. To remove all the material inside the circle, use *I* and *Q* values less than the tool diameter and a *K* value equal to the circle radius. To cut a circle radius only, use an *I* value set to the radius and no *K* or *Q* value.

%

O60121(SAMPLE G12 AND G13) ;

(G54 X0 Y0 is center of first pocket) ;

(Z0 is on top of the part) ;

(T1 is a .25 in. dia endmill) ;

(BEGIN PREPARATION BLOCKS) ;

T1 M06 (Select tool 1) ;

G00 G90 G40 G49 G54 (Safe startup) ;

G00 G54 X0 Y0 (Rapid to 1st position) ;

S1000 M03 (Spindle on CW) ;

G43 H01 Z0.1 (Tool offset 1 on) ;

M08 (Coolant on) ;

(BEGIN CUTTING BLOCKS) ;

G12 I0.75 F10. Z-1.2 D01 (Finish pocket CW) ;

G00 Z0.1 (Retract) ;

X5.(Move to center of next pocket) ;

G12 I0.3 K1.5 Q1. F10. Z-1.2 D01 ;

(Rough & finish CW) ;

G00 Z0.1 (Retract) ;

X10.(Move to center of next pocket) ;

G13 I1.5 F10. Z-1.2 D01 (Finish CCW) ;


G00 Z0.1 (Retract) ;

X15. (Move to center of the last pocket) ;

G13 I0.3 K1.5 Q0.3 F10. Z-1.2 D01 ;

```
(Rough & finish CCW) ;
(BEGIN COMPLETION BLOCKS) ;
G00 Z0.1 M09 (Rapid retract, Coolant off) ;
G53 G49 Z0 M05 (Z home, Spindle off) ;
G53 Y0 (Y home) ;
M30 (End program) ;
%
```

Circular Pocket Milling, G12 Clockwise shown: [1] I only, [2] I, K and Q only.



These G codes assume cutter compensation, so you do not need to program *G41* or *G42* in the program block. However, you must include a *D* offset number, for cutter radius or diameter, to adjust the circle diameter.

These program examples show the *G12* and *G13* format, and the different ways that you can write these programs.

Single Pass: Use *I* only.

Applications: One-pass counter boring; rough and finish pocketing of smaller holes, ID cutting of O-ring grooves.

Multiple Pass: Use *I*, *K*, and *Q*.

Applications: Multiple-pass counter boring; rough and finish pocketing of large holes with cutter overlap.

Multiple Z-Depth Pass: Using *I* only, or *I*, *K*, and *Q* (*G91* and *L* may also be used).

Applications: Deep rough and finish pocketing.

The previous figures show the tool path during the pocket milling G-codes.

Example *G13* multiple-pass using *I*, *K*, *Q*, *L*, and *G91*:

This program uses *G91* and an *L* count of 4, so this cycle will execute a total of four times. The *Z* depth increment is 0.500. This is multiplied by the *L* count, making the total depth of this hole 2.000.

The *G91* and *L* count can also be used in a *G13I* only line.

```
%
O60131 (G13 G91 CCW EXAMPLE) ;
(G54 X0 Y0 is center of 1st pocket) ;
(Z0 is on top of the part) ;
(T1 is a 0.5 in. dia endmill) ;
(BEGIN PREPARATION BLOCKS) ;
T1 M06 (Select tool 1) ;
G00 G90 G40 G49 G54 (Safe startup) ;
G00 G54 X0 Y0 (Rapid to 1st position) ;
S1000 M03 (Spindle on CW) ;
```



```
G43 H01 Z0.1 (Activate tool offset 1) ;  
M08 (Coolant on) ;  
(BEGIN CUTTING BLOCKS) ;  
G13 G91 Z-.5 I.400 K2.0 Q.400 L4 D01 F20. ;  
(Rough & finish CCW) ;  
(BEGIN COMPLETION BLOCKS) ;  
G00 G90 Z0.1 M09 (Rapid retract, coolant off) ;  
G53 G49 Z0 M05 (Z home, spindle off) ;  
G53 Y0 (Y home) ;  
M30 (End program) ;  
%
```

---