

8 密级状态：绝密() 秘密() 内部() 公开(√)

ATV_Android_8.0_WiFi_BT_移植和问题汇总

(技术部，系统产品一部)

文件状态： [√] 正在修改 [] 正式发布	当前版本：	V1.0
	作 者：	许学辉
	完成日期：	2017-12-20
	审 核：	
	完成日期：	

福州瑞芯微电子有限公司

Fuzhou Rockchips Semiconductor Co., Ltd

(版本所有, 翻版必究)

版本历史

[illegible]

目 录

1	说明	2
1.1	WIFI 移植内核部分	2
1.2	蓝牙移植内核部分	4
2	WIFI BT 兼容 ANDROID 部分	6
2.1	WIFI 芯片识别流程	6
2.1	WPA_SUPPLICANT 启动部分修改	7
3	WIFI BUG 汇总	11
4	BT BUG 汇总	17
5	WIFI KO 编译注意事项	20
6	WIFI 驱动加载方式说明	23
7	WIFI 、BT DTS 配置	24
7.1	KERNEL 4.4 平台	24
7.2	KERNEL 3.10 平台	25

1 说明

明确 ATV android .1 平台上 wifi、bt 内核相关部分修改, 自测遇到的 BUG, 方便以后 android 版本移植

1.1 WIFI 移植内核部分

wifi 全自动兼容方案 AP6xxx 系列 wifi 和 Realtek 系列 wifi 驱动都已经全部采用 module 方式, 该部分兼容代码跟以前 Android 7.1 实现原理完全一样。

最新内核代码,:

CONFIG_WL_ROCKCHIP=y

CONFIG_WIFI_BUILD_MODULE=y

CONFIG_WIFI_LOAD_DRIVER_WHEN_KERNEL_BOOTUP=y

CONFIG_AP6XXX=m

CONFIG_RTL_WIRELESS_SOLUTION=y

CONFIG_RTL8188EU=m

CONFIG_RTL8188FU=m

CONFIG_RTL8189ES=m

CONFIG_RTL8189FS=m

CONFIG_RTL8723BS=m

CONFIG_RTL8723BU=m

CONFIG_RTL8723CS=m

CONFIG_RTL8723DS=m

CONFIG_RTL8822BE=m

Device Drivers --->

[*] Network device support --->

[*] Wireless LAN --->

```
--- Wireless LAN
[*] wifi load driver when kernel bootup
[*] Realtek wireless Device Driver Support --->
[*] Espressif 8089 sdio Wi-Fi
<M> RK901/RK903/BCM4330/AP6XXX wireless cards support

--- Realtek wireless Device Driver Support
<M> Realtek 8188E USB WiFi
<M> Realtek 8189ES/ETV SDIO WiFi Support
< > Realtek 8192CU USB WiFi Support
< > Realtek 8192DU USB WiFi Support
< > Realtek 8723AU USB WiFi Support
< > Realtek 8723BU USB WiFi
<M> Realtek 8723B SDIO or SPI WiFi
< > Realtek 8723BS_VQ0 WiFi
< > Realtek 8723C SDIO or SPI WiFi
< > Realtek 8723D SDIO or SPI WiFi
< > Realtek 8812AU USB WiFi Support
< > Realtek 8189F SDIO WiFi
<M> Realtek 8188F USB WiFi
<M> Realtek 8822BS SDIO WiFi
<M> Realtek 8822B USB WiFi
```

板级 dts 无需配置 WIFI 芯片类型（配置了也可以），因为加载 wifi 驱动不依赖 wifi_chip_type

节点，如果 WIFI 没有根据 RK 发布的硬件参考设计，板级 dts 先确认如下信息：

以 RK3328 （kernel 4.4）为例：

arch/arm64/boot/dts/rockchip/rk3328-evb-android.dts dts wifi 部分只需注意如下红色部分标

记即可（配置好 WIFI_REG_ON 和 OOB 管脚）

GPIO1_C2/SDMMC1_PWREN/GMAC_CRS_M1_d	W20	WIFI_REG_ON/GMAC_CRS
GPIO1_C3/SDMMC1_DET/GMAC_MDIO_M1/PDM_FSYNC_M1_u	Y21	WIFI_HOST_WAKE/GMAC_MDIO/PDM_FSYNC_M1

```
sdio_pwrseq: sdio-pwrseq {
    compatible = "mmc-pwrseq-simple";
    pinctrl-names = "default";
    pinctrl-0 = <&wifi_enable_h>;

    /*
     * on the module itself this is one of these (depending
     * on the actual card populated):
     * - SDIO_RESET_L_WL_REG_ON
     * - PDN (power down when low)
     */
    reset-gpios = <&gpio1 18 GPIO_ACTIVE_LOW>;
};
```

```
wireless-wlan {
    compatible = "wlan-platdata";
    rockchip,grf = <&grf>;
    wifi_chip_type = "ap6354";
    sdio_vref = <1800>;
    WIFI_host_wake_irq = <&gpio1 19 GPIO_ACTIVE_HIGH>;
    status = "okay";
};
```

```
&pinctrl {
    pmic {
        pmic_int_1: pmic-int-1 {
            rockchip,pins =
                <2 RK_PA6 RK_FUNC_GPIO &pcfg_pull_up>; /* gpio2_a6 */
        };
    };

    sdio-pwrseq {
        wifi_enable_h: wifi-enable-h {
            rockchip,pins =
                <1 18 RK_FUNC_GPIO &pcfg_pull_none>;
        };
    };

    wireless-bluetooth {
        uart0_gpios: uart0-gpios {
            rockchip,pins =
                <1 10 RK_FUNC_GPIO &pcfg_pull_none>;
        };
    };
};
```

1.2 蓝牙移植内核部分

目前发现 rk3328 平台，蓝牙 wake_host_irq 管脚的状态不太正常，导致 UART 一次，蓝牙无法跑起来，这个脚为输出，状态为 lo，

```
root@rk3328:/ # cat sys/kernel/debug/gpio
```

```
GPIOs 32-63, platform/pinctrl.21, gpio1:
```

```
gpio-42 (ap6335_rts) out lo
```

```
gpio-50 (wlan_default_wlan_po) out lo
```

但是这个脚正常也是可以正常拉低拉高的。

```
拉低: io -4 0xff220004 0x00240400
```

```
拉高 io -4 0xff220004 0x04240400
```

问题原因：被主控拉低，因为接的一个管脚是内部下拉的管脚，这个脚 ipput 时会拉 low，

GPIO1_C7/I2S2_LRCK_TX_M0/GMAC_MDC_M1/PDM_SDI0_M1_d	V12	BT_WAKE_HOST/CLKOUT_GMAC_M2
GPIO1_D2/I2S2_LRCK_RX_M0/CLKOUT_GMAC_M2/PDM_SDI3_M1_d	AA17	I2S2_SDI0_M0/GMAC_RXER/PDM_SDI1_M1

考虑到其他平台也可能有相同的问题，那就不改 DTS，直接在 rkill 里面进行统一设定：

方法如下：

在拉高 BT power 之前，先吧这个脚设置为输出状态，并且为高电平，拉高 Power 后，再吧这个脚设置为输入状态，也就是还原为原本状态，内核提交号：ff766be22c901fd85992e4af80ed70e4f5ab45f2

```
commit ff766be22c901fd85992e4af80ed70e4f5ab45f2
Author: xxh <xxh@rock-chips.com>
Date: Fri Nov 24 15:23:30 2017 +0800

    bluetooth: rfkill: rockchip: ap6356s bluetooth module for RK3328 EVB board

    Change-Id: I3f1e7e792b1c4d6952080b15e5bdb2902df4ddb1
    Signed-off-by: Xu Xuehui <xxh@rock-chips.com>
```

这样蓝牙在 kernel 4.4 上就 UART 就正常通信了。

但是 adnroid 上层打开蓝牙，协议栈会崩溃，崩溃 LOG 如下：

```
01-01 00:02:02.073 F/DEBUG (4035): *** ** *
01-01 00:02:02.074 F/DEBUG (4035): Build fingerprint:
'Android/rk3328/rk3328:8.0.0/OPR5.170623.007/cw11222033:userdebug/test-keys'
01-01 00:02:02.074 F/DEBUG (4035): Revision: '0'
01-01 00:02:02.074 F/DEBUG (4035): ABI: 'arm64'
01-01 00:02:02.074 F/DEBUG (4035): pid: 3985, tid: 4014, name: stack_manager >>> com.android.bluetooth
<<<
01-01 00:02:02.074 F/DEBUG (4035): signal 6 (SIGABRT), code -6 (SI_TKILL), fault addr -----
01-01 00:02:02.085 F/DEBUG (4035): Abort message: '[0101/000201:FATAL:alarm.cc(154)] Check failed: false.
01-01 00:02:02.085 F/DEBUG (4035): '
```

分析协议栈相关源码，确认协议栈需要开启 rtc，内核提交号：c19d52e5b7955883743611c828d11519643e49cc

```
Author: xxh <xxh@rock-chips.com>
Date: Fri Nov 24 14:45:00 2017 +0800

arm64: dts: rockchip: RK3328 EVB board for bluetooth

Change-Id: Id54ef68dc939d3edf54d5cda1ee25e0014de2579
Signed-off-by: Xu Xuehui <xxh@rock-chips.com>

diff --git a/arch/arm64/boot/dts/rockchip/rk3328-evb-android.dts b/arch/arm64/boot/dts/rockchip/rk3328-evb-android.dts
index 48165cc..c7b5e31 100644
--- a/arch/arm64/boot/dts/rockchip/rk3328-evb-android.dts
+++ b/arch/arm64/boot/dts/rockchip/rk3328-evb-android.dts
@@ -168,6 +168,16 @@
    };
    vin-supply = <&vcc_io>;
};

+ wireless-bluetooth {
+     compatible = "bluetooth-platdata";
+     clocks = <&rk805 1>;
+     clock-names = "ext_clock";
+     uart_rts_gpios = <&gpio1 10 GPIO_ACTIVE_LOW>;
+     pinctrl-names = "default", "rts_gpio";
+     pinctrl-0 = <&uart0_rts>;
+     pinctrl-1 = <&uart0_gpios>;
+     BT.power_gpio = <&gpio1 21 GPIO_ACTIVE_HIGH>;
+     BT.wake_host_irq = <&gpio1 26 GPIO_ACTIVE_HIGH>;
+     status = "okay";
+ };

+ wireless-wlan {
+     compatible = "wlan-platdata";
+     rockchip,grf = <&grf>;
@@ -264,7 +277,7 @@
    clock-output-names = "xin32k", "rk805-clkout2";

-     rtc {
+         rtc {
+             status = "disabled";
+             status = "okay";
+         };
+     };

+     pwrkey {
@@ -424,6 +437,15 @@
    };

+     wireless-bluetooth {
+         uart0_gpios: uart0-gpios {
+             rockchip,pins =
+                 <1 10 RK_FUNC_GPIO &pcfg_pull_none>;
+         };
+     };
+ };

+ &pwm3 {
@@ -533,6 +553,12 @@
    status = "okay";
};
```

2 Wifi BT 兼容 android 部分

2.1 wifi 芯片识别流程

1. 开机对 wifi 模块上电，并自动进行扫描 sdio 操作
2. 系统启动打开 wifi 操作时，分别对系统 sys/bus/sdio (sdio wifi)， sys/bus/usb(usb wifi)， sys/bus/pic (pcie wifi) 文件系统下的 uevent 进行读取
3. 获取到 wifi 芯片 vid pid 加载相应的 wifi ko 驱动
4. 识别到相应的 wifi 模块后，即可知道相应的 bt 型号，走不同的 bluedroid 协议栈

Android 核心自动识别代码目录：**frameworks/opt/net/wifi/libwifi_hal/ rk_wifi_ctrl.cpp**,该部分 **check_wifi_chip_type_string** 的实现代码与 android 7.1 实现方式完全一样，原理如上描述。

8.0 上 rk_wifi_ctrl 动态库的编译有些许变化，也就是 8.0 和 7.1 的差别之处需要在 Android.bp 中添加编译规则，其他地方要用到 librkwifi-ctrl 直接引用即可

```
wifi_hal_cflags = [  
    "-Wall",  
    "-Werror",  
    "-Wextra",  
    "-Winit-self",  
    "-Wno-unused-function",  
    "-Wno-unused-parameter",  
    "-Wshadow",  
    "-Wunused-variable",  
    "-Wwrite-strings",  
]  
  
cc_library_shared {  
    name: "librkwifi-ctrl",  
    vendor: true,  
    cflags: wifi_hal_cflags,  
    local_include_dirs: ["include"],  
    shared_libs: ["libbase"],  
    header_libs: ["libcutils_headers"],  
    srcs: ["rk_wifi_ctrl.cpp"],  
}
```

额外要注意的, android 8.0 上统统放到了 vendor/rockchip/common/wifi/firmware 这个目录进行拷贝到系统的 vendor 目录下,

2.1 wpa_supplicant 启动部分修改

android 8.0 上面，将原来的 wpa_supplicant 启动和 wifi 驱动加载剥离开了，以前是统一在 wifi.c 里面处理，现在分为了 libwifi_hal/wifi_hal_common.cpp 和 libwifi_system/supplicant_manager.cpp

1. wifi_hal_common.cpp 文件修改

frameworks/opt/net/wifi/libwifi_hal/wifi_hal_common.cpp 该文件其实可以直接对应以前的 wifi.c 里面的核心部分是添加 check_wifi_chip_type_string, insmod 和 rmmmod 驱动，方式跟以前的 wifi.c 一样。

2. android 8.0 启动 wpa_supplicant bin 的方式

android 8.0 上面不在 init.rc 传入 wifi wpa 启动参数，以前直接在 init.rc 传参，现在考虑到兼容和 VTS 测试(), 所以考虑直接放到了原生态 external/wpa_supplicant_8/wpa_supplicant/main.c 里面 main_loop 函数进行兼容，当然如果不做兼容，也完全可以在 init.rc 中做，就是可以要自行对 wpa 进行修改，考虑到这里，RK android 8.0 wpa 兼容部分修改如下内容：

```
int main(int argc, char *argv[])
{
    int ret = -1;
    char module_type[20]={0};

    wpa_printf(MSG_INFO, "argc = %d\n", argc);
    if(argc == 2) {
        if (wifi_type[0] == 0) {
            check_wifi_chip_type_string(wifi_type);
        }
        wpa_printf(MSG_INFO, "Current wifi chip is %s\n", wifi_type);
        if (0 == strcmp(wifi_type, "RTL", 3)) {
            wpa_printf(MSG_INFO, "Start rtl_wpa_supplicant\n");
            ret = read_wpa_param_config(REALTEK_MODULE_NAME, argv[1]);
        } else if (0 == strcmp(wifi_type, "AP", 2)) {
            wpa_printf(MSG_INFO, "Start bcm_wpa_supplicant\n");
            ret = read_wpa_param_config(BROADCOM_MODULE_NAME, argv[1]);
        } else if (0 == strcmp(wifi_type, "SSV", 3)) {
            wpa_printf(MSG_INFO, "Start ssv_wpa_supplicant\n");
            ret = read_wpa_param_config(SSV_MODULE_NAME, argv[1]);
        } else if (0 == strcmp(wifi_type, "ESP", 3)) {
            wpa_printf(MSG_INFO, "Start esp_wpa_supplicant\n");
            ret = read_wpa_param_config(ESP_MODULE_NAME, argv[1]);
        } else {
            wpa_printf(MSG_INFO, "Start wpa_supplicant\n");
            sprintf(module_type, "[%s]", wifi_type);
            ret = read_wpa_param_config(module_type, argv[1]);
        }
    } else {
        wpa_printf(MSG_INFO, "Start wpa_supplicant\n");
        ret = main_loop(argc, argv);
    }
    return ret;
}
```

device/rockchip/common/ init.connectivity.rc 内容如下

service wpa_supplicant /vendor/bin/hw/wpa_supplicant \

/vendor/etc/wifi/wpa_config.txt

```
class main

socket wpa_wlan0 dgram 660 wifi wifi

disabled

oneshot
```

3. hardware/interfaces/wifi,该部分涉及 VTS,

WIFI-HAL: [android.hardware.wifi@1.0-service](#) 这个 service,也就是在以前 android 框架基础上又剥离了一层,以前 android 版本 wifi 相关命令都是 wpa_supplicant 直接通过 JNI 发送命令到驱动 frameworks/opt/net/wifi/service/jni/com_android_server_wifi_WifiNative.cpp, 现在与 wpa 通信的要经过如下的过程, 如下罗列一下重要的更新内容:

- ① frameworks/opt/net/wifi/service/java/com/android/server/wifi/WifiNative.java (JNI operations)
- ② SupplicantStaIfaceHal 和 mWifiVendorHal (Vendor HAL via HIDL)
- ③ **external/wpa_supplicant_8/wpa_supplicant/hidl/1.0/sta_iface.cpp**
- ④ frameworks/opt/net/wifi/service/java/com/android/server/wifi/SupplicantStaIfaceHal.java
- ⑤ frameworks/opt/net/wifi/service/jni/com_android_server_wifi_WifiNative.cpp
- ⑥ **hardware/interfaces/wifi/supplicant/1.0/ISupplicantIface.hal** (hardware 层 HAL)
- ⑦ **hardware/interfaces/wifi/supplicant/1.0/ISupplicantStaIface.hal**

可以看出, android 8.0 删除了原来 android 的 JNI 函数的注册,而大量使用 HIDL, HDIL 定义了很多对应 WIFI 的接口, 直接调用这些接口进行 IPC 交互, 跟 wpa_supplicant 方式也都统统改变, 使得上层 Framework 往下变得解耦, 使得上下层能独立更新, 用户更新系统时不依赖于硬件的限制, 所以也新增加了 WIFI VTS 的测试。

4. VtsHalWifiV1_0Target VTS 测试

标准 WIFI hal 需要在 device manifest 里面添加, 格式如下, 如下添加的标准 WIFI HAL

```
xxh@RD-DEP1-SERVER-163:~/work/rk3328_box_android_8.0_pro$ cd device/rockchip/rk3328/
xxh@RD-DEP1-SERVER-163:~/work/rk3328_box_android_8.0_pro/device/rockchip/rk3328$ git diff ./
diff --git a/manifest.xml b/manifest.xml
index 2f0d777..8ea17d2 100644
--- a/manifest.xml
+++ b/manifest.xml
@@ -118,6 +118,15 @@
     </interface>
   </hal>
   <hal format="hidl">
+    <name>android.hardware.wifi</name>
+    <transport>hwbinder</transport>
+    <version>1.0</version>
+    <interface>
+      <name>IWifi</name>
+      <instance>default</instance>
+    </interface>
+  </hal>
+  <hal format="hidl">
     <name>android.hardware.wifi.suppliment</name>
     <transport>hwbinder</transport>
     <version>1.0</version>
diff --git a/rk3328_box/manifest.xml b/rk3328_box/manifest.xml
index 2f0d777..6af21b4 100644
--- a/rk3328_box/manifest.xml
+++ b/rk3328_box/manifest.xml
@@ -118,6 +118,15 @@
     </interface>
   </hal>
   <hal format="hidl">
+    <name>android.hardware.wifi</name>
+    <transport>hwbinder</transport>
+    <version>1.0</version>
+    <interface>
+      <name>IWifi</name>
+      <instance>default</instance>
+    </interface>
+  </hal>
+  <hal format="hidl">
     <name>android.hardware.wifi.suppliment</name>
     <transport>hwbinder</transport>
     <version>1.0</version>
xxh@RD-DEP1-SERVER-163:~/work/rk3328_box_android_8.0_pro/device/rockchip/rk3328$
```

博通模块，采用 [android.hardware.wifi@1.0-service](#)+ VtsHalWifiV1_0Target 测试 VTS PASS

Realtek 模块，采用 [android.hardware.wifi@1.0-service](#)+ VtsHalWifiV1_0Target 测试 VTS FAIL

咨询过 realtek，目前他们的驱动对 VTS 这块还有缺陷 (先弄个 beta 版本)。

目前 SDK 屏蔽掉了 [android.hardware.wifi@1.0-service](#)，但是要添加驱动加载，否则 android 8.0 不会去加载 WIFI 驱动，实现方式直接加载驱动方式，由于 VTS 采用的两种方式，一种是 wpa_supplicant，一种是 wifi_hal，采用 wifi_hal VTS 都可以 PASS，也就是说目前 SDK 屏蔽掉 hardware.wifi service，采用了 android.hardware.wifi.suppliment+VTS 测试方式，realtek 不测试 WIFI hal，具体让原厂介入修复 realtek 模块的问题，manifest.xml 内容如下

```
<hal format="hidl">
  <name>android.hardware.wifi.suppliment</name>
  <transport>hwbinder</transport>
  <version>1.0</version>
  <interface>
    <name>ISuppliment</name>
    <instance>default</instance>
  </interface>
</hal>
```

说明：反正这个方式还值得讨论，目前的做法只是考虑到 VTS 测试和功能性的问题，[也就是剥离了原生态本来 libwifi_hal 和 android.hardware.wifi 的联系](#)

```
xxh@RD-DEP1-SERVER-163:~/work/rk3328_android_8.0_pro/hardware/interfaces/wifi$ ls -al
total 24
drwxrwxr-x  4 xxh xxh 4096 Dec  6 19:12 .
drwxrwxr-x 36 xxh xxh 4096 Dec 27 15:02 ..
drwxrwxr-x  4 xxh xxh 4096 Dec  6 19:14 1.0
-rw-rw-r--  1 xxh xxh 120 Nov 21 09:59 Android.bp
-rw-rw-r--  1 xxh xxh 35 Nov 21 09:59 .clang-format
drwxrwxr-x  3 xxh xxh 4096 Nov 21 09:59 supplicant
xxh@RD-DEP1-SERVER-163:~/work/rk3328_android_8.0_pro/hardware/interfaces/wifi$
```

android.hardware.wifi.serve.1@

andriod.hardware.wifi.supplliant方式

遗留问题:

1. Wpa 私有库和 wpa_supplicant 的兼容

```
# Pick a vendor provided HAL implementation library.
# =====
LIB_WIFI_HAL := libwifi-hal-fallback
VENDOR_LOCAL_SHARED_LIBRARIES :=
ifeq ($(BOARD_WLAN_DEVICE), bcmhd)
LIB_WIFI_HAL := libwifi-hal-bcm
else ifeq ($(BOARD_WLAN_DEVICE), qcom)
LIB_WIFI_HAL := libwifi-hal-qcom
VENDOR_LOCAL_SHARED_LIBRARIES := libclld80211
else ifeq ($(BOARD_WLAN_DEVICE), mrvl)
# this is commented because none of the nexus devices
# that sport Marvell's wifi have support for HAL
# LIB_WIFI_HAL := libwifi-hal-mrvl
else ifeq ($(BOARD_WLAN_DEVICE), MediaTek)
# support MTK WIFI HAL
LIB_WIFI_HAL := libwifi-hal-mt66xx
endif
# The wifi HAL that you should be linking.
```

2. GMS 项目上 VTS 和 realtek 模块的兼容 (realtek 原厂处理中, 进度缓慢)

3 Wifi BUG 汇总

1. Wifi 开关异常（解决 100%）

WIFI 驱动 free_irq 调用，free_irq 前，irq 已经 disable 了，这个没错，因为最后一次执行的是 disable_irq_nosync，由于 AP 系列 WIFI 都是使用的 OOB 中断，关闭 WIFI，需要 free_irq，以下警告，这个警告在 reboot 或者其他情况可能会导致其他系统问题

```
[11244.134024] [<fffff80089174c4>] clk_core_disable+0x18/0x18c
```

```
[11244.134039] [<fffff80089178f0>] clk_disable+0x2c/0x40
```

```
[11244.134064] [<fffff80083ab5a4>] rockchip_irq_gc_mask_set_bit+0x20/0x2c
```

```
[11244.134086] [<fffff80080f7788>] irq_shutdown+0x4c/0x68
```

```
[11244.134098] [<fffff80080f556c>] __free_irq+0x100/0x20c
```

这个问题其实有两个改法：

1. 修改 WIFI 驱动，在 free_irq 之前，enable 一次，RK3328 上面这么修改，需要修改 OOB 管脚 pinctrl，否则会出现关闭 WIFI，直接中断打死 CPU。我在 gerit 上也有临时版本

```
arm64: dts: rk3328: fix wifi oob interrupt infinitely increase
the reason is wifi oob pin internal pullup by rk3328
operation show as below:
1. close wifi or ifconfig wlan0 down
2. call enable_irq function
3. oob interrupt infinitely increase
Change-Id: I24b8c8afa592acb6be63599a7fa4cc74fff44e82
Signed-off-by: Xu Xuehui <xxh@rock-chips.com>
```

```
Author      Xu Xuehui <xxh@rock-chips.com>
Committer   Xu Xuehui <xxh@rock-chips.com>
Commit      413d3b7b6e3e7fbladalcce3807fd2bb48f7e186
Parent(s)   abb89382597546598b2d835314807b76b7e01fed
Change-Id   I24b8c8afa592acb6be63599a7fa4cc74fff44e82
```

2. 内核 irq 修复 BUG，如下是在 UPSTREAM 上查到的相关实现，一共 5 个提交，由涛哥审核后合入

e41d630 UPSTREAM: genirq/PM: Properly pretend disabled state when force resuming

interrupts ff9c8bc UPSTREAM: genirq: Avoid unnecessary low level irq function calls

52e28f1 UPSTREAM: genirq: Set irq masked state when initializing irq_desc

4095964 UPSTREAM: genirq: Warn when IRQ_NOAUTOEN is used with shared interrupts

255ba95 UPSTREAM: genirq: Handle NOAUTOEN interrupt setup proper

Revert "net: wireless: rockchip_wlan: ap6255: fix irq abnormal."

2. Wifi 掉线（解决 100%）

IpReachabilityMonitor: ALERT: NeighborEvent{elapsedMs=8086632, 192.168.31.1, [(null)], RTM_NEWNEIGH, NUD_FAILED}

IpReachabilityMonitor: FAILURE: LOST_PROVISIONING, NeighborEvent{elapsedMs=8086632, 192.168.31.1, [(null)], RTM_NEWNEIGH, NUD_FAILED}

frameworks/base/services 提交号: bf8dca855bbd972a03bdfd9dd4c9c14fcf8ebc17

```
commit bf8dca855bbd972a03bdfd9dd4c9c14fcf8ebc17
Author: xxh <xxh@rock-chips.com>
Date: Thu Dec 14 09:16:23 2017 +0800

wifi: fix wifi disconnect, the log such as below

IpReachabilityMonitor: ALERT: NeighborEvent{elapsedMs=8086632, 192.168.31.1, [(null)], RTM_NEWNEIGH, NUD_FAILED}
IpReachabilityMonitor: FAILURE: LOST_PROVISIONING, NeighborEvent{elapsedMs=8086632, 192.168.31.1, [(null)], RTM_NEWNEIGH, NUD_FAILED}

this is temporary mofiy, kernel neighbor protocol may not support well for this feature, we will check in the future

change-Id: I7e84ba8d7e5f76b32651cfe605c73599166c104a
Signed-off-by: Xu Xuehui <xxh@rock-chips.com>
```

备注：该处理方式跟以前 7.1 方式不一样，以前 7.1 我是有两个方案：

1. 直接屏蔽 IpReachabilityMonitor Service，也就是系统没有这个 service
2. 在 wifi roming 的时候才触发 IpReachabilityMonitor, 也就是保留这个 service，在 roming 触发

3. Wifi RX/TX 驱动异常（解决 100%）

dhd_dpc 跑到了 sdio 可休眠函数，直接死锁，导致 WIFI HAGUP

内核提交号: 21ff1d170f97e52366d77b2bc7506483b48f85e3

```
commit 21ff1d170f97e52366d77b2bc7506483b48f85e3
Author: xxh <xxh@rock-chips.com>
Date: Tue Dec 12 17:04:39 2017 +0800

    net: wireless: rockchip_wlan: fix bcmhd driver spin lock issue
```

```
[<ffffff8008b0f258>] schedule_timeout+0x3c/0x260

[<ffffff8008b0d48c>] wait_for_common+0x130/0x168

[<ffffff8008b0d4d8>] wait_for_completion+0x14/0x1c

[<ffffff800876947c>] mmc_wait_for_req+0x84/0x160

[<ffffff8008774518>] mmc_io_rw_extended+0x26c/0x2ec

[<ffffff8008775958>] sdio_io_rw_ext_helper+0x14c/0x1a0

[<ffffff8008775b50>] sdio_readsb+0x1c/0x24

[<ffffff8000b5d480>] sdioh_buffer_tofrom_bus+0xc0/0x238 [bcmhd]

[<ffffff8000b5e910>] sdioh_request_buffer+0x1c0/0x360 [bcmhd]

[<ffffff8000b5c1c8>] bcmsdh_rcv_buf+0x88/0xc0 [bcmhd]

[<ffffff8000b6412c>] dhd_bcmsdh_rcv_buf.constprop.25+0x64/0x98 [bcmhd]

[<ffffff8000b66fb8>] dhdsdio_readframes+0x908/0x14e0 [bcmhd]

[<ffffff8000b6bc20>] dhd_bus_dpc+0x6c0/0xb80 [bcmhd]

[<ffffff8000b35cd8>] dhd_dpc_thread+0x128/0x1a0 [bcmhd]
```

4. ATV Wifi 连接 AP 慢 (按照 box android 7.1 的方式处理)

packages/apps/TvSettings 目录如下提交

```
commit 3493d405dd8eae2ac1de88fee524b8fc056f7de
```

```
Author: xxh <xxh@rock-chips.com>
```

```
Date: Fri Jan 5 08:50:38 2018 +0800
```

```
ConnectToWifiFragment: solve wifi connect ap so slow
```

5. Kernel 4.4 wifi ko rmmmod/insmod 问题（处理中）

目前发现 kernel 4.4 SDIO 框架设置为了 no-removable，导致卸载后，无法正常加载 驱动

暂时处理办法，对于 32K 的调整，再评估

```
diff --git a/arch/arm64/boot/dts/rockchip/rk3328-evb-android.dts
```

```
b/arch/arm64/boot/dts/rockchip/rk3328-evb-android.dts
```

```
index 6bda0fd..0c63896 100644
```

```
--- a/arch/arm64/boot/dts/rockchip/rk3328-evb-android.dts
```

```
+++ b/arch/arm64/boot/dts/rockchip/rk3328-evb-android.dts
```

```
@ @ -112,6 +112,7 @ @
```

```
rockchip,grf = <&grf>;
```

```
wifi_chip_type = "ap6354";
```

```
sdio_vref = <1800>;
```

```
+ WIFI,poweren_gpio = <&gpio1 18 GPIO_ACTIVE_HIGH>;
```

```
WIFI,host_wake_irq = <&gpio1 19 GPIO_ACTIVE_HIGH>;
```

```
status = "okay";
```

```
};
```

```
@ @ -500,8 +501,6 @ @
```

```
disable-wp;
```

```
keep-power-in-suspend;
```

```
max-frequency = <150000000>;
```

```
- mmc-pwrseq = <&sdio_pwrseq>;
```

```
- non-removable;
```

```
num-slots = <1>;
```

```
pinctrl-names = "default";
```

```
pinctrl-0 = <&sdmmc1_bus4 &sdmmc1_cmd &sdmmc1_clk>;
```


6. Ap6356s 驱动概率出现扫描超时，设置界面无响应 问题（处理中）

```
[ 38.234365] Unable to handle kernel NULL pointer dereference at virtual
address 00000028
...
[ 38.234420] task: dc83bf00 task.stack: dc844000
[ 38.234438] PC is at wl_scan_timeout+0x11c/0x1dc
[ 38.234451] LR is at _raw_spin_unlock_irqrestore+0x1c/0x24
[ 38.234458] pc : [<c0675ddc>] lr : [<c0be39cc>] psr: 600c0113
[ 38.234458] sp : dc845e10 ip : dc845d28 fp : dc845e74
[ 38.234462] r10: c0e4385a r9 : 00000020 r8 : deec14a0
[ 38.234467] r7 : deec04a0 r6 : c126e864 r5 : deec16e4 r4 : deec46e8
[ 38.234472] r3 : 00000000 r2 : 00000020 r1 : dc83bf00 r0 : 0000001a
```

测试命令：

```
while true; do echo "scan"; wpa_cli scan; sleep 2; wpa_cli scan_result; done
```

自测在一台样机上出现，怀疑 WIFI 驱动概率出现空指针应用，采用如下改动暂时又没发现异常，两台 SDK 不添加改动同样正常，为复现到问题，怀疑硬件可能有点问题

```
diff --git a/drivers/net/wireless/rockchip_wlan/rkwifi/bcmdhd/wl_cfg80211.c
```

```
b/drivers/net/wireless/rockchip_wlan/rkwifi/bcmdhd/wl_cfg80211.c
```

```
index e246088..4f0f5db 100644
```

```
--- a/drivers/net/wireless/rockchip_wlan/rkwifi/bcmdhd/wl_cfg80211.c
```

```
+++ b/drivers/net/wireless/rockchip_wlan/rkwifi/bcmdhd/wl_cfg80211.c
```

```
@@ -14082,7 +14082,7 @@
```

```
struct bcm_cfg80211 *cfg = (struct bcm_cfg80211 *)data;
```

```
struct wireless_dev *wdev = NULL;
```

```
struct net_device *ndev = NULL;
```

```
- struct wl_scan_results *bss_list;
```

```
+ struct wl_scan_results *bss_list = NULL;
```

```
struct wl_bss_info *bi = NULL;
```

```
s32 i;
```

```
u32 channel;
```

7. Ap6356s Softap 功能异常（处理中）

```
dhd_os_open_image: /vendor/etc/firmware/fw_bcm4356a2_ag.bin (558327 bytes) open
```

success

dhd_os_open_image: /vendor/etc/firmware/nvram_ap6356.txt (2840 bytes) open success

原因:

1. 没有跑 libwifi-hal.so 流程, 也就是没有走 change_fw, 这个是由于引入了 rk wifi hal 导致, 目前 retek 由于驱动原因, 不支持 wifi hal,
2. 下载正常的 FW 后, 同样无法连接, 更换 WIFI FW 由可以正常连接 (没找到原因)

解决办法:

```
xxh@RD-DEP1-SERVER-163:~/work/rk3328_box_android_8.0_pro/device/rockchip/rk3328$ git diff ./
diff --git a/manifest.xml b/manifest.xml
index 2f0d777..8ea17d2 100644
--- a/manifest.xml
+++ b/manifest.xml
@@ -118,6 +118,15 @@
     </interface>
   </hal>
   <hal format="hidl">
+    <name>android.hardware.wifi</name>
+    <transport>hwbinder</transport>
+    <version>1.0</version>
+    <interface>
+      <name>Iwifi</name>
+      <instance>default</instance>
+    </interface>
+  </hal>
+  <hal format="hidl">
    <name>android.hardware.wifi.suplicant</name>
    <transport>hwbinder</transport>
    <version>1.0</version>
diff --git a/rk3328_box/manifest.xml b/rk3328_box/manifest.xml
index 2f0d777..6af21b4 100644
--- a/rk3328_box/manifest.xml
+++ b/rk3328_box/manifest.xml
@@ -118,6 +118,15 @@
     </interface>
   </hal>
   <hal format="hidl">
+    <name>android.hardware.wifi</name>
+    <transport>hwbinder</transport>
+    <version>1.0</version>
+    <interface>
+      <name>Iwifi</name>
+      <instance>default</instance>
+    </interface>
+  </hal>
+  <hal format="hidl">
    <name>android.hardware.wifi.suplicant</name>
    <transport>hwbinder</transport>
    <version>1.0</version>
xxh@RD-DEP1-SERVER-163:~/work/rk3328_box_android_8.0_pro/device/rockchip/rk3328$
```

4 BT BUG 汇总

1. ATV BLE 遥控器设备连接不上（解决 100%）

需要更新蓝牙 FW，并且放开 BLE_VND_INCLUDED, 否则 BLE 遥控器连接不上

```
Change-Id: Ia0ac12c42e67740cb8d5709e6bb4a25e5160003d
Signed-off-by: Xu Xuehui <xxh@rock-chips.com>

diff --git a/bluetooth/bdroid_buildcfg.h b/bluetooth/bdroid_buildcfg.h
index 9cb8378..4c74241 100755
--- a/bluetooth/bdroid_buildcfg.h
+++ b/bluetooth/bdroid_buildcfg.h
@@ -20,5 +20,7 @@
#define BTM_DEF_LOCAL_NAME      "rk3328"
#define BTA_DM_COD {0x1A, 0x01, 0x10}

+#define BLE_PRIVACY_SPT FALSE
+#define BLE_VND_INCLUDED TRUE
#endif
```

2. ATV HID 蓝牙鼠标设备配对失败（解决 100%）

packages/apps/TvSettings 目录如下提交解决

commit c720b9b8daad4de80d50d4c250edf62bdd566d75

Author: xxh <xxh@rock-chips.com>

Date: Fri Dec 15 14:24:21 2017 +0800

Bluetooth: solve some Bluetooth HID Device Pair fail problem

Change-Id: I52a6bdb69011e6b3d15a6df9141d202c53aa9a8c

Signed-off-by: Xu Xuehui <xxh@rock-chips.com>

xxh@RD-DEP1-SERVER-163:~/work/rk3328_android_8.0_pro/packages/apps/TvSettings\$

3. ATV BT remote ctrl 和 BLE 遥控器回连问题（解决 100%）

BLE 测试中有关配对的操作，需要将 RC 去掉，这是 ATV 上面 GOOGEL 自带的 RC 引起，过

CTS 需要去掉，以后有遥控器需求可以放开即可，目前 SDK 默认关闭

```
xxh@RD-DEP1-SERVER-163:~/work/rk3328_android_8.0_pro$ cd device/rockchip/rk3328/
xxh@RD-DEP1-SERVER-163:~/work/rk3328_android_8.0_pro/device/rockchip/rk3328$ git diff ./
diff --git a/bluetooth/bdroid_buildcfg.h b/bluetooth/bdroid_buildcfg.h
index 442b8da..4c74241 100755
--- a/bluetooth/bdroid_buildcfg.h
+++ b/bluetooth/bdroid_buildcfg.h
@@ -20,7 +20,7 @@
#define BTM_DEF_LOCAL_NAME      "rk3328"
#define BTA_DM_COD {0x1A, 0x01, 0x10}

-#define BLE_PRIVACY_SPT TRUE
+#define BLE_PRIVACY_SPT FALSE
#define BLE_VND_INCLUDED TRUE
#endif
```

4. ATV BLE CtsVerifier 测试（解决 100%）

关闭如下宏，测试完全 PASS

```
xxh@RD-DEPI-SERVER-163:~/work/rk3328_android_8.0_pro/device/rockchip/rk3328$ git show c7
commit c746ad7c288c4086c82872dfa1d8a809198a616d
Author: Xu Xuehui <xxh@rock-chips.com>
Date: Tue Dec 26 10:07:36 2017 +0800

    bluetooth: remove rc for BLE cts test

    Change-Id: Id5766deb7b60478590b0dfa8cc9ca6533db70e93
    Signed-off-by: Xu Xuehui <xxh@rock-chips.com>

diff --git a/bluetooth/bdroid_buildcfg.h b/bluetooth/bdroid_buildcfg.h
index 4c74241..442b8da 100755
--- a/bluetooth/bdroid_buildcfg.h
+++ b/bluetooth/bdroid_buildcfg.h
@@ -20,7 +20,7 @@
 #define BTM_DEF_LOCAL_NAME    "rk3328"
 #define BTA_DM_COD {0x1A, 0x01, 0x10}

-#define BLE_PRIVACY_SPT FALSE
+#define BLE_PRIVACY_SPT TRUE
 #define BLE_VND_INCLUDED TRUE
 #endif
```

5. ATV 无法接受文件（解决 100%）

ATV 上默认是关闭了 OPP Profile，打开即可支持文件传输：**profile_supported_opp**

```
diff --git a/overlay/packages/apps/Bluetooth/res/values/config.xml b/overlay/packages/apps/Bluetooth/res/values/config.xml
index 2385dd2..499bfd5 100644
--- a/overlay/packages/apps/Bluetooth/res/values/config.xml
+++ b/overlay/packages/apps/Bluetooth/res/values/config.xml
@@ -15,7 +15,7 @@
 <resources>
   <bool name="profile_supported_pbap">false</bool>
   <bool name="profile_supported_map">false</bool>
-  <bool name="profile_supported_opp">false</bool>
+  <bool name="profile_supported_opp">true</bool>
   <string name="pairing_ui_package">com.android.tv.settings</string>
 </resources>
```

```
xxh@RD-DEPI-SERVER-163:~/work/rk3328_android_8.0_pro/packages/apps/Bluetooth$ git diff ./
diff --git a/src/com/android/bluetooth/opp/BluetoothOppNotification.java b/src/com/android/bluetooth/opp/BluetoothOppNotification.java
index 19d359d..4bc712b 100644
--- a/src/com/android/bluetooth/opp/BluetoothOppNotification.java
+++ b/src/com/android/bluetooth/opp/BluetoothOppNotification.java
@@ -51,6 +51,8 @@
 import android.os.Process;

 import java.util.HashMap;
+import android.os.SystemProperties;
+import android.util.Log;

 /** This class handles the updating of the Notification Manager for the cases
@@ -512,6 +514,10 @@
     Uri contentUri = Uri.parse(BluetoothShare.CONTENT_URI + "/" + info.mId);
     Intent baseIntent = new Intent().setDataAndNormalize(contentUri)
         .setClassName(Constants.THIS_PACKAGE_NAME, BluetoothOppReceiver.class.getName());
+    if (SystemProperties.get("ro.target.product", "atv").equals("atv")) {
+        Log.d(TAG, "this is box or atv, so direct send file.");
+        mContext.sendBroadcast(new Intent(baseIntent).setAction(Constants.ACTION_INCOMING_FILE_CONFIRM));
+    } else {
     Notification.Action actionDecline =
         new Notification.Action
             .Builder(R.drawable.ic_decline,
@@ -556,6 +562,7 @@
         class BluetoothOppNotification {
             .build();
             mNotificationMgr.notify(NOTIFICATION_ID_PROGRESS, n);
         }
     }
     cursor.close();
 }
```

6. 蓝牙配对音响后，关闭蓝牙，发现蓝牙上报的断开连接时间比较长，达到 20S

如果是由 AP6356S 主动去连接音箱，这个值就会被设置，默认是 5 秒

但是当由音箱回连时候，是音箱作为 Master，但是并没有看到音箱设置 timeout 时间，因此协议栈里面默认就是 20s

```
define HCI_DEFAULT_INACT_TOUT 0x7D00    /* BR/EDR (20 seconds) */
```

这个其实跟外面蓝牙设备有关，与同样音响跟手机连接，测试发现断开连接也是 5S，音响配置无法修改，只能修改协议栈。如下修改可以解决，目前自测是 1 秒钟，（提交暂时未上 SDK，需要验证对其他蓝牙行为是否有音响，因为 BOX 和 ATV 是同一套 SDK，ATV 上不建议修改，可能会影响 CTS 或者其他测试）

修改如下：

```
/* link supervision timeout in 625uS (5 secs) */
```

```
#ifndef BTA_DM_LINK_TIMEOUT
```

Supervision_Timeout:

Size: 2 Octets

Value	Parameter Description
0xXXXX	Connection supervision timeout. Range: 0x000A to 0x0C80 Time = N * 10 msec Time Range: 100 msec to 32 seconds

```
xxh@RD-DEP1-SERVER-163:~/work/rk3328_box_android_8.0_pro/system/bt$ git diff ./
diff --git a/bta/dm/bta_dm_cfg.cc b/bta/dm/bta_dm_cfg.cc
index 4202975..0850a78 100644
--- a/bta/dm/bta_dm_cfg.cc
+++ b/bta/dm/bta_dm_cfg.cc
@@ -44,7 +44,7 @@

/* link supervision timeout in 625uS (5 secs) */
#ifndef BTA_DM_LINK_TIMEOUT
-#define BTA_DM_LINK_TIMEOUT 8000
+#define BTA_DM_LINK_TIMEOUT 1600
#endif

/* TRUE to avoid scatternet when av is streaming (be the master) */
diff --git a/include/bt_target.h b/include/bt_target.h
index eadfc92..4c37afb 100644
--- a/include/bt_target.h
+++ b/include/bt_target.h
@@ -567,7 +567,7 @@

/* whether link wants to be the master or the slave. */
#ifndef L2CAP_DESIRED_LINK_ROLE
-#define L2CAP_DESIRED_LINK_ROLE HCI_ROLE_SLAVE
+#define L2CAP_DESIRED_LINK_ROLE HCI_ROLE_MASTER
#endif
```

5 wifi ko 编译注意事项

通过跟涛哥沟通，认为可以直接在 make kernel.img 的时候，顺带吧系统的 module 编译出来，

arch/arm64/Makefile 已经集成，android 只需进行一次拷贝即可

```
$(Q)$(MAKE) modules
@echo "Image: kernel"
ifdef CONFIG_MODULES
    $(Q)$(MAKE) modules
endif
```

Android 拷贝还是按照 android 7.1 的脚本做法，为了方便，直接将该脚本集成到了 ./mkming.sh 文件中

device/rockchip/common/build_wifi_ko.sh 脚本内容：

```
#!/bin/bash
TARGET_ARCH=$1
TARGET_OUT_VENDOR=$2
echo "---- make wifi ko ----"
echo "TARGET_ARCH = $TARGET_ARCH"

#make -C kernel ARCH=$TARGET_ARCH modules -j8

mkdir -p $TARGET_OUT_VENDOR/lib/modules/wifi

find kernel/drivers/net/wireless/rockchip_wlan/* -name "*.ko" | \
xargs -n1 -i cp {} $TARGET_OUT_VENDOR/lib/modules/wifi/
echo "Install wifi ko to $TARGET_OUT_VENDOR/lib/modules/wifi/"
~
~
```

集成到 ./mkimag.sh 中的后，每次编译打包都会进行拷贝。

```
if [ `grep "CONFIG_WIFI_BUILD_MODULE=y" $KERNEL_CONFIG` ]; then
    echo "Install wifi ko to $TARGET_OUT_VENDOR/lib/modules/wifi/"
    mkdir -p $TARGET_OUT_VENDOR/lib/modules/wifi
    find kernel/drivers/net/wireless/rockchip_wlan/* -name "*.ko" | xargs -n1 -i cp {} $TARGET_OUT_VENDOR/lib/modules/wifi/
fi
```


6 Wifi 驱动加载方式说明

如果不需要 wifi 自动兼容方案，可以将 wifi 驱动 build in 到内核，因此需要客户自行决定。目前最新对外服务器 android 7.1 代码支持 ko 或者 build in 两种方式，如果是 build in 到内核，建议使用如下表格中的方式 1，以 RTL8188EU 为例，ko 方式和 build in 方式详细配置如下表：

wifi 驱动加载方式	配置
方式 1	<code>CONFIG_WIFI_LOAD_DRIVER_WHEN_KERNEL_BOOTUP=y</code> <code>WIFI_BUILD_MODULE = n</code> <code>CONFIG_RTL8188EU=y</code>
方式 2	<code>CONFIG_WIFI_LOAD_DRIVER_WHEN_KERNEL_BOOTUP=n</code> <code>WIFI_BUILD_MODULE = n</code> <code>CONFIG_RTL8188EU=y</code>
方式 3	<code>CONFIG_WIFI_LOAD_DRIVER_WHEN_KERNEL_BOOTUP=n</code> <code>WIFI_BUILD_MODULE = y</code> <code>CONFIG_RTL8188EU=m</code>

说明：方式 3 即是前面章节提到完全兼容配置，方式 1 和方式 2 不支持 wifi 完全兼容，kernel 4.4 和 kernel 3.10 只需要注意区分 64 位和 32 位，编译 wifi ko 是 `make ARCH=arm64 modules` 或者 `make modules`

方式 1：wifi 驱动 build in 到内核，内核启动阶段直接加载 wifi 驱动

方式 2：wifi 驱动 build in 到内核，打开 wifi 再加载驱动，说明方式 2 是为了兼容 android 5.1

方式 3：wifi 驱动以 ko 方式存在于系统，打开 wifi 再加载 ko

7 Wifi 、 BT dts 配置

目前 RK 平台有 kernel 4.4 和 kernel 3.10，对于不同的内核版本,DTS 有配置是有差异的，本章节对不同平台的 DTS WIFI BT 部分做相关说明

7.1 kernel 4.4 平台

以 RK3328 为例，需要注意如下 pinctrl 的配置，其中 sdio-pwrseq 是 WIFI_REG_ON 管脚和蓝牙 rts_gpio 管脚，32K 是 RK805 提供，因此要放开此 CLK，其他 RK 平台类似这样修改。

```
wireless-bluetooth {

    compatible = "bluetooth-platdata";

    clocks = <&rk805 1>;

    clock-names = "ext_clock";

    uart_rts_gpios = <&gpio1 10 GPIO_ACTIVE_LOW>;

    pinctrl-names = "default", "rts_gpio";

    pinctrl-0 = <&uart0_rts>;

    pinctrl-1 = <&uart0_gpios>;

    BT,power_gpio = <&gpio1 21 GPIO_ACTIVE_HIGH>;

    BT,wake_host_irq = <&gpio1 26 GPIO_ACTIVE_HIGH>;

    status = "okay";

};

wireless-wlan {

    compatible = "wlan-platdata";

    rockchip,grf = <&grf>;

    wifi_chip_type = "ap6354";

    sdio_vref = <1800>;
```

```

WIFI,host_wake_irq = <&gpio1 19 GPIO_ACTIVE_HIGH>; /*wifi wake host 管脚*/

status = "okay";

};

};

&pinctrl {

    sdio-pwrseq {

        wifi_enable_h: wifi-enable-h {

            rockchip,pins =

                <1 18 RK_FUNC_GPIO &pcfg_pull_none>;

        };

    };

    wireless-bluetooth {

        uart0_gpios: uart0-gpios {

            rockchip,pins =

                <1 10 RK_FUNC_GPIO &pcfg_pull_none>;

        };

    };

};

```

7.2 kernel 3.10 平台

WIFI BT 管脚 DTS 配置如下，同样以 RK3328 平台为例

```

wireless-wlan {

    compatible = "wlan-platdata";

    wifi_chip_type = "ap6335";

```

```
sdio_vref = <1800>;

WIFI,poweren_gpio = <&gpio1 GPIO_C2 GPIO_ACTIVE_HIGH>;

WIFI,host_wake_irq = <&gpio1 GPIO_C3 GPIO_ACTIVE_HIGH>;

status = "okay";

};
```

```
wireless-bluetooth {

    compatible = "bluetooth-platdata";

    uart_rts_gpios = <&gpio1 GPIO_B2 GPIO_ACTIVE_LOW>;

    pinctrl-names = "default", "rts_gpio";

    pinctrl-0 = <&uart0_rts>;

    pinctrl-1 = <&uart0_rts_gpio>;

    BT,power_gpio = <&gpio1 GPIO_C5 GPIO_ACTIVE_HIGH>;

    BT,wake_host_irq = <&gpio1 GPIO_D2 GPIO_ACTIVE_HIGH>;

    status = "okay";

};
```
